

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511  
CO. REG:200707743D GST REG:200707743D

26-Dec-18

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHD 1069 E

|          |                                           |    |          |
|----------|-------------------------------------------|----|----------|
| 1 pc     | Front bumper <i>X 14.2</i>                | \$ | 531.00   |
| 1 pc     | Front bumper emblem <i>/</i>              | \$ | 44.00    |
| 1 pc     | Front bumper n/s side retainer <i>X</i>   | \$ | 16.00    |
| 1 pc     | Front bumper n/s upper bracket <i>X</i>   | \$ | 16.00    |
| 1 pc     | Front bumper n/s support bracket <i>X</i> | \$ | 16.00    |
| 1 pc     | Front bumper n/s fog lamp cover <i>X</i>  | \$ | 66.00    |
| 2 pc     | Front bumper n/s protector <i>X</i>       | \$ | 51.00    |
| 1 pc     | Front n/s fender <i>/</i>                 | \$ | 384.00   |
| 1 pc     | Front n/s fender inner shield <i>X</i>    | \$ | 120.00   |
| 1 pc     | Front n/s wheel cover <i>/</i>            | \$ | 116.00   |
|          |                                           | \$ | 1,360.00 |
| Less 10% |                                           | \$ | 136.00   |
|          |                                           | \$ | 1,224.00 |

### S/NETT

|                                                                                                                                              |                                              |    |                           |
|----------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------|----|---------------------------|
| 1 pc                                                                                                                                         | Front bumper clips <i>X</i>                  | \$ | 48.00                     |
| 1 set                                                                                                                                        | Front n/s fender inner shield clips <i>X</i> | \$ | 24.00                     |
| 1 pc                                                                                                                                         | Front n/s fender stickers <i>X</i>           | \$ | 30.00                     |
| Sundry                                                                                                                                       |                                              | \$ | <del>50.00</del> 20       |
| To check wheel alignment                                                                                                                     |                                              | \$ | <del>80.00</del> <i>X</i> |
| To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same |                                              | \$ | <del>550.00</del> 300     |
| To putty and spray painting on front bumper, front n/s fender                                                                                |                                              | \$ | <del>400.00</del> 360     |
| To apply rustproofing on the repaired and replaced panels.                                                                                   |                                              | \$ | <del>80.00</del> 30       |
|                                                                                                                                              |                                              | \$ | 2,486.00                  |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

Ka/ln (LKK)

26/12/18 1600hrs  
3 Days  
P.P.  
Before Paint p/ln