

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 16:56

Company Reg. No. 199902271W
GST Reg. No. 199902271W

Customer

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013931 Date : 17/06/2019 Order : SJJ8831U Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No: SJJ8831U (V 31608)	Regn Date: 29/12/2016	Mileage: 46119	WIP No.: 37187
Model: A3 SEDAN 1.0 TFSI 8VMANG	Chassis: WAUZZZ8V7H1012229	Engine: CHZ 132234	Dept: U
You have been assisted by :- UB-Justin Ee (R) (46)			

		Details	Qty	Unit Price	Amount
S	SUBLET	M: TO SUPPLY VEHICLE NUMBER PLATE	25.00	1.00	25.00
Q	EXC	M: 8888 Insurance Excess/Liability	-300.00	1.00	-300.00
S	BODYWORK	M: TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	360.00	1.00	360.00
S	BODYWORK	M: TO DISMANTLE AND REPAIR FRONT BUMPER ASSY. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	500.00	1.00	500.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER.	550.00	1.00	550.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK.	192.00	1.00	192.00
X	A8V3853651AA3F2	GRILLE	1.00	1239.00	991.20
X	A8V4807109C	BEAM	1.00	632.50	506.00
X	A8K0010520A	PLATE	1.00	11.60	9.28
X	A8V0010515A	STICKER	1.00	6.10	4.88
X	A8V3853949	PLATE	1.00	166.50	133.20

Parts 1,644.56
Labour 0.00
Sublet 1,627.00
Menus 0.00
Lubricant 0.00



Sub-Total	2,971.56
7% GST	208.01
Grand Total	3,179.57

Received by

For & on behalf of
Premium Automobiles Pte Ltd