

Volkswagen Centre Singapore



Biz Reg. No. 53103069E
SST No. M28098505-2
RECEIVED
27 DEC 2018

EQ INSURANCE CO. LTD.

insig (winner): 12/1/18

* No video *

Letter of Claims
Request for direct settlement.

We are submitting a claim on behalf of our customer OR POH HONGNRIC S62471427 insured of vehicle 2LN8247L againstyour insured vehicle number QBF 5545G (EQ)On the accident dated on 20-12-18 (ddmmyyyy) along WORME RDTOWARDS YPP- THOMSON RD-Dated this 21 DEC 2018 (day) of _____ (month) 2018.

Charmaine Kong
Volkswagen Group Singapore
Accident Claims Dept.
charmaine.kong@vw.com.sg
DID : 63057176/ 63057299
HP: 92361399

VGS Singapore

247

Alexandra Road

159934 Singapore

VGS Singapore, 247, 159934 Singapore

OR POH HONG
9 JALAN MATA AYER
#03-58
Singapore, 759153
Singapore

Phone No. +65 6305 7299
Fax No. +65 6474 3643
E-Mail service@vw.com.sg

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV034238
Quote No. SER/QUO/1802198
QuoteDate 21/12/18
Salesperson Jude Kwan
Page 1

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	GOLF A7 1.2 TL 81 (DSG)	48,522	
License No.	VIN	Initial Registration	Sales Advisor
SLN8247L	WVWZZZAUZHW099433	18/05/17	Jude Kwan
Engine Code	Labor Type	Engine No.	Model Code
	1T	CYV 509095	5G12BZ

No.	Description	Qty.	UoM	Unit Price	Amount
P B&P ALEX LABOUR	LABOUR	8	Labor		6,720.00
P B&P ALEX LABOUR	R&R REAR W/SCREEN	1	Labor		840.00
P B&P ALEX LABOUR	R&R REAR LUGGAGE TRIM	1	Labor		840.00
P B&P ALEX PAINT	SPRAY PAINT	6	Labor		4,800.00
P B&P NUMBER PLATE	B&P NUMBER PLATE -NETT	1	pcs		80.00
P B&P SENSOR	SUPPLY & INSTALL REVERSE SE	1	Pieces		400.00
P B&P DIAG	PROGRAMMING & CALIBRATION	1	Time Un		480.00
	COMPULSORY TO DO AFTER AC				
P B&P MECH	CHECK WIRE HARNESS, ECU, S	1	Time Un		280.00
	Nett				
	Sum Labor				14,440.00
P 1K8943021	REAR NUMBER PLATE LAMP	2	Pieces		89.98
P 533867910A	FELT STRIP	1	Pieces		17.70
P 5G0807305D	REINFORCEMENT	1	Pieces		648.28
	Use Predecessor 5G0807305B				
P 5G0853675AR2ZZ	NAME PLATE - 180 TSI	1	Pieces		68.13
P 5G0853687 2ZZ	NAME PLATE - GOLF	1	Pieces		77.37
P 5G0945087B	3RD BRAKELIGHT	1	Pieces		184.04
P 5G0945093AD	TAILLIGHT INNER LH	1	Pieces		308.00
	Use Predecessor 5G0945093S				
P 5G0945094AD	TAILLIGHT INNER RH	1	Pieces		308.00
P 5G0945105	REFELCTOR LH	1	Pieces		84.35
P 5G6807393	BUMPER SIDE BRACKET LH	1	Pieces		39.97
P 5G6807393A	TAILLIGHT LOWER BRACKET LH	1	Pieces		39.97
P 5G6807394	BUMPER SIDE BRACKET RH	1	Pieces		39.97

Sum carried forward

16,345.76

Payments to:

- BBN: - Acc.-No.:

VGS Singapore
247
Alexandra Road
159934 Singapore

Phone No. +65 6305 7299
Fax No. +65 6474 3643
E-Mail service@vw.com.sg

VGS Singapore, 247, 159934 Singapore

OR POH HONG
9 JALAN MATA AYER
#03-58
Singapore, 759153
Singapore

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV034238
Quote No. SER/QUO/1802198
QuoteDate 21/12/18
Salesperson Jude Kwan
Page 2

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	GOLF A7 1.2 TL 81 (DSG)	48,522	
License No.	VIN	Initial Registration	Sales Advisor
SLN8247L	WVWZZZAUZHW099433	18/05/17	Jude Kwan
Engine Code	Labor Type	Engine No.	Model Code
	1T	CYV 509095	5G12BZ

Continued			16,345.76
P 5G6807394A	TAILLIGHT LOWER BRACKET RH	1 Pieces	39.97
P 5G6807417APGRU	REAR BUMPER	1 Pieces	996.45
	Predecessor 5G6807417ARGRU		
P 5G6807568B 9B9	REAR BUMPER SPOILER	1 Pieces	322.40
P 5G6807863C	BUMPER CENTRE BRACKET	1 Pieces	91.68
P 5G6813309	END PANEL OUTER	1 Pieces	129.20
P 5G6827025Q	REAR BOOT LID	1 Pieces	1,511.56
	Use Predecessor 5G6827025H		
P 5G6827469F FOD	OPEN MECHANISM	1 Pieces	600.54
P 5G6827505B 9B9	REAR BOOT LID LOCK	1 Pieces	305.70
P 5G6827705E	BOOT WETHERSTRIP	1 Pieces	276.43
	Use Predecessor 5G6827705C		
P 5G6863459K 82V	END PANEL TRIM COVER	1 Pieces	132.21
P 5G6867605E 82V	REAR BOOT LID TRIM	1 Pieces	178.42
	Use Predecessor 5G6867605D 82		
P 5G6971829B	GROMMET	2 Pieces	26.48
	Use Predecessor 5G6971829A		
P 8K0973702	REAR NUMBER PLATE LAMP WI	2 Pieces	10.14
P D 004660M2	2K GLUE	1 Pieces	159.35
P D 007600A1	INOXSPRAY	1 Pieces	67.97
P D 00920002	PRIMER	1 Pieces	29.06
P D 00940104	CLEANER	1 Pieces	100.93
	66H3 Service Campaign (GOLF)		
P D 00950025	APPLICATOR	2 Pieces	21.20
P D 180003M2	2KADHESIV	1 Pieces	286.20
P D 181802M1	ACTIVATOR	1 Pieces	28.52
Sum carried forward			21,658.17

Payments to: - BBN: - Acc.-No.:

VGS Singapore

247

Alexandra Road

159934 Singapore

VGS Singapore, 247, 159934 Singapore

OR POH HONG
9 JALAN MATA AYER
#03-58
Singapore, 759153
Singapore

Phone No. +65 6305 7299
Fax No. +65 6474 3643
E-Mail service@vw.com.sg

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV034238
Quote No. SER/QUO/1802198
QuoteDate 21/12/18
Salesperson Jude Kwan
Page 3

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description
Volkswagen Passeng	GOLF A7 1.2 TL 81 (DSG)
License No.	VIN
SLN8247L	WVWZZZAUZHW099433
Engine Code	Labor Type
	1T

Mileage	Service Advisor
48,522	
Initial Registration	Sales Advisor
18/05/17	Jude Kwan
Engine No.	Model Code
CYV 509095	5G12BZ

P D 476KD1M2
P WHT005263

SEALANT
POP-RIVET
Sum Item

Continued	21,658.17
1 Pieces	77.38
6 Pieces	8.76
	7,304.31

Sum Labor	14,440.00
Sum Item	7,304.31

Total SGD	21,744.31
7% GST	1,522.10
Total SGD Incl. GST	23,266.41

Explanations

P = Proportionately Charged

Payment Terms No Credit

Payments to: - BBN: - Acc.-No.: