

ASS. REC. BY:

REF: CS/SMO18023320/RI rd3⁰²

Special Instruction:

Surveyor:

Rasul

ASSIGNMENT (Office)

Merimen

From (Person):

Ngo San Weishawn

of

SMO

Date/Time: 28/12/18 @ 17:17pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No:

EY 1028Z

Insured:

XE 2448T

at Workshop n/s

cycle & Cernigge Ind.
leapenden loop

Tel:

91865109

of

Policy No:

D18MTHCVC002961

Claim No:

CMTD1806691

Sum Insured:

Excess:

Make of Veh:

D.O.A. 27/12/18

(Client's Record)

CA / REV / REP. / REV 24 HRS

lup

H.O.D. Endorsement:

Date/Time:

8:41am @ 31/12/18

Person Contacted:

yik

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

EY 1028Z - X

XE 2448T - X

31/19

Send preli revised via merimen

4/1/19

check with Rasul 12 days - OK

Signature: *Pam*

REF: SMO

6939B

ASSIGNMENT

From: Date: 31/12/18

Estimated Cost

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No. EY10282
at Workshop m/s cycle & Camidge Ind.
of 188 penden loop

Insured

Policy No

Claims No

Sum Insured

Excess:


(Client's Record)

Make of Veh:

Yik @ 91865109

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res: Yes or No

Lump Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS ^{1 up}

Vehicle: IN / OUT

Date: Person Contacted:

Veh No. EY10282 Yt Regn. 2015 / AN4

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mercedes Benz A180 C.C. 1595

Colour: Black A/C Insured / Std / NI / NA

Sp Reading 51582 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WDP 1760 4223 389991

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/40 R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 27/12/18 D.O.I. 31/12/18

Survey held at

CRC (PL)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

13/2/19 final fig \$17,238.77 confirmed by email (Rec 2600.92, 13/2)

RECEIVED 13 FEB 2019

[Signature]
13/2/2019

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 13/2 - typist

Days Of Repair: 12

Resurvey No. of Trip: -

Survey Fee:

Transportation

) S + RS SI

) Photos

) Others

TOTAL

Report Format :

merimen

Lump Sum / I.B.I. (\$

17,238.77

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Dec 2018		28 Dec 2018 17:17 Assign				New Assignment Cancel Case

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	TAN YEW ENG AND BROTHER COMPAN, Co. Reg. No.: T07LL1773D		
Main Claimant:	CHIA AIK TONG (XIE YIZHONG), ID: S16869398		
Vehicle Reg. No.:	EY1028Z	Date of Loss:	27/12/2018 13:00 - :59
Claim Type:	TP / CMTD1805691	Policy/Cover Note No.:	D18MTHCVE002961 (Comprehensive)
Vehicle Reg. No. (Insured):	XE2448T	Policy No. (Claimant):	
		Excess:	
Repairer:	Cycle & Carriage Industries Pte Ltd (Pandan Loop) 188 Pandan Loop, 128378 West Coast - Tel: 91865300		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by NGO SAU WEI SHAWN - 6329 5202]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 09/01/2019]		
Driver/Custodian (Insured):	TAN YEW KOON (), NRIC: S0099832Z, Tel: +6596822329		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sampo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: NGO SAU WEI SHAWN

Date: 03 Jan 2019

Preliminary Advice

Insured Vehicle No	: XE2448T		
TP Vehicle No	: EY1028Z	Accident Date	: 27/12/2018
Make	: MERCEDES-BENZ A180 R18	Assignment Date	: 28/12/2018
Date of Inspection	: 31/12/2018	Est. Duration of Repair	: 7.00
Inspection At	: CYCLE & CARRIAGE INDUSTRIES PTE LTD (PANDAN LOOP) 188 PANDAN LOOP SINGAPORE 128378		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	19,377.70
Revised Amount	:S\$	16,777.61
Check Items (Estimated)	:S\$	137.52
Total	:S\$	16,915.13

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments :The above survey was conducted on a 'Without Prejudice' basis.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 13 February 2019 3:18 PM
To: Rasul (LKKAUTO); 'Dennis Yap'; Yik (chanhoe.yik@cyclecarriage.com.sg)
Cc: SUR
Subject: RE: EY1028Z final bill

Dear Mr Yik,

WITHOUT PREJUDICE

Finalize amount \$17,238.77 @ 12 working days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Monday, 11 February 2019 4:20 PM
To: Rasul (LKKAUTO) <Rasul@lkkauto.com>; 'Dennis Yap' <dennis.yap@cyclecarriage.com.sg>; Yik (chanhoe.yik@cyclecarriage.com.sg) <chanhoe.yik@cyclecarriage.com.sg>
Subject: RE: EY1028Z final bill

Dear Dennis,

Kindly forward us resurvey photos.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Yik Chan Hoe [mailto:chanhoe.yik@cyclecarriage.com.sg]
Sent: Monday, 21 January, 2019 7:22 PM
To: Rasul (LKKAUTO); Dennis Yap
Subject: EY1028Z final bill

Hi Rasul,

Fyna.

Aside to Dennis,

Please forward the photos to Rasul if any.

Thanks & Regards,

Yik Chan Hoe
Mercedes-Benz Body Care & Repair Center
Cycle & Carriage Industries Pte Ltd
Pandan Loop Service Center
Mobile: 9186 5109 | DID: 6771 4353 | Fax: 6872 1272
Website: www.mercedes-benz.com.sg

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.

Veron Chen (LKKAUTO)

From: Yik Chan Hoe <chanhoe.yik@cyclecarriage.com.sg>
Sent: Thursday, 3 January 2019 4:39 PM
To: Rasul (LKKAUTO); SUR
Subject: EY1028Z surveyed on 31/12/2018
Attachments: img-103163129-0001.pdf

Hi Rasul,

Please note that we need at least 12 workings days to complete the repairs.

Thanks & Regards,

Yik Chan Hoe
Mercedes-Benz Body Care & Repair Center
Cycle & Carriage Industries Pte Ltd
Pandan Loop Service Center
Mobile: 9186 5109 | DID: 6771 4353 | Fax: 6872 1272
Website: www.mercedes-benz.com.sg

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.

Nivitha (LKK Auto)

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Friday, 28 December 2018 5:16 PM
To: admin-d@lkkauto.com; assignments@lkkauto.com
Cc: Yik Chan Hoe; Ye, Yong Kang Melvin; Ngo, Sau Wei Shawn
Subject: CMTD1805691/NSW - SUV(LKK)/ Accident involving XE2448T & EY1028Z ON 27.12.18

Our Reference : CMTD1805691/NSW

Your Reference: EY1028Z

Dear LKK AUTO,

Please make arrangement to conduct the survey for EY1028Z on a without Prejudice Basis and any admission of liability basis.

Please submit with your report via Merimen upon completion of survey.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



SOMPO
INSURANCE

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @  or 

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Yik Chan Hoe [mailto:chanhoe.yik@cyclecarriage.com.sg]

Sent: Friday, December 28, 2018 4:42 PM

To: Ngo, Sau Wei Shawn; Teo, Grace

Cc: Ye, Yong Kang Melvin

Subject: RE: CMTD1805691/NSW - LIA/ Accident involving XE2448T & EY1028Z ON 27.12.18 // Propose for Direct Settlement

Dear Shawn,

Thanks for the reply, kindly arrange survey asap, vehicle is in.

Thanks & Regards,

Yik Chan Hoe

Mercedes-Benz Body Care & Repair Center
Cycle & Carriage Industries Pte Ltd
Pandan Loop Service Center
Mobile: 9186 5109 | DID: 6771 4353 | Fax: 6872 1272
Website: www.mercedes-benz.com.sg

From: Ngo, Sau Wei Shawn [mailto:Shawn.Ngo@sompo.com.sg]

Sent: Friday, 28 December, 2018 3:40 PM

To: Teo, Grace; Yik Chan Hoe

Cc: Ye, Yong Kang Melvin

Subject: RE: CMTD1805691/NSW - LIA/ Accident involving XE2448T & EY1028Z ON 27.12.18 // Propose for Direct Settlement

WITHOUT PREJUDICE

Dear Mr. Yik,

Liability clear and kindly finalize the cost of repair with our surveyor.

For loss of use, we are prepare to offer at \$60 per day and loss of rental at \$100 per day.

Best Regards,

Shawn Ngo

Claims Division

D: 6329 5202 | T: 6461 6555 | F: 6221 3147

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @  or 

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

From: Teo, Grace

Sent: Friday, December 28, 2018 3:20 PM

To: Yik Chan Hoe <chanhoe.yik@cyclecarriage.com.sg>

Cc: Ngo, Sau Wei Shawn <Shawn.Ngo@sompo.com.sg>; Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>

Subject: CMTD1805691/NSW - LIA/ Accident involving XE2448T & EY1028Z ON 27.12.18 // Propose for Direct Settlement

Our Claim Reference: CMTD1805691/NSW

Your Reference: EY1028Z

Hi Chan Hoe,

We acknowledged receipt of your claim documents.

Please be informed that Mr. Shawn Ngo is the handler of this case.

Aside to Shawn,

Please refer to the liability request from Cycle & Carriage Industries Pte Ltd.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @  or 

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

-----Original Message-----

From: Yik Chan Hoe [<mailto:chanhoe.yik@cyclecarriage.com.sg>]

Sent: Friday, December 28, 2018 2:09 PM

To: Claims - Motor Survey

Subject: Accident involving motor vehicle nos. EY 1028 Z & XE 2448 T // Propose for Direct Settlement

To: Sompo

Attn: Motor Claims Dept

RE: Accident involving motor vehicle nos. EY 1028 Z & XE 2448 T along Jalan Sultan, Accident date: 27/12/2018

Dear Officer In-Charge,

This email is with regards to the above accident which has been reported by our customer. We have since been instructed by him/her (motor vehicle number EY 1028 Z), to submit a claim on his/her behalf as we are the authorised repair workshop for his/her car.

We note that you are the insurer (3rd party) of the (motor vehicle number XE 2448 T) involved. As such we are proposing for a Direct Settlement with regards to the repair costs and other consequential losses.

We appreciate your assistance in this matter and look forward to your agreement on this direct settlement.

I can be reached at chanhoe.yik@cyclecarriage.com.sg

Thanks & Regards,

Yik Chan Hoe
Mercedes-Benz Body Care & Repair Center
Cycle & Carriage Industries Pte Ltd
Pandan Loop Service Center
Mobile: 9186 5109 | DID: 6771 4353 | Fax: 6872 1272
Website: www.mercedes-benz.com.sg

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6939B
Vehicle Details	
Vehicle No.:	EY1028Z
Vehicle to be Exported:	No
Intended Deregistration Date:	03 Jan 2019
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	A180 (R18 BI SR)
Primary Colour:	Black
Manufacturing Year:	2015
Engine No.:	27091030718497
Chassis No.:	WDD1760422J389991
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$25,858.00
Original Registration Date:	03 Aug 2015
First Registration Date:	03 Aug 2015
Transfer Count:	0
Actual ARF Paid:	\$23,202.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	02 Aug 2025
PARF Rebate Amount:	\$17,401.00
Intended COE Rebate Details	
COE Expiry Date:	02 Aug 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$66,000.00
COE Rebate Amount:	\$43,432.00
Total Rebate Amount:	\$60,833.00

The information contained herein is correct as at 03 Jan 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/12/2018 16:51
Date Of Accident	27/12/2018 13:30
Exact Location Of Accident	JALAN SULTAN
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	EY1028Z
Insured/Policyholder	
Name Of Registered Owner	CHIA AIK TONG (XIE YIZHONG)
NRIC No	S1686939B
Email Address	FATTYCAT25@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-82829954
Alternative Phone No	OFFICE-82829954

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	A180 R18-1.6 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D18MTPV01012588
Cover Note Number	

Driver

Name of Driver	CHIA AIK TONG (XIE YIZHONG)
NRIC No	S1686939B
Date Of Birth	09/10/1965
Occupation	INDOOR
Date Of Driving Pass	19/08/1988
Driving Experience	30 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82829954
Fax Number	
Contact Number	OFFICE-82829954
EMail Address	FATTYCAT25@HOTMAIL.COM

Address	25 FIRST STREET
Postcode	458295
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : CHIA LI-SHENG, LEXUS GENDER: : MALE
Passenger 2	NAME: : CHIA LE-ANNE, LOTUS GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON 27/12/2018 AROUND 1.30PM, I WAS TRAVELLING ALONG NORTH BRIDGE ROAD TURNING INTO JALAN SULTAN. AFTER ENTER JALAN SULTAN (3RD LANE), VEHICLE B (XE2448T) DROVE ON 1ST LANE MAKE A OVERTURN AND HIT ONTO REAR RIGHT PORTION OF MY VEHICLE.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XE2448T
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	TAN YEW KOON
NRIC/Passport Number	S0099832Z
Contact Number	
Address	

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

1

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The signing and completion of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Funds Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents including their lawyers/law firms, which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (b) above may be shared/disclosed:
- (i) to all Insurers and/or any other third parties that exist in evaluating, investigating, controlling or managing fraud, including insurers, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
(Print Name) 21/12/2018
4:45pm

Insurer's Signature
(If more than the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name: Jessy Soe
NRIC/FIN No.: G2031072W

SKETCH PLAN Vehicle A: EY105SZ Vehicle B: XE 2448T

Date of Accident 27/12/2018 Time of Accident 1:30pm

On 27/12/2018 around 1:30pm, I was travelling along North Bridge Road turning into Jalan Sultan. After enter Jalan Sultan (3rd lane), vehicle B drove on 1st lane make a overturn and hit onto rear right portion of my vehicle.

4-45 PM


 Reporting Center Personnel's Signature:
 Name: Jesse Sola
 ARI, PIN No.: G2031072W



Sampo Insurance Singapore Pte. Ltd.

30, 32, 34, 36, 38, 40, 42, 44, 46, 48, 50, 52, 54, 56, 58, 60, 62, 64, 66, 68, 70, 72, 74, 76, 78, 80, 82, 84, 86, 88, 90, 92, 94, 96, 98, 100, 102, 104, 106, 108, 110, 112, 114, 116, 118, 120, 122, 124, 126, 128, 130, 132, 134, 136, 138, 140, 142, 144, 146, 148, 150, 152, 154, 156, 158, 160, 162, 164, 166, 168, 170, 172, 174, 176, 178, 180, 182, 184, 186, 188, 190, 192, 194, 196, 198, 200, 202, 204, 206, 208, 210, 212, 214, 216, 218, 220, 222, 224, 226, 228, 230, 232, 234, 236, 238, 240, 242, 244, 246, 248, 250, 252, 254, 256, 258, 260, 262, 264, 266, 268, 270, 272, 274, 276, 278, 280, 282, 284, 286, 288, 290, 292, 294, 296, 298, 300, 302, 304, 306, 308, 310, 312, 314, 316, 318, 320, 322, 324, 326, 328, 330, 332, 334, 336, 338, 340, 342, 344, 346, 348, 350, 352, 354, 356, 358, 360, 362, 364, 366, 368, 370, 372, 374, 376, 378, 380, 382, 384, 386, 388, 390, 392, 394, 396, 398, 400, 402, 404, 406, 408, 410, 412, 414, 416, 418, 420, 422, 424, 426, 428, 430, 432, 434, 436, 438, 440, 442, 444, 446, 448, 450, 452, 454, 456, 458, 460, 462, 464, 466, 468, 470, 472, 474, 476, 478, 480, 482, 484, 486, 488, 490, 492, 494, 496, 498, 500, 502, 504, 506, 508, 510, 512, 514, 516, 518, 520, 522, 524, 526, 528, 530, 532, 534, 536, 538, 540, 542, 544, 546, 548, 550, 552, 554, 556, 558, 560, 562, 564, 566, 568, 570, 572, 574, 576, 578, 580, 582, 584, 586, 588, 590, 592, 594, 596, 598, 600, 602, 604, 606, 608, 610, 612, 614, 616, 618, 620, 622, 624, 626, 628, 630, 632, 634, 636, 638, 640, 642, 644, 646, 648, 650, 652, 654, 656, 658, 660, 662, 664, 666, 668, 670, 672, 674, 676, 678, 680, 682, 684, 686, 688, 690, 692, 694, 696, 698, 700, 702, 704, 706, 708, 710, 712, 714, 716, 718, 720, 722, 724, 726, 728, 730, 732, 734, 736, 738, 740, 742, 744, 746, 748, 750, 752, 754, 756, 758, 760, 762, 764, 766, 768, 770, 772, 774, 776, 778, 780, 782, 784, 786, 788, 790, 792, 794, 796, 798, 800, 802, 804, 806, 808, 810, 812, 814, 816, 818, 820, 822, 824, 826, 828, 830, 832, 834, 836, 838, 840, 842, 844, 846, 848, 850, 852, 854, 856, 858, 860, 862, 864, 866, 868, 870, 872, 874, 876, 878, 880, 882, 884, 886, 888, 890, 892, 894, 896, 898, 900, 902, 904, 906, 908, 910, 912, 914, 916, 918, 920, 922, 924, 926, 928, 930, 932, 934, 936, 938, 940, 942, 944, 946, 948, 950, 952, 954, 956, 958, 960, 962, 964, 966, 968, 970, 972, 974, 976, 978, 980, 982, 984, 986, 988, 990, 992, 994, 996, 998, 1000

Certificate of Insurance

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES 1962
ROAD TRANSPORT ACT 1967 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES 1969 (MALAYSIA)

Cert No./Policy No.	DTMTT/0101258
Insured	MSB J&K TRADING Sdn Bhd (1017999)
Motor Car (Registration No.)	ET10242
Cover	Comprehensive - ExceDrive PRESTIGE
Policy Commencement Date	10 AUGUST 2016 00:00
Policy Expiry Date	09 AUGUST 2019 23:59
Maximum Liability (Section B Excess)*	Marked value at time of loss \$400 - Section B (Waived up to \$21,400 if accident repair is done at ExceDrive Workshops for the first claim per policy year)
Voluntary Excess*	N/A
Windscreen Excess*	\$210.00 - Waived if Repair at ExceDrive Workshops
Limit of Use	Per Policy Schedule

* Subject to GST, wherever applicable

Persons entitled to drive¹

- The Insured
- Any other person who is driving on the Insured's behalf or with her permission
- As the result of the death of the Insured:
 - any executor of the Insured's estate; or a part driver who has been driving the Motor Car during the life of the Insured and permission to drive had not been withdrawn prior to the death of the Insured; and
 - any other person who had been given permission to drive the Motor Car prior to the death and such permission had not been withdrawn by the Insured

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Car or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in this behalf from driving the Motor Car. And provided further that the Motor Car is registered under the Road Traffic Act (Chapter 276) and its registration under the Road Traffic Act (Chapter 276) has not been cancelled at the time of the accident, loss or damage.

Limitations As To Use

Use only for social, domestic and pleasure purpose and for the Insured's business. The Policy does not cover use for hire or reward, racing, pace-making, speed testing, reliability trial, the carriage of goods other than samples in connection with any trade or business or use for any purposes in connection with the Motor Trade.

ExceDrive Workshops and Accident Reporting

It is a condition precedent to liability that the Insured shall call at the Company's Accident Reporting Centre with the Motor Car within 24 hours of the accident or by the next working day thereafter.

All accident repairs to the Motor Car must be carried out at ExceDrive Workshops, otherwise the claim is not payable under the Policy. For ExceDrive Prestige Plan, accident repairs to the Motor Car can be carried out at any workshop other than ExceDrive Workshops.

For the list of Accident Reporting Centres and ExceDrive Workshops, please visit our website at www.sompo.com.sg or call our Emergency hotline: (65) 6220 3345.

WE HEREBY CERTIFY that the policy which this Certificate represents complies with the provisions of the Motor Vehicle (Third-Party Risks and Compensation) Act (Chapter 189) of the Road Transport Act 1967 (Malaysia) and with the Policy terms, conditions and exclusions of the Motor Car Policy no. DTMTT/0101258.

Sampo Insurance Singapore Pte. Ltd.

Authorized Signatory

Date/Time of Issue: 12 JULY 2016 10:14

IMPORTANT NOTICE

- Keep this Certificate in your Motor Car.
- Under the Motor Vehicle (Third-Party Risks and Compensation) Act (Chapter 189) it shall be unlawful for any person to use or cause to permit any other person to use a motor vehicle without a valid policy which complies with the Act.
- For the Motor Vehicle (Third-Party Risks and Compensation) Act (Chapter 189) to be enforced during an accident, the Insured must inform the Insurer of the accident and the Motor Car details, give evidence, make a written statement and sign a statement of fact which must be made. Failure to comply with the subject of a written statement, the Motor Vehicle (Third-Party Risks and Compensation) Act (Chapter 189).
- This Policy will remain in full force and effect unless it has been withdrawn or varied in writing.

Information Code & Name: 115187X-A, ACCORD INSURANCE AGENCY, CI Code: 22A-FH-P00000000000

NRIC & DL

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S1686939B



CHIA AIK TONG
(XIE YIZHONG)
謝逸中
Chinese
Date of Birth: 09-10-1965 Sex: M
Place of Birth: SINGAPORE

REPUBLIC OF SINGAPORE DRIVING LICENCE



CHIA AIK TONG
(XIE YIZHONG)
Pub. Date: 09 Oct 1965
Issue Date: 20 Sep 2003

000492160

963444



NRIC No: S1686939B



Place of Birth: SINGAPORE
Date of Birth: 25-11-1992

25 FIRST STREET
SINGAPORE 558205
NRIC No: S1686939B Date: 01/04/2012 No: 7983281

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

Issue Date: 18 Aug 1965

License No: S1686939B





Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-9500111-X

ESTIMATE FOR EY1028Z

Chia Aik Tong (Xie Yizhong)

25 First Street
Singapore 458295

Mobile: 82829954

Vehicle & Document Information

WIP No **29722**
Reg No/Reg Date **EY1028Z / 03/08/2015**
Date In/Mileage **/ 0**
Chassis No **WDD1760422J389991**
Engine No **27091030718497**
Make/Model **MB/A 180 (W176) "URBAN"**
Colour/Trim **021 191 Cosmos Blac/ 043 361 ARTICO Laro**

Account No	Terms	Date/Time Printed	CSE	Operator				
CSM00128	Cash	28/12/2018/ 14:01	YK	395 / Yik Chan Hoe				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
Z REQUEST								
Customer Request								
M BPNSUN								
POLICY NO/ACC DATE : D18MTPV01012588 // 27/12/2018								
DRIVE IN/EXCESS : 28/12/2018 // TP VEH NO XE2448T SOMPO								
DATE IN/DATE SURVEY:								
BY/AUTHORIZED ON :								
S BPNSUB								60.00
TRANSFER TYRE OVER TO NEW RIM								✓ 4800 5780.00
A BPILAB								
PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW								
BODY PANELS WITH REFINISH.								✓ 2400 3000.00
A BPIRES								
RESPRAY REAR BUMPER, RIGHT REAR FENDER, RIGHT REAR DOOR								
AND REAR END PANEL								
A BPILAB					0.10			✓ 380.00
USING XENTRY SYSTEM TO CHECK CONTROL UNITS, RESET MEMORY TO								
STANDARD SETTINGS.								✓ 120.00
A BPILAB								
CHECK REAR LIGHTING SYSTEM AND CONDUCT WATER TEST FOR ANY LEAKAGE.NETT								✓ 960 1200.00
A BPILAB								
REMOVE AND REFIT REAR UPHOLSTERY, TRIMS GARNISHS								✓ 480.00
AND SEATS FOR NEC. REPAIRS.								
A BPILAB								
TRANSFER MECHANICAL & ELECTRICAL COMPONENTS TO NEW DOOR.NETT								✓ 540.00
A BPILAB								
INSPECT & CONDUCT WHEEL ALIGNMENT.NETT								
M REAR BUMPER ✓					1.00	1300.73	1275.24	00.00 1275.24
M RIGHT REAR BUMPER MOUNTING RAIL ? X ✓					1.00		23.43	00.00 23.43
M RIGHT REAR LAMP COMBINATION X ✓					1.00		662.57	00.00 662.57
M RIGHT REAR ALLOY WHEEL ✓					1.00	696.89	688.91	00.00 688.91

Confirmed & accepted by

Authorized signatory and company stamp

Yik Chan Hoe
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
6771 4353 HP: 9186 5109 Fax: 6872 1272
yikchanhoe.yik@cyclecarriage.com.sg

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR EY1028Z

Chia Aik Tong (Xie Yizhong)

25 First Street
Singapore 458295

Mobile: 82829954

WIP No

Reg No/Reg Date

Date In/Mileage

Chassis No

Engine No

Make/Model

Colour/Trim

Vehicle & Document Information

29722

EY1028Z / 03/08/2015

/ 0

WDD1760422J389991

27091030718497

MB/A 180 (W176) "URBAN"

021 191 Cosmos Blac/ 043 361 ARTICO Laro

Account No	Terms	Date/Time Printed	CSE	Operator				
CSM00128	Cash	28/12/2018/ 14:01	YK	395 / Yik Chan Hoe				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	RIGHT REAR FENDER	PA-			1.00	2120.42	00.00	2120.42
M	RIGHT REAR FENDER LINER	DE-			1.00	124.93	00.00	124.93
M	RIGHT REAR DOOR	BT-			1.00	1595.79	00.00	1595.79
M	RIGHT REAR DOOR WEATHERSTRIP	NA-			1.00	280.72	00.00	280.72
M	RIGHT REAR DOOR INSULATION	NA-			1.00	62.05	00.00	62.05
M	RIGHT REAR DOOR SELF-ADH. PRE-CUT PART	NA-			1.00	0.83	00.00	0.83
M	RIGHT REAR DOOR HANDLE	SEA-			1.00	133.41	00.00	133.41
M	RIGHT REAR DOOR WINDOW GUIDE RAIL	NA-			1.00	114.09	00.00	114.09
M	TS TWO-COMPONENT ADHESIVE	NA-			1.00	755.31	00.00	755.31
<p><i>RASUL</i> <i>Hp 90010068</i> <i>7 days</i> <i>P/P</i> <i>31/12/18 @ 1055 hrs</i> <i>Repair by point</i></p> <p><i>31/1/19</i></p>								
								19,839.69

Confirmed & accepted by

7% GST on **19,377.70** **1356.44**

Authorized signatory and company stamp

Total Payable 20,734.14

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400347W
GST Reg No. MR-8500111-X

Finalization

ESTIMATE FOR EY1028Z

SOMPO INSURANCE SINGAPORE PTE LTD

MOTOR CLAIM DEPARTMENT
50 Raffles Place #05-01/06
Singapore Land Tower
Singapore 048623
64616555

Vehicle & Document Information

WIP No 29722
Reg No/Reg Date EY1028Z / 03/08/2015
Date In/Mileage 34/12/2018 / 51582
Chassis No WDD1760422J389991
Engine No 27091030718497
Make/Model MB/A 180 (W176) "URBAN"
Colour/Trim 021 191 Cosmos Blac/ 043 361 ARTICO Laro

Account No	Terms	Date/Time Printed	CSE	Operator	Description of Goods / Services	Qty	Unit Price	Disc%	Amount
WT009122	Credit	21/01/2019/ 19:17	YK	395 / Yik Chan Hoe					
Z REQUEST									
Customer Request									
M BPNSUN									
POLICY NO/ACC DATE : D18MTPV01012588 // 27/12/2018									
DRIVE IN/EXCESS : 28/12/2018 // TP VEH NO XE2448T SOMPO									
DATE IN/DATE SURVEY: 31/12/2018 // RASUL LKK									
BY/AUTHORIZED ON : DIRECT SETTLEMENT // SHAWN SOMPO									
S BPNSUB									
LABOUR TO REMOVE AND INSTALL TYRE FROM RIM, (RUN FLAT)									
WHEEL BALANCE AND INSTALL NEW VALVE HEAD									
A BPILAB									
PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW									
BODY PANELS WITH REFINISH.									
A BPIRES									
RESPRAY REAR BUMPER, RIGHT REAR FENDER, RIGHT REAR DOOR									
AND REAR END PANEL									
A BPILAB									
USING XENTRY SYSTEM TO CHECK CONTROL UNITS, RESET MEMORY TO									
STANDARD SETTINGS.									
A BPILAB									
CHECK REAR LIGHTING SYSTEM AND CONDUCT WATER TEST FOR ANY LEAKAGE.NETT									
A BPILAB									
REMOVE AND REFIT REAR UPHOLSTERY, TRIMS GARNISHS									
AND SEATS FOR NEC. REPAIRS.									
A BPILAB									
TRANSFER MECHANICAL & ELECTRICAL COMPONENTS TO NEW DOOR.NETT									
A BPILAB									
INSPECT & CONDUCT WHEEL ALIGNMENT.NETT									
X REAR BUMPER									
X RIGHT REAR ALLOY WHEEL									
X RIGHT REAR FENDER									

Confirmed & accepted by

Yik Chan Hoe

Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272
Email: chanhoe.yik@cyclecarrage.com.sg

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany



Mercedes-Benz

Finalization

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR EY1028Z

SOMPO INSURANCE SINGAPORE PTE LTD

MOTOR CLAIM DEPARTMENT
50 Raffles Place #05-01/06
Singapore Land Tower
Singapore 048623
64616555

WIP No

Reg No/Reg Date

Date In/Mileage

Chassis No

Engine No

Make/Model

Colour/Trim

Vehicle & Document Information

29722

EY1028Z / 03/08/2015

34/12/2018/ 51582

WDD1760422J389991

27091030718497

MB/A 180 (W176) "URBAN"

021 191 Cosmos Blac/ 043 361 ARTICO Laro

Account No	Terms	Date/Time Printed	CSE	Operator				
WT009122	Credit	21/01/2019/ 19:17	YK	395 / Yik Chan Hoe				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
X	RIGHT REAR FENDER LINER				1.00	128.68	00.00	128.68
X	RIGHT REAR DOOR				1.00	1643.66	00.00	1643.66
X	RIGHT REAR DOOR WEATHERSTRIP				1.00	290.64	00.00	290.64
X	RIGHT REAR DOOR INSULATION				1.00	63.93	00.00	63.93
X	RIGHT REAR DOOR HANDLE				1.00	137.42	00.00	137.42
X	TS TWO-COMPONENT ADHESIVE				1.00	781.76	00.00	781.76
X	TWO-COMPONENT ADHESIVE				1.00	102.64	00.00	102.64
X	SEAM SEAL				1.00	101.12	00.00	101.12
X	BLIND RIVET WITH PAN HEAD				10.00	2.35	00.00	23.50
X	RIVET				5.00	2.35	00.00	11.75
X	MOLDING CLIP				1.00	6.07	00.00	6.07
X	RIVET				5.00	5.21	00.00	26.05

THIS IS NOT AN OFFICIAL TAX INVOICE

ESTIMATE

Yik Chan Hoe
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4353 HP: 9186 5109 Fax: 6872 272
Email: chanhoe.yik@cyclecarriage.com.sg

Confirmed & accepted by

7% GST on **Nett 17,238.77**
1206.71

Total Payable 18,445.48

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for removal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR EY1028Z

SUPPLEMENTARY

SOMPO INSURANCE SINGAPORE PTE LTD

MOTOR CLAIM DEPARTMENT
50 Raffles Place #05-01/06
Singapore Land Tower
Singapore 048623
64616555

Vehicle & Document Information
WIP No 29722
Reg No/Reg Date EY1028Z / 03/08/2015
Date In/Mileage 31/12/2018 / 51582
Chassis No WDD1760422J389991
Engine No 27091030718497
Make/Model MB/A 180 (W176) "URBAN"
Colour/Trim 021 191 Cosmos Blac/ 043 361 ARTICO Laro

Account No	Terms	Date/Time Printed	CSE	Operator
WT009122	Credit	21/01/2019/ 19:18	YK	395 / Yik Chan Hoe

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X TWO-COMPONENT ADHESIVE	1.00	102.64	00.00	102.64
X SEAM SEAL	1.00	101.12	00.00	101.12
X BLIND RIVET WITH PAN HEAD	10.00	2.35	00.00	23.50
X RIVET	5.00	2.35	00.00	11.75
X MOLDING CLIP	1.00	6.07	00.00	6.07
X RIVET	5.00	5.21	00.00	26.05

THIS IS NOT AN OFFICIAL TAX INVOICE

ESTIMATE

Yik Chan Hoe
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272
Email: chanhoe.yik@cyclecarriage.com.sg

Confirmed & accepted by

Nett 271.13
7% GST on 271.13 18.98
Total Payable 290.11

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
186 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO18023320/R1VD3N2

Date: 13/02/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTHCVE002961
Claimant Vehicle No :	EY1028Z	Insured Vehicle No :	XE2448T
Date of Loss:	27/12/2018	Nature of Claim:	TP
		Claim No:	CMTD1805691

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	EY1028Z	Engine No:	27091030718497
Make & Model:	MERCEDES-BENZ A180 R18, 1.6 (A)	Chassis No:	WDD1760422J389991
Reg. Date:	03/08/2015 (Man. Year: 2015)	Odometer:	51582 km
Colour:	Black		
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40R18	Rear Tyre Size:	225/40R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,299.69	7,498.77	800.92	9.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,540.00	9,740.00	1,800.00	15.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	19,839.69	17,238.77	2,600.92	13.11
+ GST 7.00/7.00% (S\$)	1,388.78	1,206.71	182.07	13.11
Nett Amount (S\$)	21,228.47	18,445.48	2,782.99	13.11

INSPECTION

Date of Assignment:	28/12/2018	
Date Inspected:	31/12/2018 Inspected At:	Cycle & Carriage Industries Pte Ltd (Pandan Loop) 188 Pandan Loop Singapore 128378

Estimated Period of Repair: 12.0 days

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 13 Feb 2019)
Parts: 143	MERCEDES-BENZ A180 R18 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for EY1028Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BUMPER	Deformed	1,300.73 FS	*1,300.73 FS
2	1	*RIGHT REAR BUMPER MOUNTING RAIL	Serviceable	23.43 FS	*- FS
3	1	*RIGHT REAR LAMP COMBINATION	Serviceable	662.57 FS	*- FS
4	1	*RIGHT REAR ALLOY WHEEL	Scratched	696.89 FS	*696.89 FS
5	1	*RIGHT REAR FENDER	Bent	2,184.03 FS	*2,184.03 FS
6	1	*RIGHT REAR FENDER LINER	Deformed	128.68 FS	*128.68 FS
7	1	*RIGHT REAR DOOR	Bent	1,643.66 FS	*1,643.66 FS
8	1	*RIGHT REAR DOOR WEATHERSTRIP	Necessary	290.54 FS	*290.54 FS
9	1	*RIGHT REAR DOOR INSULATION	Necessary	63.93 FS	*63.93 FS
10	1	*RIGHT REAR DOOR SELF-ADH.PRE-CUT PART	Not Necessary	0.83 FS	*- FS
11	1	*RIGHT REAR DOOR HANDLE	Scratched	137.42 FS	*137.42 FS
12	1	*RIGHT REAR DOOR WINDOW GUIDE RAIL	Not Necessary	114.09 FS	*- FS
13	1	*TS TWO-COMPONENT ADHESIVE	Necessary	781.76 FS	*781.76 FS
14	1	*TWO-COMPONENT ADHESIVE	Necessary	102.64 FS	*102.64 FS
15	1	*SEAM SEAL	Necessary	101.12 FS	*101.12 FS
16	5	*RIVET	Necessary	11.75 FS	*11.75 FS
17	1	*MOLDING CLIP	Necessary	6.07 FS	*6.07 FS
18	5	*RIVET	Necessary	26.05 FS	*26.05 FS
19	10	*BLIND RIVET WITH PAN HEAD	Necessary	23.50 FS	*23.50 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	8,299.69	7,498.77
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO TRANSFER TYRE OVER TO NEW RIM	New	60.00	60.00
2	PANEL BEATING TO REPAIR AFFECTED AREAS,REMOVE AND REPLACE WITH NEW BODY PANELS WITH REFINISH	New	5,760.00	4,800.00
3	RESPRAY REAR BUMPER,RIGHT REAR FENDER,RIGHT REAR DOOR AND REAR END PANEL	New	3,000.00	2,400.00
4	USING XENTRY SYSTEM TO CHECK CONTROL UNITS,RESET MEMORY TO STANDARD SETTINGS	New	380.00	380.00
5	CHECK REAR LIGHTING SYSTEM AND CONDUCT WATER TEST FOR ANY LEAKAGE	New	120.00	120.00
6	REMOVE AND REFIT REAR UPHOLSTERY,TRIMS GARNISHS AND SEATS FOR NEC.REPAIRS.	New	1,200.00	960.00
7	TRANSFER MECHANICAL & ELECTRICAL COMPONENTS TO NEW DOOR	New	480.00	480.00
8	INSPECT & CONDUCT WHEEL ALIGNMENT	New	540.00	540.00
Gross Labour Cost (S\$)			11,540.00	9,740.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >