

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 3816H

DATE 12/28/2018 10:36

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Bonnet <i>X Rep</i>			\$ 2,265.90
	Bonnet Hinge (LH/RH) <i>X Rep</i>		\$ 41.00	\$ 82.00
	Front Bumper Cover <i>/</i>			\$ 544.50
	Front Bumper Sponge <i>X</i>			\$ 99.20
	Front Bumper Reinforcement <i>X</i>			\$ 402.10
	Front Bumper Grille (LH/RH) <i>WA /</i>		\$ 41.60	\$ 83.20
	Front Bumper Centre Grille <i>X</i>			\$ 178.60
	Front Bumper Centre Grille Top Garnish (RH) <i>X</i>			\$ 80.00
	Front Bumper Bracket Top (LH/RH) <i>/</i>		\$ 22.40	\$ 44.80
	Front Bumper Bracket (LH/RH) <i>/</i>		\$ 24.60	\$ 49.20
	Headlamp Support Panel Assy <i>/</i>			\$ 907.40
	Headlamp (LH/RH) <i>/</i>		\$ 1,388.00	\$ 2,776.00
	Radiator Expansion Tank <i>?</i>			\$ 28.30
	Front Fender (LH/RH) <i>/</i>		\$ 566.30	\$ 1,132.60
	Front Fender Shield (LH/RH) <i>/</i>		\$ 174.90	\$ 349.80
	Aircon Condenser <i>?</i>			\$ 927.50
	Wiper Container <i>/</i>			\$ 61.90
	Wiper Container Motor <i>?</i>			\$ 75.00
	Front Wheel Rim (LH/RH) <i>X</i>		\$ 325.30	\$ 650.60
	Front Wheel Hub Cap (LH/RH) <i>/</i>		\$ 107.10	\$ 214.20
	Front Wheel Bearing (LH/RH) <i>X</i>		\$ 540.50	\$ 1,081.00
	Front Shock Absorber (Assy) (LH/RH) <i>X</i>		\$ 342.20	\$ 684.40
	Front Shock Absorber Mounting (LH/RH) <i>X</i>		\$ 108.80	\$ 217.60
	Rack & Pinion Assy <i>X</i>			\$ 969.60
	STG Tie End (RH) <i>X</i>			\$ 62.60
	Front Suspension Lower Arm (LH/RH) <i>X</i>		\$ 529.30	\$ 1,058.60
	Knuckle Arm (LH/RH) <i>X</i>		\$ 552.00	\$ 1,104.00
	ABS Sensor <i>X</i>			\$ 234.00
	SUB TOTAL			\$ 16,364.60
	LESS 20%			\$ 3,272.92
	DISCOUNTED TOTAL			\$ 13,091.68
	Front Tyre (LH/RH) <i>X</i>		\$ 216.00	\$ 432.00 Nett
				\$ 432.00
	Labour Charge			
	Panel Beating			\$ 1,000.00 <i>600</i>
	Spray Painting Charge			\$ 1,000.00 <i>800</i>
	Wiring Charge			\$ 50.00 <i>20</i>
	Tuff Kote			\$ 100.00 <i>50</i>
	Towing Charge			\$ 60.00 <i>/</i>
	Remove/Refix Undercarriage (FRT)			\$ 200.00 <i>X</i>
	FRT Wheel Alignment			\$ 80.00 <i>60</i>

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Remove/Refix Aircon & Refill Gas			\$ 150.00 60
	TOTAL LABOUR			\$ 2,640.00
	ESTIMATE TOTAL			\$ 16,163.68
Ka/lini 1 (LKK) 28/12/18 1530hrs 4 Days 4/5 After Repair photo				
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To survey damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party surveys on a "Without Prejudice" basis • All reasonable adjustments allowed • Supplemental claims may be resurveyed and is subject to the insurance company Acknowledged by Repairer: Signature: Date:				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				