

ASS. REC. BY:

REF:

CS/7CL19000016/174bn2

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person):

CWS Serene Lee

of

FCL

Date/Time:

02012019 11:42am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKU 739L

Insured:

SHD 8819L

at Workshop m/s

Premium

Tel:

of

55 Wai Rd 1

Policy No:

Claim No:

DIB 009013M FSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

22.12.2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'DS'

03012019 @ 230pm

H.O.D. Endorsement:

Date/Time:

02012019 11:54am

Person Contacted:

Tony

Vehicle:

IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SKU 739L - CCG / ALH17004179 / 174bn2

DIB: 16022017

SHD 8819L - X

4/1/19

Email preli revised to FCL

14/2/19

Final fig \$3710 confirmed by email (Ref 2345, 3910)

REF: FCI

ASSIGNMENT

From

Date: 03012019

Estimated Cost:

OD / ☒ WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SKU 739L

at Workshop m/s

Premium

of

55 Ubi Rd 1

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

2:30pm

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SKU 739L

Yr Regn: 2015 June

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Audi A4 Sedan

c.c 1298

Colour:

Bronze

A/C: Insured / Std / NI / NA

Sp. Reading

S1058

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WAU228K1FA124950

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

245/40R18

R:

245/40R18

BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

03/01/19

Survey held at

Premium

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP / 1st Cap.

RECEIVED 14 FEB 2019

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2) 14/2- typist

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

) S - RS - SI

) Photos

) Others

TOTAL

Report Format:

cws

Lump Sum / I.B.I: (\$

3710/2

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

145

50

50

12

257



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18009013MFSH

Our ref: CS/FCI19000016/Avb

Date : 4/1/2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SKU 739L


We thank you for your instruction on 2/1/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle on 3/1/2019 at the premises of M/s PREMIUM AUTOMOBILES PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$6,055.00
Revised Estimate Amount	: S\$3,710.00
"Check" Items Amount	: S\$300.00
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear portion



Comments/Present Status:

Damages Consistent

Yours faithfully,

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	24-12-2018	Our Ref No. D18009013MFSH
Accident Date	22-12-2018	Claim Type. Third Party
Insured Vehicle	SHD8819L	Third Party Vehicle. SKU0739L
Survey Location	55 UBI ROAD 1	
Contact Person.	MASTURA	
Contact No.	63882323/ 67689828	Fax No. 68411183
Survey Type	WITHOUT PREJUDICE: NO EST. COR (ADMIT LIABILITY QUANTUM TO BE AGREED)	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PREMIUM AUTOMOBILES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 4 January 2019 10:17 AM
To: 'CWS Motor Claims'
Cc: 'Serene Ler'; SUR
Subject: RE: SURVEY ASSESSMENT - D18009013MFSH/1, SKU 739L
Attachments: SKU 739L PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SKU 739L
Date of survey: 3/1/2019
Number of days : 3 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Wednesday, 2 January 2019 11:59 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Serene Ler' <Serener@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18009013MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer arrange survey on 03.01.2019.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 2 January, 2019 11:42 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Serene Ler <Serener@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D18009013MFSH/1

Dear Sir/Mdm,

We refer to the above reference.
Please find attached the necessary documents for survey.
Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : TAN BEE CHUAN
Period of Insurance : 29 Jun 2018 To 28 Jun 2019
Engine No. : CJE101993
Chassis No. : WAUZZZ8K1FA124950

Vehicle No. : SKU739L
Policy No. : 2100420030-03
Endorsement No. :
Issued Date : 15 May 2018

ABOUT THE COVER

Make/Model : AUDI A4 1.8 TFSI MU ATTRACTION (WBW)
Engine Capacity/Tonnage : 1,798.00 CC
Sum Insured : Market Value
Driver Restriction : NA
Off Peak Car : No
First Year of Registration : 2015
Insuring with COE/PAF : Yes

Person or Classes of Persons Entitled to Drive*

- a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$800 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

TAN BEE CHUAN - \$800 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: DBS BANK LTD

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles(Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125206

PREMIUM LEASING - SP

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE

SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

Mobile

AIG Asia Pacific Insurance Pte. Ltd.

AUTHORISED REPRESENTATIVE

AIGSGMOBILEAPP

24-HOUR AIG AUTO HOTLINE: +65 6338 6200

IMPORTANT: KEEP THIS DOCUMENT IN YOUR CAR AT ALL TIMES.

What can the 24-hour AIG Auto Emergency Hotline provide for you?

- Immediate assistance after an accident
- Emergency breakdown service
- Towing service (accident or non-accident related)
- Advice on Motor Claims procedures
- Medical Referral Assistance

If no one is injured in the accident:

- You are not required to make any police report.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s).
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

If the accident involves injuries or damage to government property & vehicles, foreign registered vehicles or non-injury hit & run case:

- Report the accident to the police, providing full details of the circumstances of the accident.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s), if applicable.
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

What should I do in the event of an accident?

- Keep calm and move your car to a safe place.
- Do not admit or discuss fault or blame with the other party(ies).
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.
- Submit Writ/Summons/Correspondences from third party(ies) to AIG immediately.

LOSS OF USE CAR REPLACEMENT BENEFIT

Applicable only if this benefit is included in your motor insurance. Please refer to your Policy Schedule for details. Policy terms and conditions apply. Please call our customer service hotline number **(65) 6419-3000** for assistance.

The Certificate of Insurance (CI) should be produced without demand when collecting the Rental Car and the Rental Car Company reserves the right to verify the identity of the holder. The CI is the property of AIG and its use is subject to the terms and conditions contained in the Loss of Use Endorsement under the policy issued to the policyholder.

Steps to activate Loss of Use Car Replacement Benefit and Important Information

1. To activate your loss of use car replacement, please contact the Rental Car Company (listed below) after filing/reporting your accident claim.
2. Your rental car will be made available within **5** working hours of activation with the Rental Car Company.
3. At the time of collection of the Rental Car, the **original** insurance policy and schedule issued by AIG, a copy of the Accident Report from **Audi Customer Service Centre** must be produced.
4. The number of days is based on the period your vehicle is in the repair workshop unless the number of days of loss of use entitlement is stated in the Policy.
5. Rental cars are strictly for use in Singapore only.
6. Extension of rental beyond repair period approved by AIG surveyor will be chargeable by the Rental Car Company on per day basis.
7. Upgrade of Rental Car is available upon request subject to additional charges by the Rental Car Company.

Rental Car Company: Popular Rent A Car Pte. Ltd.

Activation Hotline: 67428888

501 Guillemard Road Singapore 399840

Operation Hours: Monday to Friday: 9am to 6pm Saturday (Half Day): 9am to 4pm

*The Rental Car Company's Terms & Conditions apply (i.e., refundable security deposit, excess liability for the Rental Car, Collision Damage Waiver, etc).

IMPORTANT NOTICE

If you sell your motor vehicle, this Notice is **IMPORTANT** and **MUST** be complied with. Policyholders are hereby warned that under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.99), it shall be unlawful for any person to use or cause or permit any other person to use a motor vehicle without a valid policy of insurance under the Act.

The Policyholder is further warned that on the sale of a motor vehicle, they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.88).

This Policy will cease to be valid once the motor vehicle has been sold to another person unless the transfer of interest has been duly notified to and agreed to by the insurance company concerned. If the insurance company agrees to cover the new owner, they will issue a new Certificate of Insurance in the new owner's name. The premium chargeable may vary according to the new owner's profile.

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S1544737J



Name

CHAN KOK HEE
(TIAN GUOXI)

田 国 熹

Race

CHINESE

Date of birth

12-11-1962

Country/Place of birth
SINGAPORE

Sex
M

S1544737J

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number S1544737J
Name

CHAN KOK HEE
(TIAN GUOXI)

Birth Date 12 Nov 1962

Issue Date 10 Feb 2003



REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S1709327D



Name

TAN BEE CHUAN

陈 美 专

Race

CHINESE

Date of birth

22-10-1965

Sex

F

Country of birth

SINGAPORE

S1709327D

6009201



NRIC No. S1544737J



Date of issue
27-08-2018


Address

APT BLK 297 BEDOK SOUTH AVENUE 3
#07-02
SINGAPORE 469297

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

Class 3 Motor Cars and Motor Tractors the weight of
which unladen does not exceed 2500 kilograms

PASS DATE
02 Mar 1985




NP 428A



0060266

NRIC No. S1709327D



Blood Group Date of issue
B+ 27-08-1991

APT BLK 297 BEDOK SOUTH AVENUE 3 #07-02
SINGAPORE 469297

NRIC No. S1709327D

Date: 18-06-2002 (R) No: 4095365

Accident Photo



Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/1462/2018/PH
Date : 27-Dec-18

Vehicle not IN workshop. Kindly assist to arrange for survey.

Your insured vehicle : SHD 8819 L

First Capital Insurance Ltd

36 Robinson Road

16-01 City House

Singapore 068877

Attn: Motor Claims Dept

Tel:6854 3909 Fax: 6507 3849

Owner's Name : Mr Tan Bee Chuan
Address : Blk 297 Bedok South Ave 3
#07-02
Singapore 469297
Telephone : HP +65 82825775
Type of Claim : Third party Claims
Policy No. : 2100420030-03
Vehicle No : **SKU 739 L**
Model Code : Audi A4 Sedan 1.8 TFSI
Model / Year : Jun-15
Engine No : CJE 101993
Chassis No : WAUZZZ8K1FA124950
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 22-Dec-18
Place of Accident : Devonshire Road towards Orchard Boulevard

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKU 739 L .

S/N	Nature of Jobs	Estimated Charges
1	To remove and reinstall rear parking aid.Check function.	S/N \$ 280.00 ✓ ✓
2	To dismantle and renew rear bumper.Re-organize crash management components.Reinstall all parts removed.	\$ 900.00 800 ✓
3	To respray rear bumper.	\$ 800.00 600 ✓
4	To carry out diagnostic check.	S/N \$ 192.00 ✓ ✓
TOTAL LABOUR CHARGES		: \$ 2,172.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKU 739 L.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER <i>reld</i>	\$ 2,038.00	<i>2038</i>
2	STICKY PAD <i>new</i>	4 \$ 20.00	<i>+</i>
3	FIXING PARTS FOR REAR BUMPER	\$ 195.00	<i>+</i>
4	REAR BUMPER SPOILER	\$ 232.00	<i>+</i>
5	REAR BUMPER CARRIER	\$ 563.00	<i>+</i>
6	REAR BUMPER GUIDE SECTION - LH/RH	2 \$ 76.00	<i>+</i>
7	REAR BUMPER GUIDE SECTION - UPPER LH/RH	2 \$ 40.00	<i>+</i>
8	REAR BUMPER SECURING STRIP	\$ 11.00	<i>+</i>
9	REAR BUMPER SENSOR	2 \$ 392.00	<i>+</i>
10	REAR BUMPER SENSOR SEAL RING	4 \$ 16.00	<i>+</i>
11	SUNDRIES <i>nn</i>	\$ 300.00	<i>? X</i>
TOTAL SPARE PARTS		:	\$ 3,883.00
TOTAL LABOUR CHARGES		:	\$ 2,172.00
GRAND TOTAL		:	\$ 6,055.00

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Admin King
Surveyed Date : 03/01/19
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 03 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/1462/2018/PH
Date : 27-Dec-18

Vehicle not IN workshop. Kindly assist to arrange for survey.

Your insured vehicle : SHD 8819 L

First Capital Insurance Ltd

36 Robinson Road

16-01 City House

Singapore 068877

Hi Adrian

3 days - ok - jb - 13 Feb 19

Attn: Motor Claims Dept

Tel:6854 3909 Fax: 6507 3849

Owner's Name : Mr Tan Bee Chuan
Address : Blk 297 Bedok South Ave 3
#07-02
Singapore 469297
Telephone : HP +65 82825775
Type of Claim : Third party Claims
Policy No. : 2100420030-03
Vehicle No : **SKU 739 L**
Model Code : Audi A4 Sedan 1.8 TFSI
Model / Year : Jun-15
Engine No : CJE 101993
Chassis No : WAUZZZ8K1FA124950
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 22-Dec-18
Place of Accident : Devonshire Road towards Orchard Boulevard

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKU 739 L .

S/N	Nature of Jobs	Estimated Charges			
1	To remove and reinstall rear parking aid.Check function.	S/N	\$	280.00	\$ 280.00
2	To dismantle and renew rear bumper.Re-organize crash management components.Reinstall all parts removed.		\$	900.00	\$ 600.00
3	To respray rear bumper.		\$	800.00	\$ 600.00
4	To carry out diagnostic check.	S/N	\$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$	2,172.00	\$ 1,672.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKU 739 L .

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER	\$ 2,038.00	\$ 2,038.00
2	STICKY PAD	4 \$ 20.00	
3	FIXING PARTS FOR REAR BUMPER	\$ 195.00	
4	REAR BUMPER SPOILER	\$ 232.00	
5	REAR BUMPER CARRIER	\$ 563.00	
6	REAR BUMPER GUIDE SECTION - LH/RH	2 \$ 76.00	
7	REAR BUMPER GUIDE SECTION - UPPER LH/RH	2 \$ 40.00	
8	REAR BUMPER SECURING STRIP	\$ 11.00	
9	REAR BUMPER SENSOR	2 \$ 392.00	
10	REAR BUMPER SENSOR SEAL RING	4 \$ 16.00	
11	SUNDRIES	\$ 300.00	
TOTAL SPARE PARTS		: \$ 3,883.00	\$ 2,038.00
TOTAL LABOUR CHARGES		: \$ 2,172.00	\$ 1,672.00
GRAND TOTAL		: \$ 6,055.00	\$ 3,710.00

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 14 February 2019 9:01 AM
To: Mei Kwan (LKKAUTO); Boo seng yak
Cc: Carrine Leong; jiayee.yap@premiumauto.com.sg; Claims; SUR
Subject: RE: FINAL REVISION - SKU739L - TP FIRSTCAP - SURVEYED 3 JAN 19

Dear Mr Boo,

WITHOUT PREJUDICE

confirm repair cost of \$3710.00 before GST @ 3 days of repairs.

Kindly send Final invoice and all supporting documents to First Capital Ins Ltd.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Mei Kwan (LKKAUTO)
Sent: Wednesday, 13 February 2019 6:05 PM
To: Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Subject: FW: FINAL REVISION - SKU739L - TP FIRSTCAP - SURVEYED 3 JAN 19

[CS/FCI19000016/Avb](#)

From: Boo seng yak <boojohnny@gmail.com>
Sent: Wednesday, 13 February, 2019 6:04 PM
To: Adrian Ling (LKKAUTO) <adrianling@lkkauto.com>; CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>; jiayee.yap@premiumauto.com.sg; Chang Chee Sing <claims@premiumauto.com.sg>
Subject: FINAL REVISION - SKU739L - TP FIRSTCAP - SURVEYED 3 JAN 19

Hi Adrian and all,

Revised estimate and B4 paint photographs attached.

Please confirm repair cost of \$3710.00 @ 3 days of repairs.

Your early closure is well appreciated.

Best regards - jb




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19000016/Avbn2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 14-02-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 8819L	Veh. Inspected	SKU 739L	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18009013MFSH	Excess (\$)	0.00	
Assign From	SERENE	Assign Date	02/01/2019	
2. Vehicle Particulars & Condition				
Make & Model	AUDI A4 SEDAN	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	WAUZZZ8K1FA124950	Colour	BRONZE	
Odometer	51058	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/40 R18	MICHELIN	6 mm	
L/H Front Tyre	245/40 R18	MICHELIN	6 mm	
R/H Rear Tyre	245/40 R18	MICHELIN	6 mm	
L/H Rear Tyre	245/40 R18	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	22/12/2018	Inspection Date	03/01/2019	
Survey held at	PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1. SINGAPORE 408699			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKU 739L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER (SN)	DEFORMED	2,038.00	2,038.00
4	STICKY PAD (SN)	NOT NECESSARY	20.00	-
1	FIXING PARTS FOR REAR BUMPER (SN)	NOT NECESSARY	195.00	-
1	REAR BUMPER SPOILER (SN)	NOT NECESSARY	232.00	-
1	REAR BUMPER CARRIER (SN)	NOT NECESSARY	563.00	-
2	REAR BUMPER GUIDE SECTION-LH/RH (SN)	NOT NECESSARY	76.00	-
2	REAR BUMPER GUIDE SECTION-UPPER LH/RH (SN)	NOT NECESSARY	40.00	-
1	REAR BUMPER SECURING STRIP (SN)	NOT NECESSARY	11.00	-
2	REAR BUMPER SENSOR (SN)	NOT NECESSARY	392.00	-
4	REAR BUMPER SENSOR SEAL RING (SN)	NOT NECESSARY	16.00	-
1	SUNDRIES (SN)	NOT NECESSARY	300.00	-
			3,883.00	2,038.00
LABOUR				
TO REMOVE AND REINSTALL REAR PARKING AID.CHECK FUNCTION.			280.00	280.00
TO DISMANTLE AND RENEW REAR BUMPER.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED.			900.00	600.00
TO RESPRAY REAR BUMPER.			800.00	600.00
TO CARRY OUT DIAGNOSTIC CHECK.			192.00	192.00
			2,172.00	1,672.00
GRAND TOTAL			6,055.00	3,710.00
RECOMMENDED COST OF REPAIRS				3,710.00

Report Ref No. CS/FCI19000016/Avbn2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.