

CITYCAB PTE LTD

VEHICLE NO : SHC 7813P

DATE 12/27/2018 11:13

MAKE :

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid			\$ 1,349.50
	Boot Lid Rubber			\$ 110.90
	Boot Lid Hinge (LH/RH)		\$ 170.60	\$ 341.20
	Boot Lid Lock Upper			\$ 132.10
	Boot Lid Lock Lower			\$ 30.30
	Boot Lid Key Lock			\$ 78.20
	Boot Lid Sonata Plate			\$ 43.60
	Boot Lid Hyundai Plate			\$ 24.20
	Boot Lid 'H' Emblem			\$ 26.10
	Boot Lid CRDI Plate			\$ 22.70
	Boot Lid Lamp (LH/RH)		\$ 230.20	\$ 460.40
	Boot Lid Trimboard			\$ 165.40
	Boot Lid Trimboard Clips (10pcs)			\$ 11.00
	Rear Bumper			\$ 578.40
	Rear Bumper Reinforcement			\$ 483.30
	Rear Bumper Clip			\$ 22.00
	Rear Bumper Bracket (LH/RH)		\$ 49.00	\$ 98.00
	Rear Bumper Sponge			\$ 137.40
	Rear Bumper Under Cover			\$ 185.80
	Rear Bumper Protector (LH/RH)		\$ 38.00	\$ 76.00
	Tail Lamp (LH/RH)		\$ 344.00	\$ 688.00
	Tail Lamp Quarter Panel (LH/RH)		\$ 93.80	\$ 187.60
	Rear Panel			\$ 391.80
	Rear Panel Garnish			\$ 95.80
	Spare Tyre Holder			\$ 27.60
	Tail Lamp Panel Top (RH)			\$ 217.40
	Spare Tyre Panel			\$ 863.00
	Spare Tyre Panel Cushion			\$ 200.30
	Rear Towing Hook			\$ 135.30
	Member Assy- Rear Floor Centre			\$ 163.60
	Panel Assy-Rear Floor Side (LH/RH)		\$ 88.55	\$ 177.10
	Rear Floor Chassis Member (LH/RH)		\$ 1,280.50	\$ 2,561.00
	Exhaust Pipe Insulator			\$ 56.10
	Exhaust Silencer			\$ 723.00
	Exhaust Pipe Hanger			\$ 56.10
	Rear Fender (LH/RH)		\$ 1,935.90	\$ 3,871.80
	Rear Fender Inner Panel (LH/RH)		\$ 1,255.00	\$ 2,510.00
	Rear Fender Inner Lining (LH/RH)		\$ 74.10	\$ 148.20
	Rear Fender Corner Hardboard Cover (LH)			\$ 204.30
	Rear Tray Lugg Side (RH)			\$ 37.40
	Rear Fender Air-Duct (LH)			\$ 49.40
	Rear Fender Trim Board (LH/RH)		\$ 180.90	\$ 361.80
	Rear Windscreen Moulding			\$ 60.00
	Fuel Tank Sub Hose			\$ 78.20
	Fuel Tank Upper Neck			\$ 221.60
	Rear Wiring Assy			\$ 1,458.00

DATE 12/27/2018 11:13

Page 1 of 1