

INSURANCE

INS. CASE OWNER:

CC 4/EQ11900

0128, Agt

LOCK

IDAC:

Surveyor:

Adrian

DOI:

2/1/19

Date / Time:

2/1/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SJB 27512

Name of Insured:

IMMIL BIN SAID

Insured Tel No.:

HP:

Claim No.:

Policy No.:

Make / Model:

MITSUBISHI

Excess Sec II :SS

D.O.A:

27/1/18

Place of Accident:

SUNTEL CITY BRVD

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SJR 54214



INSRS:

WSP:

Tel:

Liability:

RMKS:

JCN



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time	STAGE	DATE / PIC
8/1/19	Non-Reporting lr (1st):	
	Non-Reporting lr (2nd):	
	Non-Reporting lr (Final):	
	Notification lr (if non-pickup):	
	Call OI:	
	After call lr to OI:	
	Documentation Check List:	Handler Typist
	Notification lr (if non-pickup)	☒
	After call lr to OI:	☒
	Authorisation To Act:	☒
	Release Voucher:	☒
	Final Repair Bill:	☒
	Car Rental Invoice:	☒
	Towing Invoice:	☒
	LTA / GIA:	☒
	Medical Bill:	☒
	PIR:	☒
	Mandate/Reject Instruction:	☒
	LOD:	☒
	Payment Breakdown Form:	☒
	Post-Repair Photos:	☒
	Others:	☒

PRELIMINARY ADVICE Date/Time: Sent By: Confirm with: Confirm by: Adrian

Repair Cost: US \$54700.00 (6 days) Reduction: \$1050.00 = 62 Email: Call:

FINAL SETTLEMENT Date/Time: 20/02/2020 Confirm with: Email: Call:

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: 27

Repair Cost: \$54700.00

Loss of Rental (LOR): \$5 (5 days)

Loss of Use (LOU): \$5470.00 (\$570 x 7 days)

Loss of Income (LOI): \$5 (5 x days)

LOR only ☐ LOU only ☒ LOR + LOU ☐ LOR + LO ☐ [Tick only one]

GIA/LTA Search: \$5 7.45

Medical: \$5

Disbursement: \$5 (e.g. Tow/Independent)

Legal Cost: \$5

Total: \$54057.45 **Global Sum \$5:** 5050.00

FINAL PAYMENT Date/Time: Confirm with: Email: Call:

Payee 1: \$54050.00 Name 1: JCN Autolution Pte Ltd

Payee 2: (Strike if N.A.) \$5 Name 2:

Payee 3: (Strike if N.A.) \$5 Name 3:

COPY SENT

OK 5/2 02

ASSIGNMENT

29/06/09

From

Date

02/01/2019

Estimated Cost

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle No

SJR5421Y

at Workshop mis

JCN Autolub

of

8 Kaki Bukit Ave 4 #06-21

Insured

Policy No.

Claims No.

Sum Insured

Excess

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? Yes or No

GIA / PR Seen:

Consistent? Yes or No

Est. Repairs:

6

days

Res:

Yes or No

Lum Sum:

20

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted

Vehicle: IN / OUT

Veh No.

SJR5421Y

Yr Regn:

2009, June

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Suzuki Swift

C.C. 1586

Colour

White

A/C

Insured / Std / NI / NA

Sp Reading

135965

T/Radio:

Insured / Std / NI / NA

Eng/No

C/Nr:

JSAEZC31500204374

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/45R17

R:

205/45R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Leao

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

02/01/19

Survey held at

JCN

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP EQ

COE Expiry: 30/09/23

45 A4700.00 (Red - 47558.06 / 62%)

MV: 25K.

PV: 15.3K.

Nett: 9.7K.

1796H

Date/Time: File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time: File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

1) S + RS \$

2) Photos

3) Others

TOTAL

Report Format :

Lump Sum / L.B.I: (\$

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD		Ref : CC4/EQI19000128/Ajb3		
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date : 03-01-2019		
		Code : EQI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJB 2751Z	Veh. Inspected	SJR 5421Y	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	03/01/2019	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	27/12/2018	Inspection Date	02/01/2019	
Survey held at	JCN AUTOLUTION PTE LTD 8 KAKI BUKIT AVENUE 4 #07-23 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



JCN Autolution Pte Ltd

COMPANY REG NO: 201812309W

8 Kaki Bukit Ave 4, #07-23, Premier @ Kaki Bukit,
Singapore 415875

+65 6881 1772 sales@jcngroup.com

ESTIMATE

SARINA BINTE MOHAMED NOOR
BLK 685B JURONG WEST STB4 #04-169
Singapore 642685

Contact: 91519993

TP EQ
Cecilia

Code: C100035
Date in: 28/12/2018
Vehicle Num: SJR5421Y
Model: SUZUKI SWIFT 1.6 MT
Chassis/Eng#: JSAEYC31S00204374/M16A1469499

Parts and Labour Assessment

Description of part	Qty	Unit Price	Amount
REAR TAILGATE <i>Not New</i>	1	628.15	628.15 X
REAR BUMPER <i>Distorted</i>	1	549.65	549.65 ✓
REAR BUMPER CORNER RETAINER L/R <i>LH Dmg</i>	2	20.05	40.10 <i>20.05</i>
REAR BUMPER IMPACT BRACKET LH <i>Not New</i>	1	26.00	26.00 X
REAR BUMPER LOWER SPOILER <i>Red</i>	1	479.25	479.25 ✓
REAR BUMPER SIDE RETAINER L/R <i>LH Dmg</i>	2	23.00	46.00 <i>23</i>
REAR CROSS MEMBER <i> Bent</i>	1	889.90	889.90 ✓
REAR END PANEL <i>Regrs</i>	1	274.85	274.85 X
REAR END PANEL AIR VENT LH <i>Not New</i>	1	35.95	35.95 X
REAR EXHAUST SYSTEM RUBBER MOUNTING <i>Not New</i>	2	20.00	40.00 X
REAR FENDER INNER SHIELD <i>torn</i>	1	92.65	92.65 ✓
REAR FENDER INNER SHIELD CLIPS <i>new</i>	3	3.00	9.00 ✓
REAR FENDER INNER TRIMBOARD <i>new</i>	1	69.55	69.55 X
REAR FENDER LH <i>Distorted</i>	1	350.70	350.70 ✓
REAR KNUCKLE BEARING LH <i>Dmg</i>	1	376.90	376.90 ✓
REAR KNUCKLE HUB LH <i>Dmg</i>	1	302.50	302.50 ✓
REAR SHOCK ABSORBER LH <i>Bent</i>	1	303.50	303.50 ✓



JCN Autolution Pte Ltd

COMPANY REG NO: J 201812035W

8 Kall Bukit Ave 4, #07-23, Premier @ Kall Bukit,
Singapore 415875

+65 6881 1772 sales@jcngroup.com

REAR TAILGATE DAMPER L/R	2	120.40	240.80	x
REAR TAILGATE MECHANISM LOCK	1	180.10	180.10	x
REAR TAILGATE RUBBER WEATHER STRIP	1	92.65	92.65	x
REAR TAILLAMP LH <i>cracked</i>	1	287.90	287.90	✓
REAR TAILLAMP LIGHT BULB LH <i>not new</i>	1	10.00	10.00	x
REAR TAILLAMP PANEL LH <i>3688</i>	1	73.38	73.38	x
REAR TAILLAMP STAY CLIPS <i>313480</i>	2	5.00	10.00	x
Subtotal before discount			5,409.48	
Percentage discount 15%			811.42	
Sub-total 1			4,598.06	
REAR BUMPER CARBON GARNISH (ACCESSORY) <i>cracked</i>	1	600.00	600.00	480
REAR BUMPER CLIPS SET <i>new</i>	1	30.00	30.00	✓
REAR BUMPER REVERSE SENSOR <i>new</i>	1	350.00	350.00	x
REAR EXHAUST SYSTEM <i>new</i>	1	1500.00	1,500.00	x
REAR FENDER PETROL INLET COVER <i>new</i>	1	280.00	280.00	x
REAR SPORTS RIM LH <i>new</i>	1	500.00	500.00	400
REAR TAILGATE WINDSCREEN SEALANT <i>new</i>	1	80.00	80.00	x
REAR TYRE LH <i>Not new</i>	1	380.00	380.00	x
Subtotal before discount			3,720.00	
Percentage discount 0%			0.00	
Sub-total 2			3,720.00	
Parts-total			8,318.06	



JCN Autolution Pte Ltd COMPANY REG NO: 30181330W
 8 Kaki Bukit Ave 4, #07-23, Premier @ Kaki Bukit,
 Singapore 415875
 +65 6881 1772 sales@jcngroup.com

LABOUR

Description	Price
TO PROVIDE TOWING CHARGE	50.00 ✓
TO DIAGNOSE, REPLACE AND/OR REPAIR TO RECTIFY REAR PORTION ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	100.00 X
TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING (FR)	60.00 30
TO REFIX/RENEW REVERSE SENSOR ASSY AND RECTIFY FOR PROPER FUNCTIONING	100.00 50
TO REMOVE, REINSTALL REAR TAILGATE WINDSCREEN (TO FR)	100.00 X
TO REMOVE, CHANGE REAR SUSPENSION PARTS, AXLE CARRIAGE, ABSORBER, LOWER ARM, TOP ARM, TRAILING ARM, KNUCKLE ARM, WHEEL BEARING, BEARING HUB AND ETC.	450.00 300
TO REMOVE, REINSTALL BRAKE PARTS, BRAKE LINE, BRAKE PUMP AND BLEEDING BRAKE SYSTEM	200.00 X
TO REMOVE, REINSTALL PETROL TANK (TO FR)	80.00 ✓
TO REMOVE, REINSTALL ROOF TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET (TO FR)	80.00 60
TO RESPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT	1,000.00 600
TO REMOVE AND CHANGE EXHAUST SILENCER BOX WITH PIPE, RE-ALIGN WHERE NECESSARY CONSISTENT TO THE ACCIDENT	100.00 X
TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	1,500.00 700
TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	120.00 60
Labour Total	3,940.00
Parts & Labour Total	12,258.06

page 3

total: 5974.80
 L/S: A.7K
 06 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
 Signature:
 Date:

7/12/2019, 12:06 PM



JCN Autolution Pte Ltd COMPANY REG NO.: 201813308W
8 Kaki Bukit Ave 4, #07-23, Premier @ Kaki Bukit,
Singapore 415875
+65 6881 1772 sales@jcngroup.com

ESTIMATE

SARINA BINTE MOHAMED NOOR
BLK 685B JURONG WEST ST64 #04-169
Singapore 642685
Contact : 91519993

Code : C100035
Date in : 28/12/2018
Vehicle Num. : SJR5421Y
Model : SUZUKI SWIFT 1.6 MT
Chassis/Eng# : JSAEYC31S00204374/M16A1469499

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR TAILGATE	1	628.15	628.15
REAR BUMPER	1	549.65	549.65
REAR BUMPER CORNER RETAINER L/R	2	20.05	40.10
REAR BUMPER IMPACT BRACKET LH	1	26.00	26.00
REAR BUMPER LOWER SPOILER	1	479.25	479.25
REAR BUMPER SIDE RETAINER L/R	2	23.00	46.00
REAR CROSS MEMBER	1	889.90	889.90
REAR END PANEL	1	274.85	274.85
REAR END PANEL AIR VENT LH	1	35.95	35.95
REAR EXHAUST SYSTEM RUBBER MOUNTING	2	20.00	40.00
REAR FENDER INNER SHIELD	1	92.65	92.65
REAR FENDER INNER SHIELD CLIPS	3	3.00	9.00
REAR FENDER INNER TRIMBOARD	1	69.55	69.55
REAR FENDER LH	1	350.70	350.70
REAR KNUCKLE BEARING LH	1	376.90	376.90
REAR KNUCKLE HUB LH	1	302.50	302.50
REAR SHOCK ABSORBER LH	1	303.50	303.50



JCN Autolution Pte Ltd COMPANY REG NO.: 201812389W
 8 Kaki Bukit Ave 4, #07-23, Premier @ Kaki Bukit,
 Singapore 415875
 ☎ +65 6881 1772 ✉ sales@jcngroup.com

REAR TAILGATE DAMPER L/R	2	120.40	240.80
REAR TAILGATE MECHANISM LOCK	1	180.10	180.10
REAR TAILGATE RUBBER WEATHER STRIP	1	92.65	92.65
REAR TAILLAMP LH	1	287.90	287.90
REAR TAILLAMP LIGHT BULB LH	1	10.00	10.00
REAR TAILLAMP PANEL LH	1	73.38	73.38
REAR TAILLAMP STAY CLIPS	2	5.00	10.00
Subtotal before discount			5,409.48
Percentage discount 15%			811.42
Sub-total 1			4,598.06
REAR BUMPER CARBON GARNISH (ACCESSORY)	1	600.00	600.00
REAR BUMPER CLIPS SET	1	30.00	30.00
REAR BUMPER REVERSE SENSOR	1	350.00	350.00
REAR EXHAUST SYSTEM	1	1500.00	1,500.00
REAR FENDER PETROL INLET COVER	1	280.00	280.00
REAR SPORTS RIM LH	1	500.00	500.00
REAR TAILGATE WINDSCREEN SEALANT	1	80.00	80.00
REAR TYRE LH	1	380.00	380.00
Subtotal before discount			3,720.00
Percentage discount 0%			0.00
Sub-total 2			3,720.00
Parts-total			8,318.06



JCN Autolution Pte Ltd COMPANY REG NO.: 201813309H
 8 Kaki Bukit Ave 4, #07-23, Premier @ Kaki Bukit,
 Singapore 415875
 ☎ +65 4881 1772 ✉ sales@jcngroup.com

LABOUR

Description	Price
TO PROVIDE TOWING CHARGE	50.00
TO DIAGNOSE, REPLACE AND/OR REPAIR TO RECTIFY REAR PORTION ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	100.00
TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING. (FR)	60.00
TO REFIX/RENEW REVERSE SENSOR ASSY AND RECTIFY FOR PROPER FUNCTIONING	100.00
TO REMOVE, REINSTALL REAR TAILGATE WINDSCREEN. (TO FR)	100.00
TO REMOVE, CHANGE REAR SUSPENSION PARTS, AXLE CARRIAGE, ABSORBER, LOWER ARM, TOP ARM, TRAILING ARM, KNUCKLE ARM, WHEEL BEARING, BEARING HUB AND ETC.	450.00
TO REMOVE, REINSTALL BRAKE PARTS, BRAKE LINE, BRAKE PUMP AND BLEEDING BRAKE SYSTEM	200.00
TO REMOVE, REINSTALL PETROL TANK (TO FR)	80.00
TO REMOVE, REINSTALL ROOF TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET (TO FR)	80.00
TO RESPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT	1,000.00
TO REMOVE AND CHANGE EXHAUST SILENCER BOX WITH PIPE, RE-ALIGN WHERE NECESSARY CONSISTENT TO THE ACCIDENT	100.00
TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	1,500.00
TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	120.00
Labour Total	3,940.00
Parts & Labour Total	12,258.08

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	1796H
Vehicle No.:	SJR5421Y
Vehicle to be Exported:	Yes
Intended Deregistration Date:	02 Jan 2019
Vehicle Make:	SUZUKI
Vehicle Model:	SWIFT 1.6 MT
Primary Colour:	White
Manufacturing Year:	2009
Engine No.:	M16A1469499
Chassis No.:	J5AEZC31S00204374
Maximum Power Output:	92.0 kW (123 bhp)
Open Market Value:	\$14,396.00
Original Registration Date:	29 Jun 2009
First Registration Date:	29 Jun 2009
Transfer Count:	4
Actual ARF Paid:	\$14,396.00

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Jun 2019
PARF Rebate Amount:	\$7,198.00

COE Expiry Date:	30 Sep 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$16,170.00
COE Rebate Amount:	\$15,343.00
Total Rebate Amount:	\$22,541.00

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 02 Jan 2019

OK

- 10 days self drive in Hokkaido
- Kia Stonic
- KIA Stinger GT



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

 Post an Ad  Advertiser Login  Ways of Selling

New 5 Years COE Renewal Toyota Wish 1.8A.

2.88% P.A. Lowest Interest @ GV
Cars Financing.
GV Credit For Life StarAd




HIN LUNG AUTO
Ho Bee Group

30 years
of car sales

One Stop Car Hub
Finance, Insurance, Workshop
New and Used Cars

Browse by Category  Save Search  Print Sort by Date Posted 20 results/page

16 vehicles **Search** Advanced Search Search View All

Make: Model: Price: Depreciation: Reg Date: Eng Cap: Mileage: Veh Type: Status:

Search Selection ☐ Swift



☐ Suzuki Swift 1.2A XG \$9,800 N/A 22-Jan-2009 1,242 cc 156,800 km Hatchback Available

COE Renewal Available At \$24,800 For 5 Years, High Loan Available, Trade In Welcome. Very Good Condition, View And Test Drive Today!

 [Home](#) [About Us](#) [Contact Us](#) [Privacy Policy](#) [Terms & Conditions](#) [Sitemap](#) [Feedback](#) [Help](#) [FAQ](#) [Glossary](#) [Links](#) [Partners](#) [Sponsors](#) [Advertise](#) [Affiliate](#) [Wholesale](#) [Retail](#) [Franchise](#) [Investment](#) [Consulting](#) [Training](#) [Support](#) [Marketing](#) [Sales](#) [Distribution](#) [Manufacturing](#) [Research & Development](#) [Quality Control](#) [Customer Service](#) [Logistics](#) [Finance](#) [Insurance](#) [Legal](#) [Tax](#) [Accounting](#) [Human Resources](#) [Information Technology](#) [Operations](#) [Production](#) [Supply Chain](#) [Procurement](#) [Inventory Management](#) [Transportation](#) [Warehousing](#) [Packaging](#) [Marketing](#) [Sales](#) [Distribution](#) [Manufacturing](#) [Research & Development](#) [Quality Control](#) [Customer Service](#) [Logistics](#) [Finance](#) [Insurance](#) [Legal](#) [Tax](#) [Accounting](#) [Human Resources](#) [Information Technology](#) [Operations](#) [Production](#) [Supply Chain](#) [Procurement](#) [Inventory Management](#) [Transportation](#) [Warehousing](#) [Packaging](#)



☐ Suzuki Swift 1.3A (New 5-yr COE) \$22,800 \$4,560 /yr 06-Feb-2009 1,328 cc 105,339 km Hatchback Available

\$3k Down Payment! 1 Year Comprehensive Warranty Inclusive, Accident Free Quality Pre-Owned With Low Mileage For Peace Of Mind. 100% Loan Approval With Our Flexible In House Financing Options. View Today...

Cosmo Automobiles

 [Home](#) [About Us](#) [Contact Us](#) [Privacy Policy](#) [Terms & Conditions](#) [Sitemap](#) [Feedback](#) [Help](#) [FAQ](#) [Glossary](#) [Links](#) [Partners](#) [Sponsors](#) [Advertise](#) [Affiliate](#) [Wholesale](#) [Retail](#) [Franchise](#) [Investment](#) [Consulting](#) [Training](#) [Support](#) [Marketing](#) [Sales](#) [Distribution](#) [Manufacturing](#) [Research & Development](#) [Quality Control](#) [Customer Service](#) [Logistics](#) [Finance](#) [Insurance](#) [Legal](#) [Tax](#) [Accounting](#) [Human Resources](#) [Information Technology](#) [Operations](#) [Production](#) [Supply Chain](#) [Procurement](#) [Inventory Management](#) [Transportation](#) [Warehousing](#) [Packaging](#)



☐ Suzuki Swift 1.2A XG (New 5-yr COE) \$23,800 \$4,760 /yr 09-Feb-2009 1,242 cc - Hatchback Available

Good Condition And Nice. Can Loan \$20000, View To Believe It.

 [Home](#) [About Us](#) [Contact Us](#) [Privacy Policy](#) [Terms & Conditions](#) [Sitemap](#) [Feedback](#) [Help](#) [FAQ](#) [Glossary](#) [Links](#) [Partners](#) [Sponsors](#) [Advertise](#) [Affiliate](#) [Wholesale](#) [Retail](#) [Franchise](#) [Investment](#) [Consulting](#) [Training](#) [Support](#) [Marketing](#) [Sales](#) [Distribution](#) [Manufacturing](#) [Research & Development](#) [Quality Control](#) [Customer Service](#) [Logistics](#) [Finance](#) [Insurance](#) [Legal](#) [Tax](#) [Accounting](#) [Human Resources](#) [Information Technology](#) [Operations](#) [Production](#) [Supply Chain](#) [Procurement](#) [Inventory Management](#) [Transportation](#) [Warehousing](#) [Packaging](#)



☐ Suzuki Swift Sport 1.6M (New 5-yr COE) \$31,000 \$6,200 /yr 11-Feb-2009 1,586 cc 94,000 km Hatchback Available

Reason Of Selling My Ride Friend Has Revoked His License And Selling His Very Good 335 At A Good Price To Me. Due To Respray Outer Casing, Gasket, Drive Shaft, Shock Absorber And Cooling Coil Wanted T...

 [Home](#) [About Us](#) [Contact Us](#) [Privacy Policy](#) [Terms & Conditions](#) [Sitemap](#) [Feedback](#) [Help](#) [FAQ](#) [Glossary](#) [Links](#) [Partners](#) [Sponsors](#) [Advertise](#) [Affiliate](#) [Wholesale](#) [Retail](#) [Franchise](#) [Investment](#) [Consulting](#) [Training](#) [Support](#) [Marketing](#) [Sales](#) [Distribution](#) [Manufacturing](#) [Research & Development](#) [Quality Control](#) [Customer Service](#) [Logistics](#) [Finance](#) [Insurance](#) [Legal](#) [Tax](#) [Accounting](#) [Human Resources](#) [Information Technology](#) [Operations](#) [Production](#) [Supply Chain](#) [Procurement](#) [Inventory Management](#) [Transportation](#) [Warehousing](#) [Packaging](#)

GET YOUR COE RENEWAL LOAN

Is your COE expiring? Let us help you renew it!

Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.



☐ Suzuki Swift Sport 1.6M (New 5-yr COE) \$26,800 \$5,360 /yr 17-Feb-2009 1,586 cc 158,000 km Hatchback Available

Car Is Very Well Maintained. Just Serviced On December With Full Receipt. Oil Leak Has Been Done Up. Totally No Leak At All. New Aircon Compressor, New Belting, New Coolant, New Gear Oil And A Lot. So...

 [Home](#) [About Us](#) [Contact Us](#) [Privacy Policy](#) [Terms & Conditions](#) [Sitemap](#) [Feedback](#) [Help](#) [FAQ](#) [Glossary](#) [Links](#) [Partners](#) [Sponsors](#) [Advertise](#) [Affiliate](#) [Wholesale](#) [Retail](#) [Franchise](#) [Investment](#) [Consulting](#) [Training](#) [Support](#) [Marketing](#) [Sales](#) [Distribution](#) [Manufacturing](#) [Research & Development](#) [Quality Control](#) [Customer Service](#) [Logistics](#) [Finance](#) [Insurance](#) [Legal](#) [Tax](#) [Accounting](#) [Human Resources](#) [Information Technology](#) [Operations](#) [Production](#) [Supply Chain](#) [Procurement](#) [Inventory Management](#) [Transportation](#) [Warehousing](#) [Packaging](#)



☐ Suzuki Swift 1.3A (New 5-yr COE) \$28,000 \$5,600 /yr 20-Feb-2009 1,328 cc - Hatchback Available

Repairs Done Up Worth \$3K, Flexible In House Loan Available. For A Transport Car, Its' Definitely A Worthy Ride. 100% Loan Approval. Catch It While The COE Is Low. Call Now.

 [Home](#) [About Us](#) [Contact Us](#) [Privacy Policy](#) [Terms & Conditions](#) [Sitemap](#) [Feedback](#) [Help](#) [FAQ](#) [Glossary](#) [Links](#) [Partners](#) [Sponsors](#) [Advertise](#) [Affiliate](#) [Wholesale](#) [Retail](#) [Franchise](#) [Investment](#) [Consulting](#) [Training](#) [Support](#) [Marketing](#) [Sales](#) [Distribution](#) [Manufacturing](#) [Research & Development](#) [Quality Control](#) [Customer Service](#) [Logistics](#) [Finance](#) [Insurance](#) [Legal](#) [Tax](#) [Accounting](#) [Human Resources](#) [Information Technology](#) [Operations](#) [Production](#) [Supply Chain](#) [Procurement](#) [Inventory Management](#) [Transportation](#) [Warehousing](#) [Packaging](#)



☐ Suzuki Swift Sport 1.6M (New 10-yr COE) \$40,900 \$4,090 /yr 28-Feb-2009 1,586 cc - Hatchback Available

5 Years COE \$32,800.00. In House Loan And Bank Loan Available. Choice Of New Colour. From 1.18 Onwards.

 [Home](#) [About Us](#) [Contact Us](#) [Privacy Policy](#) [Terms & Conditions](#) [Sitemap](#) [Feedback](#) [Help](#) [FAQ](#) [Glossary](#) [Links](#) [Partners](#) [Sponsors](#) [Advertise](#) [Affiliate](#) [Wholesale](#) [Retail](#) [Franchise](#) [Investment](#) [Consulting](#) [Training](#) [Support](#) [Marketing](#) [Sales](#) [Distribution](#) [Manufacturing](#) [Research & Development](#) [Quality Control](#) [Customer Service](#) [Logistics](#) [Finance](#) [Insurance](#) [Legal](#) [Tax](#) [Accounting](#) [Human Resources](#) [Information Technology](#) [Operations](#) [Production](#) [Supply Chain](#) [Procurement](#) [Inventory Management](#) [Transportation](#) [Warehousing](#) [Packaging](#)

SHORTLISTED HISTORY

Compare 



View

100% Loan Available



☐ Suzuki Swift Sport 1.6A (New 10-yr COE) \$40,800 \$4,080 /yr 17-Mar-2009 1,586 cc 90,257 km Hatchback Available

New Arrival, Cheapest In The Market, Only \$4.8k Per Year. 100% Loan Available. Bank Loan/In House Loan And Trade In Available. Call Friends Auto Traders Your Trusted Dealership And Drive Home Your Suz...

PREMIUM LISTING

Posted: 11-Jan-2019 Tags: 2009 Suzuki Swift, 2009 Suzuki Swift, Suzuki Swift, Suzuki Swift, Suzuki Swift, Suzuki Swift, Suzuki Swift, Suzuki Swift, Suzuki Swift, Suzuki Swift



☐ Suzuki Swift 1.2A XG (New 5-yr COE) \$26,800 \$5,360 /yr 26-Mar-2009 1,242 cc 127,000 km Hatchback Available

ZERO Drive Away! Get Your Own Transport With LESS Than \$15/Day, Cheaper Than Rental. Very Low Mileage, In House Loan, 100% Loan Available! Limited ONLY Time Offer. Please Call/SMS/WhatsApp JJ Now! Don't...

Hua Yang Credit Pte Ltd

Posted: 10-Jan-2019 Tags: 2009 Suzuki Swift, 2009 Suzuki Swift, Suzuki Swift, Suzuki Swift, Suzuki Swift, Suzuki Swift, Suzuki Swift, Suzuki Swift, Suzuki Swift, Suzuki Swift



☐ Suzuki Swift 1.5A GL (New 5-yr COE) \$24,000 \$4,800 /yr 16-Apr-2009 1,490 cc - Hatchback Available

Monthly Installment \$560 x 4 Years. Welcome Trade In. Smooth Engine And Gearbox. No Repair Needed. Message Or Whatsapp For More Information.

Posted: 12-Jan-2019 Tags: 2009 Suzuki Swift, 2009 Suzuki Swift, Suzuki Swift, Suzuki Swift, Suzuki Swift, Suzuki Swift, Suzuki Swift, Suzuki Swift, Suzuki Swift, Suzuki Swift



Car Wash By Professional Groomers

Skipping the car after the rain can cause acidic deposit and containment build up. Get your car washed by professional groomers from just \$10. Find the list right here.

Find out more!



☐ Suzuki Swift Sport 1.6M (New 5-yr COE) \$27,800 \$5,560 /yr 21-Apr-2009 1,586 cc - Hatchback Available

For More Enquire Call Or Text.

DIRECT OWNER

Posted: 26-Dec-2018 Tags: 2009 Suzuki Swift, 2009 Suzuki Swift, Suzuki Swift, Suzuki Swift, Suzuki Swift, Suzuki Swift, Suzuki Swift, Suzuki Swift, Suzuki Swift, Suzuki Swift



☐ Suzuki Swift Sport 1.6A \$12,800 N.A 11-May-2009 1,586 cc - Hatchback Available

Single Exhaust Mod Legally With Sunline Racing. Super Loud And Fun. Changed Engine Mounting, Radiator, Alternator With Receipts.

DIRECT OWNER

Posted: 19-Dec-2018 Tags: 2009 Suzuki Swift, 2009 Suzuki Swift, Suzuki Swift, Suzuki Swift, Suzuki Swift, Suzuki Swift, Suzuki Swift, Suzuki Swift, Suzuki Swift, Suzuki Swift



☐ Suzuki Swift Sport 1.6A (New 5-yr COE) \$26,800 \$5,360 /yr 28-May-2009 1,586 cc 105,787 km Hatchback Available

\$3k Deposit! Super Well Taken Care Of By Previous 1 Owner! Free 6 Months Warranty To Be Provided For A Peace Of Mind! Can Send To Own Workshop To Check. Non-Obligatory Test Drive Now.

Creative Auto

Posted: 27-Dec-2018 Tags: 2009 Suzuki Swift, 2009 Suzuki Swift, Suzuki Swift, Suzuki Swift, Suzuki Swift, Suzuki Swift, Suzuki Swift, Suzuki Swift, Suzuki Swift, Suzuki Swift



☐ Suzuki Swift 1.2A XG \$10,500 \$7,550 /yr 15-Sep-2009 1,242 cc 97,000 km Hatchback Available

Very Well Maintained, Only 1 Owner With Genuine Low Mileage! Sporty Swift. Good For Daily Usage. Good For COE Renewal. Monitor Screen For Passenger Included. Trade In Available. Call Now! Viewing By App...

360 VR Cars

Posted: 14-Dec-2018 Tags: 2009 Suzuki Swift, 2009 Suzuki Swift, Suzuki Swift, Suzuki Swift, Suzuki Swift, Suzuki Swift, Suzuki Swift, Suzuki Swift, Suzuki Swift, Suzuki Swift



☐ Suzuki Swift Sport 1.6M (New 10-yr COE) \$60,888 \$6,088 /yr 29-Sep-2009 1,586 cc 10,000 km Hatchback Available

Good Car Not Cheap, Cheap Car Not Good. Spend More Than 20k Rebuilding. Still Got A lot Parts Not Listed. Perfect For 10 Years Renewal!

DIRECT OWNER

Posted: 26-Nov-2018 Tags: 2009 Suzuki Swift, 2009 Suzuki Swift, Suzuki Swift, Suzuki Swift, Suzuki Swift, Suzuki Swift, Suzuki Swift, Suzuki Swift, Suzuki Swift, Suzuki Swift



☐ Suzuki Swift Sport 1.6A \$16,800 \$10,050 /yr 27-Oct-2009 1,586 cc 160,000 km Hatchback Available

Taken Care By Owner. Beautiful Exterior And Interior. Bluetooth Function Added By Owner. Bank/In House Loan Can Be Arranged. Trade In Welcome. Consignment Unit. Call/SMS/WA Now To View This Swift. Be ...

Posted: 22-Dec-2018 Tags: 2009 Suzuki Swift, 2009 Suzuki Swift, Suzuki Swift, Suzuki Swift, Suzuki Swift, Suzuki Swift, Suzuki Swift, Suzuki Swift, Suzuki Swift, Suzuki Swift

Save this search criteria, to get email alerts whenever a match is found.

Save Search

SHORTLISTED: 0000004

Compare

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

view Expired ads

20 results/page

Catherine Chong (LKK Auto)

From: Janet Tan <janet.tan@eqinsurance.com.sg>
Sent: Wednesday, 2 January, 2019 2:06 PM
To: assignments
Cc: 'Admin A'
Subject: Our ref: SJB2751Z, PRI for vehicle SJR5421Y
Attachments: EQ INSURANCE new format SJR5421Y (2).odt; SAS2527262.pdf; SAS2527204.pdf

Dear Catherine

Please arrange to attend to the PRS as SJE.

For your info, we are of the view that the dmages on both vehicles did not appear to be consistent.

Regards,

Janet Tan
Senior Executive | Claims

07012019 @ 2:34pm
Mr. Chon vth in
Action



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6496 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4190
www.eqinsurance.com.sg

 A Member of Citystate



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify ti

From: Serene Apple [mailto:serenefmm@yahoo.com.sg]
Sent: Wednesday, January 2, 2019 12:25 PM
To: EQI PRS <EQIPRS@eqinsurance.com.sg>; Janet Tan <janet.tan@eqinsurance.com.sg>
Subject: PRI for vehicle SJR5421Y



JCN Autolution Pte Ltd

COMPANY REG. NO.: 201813305W

📍 No.1 Kaki Bukit Ave 6, Blk D #01-85, AutoBay @ Kaki Bukit,
Singapore 417883.

☎ +65 6881 1772 ✉ sales@jcngroup.com

Date: 28TH DECEMBER 2018

EQ Insurance Company Ltd,
22, Gemmill Lane
Singapore 069257

Fax: 6223 4290
Email: eqirs@eqinsurance.com.sg
Surveyor: LKK Auto Consultants Pte Ltd

Attn: Motor Claims Department

Dear Sir/Madam

ACCIDENT INVOLVING VEHICLES SJR5421Y AND SJB2751Z ON 27-DEC-2018 0530HRS
AT RAFFLES BLVD.

1. We act for the Owner of Vehicle No. SJR5421Y whose vehicle was damaged as a result of an accident with your Insured, the Driver of Vehicle No. SJB2751Z on 27-DEC-2018.
2. As a result of the accident, our client's vehicle has been damaged. Please kindly revert back to us once you/Insurer have received this notice and a Pre-Repair Inspection will be arranged within the next 02 working days before we carry out any repairs to the mentioned vehicle.
3. If we do not receive any reply or instruction from you/Insurer within the stipulated timeline, our client/we shall proceed to repair the mentioned vehicle without further reference to you/Insurer.

Please kindly contact me @ 9677 5772 should you require more information.

Inspection & Repair Location: **8 Kaki Bukit Ave 4 #06-21, Premier@Kaki Bukit S417 875.**

Yours faithfully,

Chan
JCN Autolution Pte Ltd
M: 9677 5772
O: 6881 1772
E: erik@jcngroup.com



JCN Autolution Pte Ltd

COMPANY REG. NO.: 201813305W

📍 No.1 Kaki Bukit Ave 6, Blk D #01-85, AutoBay @ Kaki Bukit,
Singapore 417883.

☎ +65 6881 1772 ✉ sales@jcngroup.com



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

To : M/s EQ INSURANCE COMPANY LTD

Date: 17/03/2020

THIRD PARTY DIRECT SETTLEMENT

Vehicle No.	SJB 2751Z (Insd Veh)	Your Ref. No. :
	SJR 5421Y (TP Veh)	Our Ref. No. : CC4/EQI19000128/Aga3q2
Date of Accident	27/12/2018	

Liability	100%	
Final Repair Cost	: \$ 4,700.00	
Loss of Use	: \$ 350.00	7 days
Rental (If any)	: \$	days
Others:	: \$ 7.45	
	: \$	
	5,057.45	
Final Settlement Sum	: \$ 5,050.00	GLOBAL SUM
Remarks	:	

<u>Payment Instruction: Payee's Breakdown</u>		
1)	JCN AUTOLUTION PTE LTD	: \$ 5,050.00
		: \$

JOANNE LEE

LKK Auto Consultants Pte Ltd

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CC4/EQI19000128/Aga3q2

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEXSINGAPORE 069110

Date : 17-03-2020



Code : EQI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJB 2751Z	Veh. Inspected	SJR 5421Y
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	JANET	Assign Date	02/01/2019

2. Vehicle Particulars & Condition

Make & Model	SUZUKI SWIFT	c.c	1586
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	JSAEZC31S00204374	Colour	WHITE
Odometer	135965	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/45 R17	LEAO	6 mm
L/H Front Tyre	205/45 R17	LEAO	6 mm
R/H Rear Tyre	205/45 R17	LEAO	6 mm
L/H Rear Tyre	205/45 R17	LEAO	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	27/12/2018	Inspection Date	02/01/2019
Survey held at	8 KAKI BKT AVE 4 #06-21		
Repairer	JCN AUTOLUTION PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJR 5421Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR TAILGATE	NOT NECESSARY	628.15	-
1	REAR BUMPER	DISTORTED	549.65	549.65
2	REAR BUMPER CORNER RETAINER L/R @\$20.05	N/S DAMAGED	40.10	20.05
1	REAR BUMPER IMPACT BRACKET LH	NOT NECESSARY	26.00	-
1	REAR BUMPER LOWER SPOILER	DEFORMED	479.25	479.25
2	REAR BUMPER SIDE RETAINER L/R @\$23.00	N/S DAMAGED	46.00	23.00
1	REAR CROSS MEMBER	BENT	889.90	889.90
1	REAR END PANEL	TO REPAIR SEE LABOUR	274.85	-
1	REAR END PANEL AIR VENT LH	NOT NECESSARY	35.95	-
2	REAR EXHAUST SYSTEM RUBBER MOUNTING @\$20.00	NOT NECESSARY	40.00	-
1	REAR FENDER INNER SHIELD	TORN	92.65	92.65
3	REAR FENDER INNER SHIELD CLIPS @\$3.00	NECESSARY	9.00	9.00
1	REAR FENDER INNER TRIMBOARD	NOT NECESSARY	69.55	-
1	REAR FENDER LH	DISTORTED	350.70	350.70
1	REAR KNUCKLE BEARING LH	DAMAGED	376.90	376.90
1	REAR KNUCKLE HUB LH	DAMAGED	302.50	302.50
1	REAR SHOCK ABSORBER LH	BENT	303.50	303.50
2	REAR TAILGATE DAMPER L/R @\$120.40	NOT NECESSARY	240.80	-
1	REAR TAILGATE MECHANISM LOCK	NOT NECESSARY	180.10	-
1	REAR TAILGATE RUBBER WEATHER STRIP	NOT NECESSARY	92.65	-
1	REAR TAILLAMP LH	CRACKED	287.90	287.90
1	REAR TAILLAMP LIGHT BULB LH	NOT NECESSARY	10.00	-
1	REAR TAILLAMP PANEL LH	NOT NECESSARY	73.38	-
2	REAR TAILLAMP STAY CLIPS @\$5.00	NOT NECESSARY	10.00	-
	LESS 15% DISCOUNT		-811.42	-552.75
			4,598.06	3,132.25
<u>SPECIAL NETT ITEMS</u>				
1	REAR BUMPER CARBON GARNISH (ACCESSORY) (SN)	CRACKED	600.00	480.00
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	30.00	30.00
1	REAR BUMPER REVERSE SENSOR (SN)	NOT NECESSARY	350.00	-

Report Ref No. CC4/EQI19000128/Aga3q2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR EXHAUST SYSTEM (SN)	NOT NECESSARY	1,500.00	-
1	REAR FENDER PETROL INLET COVER (SN)	NOT NECESSARY	280.00	-
1	REAR SPORTS RIM LH (SN)	CUT	500.00	400.00
1	REAR TAILGATE WINDSCREEN SEALANT (SN)	NOT NECESSARY	80.00	-
1	REAR TYRE LH (SN)	NOT NECESSARY	380.00	-
			3,720.00	910.00
	LABOUR			
	TO PROVIDE TOWING CHARGE.		50.00	50.00
	TO DIAGNOSE ,REPLACE AND /OR REPAIR TO RECTIFY REAR PORTION ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	NOT NECESSARY	100.00	-
	TO REMOVE ,REINSTALL ELECTRICAL WIRING HARNESS ,CHECK LIGHTING (FR).		60.00	30.00
	TO REFIX /RENEW REVERSE SENSOR ASSY AND RECTIFY FOR PROPER FUNCTIONING.		100.00	50.00
	TO REMOVE ,REINSTALL REAR TAILGATE WINDSCREEN ,(TO FR).	NOT NECESSARY	100.00	-
	TO REMOVE,CHARGE REAR SUSPENSION PARTS ,AXLE CARRIAGE ,ABSORBER ,LOWER ARM ,TOP ARM ,TRAILING ARM ,KNUCKLE ARM WHEEL BEARING ,BEARING HUB AND ETC.		450.00	300.00
	TO REMOVE,REINSTALL BRAKE PARTS ,BRAKE LINE ,BRAKE PUMP AND BLEEDING BRAKE SYSTEM.	NOT NECESSARY	200.00	-
	TO REMOVE ,REINSTALL PETROL TANK (TO FR).		80.00	80.00
	TO REMOVE,REINSTALL ROOF TOP TRIM UPHOLSTERY ,CUSHION SEAT ,TRIM GARNISH ,TRIM LINER CARPET (TO FR).		80.00	60.00
	TO RESPRAY PAINTING ON THE CHARGE BODYPARTS ,REPAIR PORTION AND WHERE CONSISTENT TO THE ACCIDENT.		1,000.00	600.00
	TO REMOVE AND CHARGE EXHAUST SILENCER BOX WITH PIPE ,RE-ALIGN WHERE NECESSARY CONSISTENT TO THE ACCIDENT.	NOT NECESSARY	100.00	-
	TO PROVIDE LABOUR ,WORKMANSHIP TO CHARGE THE ABOVE DAMAGED BODYPARTS ,REPAIR ,RE-ALIGN BODY STRUCTURE ,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT .INCLUSIVE OF THE REPAIR OF REAR END PANEL .		1,500.00	700.00

Report Ref No. CC4/EQI19000128/Aga3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.		120.00	60.00
			3,940.00	1,930.00
GRAND TOTAL			12,258.06	5,972.25
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,700.00

Report Ref No. CC4/EQI19000128/Aga3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.