

ASS. REC. BY:

REF

es/FCI19000153/ Kqd3

n2

Special Instruction:

Surveyor

CWS

Kenneth

ASSIGNMENT (Office)

From (Person):

Joanne Yong

of

FCI

Date/Time:

4:41pm @ 3/1/19

Estimated Cost:

Bill to:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHD G24J

Insured:

SHC 36074

at Workshop m/s

Trans-Cub

Tel:

G287 6666

of

No. 2 AMK St - 63

Policy No:

Claim No:

D19000103MFS4

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

28/12/2018

CA / REV / REP. / REV 24 HRS 'Ds'

04/01/2019

H.O.D. Endorsement:

Date/Time:

4:44pm @ 3/1/19

Person Contacted:

kek zhe wei

Vehicle

IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SHD G24J - CC4/AXA15016732/Ky3s2
	SHC 36074-X:
09/1/19 @ 4:22pm	revised to Joanne Yong by email.

REF: FCI

ASSIGNMENT

From:

Date:

04/01/2019

Veh No:

S1TD 624J

Yt Regn:

07 17

Estimated Cost:

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD ☒ TP/WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No:

SHD 624J

Make:

Renault Latitude

C.C.

1995

at Workshop m/s:

Trans-Cab

Colour:

h. white/red

A/C:

Insured / Std / NI / NA

of

No. 2 Amk st-63

Sp. Reading

145917

T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

Policy No:

C/No:

VI-1ABL-15/AUC 283464

Claims No:

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: ☒ In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: ☒ In order / Jammed / Leaked / Burnt or

Make of Veh:

Modi: ☒ Nil / S/Rim / STD A/Rim or

(Policy Condition)


Tyre Size:

F:

215/60R16

R:

Remark: The veh had commenced its repair at the time of inspection.



BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Giti

Bal. or Market Value:

Front

Rear

IDAC Accident Rpt:

Consistent? : Yes or No

R/Bal.

9

mm

R/Bal.

9

mm

GIA / PR Seen:

Consistent? : Yes or No

L/Bal.

9

mm

L/Bal.

9

mm

Est. Repairs:

2 1/2 days

Res: Yes or No

D.O.A.

28/12/18

D.O.I.

4/1/19

Lum Sum:

1.8-1 %

3 Val: Yes or No

Survey held at

✓

CA / REV / REP. / 24 HRS (Ds)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S body

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

7/1 16h 10m to Car

3650.19 3710.19 (Red 12207.53, 77%)

RECEIVED 10 JAN 2019

Date/Time, File Pass to?

☐

Preli. Report

Days Of Repair:

2 1/2

11/01/19 10:00 AM

☐

Final Report

Resurvey No. of Trip:

Survey Fee:

Transportation

Date/Time, File Return to?

2)

Add Fee:

☐

Site Insp (\$)

) S + RS \$1

☐

Interview (\$)

) Photos

☐

Tech. Invs (\$)

) Others

☐

Weekend (\$)

) "

Report Format:

71

Lump Sum / I.B.I. (\$)

3710.19

TOTAL

350



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19000103MFSH

Date: 09 January 2019

Our Ref: CS/FCI19000153/Kqd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHD 624J

Please be informed that we had conducted the inspection of the abovementioned vehicle on 04/01/2019 at the premises of M/s TRANS-CAB, and have the following to report:-

Workshop Estimate Amount	: S\$ 15,912.72 .
Revised Estimate Amount	: S\$ 3,710.19 .
"Check" Items Amount	: S\$ - .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:

The vehicle sustained damages at the o/s body.



Yours faithfully

KONG SENG CHEONG
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	31-12-2018	Our Ref No. D19000103MFSH
Accident Date	28-12-2018	Claim Type. Third Party
Insured Vehicle	SHC3607U	Third Party Vehicle. SHD624J
Survey Location	NO. 2 ANG MO KIO STREET 63	
Contact Person.	KEK ZHEWEI	
Contact No.	62876666/ 0	Fax No. 62571330
Survey Type	DIRECT SETTLEMENT: QUANTUM TO BE AGREED (EST. COR - \$15,912.72)	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TRANS-CAB AUTO SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 9 January 2019 4:22 PM
To: 'CWS Motor Claims'; assignments
Cc: 'Joanne Yong Lai fong'; SUR
Subject: RE: SURVEY ASSESSMENT - D19000103MFSH/1
Attachments: CSFCI19000153Kqd3.pdf

Dear Joanne,

Enclosed herewith preliminary advice of SHD 624J.

Best Regards,

Shiau Chan (Ms) | Case Handler
LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Thursday, 3 January 2019 4:50 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Joanne Yong Lai fong' <Joanneyong@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19000103MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed repairer agreed survey on 04/01/2019.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 3 January 2019 4:41 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Joanne Yong Lai fong <Joanneyong@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19000103MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

12/28/2018

PARF/COE Rebate Enquiry

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	3878K

Vehicle Details

Vehicle No.:	SHD624J
Vehicle to be Exported:	Yes
Intended Deregistration Date:	28 Dec 2018
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2016
Engine No.:	M9R8839C003173
Chassis No.:	VF1ABL15AUC283464
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	17 Jul 2017
First Registration Date:	17 Jul 2017
Transfer Count:	0
Actual ARF Paid:	\$19,998.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	16 Jul 2025
PARF Rebate Amount:	\$14,998.00

Intended COE Rebate Details

COE Expiry Date:	16 Jul 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$38,560.00
COE Rebate Amount:	\$30,848.00
Total Rebate Amount:	\$45,846.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 28 Dec 2018

OK

Trans-cab Auto Services Pte Ltd

AAD1812-229

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 624J

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHD 624J

VF1ABL15AUC283464

RENAULT

LATITUDE

28.12.2018

FCIL

17/7/2017

PART**LIST**

1	DOOR PANEL FRT RH	\$	<i>R</i> 2,844.66 <i>X</i>
1	DOOR HINGE UPPER RH	\$	<i>R</i> 261.28 <i>X</i>
1	DOOR HINGE LOWER RH	\$	<i>R</i> 300.55 <i>X</i>
1	DOOR PANEL REAR RH	\$	<i>By/wap</i> 2,844.66 <i>✓</i>
1	DOOR MIRROR ASSY RH	\$	<i>R</i> 1,483.40 <i>X</i>

\$ 7,734.5410% **\$ 773.45****\$ 6,961.09****Special Nett**

1	FRONT DOOR ADVERTISEMENT STICKER	\$	<i>R</i> 300.00 <i>150/12</i>
1	REAR DOOR ADVERTISEMENT STICKER	\$	<i>R</i> 300.00 <i>150/12</i>
1	DOOR CHECK BOLT	\$	<i>R</i> 22.69
1	DOOR GUIDE SCREW	\$	<i>R</i> 10.85
1	DOOR HINGE BOLT	\$	<i>R</i> 10.85
1	DOOR HINGE NUT RH	\$	<i>R</i> 14.60
1	DOOR CHECK BOLT	\$	<i>R</i> 22.69
1	DOOR CHECK NUT	\$	<i>R</i> 3.75
1	DOOR LOCK SCREW L70Y	\$	<i>R</i> 6.12
1	DOOR CATCH SCREW L70Y	\$	<i>R</i> 10.06

TOTAL \$ 701.63**TOTAL PARTS \$ 7,662.72**

Trans-cab Auto Services Pte Ltd

AAD1812-229

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 624J

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	3,000.00	300/
Putty and spray painting of the affected portion.	\$	3,000.00	440/
To rust-proofing of the affected areas.	\$	170.00	30/
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00	X
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	20/
To transfer of front fender fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To transfer of front door fittings, attachment and perform water seepage test.	\$	380.00	60/
To transfer of Rear door fittings, attachment and perform water seepage test.	\$	nn 380.00	X

TOTAL \$ 8,250.00**Over All Total \$ 15,912.72**

LKK Auto Consultants hence notify
PART-BY-PART (REPAIR DAY)
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

10-DAYS

2 1/2 days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19000153/Kqd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 11-01-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 3607U	Veh. Inspected	SHD 624J	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19000103MFSH	Excess (\$)	0.00	
Assign From	JOANNE YONG	Assign Date	03/01/2019	
2. Vehicle Particulars & Condition				
Make & Model	RENAULT LATITUDE (A)	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	VF1ABL15AUC283464	Colour	METALLIC WHITE / RED	
Odometer	145917	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	GITI	9 mm	
L/H Front Tyre	215/60 R16	GITI	9 mm	
R/H Rear Tyre	215/60 R16	GITI	9 mm	
L/H Rear Tyre	215/60 R16	GITI	9 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	28/12/2018	Inspection Date	04/01/2019	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2.500 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 624J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	DOOR PANEL FRT RH	TO REPAIR SEE LABOUR	2,844.66	-
1	DOOR HINGE UPPER RH	TO REPAIR SEE LABOUR	261.28	-
1	DOOR HINGE LOWER RH	TO REPAIR SEE LABOUR	300.55	-
1	DOOR PANEL REAR RH	BENT / WARPED	2,844.66	2,844.66
1	DOOR MIRROR ASSY RH	SERVICEABLE	1,483.40	-
	LESS 10% DISCOUNT		-773.46	-284.47
			6,961.09	2,560.19
SPECIAL NETT ITEMS				
1	FRONT DOOR ADVERTISEMENT STICKER (SN)	NECESSARY	300.00	150.00
1	REAR DOOR ADVERTISEMENT STICKER (SN)	NECESSARY	300.00	150.00
1	DOOR CHECK BOLT (SN)	SERVICEABLE	22.69	-
1	DOOR GUIDE SCREW (SN)	SERVICEABLE	10.85	-
1	DOOR HINGE BOLT (SN)	SERVICEABLE	10.85	-
1	DOOR HINGE NUT RH (SN)	SERVICEABLE	14.60	-
1	DOOR CHECK BOLT (SN)	SERVICEABLE	22.69	-
1	DOOR CHECK NUT (SN)	SERVICEABLE	3.75	-
1	DOOR LOCK SCREW L70Y (SN)	SERVICEABLE	6.12	-
1	DOOR CATCH SCREW L70Y (SN)	SERVICEABLE	10.06	-
			701.61	300.00
LABOUR				
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF DOOR PANEL FRT RH,DOOR HINGE UPPER RH AND DOOR HINGE LOWER RH.		3,000.00	300.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		3,000.00	440.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	30.00
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,	NOT NECESSARY	380.00	-

Report Ref No. CS/FCI19000153/Kqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	TO TRANSFER OF FRONT FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF FRONT DOOR FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.		380.00	60.00
	TO TRANSFER OF REAR DOOR FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
			8,250.00	850.00
GRAND TOTAL			15,912.70	3,710.19
RECOMMENDED COST OF REPAIRS				3,710.19

Report Ref No. CS/FCI19000153/Kqd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.