

BMW Dealer

Performance Motors LimitedA member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)# Car In
on 16/01TP repaired.
Pending India's
approval.

GST REG. NO : M2 - 0020081 - X

04 JAN 2019

E S T I M A T E

Estimate No.	: b1 49631	Page No. : 1 of 4
Date Estimated	: 04/01/2019	
Prepared By	: Inthiran A/L Thurasamy	

- ESTIMATE REPAIR FOR - Mohamed Yazid Bin Abdullah 32A Jalan Ismail Singapore 419287	- ACCOUNT - 40000 Cash Sales - Service Singapore
---	---

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKX1247S	P836751	27/11/2015	216d G TOURER	0

DESCRIPTION	VALUE
To replace rear bumper, attachments and repair rear right fender.	1700 2,550.00
Painting rear bumper and rear right fender.	1730 1,923.00
To check electrical wiring systems and lightings at the rear section for proper function.	150 177.00
Sundries.	? 80.00
Total Labour 1: 4,730.00	

DESCRIPTION	QTY	PRIC	VALUE
RR BUMPER RH SIDE GUIDE	1	61.50	? 61.50
REAR BUMPER PANEL PRIMED (LINES PDC	1	1,029.50	Rx 1,029.50
SET MOUNTS PDC SENSOR REAR	1	62.95	? 62.95
REAR LH LIGHT IN THE SIDE PANEL	1	365.20	cm 365.20
Total Parts :			1,519.15

Claims OD / 3rd Party / Uninsured losses / Direct Settlement		LKK Auto Consultants hence notify the Repairer of the following:	
Regn No. 1611901340	Claim No.	• To resurvey before/after spray painting	
Date&Time 16/1/2019	Excess S\$	• To display damaged part(s) during resurvey	
Surveyor's Name Taufiq	Sign	• Parts prices are subject to confirmation	4,730.00
Surveyor's Tel 9349519	Authorised Yes / No	• Third party survey is on a "Without Prejudice" basis	1,519.15
Authorised Date WP	Time	• No illegal modification(s) is allowed	0.00
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No	PML Yes / No	• Supplier's price(s) must be resurveyed and is subject to final approval from Insurance Company	0.00
Surveyor's E-mail tafiq@lkkauto.com		Excess	0.00
No. of Working Days Recommend 3-4 days		Total GST @ 7%	437.44
		Acknowledged by Repairer	
		Signature:	
		Date:	
		Grand Total	6,686.59

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **