

Joy

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

Estimate : ES000142

INDIA INTERNATIONAL INSURANCE PTE LTD
 64 CECIL ST #04-05 IOB BUILDING
 049711

Attention : Motor Claim Department
 Contact : 6223 8122

Date : 03/01/2019
 Vehicle Num. : SLQ 7632Z (LCR)
 Make/Model : TOYOTA PRIUS HYBRID
 Chassis/Eng# : JTDKB3FU0V12017
 Accident Date : 03/01/2019
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	REAR BOOTLID OUTER GARNISH X		570.00 X
2.	1	REAR BOOT HYBRID EMBLEM (PRIUS) X		89.00 X
3.	1	REAR BOOT PRIUS EMBLEM X		89.00 X
4.	1	REAR BOOT WEATHER STRIP X		280.00 X
5.	2	REAR TAIL LAMP X <i>old damage</i>	900.00	1,800.00 X
6.	1	REAR BUMPER <i>bt</i>		900.00 458-
7.	1	REAR END PANEL <i>repair</i>		750.00 X
8.	1	REAR END PANEL TOP GARNISH <i>cut ? X</i>		170.00 X
9.	1	REAR BUMPER TOW COVER <i>cut ? X</i>		89.00 82-
10.	1	REAR BUMPER REINFORCEMENT <i>bt</i>		350.00 318-
11.	2	REAR BUMPER TAIL LAMP X <i>old damage</i>	750.00	1,500.00
12.	2	REAR BUMPER RETAINER X	110.00	220.00
List Total S\$:				6,807.00
25.00% Discount S\$:				1,701.75
				<hr/>
				5,105.25
SPECIAL NETT ITEMS :				
1.	1	REAR BOOTLID OUTER GARNISH CLIPS X	40.00	40.00 X
2.	2	REAR TAILLAMP CLIPS X		80.00 X
3.	1	REAR BUMPER CLIP <i>na</i>		40.00 30-
4.	1	REAR END PANEL TOP GARNISH CLIPS <i>na</i>		40.00 20-
5.	1	REVERSE SENSOR ? X		280.00 200? X
Special Nett Total S\$:				480.00
LABOUR :				
TO APPLY RUSTPROOFING/TUFFCOATING TREATMENT				180.00

858
 258
643.50
 50

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

INDIA INTERNATIONAL INSURANCE PTE LTD
 64 CECIL ST #04-05 IOB BUILDING
 049711

Attention : Motor Claim Department
 Contact : 6223 8122

Estimate : ES000142

Date : 03/01/2019
 Vehicle Num. : SLQ 7632Z (LCR)
 Make/Model : TOYOTA PRIUS HYBRID
 Chassis/Eng# :
 Accident Date : 03/01/2019
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

TO REPLACE PARTS

LABOUR TO REMOVE ACCIDENT DAMAGED PARTS IN ORDER REPAIRS INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN PANEL WHERE NECESSARY & REPLACE ABOVE PARTS

~~1,200.00~~ 350

TO PUTTY & SPRAY PAINTING ON REAR AFFECTED AREAS

~~1,000.00~~ 400

TO CHECK REAR WIRES, CONNECTORS, REPLACE DAMAGED LAMPS REVERSE SENSORS AND START/STOP UNIT CAPACITORS

~~180.00~~ 60

DEACTIVATE HV BATTERY SYSTEM IN ORDER TO FACILITATE REPAIRS AND REACTIVATE BACK SAME (HV HYBRID SYSTEM SAFETY PROCEDURES)

450.00 X 810

PERFORM WHOLE VEHICLE DIAGNOSTICS INCLUDING CLEARING FAULT CODES AND REINITIALISING HV HYBRID SYSTEM FOR POST REPAIRS. (HV HYBRID SYSTEM SAFETY PROCEDURES)

450.00 X

Labour Total S\$:

3,460.00

643.50
 50.00
 810.00

 1503.50

E. & O.E.

Total S\$: 9,045.25

for WORLD AUTO PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Any illegal modification(s) is allowed
- Supplementary work(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Rasul
 H# 50010068
 3 days
 P/P
 04/01/19 @ 1110
 Resurvey by paint

3 days
 P/P