



51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

Your Ref: MCT18090602

Date: 07th January 2019

Our Ref: CS1/III19000308/Bqbs2

M/s India International Insurance Pte Ltd

64 Cecil Street

#05-02 IOB Building

Singapore 049711

(The Motor Claims Department)

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO:
FBC 8027G**

INSURED VEHICLE: SHC 8745X

ACCIDENT DATE: 21/09/2018

We thank you for your instruction on 07/01/2019.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of FBC 8027G from M/s Constant Appraiser Services.
- b) Final Repair Bill of FBC 8027G from M/s Moto 51 Pte Ltd.
- c) Singapore Accident Statement of Vehicles FBC 8027G and SHC 8745X.
- d) Colour damaged vehicle photographs of FBC 8027G.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: FBC 8027G
Make & Model	: Suzuki FU150SCD
Year of Registration	: 2008
Chassis Number	: BG41BTH200434
Engine Capacity	: 147 cc

2. We recommend that the repairs of the entire damage require about 4 (Four) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.