

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO :
REFERENCE : INS/IC/JHI/002/2019
DATE : 02-JAN-2019

FWD SINGAPORE PTE LTD
6 TEMASEK BOULEVARD, #18-01 SUNTEC TOWER 4

S(038986)
TEL : 68208888
FAX :

OWNER'S NAME : ONG ENG SENG
ADDRESS : 7 RIVERVALE LINK #03-33
SINGAPORE
S(545125)
TELEPHONE NO : 97450850

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : PNPV2018-00011196
VEHICLE NO : SKV9707P
MODEL CODE : SJGCKK8
MODEL/YEAR : FORESTER 2.0XT AWD CVT
ENGINE NO : FA20K944764
CHASSIS NO : JF1SJGK85FG057197
MILEAGE : 1 KM
DATE IN : 02/01/2019
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : DENNIS LEONG JIA HUI
ACCIDENT DATE : 02/01/2019

Print Date : 02/01/2019
Print Time : 20:30:29

Tanpin 97495749
WP
3 days
31/1/19 @ 1240
Resurvey before paint.
sure lkkauto.com.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SKV9707P

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	REPLACE REAR BUMPER, BRACKET LHS AND UNDER SPOILER	1680.00	560.
2	ZZ/002	RESPRAY REAR BUMPER ASSY	460.00	440.
3	ZZ/003	REMOVE AND REFIX REVERSE SENSOR	80.00	✓
4	ZZ/004	TO INSTALL REAR UNDER SPOILER (STI)	150.00	✓
5	ZZ/005	SUNDRIES	100.00	?
TOTAL LABOUR CHARGES			2470.00	

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SKV9707P

		DAMAGED PARTS & PRICES				
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	S/LIST REMARKS
1	BUMPER FACE R	57704SG012	540.00	de ✓		
2	REAR BUMPER BRACKET - RHS	57707SG080	14.40	per ✓		
3	BRKT SD R LH	57707SG090	14.40	use ✓		
4	BEAM COMPL R EU (SUPP)	57711SG0219P	288.00	?		
5	CLIP 2 PCS	909140062	11.60	use ✓		
6	STI REAR UDR SPR SJG ONLY	SILVER ST96050SF060			750.00	?
SUB TOTAL			868.40	0.00	750.00	0.00
LESS DISCOUNT (NETT-20 %)			173.68	0.00	0.00	0.00
GRAND TOTAL			694.72	0.00	750.00	0.00
OVERALL TOTAL			1444.72			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SKV9707P

TOTAL LABOUR CHARGES	2470.00
TOTAL SPARE PARTS CHARGES	1444.72

GRAND TOTAL	3914.72 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.