

SME Motor Pte Ltd
1 Kaki Bukit Ave 6, BLK D,
#02-15
417883

Claim Reference:
Assessment number: 19/AXA/TP-005(01)
Version: 1712
Date calculated: 01/05/2019 10:30 AM

Full Report
Registration: SLZ6298P
Printed: 01/05/2019 10:30 AM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	AXA Insurance Pte Ltd
Printed by:	Gary Seah	Currency:	SGD
Claim Reference:		Date of Incident:	2019-01-04
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	KIA
Model:	CERATO/FORTE/K3
Sub Model:	BASE MODEL
Model Sheet Number:	28 98 01
Registration:	SLZ6298P
VIN number:	
Odometer:	
Model Specs	
TWO COAT METALLIC	PREPARE OFF VEHICLE

*not attached
 note
 Whatsapp Atlas rep.
 4/3/19
 2 day.*

Labour

Code	Description	Time Base 10 WU/h	Price = 45.00 SGD/h	
			WU	Price SGD
86512R00	RENEW FRONT BUMPER INCLUDES: R + R NECESSARY ATTACHED PARTS, RENEW IF NECESSARY		9.0	40.50
92000R00	R + R RIGHT HEADLAMP		2.0	9.00
18600A00	ADJUST HEADLAMPS		3.0	13.50
Labour Cost			Hrs	WU
Panel / Mechanical Labour			1.40	14.0
Total of Labour				63.00

Paint

Code	Description - TWO COAT METALLIC	SYSTEM AZT	Time Basis 10WU/h	WU	Price SGD

Audatex System Using Manufacturer Times

Page 1 of 3

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Any supplementary item(s) must be resurveyed
 is subject to final approval from Insurance Company

PRINT DATE 01/05/2019

Acknowledged by Repairer
 Signature:
 Date:

SME Motor Pte Ltd
1 Kaki Bukit Ave 6, BLK D,
#02-15
417883

Claim Reference:
 Assessment number: 19/AXA/TP-005(01)
 Version: 1712
 Date calculated: 01/05/2019 10:30 AM

Full Report
 Registration: SLZ6298P
 Printed: 01/05/2019 10:30 AM

Paint Work SYSTEM AZT Time Basis 10WU/h
Code **Description - TWO COAT METALLIC** **WU Price SGD**

Paint Material Per Part

Code	Description	Price SGD
0283	FRONT BUMPER NEW PART PAINT K1R	55.10

Labour Cost - Paint	Hrs	WU	Price SGD
Factor			45.00 SGD/h
Time Paint		12.0	
Preparation Comp. Work Plastic	1.50	15.0	67.50
Total	10 WU/h	2.70	121.50

Material Cost - Paint	Price SGD
New Part Painting - Plastic K1R	55.10
Material-constant Plastic	28.60
Total	83.70

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01	Price SGD
0283	FRONT BUMPER	86511A7000		<i>n</i>	280.00 X
0320	R/F UPP BUMPER BRKT	86518A7000		<i>n</i>	8.00 X
0562	RIGHT HEADLAMP ASSY	92102A7120		<i>SCR</i>	330.00
1000	FRT BUMPER CLAMP KIT	CLIPS		<i>scr</i>	20.00
f: OEM Parts	Savings				0.00
n: Non-OEM Parts	Subtotal				638.00
u: Used parts	Addition(+15.00%)				95.70
	Total				733.70

SME Motor Pte Ltd
1 Kaki Bukit Ave 6, BLK D,
#02-15
417883

Claim Reference:
 Assessment number: 19/AXA/TP-005(01)
 Version: 1712
 Date calculated: 01/05/2019 10:30 AM

Full Report
 Registration: SLZ6298P
 Printed: 01/05/2019 10:30 AM

Final Calculation

	SGD	SGD
Parts		
Addition(+15.00%)	638.00	
Total Parts	95.70	733.70
Labour Time Base 10 WU/h		
Total 14.0 WU X 45.00 SGD/h	63.00	
Total of Labour		63.00
Paint Work Time Base 10 WU/h		
Labour Cost 27.0 WU X 45.00 SGD/h	121.50	
Material Cost	83.70	
Total Paint Including Material		205.20
Repair Cost Excludes GST		1,001.90
GST (+7.0%)		70.13
Repair Cost Included GST		1,072.03

Comments

* - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

+ 2 days. rental @ \$80/day

\$160.

+ GIA search fee \$2.

\$1001.90 - Repair

+ \$160 - rental 2 days.

\$1161.90 (before GST).

\$1243.23 +7%

+ \$2 GIA search fee

\$1245.23

\$1234.03