

INS. CASE OWNER

MANS.

CC 3, LOR 1900

0423, K#13

LKK:

IDAC:

Surveyor:

KSL

DOI:

21/1/19

Date / Time:

21/1/19

Registered in Marimen:

8/1/19

Pre-assign / CCU / FTE

SLL 9519 G



Insured Vehicle No.:

LPP PLU

Name of Insured:

Insured Tel No.:

HP:

Excess Sec II :S\$

D.O.A:

2-1-19

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

SHD 206H



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

COT
CHSHD 206H - COT/ACC 11017848/Kyng 2, van 21/1/19
SLL 9519 G - X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

LIS S\$ 900

(1 1/2 days) Reduction: 96 %

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with: hywa, yin

Email ☒ Call ☐

Final Liability:

S\$ 963

(Agreed / Assessed) BOLA S/N No.: 27

If NO or B 28, Ass. Lia:

Repair Cost:

COT/ACC S\$ 963

Loss of Rental (LOR):

S\$ 101.46 (1 days) X \$101.46

Loss of Use (LOU):

S\$ - (S - x - days)

Loss of Income (LOI):

S\$ 50 (S 50 x 1 days)

LOR only ☐ LOU only ☐LOR + LOU ☐ LOR + LOI ☒ [Tick only one]

GIA/LTA Search

S\$ 7.49

Medical:

S\$ -

Disbursement:

S\$ -

(e.g. Tow/ Independent)

Legal Cost

S\$ -

1) Claim status: No claim/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

S\$ 1,121.95

Global Sum S\$: 1,121.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

S\$ 1,121.00

Name 1:

TRANS-CAB SERVICES PTE LTD

Payee 2: (Strike if N.A.)

S\$ -

Name 2:

Payee 3: (Strike if N.A.)

S\$ -

Name 3:

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 206H**AAD1901-028***Not Noted*
11 Sep 8900h

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHD 206H

VF1ABL15AUC282394

RENAULT

LATITUDE

3.1.2019

AIG

2/10/2015

PART**LIST**

- | | |
|----|------------------------------------|
| 1 | 1 BUMPER COVER REAR |
| 2 | 1 BUMPER LOWER REAR |
| 3 | 1 BUMPER BRACKET CTR REAR |
| 4 | 1 BUMEP R BRACKET SIDE RH REAR |
| 5 | 1 BUMEP R RETAINER RH REAR |
| 6 | 1 BUMPER REFLECTOR RH |
| 7 | 1 BUMEP R BRACKET SIDE LH REAR |
| 8 | 1 BUMPER RETAINER LH REAR |
| 9 | 1 BUMPER REFLECTOR LH |
| 10 | 1 BUMPER BEAM REAR |
| 11 | 1 BUMPER BEAM BRACKET LH REAR |
| 12 | 1 BUMPER BEAM BRACKET RH REAR |
| 13 | 1 OUTER PANEL REAR (End Panel) |
| 14 | 1 OUTER PANEL REAR (End Panel)TRIM |
| 15 | 1 TAILLAMP LH |
| 16 | 1 TAILLAMP PANEL LH |
| 17 | 1 BOOT REAR |

\$	<i>fl</i>	1,108.46	<i>X</i>
\$	<i>nd/h</i>	768.84	<i>✓</i>
\$	<i>fl</i>	113.47	<i>X</i>
\$	<i>fl</i>	135.97	
\$	<i>fl</i>	44.99	
\$	<i>fl</i>	43.61	
\$	<i>fl</i>	135.97	
\$	<i>fl</i>	44.99	
\$	<i>fl</i>	43.61	
\$	<i>fl</i>	777.52	
\$	<i>fl</i>	225.95	
\$	<i>fl</i>	225.95	
\$	<i>fl</i>	1,471.77	
\$	<i>fl</i>	404.56	
\$	<i>fl</i>	552.55	
\$	<i>fl</i>	986.70	
\$	<i>fl</i>	2,872.68	

\$ 9,957.60**10% \$ 995.76****\$ 8,961.84****Special Nett**

- | | | | | | |
|---|------------------------------|----|-----------|--------|----------|
| 1 | 1SET PARKING AID | \$ | <i>fl</i> | 700.00 | <i>X</i> |
| 2 | 1SET REAR BUMPER CLIP | \$ | <i>nn</i> | 66.00 | <i>X</i> |
| 3 | 1SET BUMPER BRACKET CTR CLIP | \$ | <i>nn</i> | 33.00 | <i>X</i> |

Trans-cab Auto Services Pte Ltd**AAD1901-028**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 206H

4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	<i>na</i>	10.00	X
5	1SET BUMPER RETAINER RH CLIP RR	\$	<i>na</i>	20.00	X
6	1SET BUMPER BRACKET SIDE CLIP LH RR	\$	<i>na</i>	10.00	X
7	1SET BUMPER RETAINER CLIP LH RR	\$	<i>na</i>	20.00	X
8	1SET BUMPER LOWER REAR RIVET	\$	<i>na</i>	22.00	X
9	1SET BUMPER LOWER REAR CLIP	\$	<i>na</i>	66.00	✓
10	1 EXHAUST MOUNTING REAR	\$	<i>Sm</i>	17.82	X
11	2 REAR WINDSCREEN SELANT	\$	<i>na</i>	80.00	X
12	1 WINDSCREEN MOULDING	\$	<i>na</i>	100.00	X
13	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>na</i>	100.00	X

TOTAL \$ 1,244.82**TOTAL PARTS \$ 10,206.66****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	<i>220l</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	<i>150l</i>
To Rust-Proofing Of The Affected Areas.	\$	<i>na</i>	170.00 X
To reinstall rear bumper parking sensor.	\$	<i>L</i>	170.00 X
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	<i>L</i>	170.00 X
To repair and realign rear exhaust pipe.	\$	<i>L</i>	170.00 X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>L</i>	170.00 X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>L</i>	170.00 X

Trans-cab Auto Services Pte Ltd**AAD1901-028**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 206H

To transfer of rear windscreen fittings and conduct
water seepage test.

\$ *ru* 170.00 *X*

To check steering geometry and computer wheel
alignment

\$ *ru* 220.00 *X***TOTAL \$ 7,410.00****Over All Total \$ 26,578.50****(LUMP SUM)****Repair Days****10 DAYS***1 1/2 days*

LRK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Reinsurer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3878K
Vehicle Details	
Vehicle No.:	SHD206H
Vehicle to be Exported:	Yes
Intended Deregistration Date:	03 Jan 2019
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2015
Engine No.:	M9R8839C002962
Chassis No.:	VF1ABL15AUC282394
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	02 Oct 2015
First Registration Date:	02 Oct 2015
Transfer Count:	0
Actual ARF Paid:	\$19,998.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	01 Oct 2023
PARF Rebate Amount:	\$14,998.00
Intended COE Rebate Details	
COE Expiry Date:	01 Oct 2023
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$45,439.00
COE Rebate Amount:	\$26,947.00
Total Rebate Amount:	\$41,945.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	
The information contained herein is correct as at 03 Jan 2019	

OK

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Monday, 6 January 2020 4:09 PM
To: 'Ng Wai Yin'
Cc: Admin A; 'Jasmine Tan'; 'claims'
Subject: RE: OFFER - Accident between SHD 206H & SLL 9519G (AIG) on 03/01/2019 -- AAD1901-028
Attachments: AIG DV.pdf

Without Prejudice
(save as to costs)

Dear Sirs/Mdm,

We refer to the above matter.

Thank you for the acceptance.

We attach herewith a copy of the DV for your further action.

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Khanchna | Case Handler

LKK Auto Consultants Pte Ltd

DID: 6841 2360 | email: Khanchna@lkkauto.com | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ng Wai Yin <waiyin.ng@transcab.com.sg>

Sent: Monday, 6 January 2020 2:26 PM

To: Khanchna (LKK Auto) <khanchna@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>; 'Jasmine Tan' <jasminetan@transcab.com.sg>; 'claims' <claims@transcab.com.sg>

Subject: FW: OFFER - Accident between SHD 206H & SLL 9519G (AIG) on 03/01/2019 -- AAD1901-028

Without Prejudice

Dear Khanchna

Please proceed to send us the DV.

Thank You
Best Regards,
Ng Wai Yin
Finance Department
TEL: 6603 1265 Ext.308

***** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg**

TRANS-CAB SERVICES PTE LTD
No. 2 Ang Mo Kio Street 63
Singapore 569111
Tel: 6287 6666 Fax: 6287 7764

From: Jasmine Tan [<mailto:jasminetan@transcab.com.sg>]
Sent: Tuesday, 31 December, 2019 6:26 PM
To: 'Khanchna (LKK Auto)' <khanchna@lkkauto.com>; 'Ng Wai Yin' <waiyin.ng@transcab.com.sg>; 'claims' <claims@transcab.com.sg>
Cc: 'Admin A' <admin-a@lkkauto.com>
Subject: RE: OFFER - Accident between SHD 206H & SLL 9519G (AIG) on 03/01/2019

Without Prejudice

Dear Khanchna

Please proceed to send us the DV.

Thank you
Best Regards
Jasmine Tan



TRANS-CAB SERVICES PTE LTD
No. 2 Ang Mo Kio Street 63, Singapore 569111
Main Line : (65) 6287 6666 Fax Line: (65) 6257 1330
Direct Line : (65) 6603 1250
Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From: Khanchna (LKK Auto) [<mailto:khanchna@lkkauto.com>]
Sent: Tuesday, 19 November 2019 5:16 PM
To: Ng Wai Yin <waiyin.ng@transcab.com.sg>; 'claims' <claims@transcab.com.sg>
Cc: Admin A <admin-a@lkkauto.com>
Subject: OFFER - Accident between SHD 206H & SLL 9519G (AIG) on 03/01/2019

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Tuesday, 19 November 2019 5:16 PM
To: Ng Wai Yin; 'claims'
Cc: Admin A
Subject: OFFER - Accident between SHD 206H & SLL 9519G (AIG) on 03/01/2019

WITHOUT PREJUDICE

Dear Sirs/Mdm,

We refer to the above matter.

We propose settlement on a global sum of **\$1,121.00(all in)**.

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,
Khanchna | Case Handler
LKK Auto Consultants Pte Ltd
DID: **6841 2360** | email: Khanchna@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Jan 2019 Edit Reg		07 Jan 2019 00:00 Edit Adj Rpt	S\$900.00 Edit Estimates	S\$900.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	LCRF PTE LTD, Co. Reg. No.: NA								
Main Claimant:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K								
Vehicle Reg. No.:	SHD206H	Date of Loss:	03/01/2019 10:00 - :59 [39 Months and 1 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 0815781665SG	Policy/Cover Note No.:	(Comprehensive)						
Vehicle Reg. No. (Insured):	SLL9519G	Policy No. (Claimant):	VPX/P1680520						
		Excess:							
Repairer:	Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel: 62876666								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chew, Mavis] Chew.Mavis@aig.com								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6880 4888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 17/01/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (09/01/2019): Request To Upload TP GIA Report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SHD206H (0815781665SG)
[SLL9519G]
TP
TRANS-CAB SERVICES PTE LTD
Jan 3 2019 10:00AM
[LCRF PTE LTD]
Trans-cab Auto Services Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View View in Browser	
------------------	--	---------------	--	--------------------	--	--------------	--	--------------	--	---------------------------------------------------------	--

Letters/Correspondences										1 per page		<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print		
1	(Draft)	Third Party Express Settlement - Payment Breakdown						1	Edit			

Photos/Images										1 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print		
1	04/03/19 11:48	General View						1	Load JPG	<input checked="" type="checkbox"/>		
2	04/03/19 11:48	General View						1	Load JPG	<input checked="" type="checkbox"/>		
3	04/03/19 11:48	General View						1	Load JPG	<input checked="" type="checkbox"/>		
4	04/03/19 11:48	General View						1	Load JPG	<input checked="" type="checkbox"/>		
5	04/03/19 11:48	General View						1	Load JPG	<input checked="" type="checkbox"/>		
6	04/03/19 11:48	General View						1	Load JPG	<input checked="" type="checkbox"/>		
7	04/03/19 11:48	General View						1	Load JPG	<input checked="" type="checkbox"/>		
8	04/03/19 11:48	General View						1	Load JPG	<input checked="" type="checkbox"/>		

Documentation										1 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print		
1	10/01/19 13:13	TP ESTIMATE - MARKED						1	Load PDF			
2	10/01/19 13:13	TP GIA REPORT						1	Load PDF			
3	13/01/20 11:12	WORKSHOP INVOICE						1	Load PDF			
4	13/01/20 11:12	AUTHORISATION TO ACT FORM						1	Load PDF			
5	13/01/20 11:12	Release Voucher						1	Load PDF			
6	13/01/20 11:12	RENTAL RECEIPT						1	Load PDF			
7	13/01/20 11:12	RENTAL MILEAGE						1	Load PDF			
8	13/01/20 11:12	LTA SEARCH						1	Load PDF			
9	13/01/20 11:12	LOD						1	Load PDF			
10	13/01/20 11:12	LETTER TO OI						1	Load PDF			
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)							Thumbnail	Print		
1	09/01/19 14:19	OI GIA REPORT						1	Load PDF			

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
^ v	
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>	

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLL9519G (Insd veh)	Model:	RENAULT LATITUDE 2.0 L
	SHD206H (TP veh)		DCI AUTO D/AB 4DR (A)
Date of Accident:	03/01/2019		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Repair Estimate	:	\$	18,849.82
Final Repair Cost	:	\$	1,121.00
Loss of Use	:	\$	1.00 days at \$50.00 per day
Rental (if any)	:	\$	1 days
LTA / GIA Search Fee	:	\$	
Others:	:	\$	
	:	\$	
Final Settlement Sum (Global Sum)	:	\$	1,121.00

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 100 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Trans-cab Auto Services Pte Ltd	:	\$ 1,121.00
2)		:	\$
3)		:	\$
4)		:	\$

JOANNE LEE KHANG MIN

13 Jan
2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/LCR19000423/KKA3Q2

Date: 13/01/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant

Vehicle No : SHD206H

Insured Vehicle No : SLL9519G

Date of Loss: 03/01/2019

Nature of Claim: TP

Claim No: 0815781665SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHD206H

Make & Model: RENAULT LATITUDE, 2.0 L DCI AUTO D/AB 4DR (A)

Engine No: M9R8839C002962

Reg. Date: 02/10/2015 (Man. Year: 2015)

Chassis No: VF1ABL15AUC282394

Colour: Metallic White/Red

Odometer: 435210 km

Engine Capacity: 1995 cc

Market Value/New Car

N/A

Price:

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size:

215/60 R16

Front Left Side: Goodyear 8 mm

Rear Left Side:

Goodyear 8 mm

Front Right Side: Goodyear 8 mm

Rear Right Side:

Goodyear 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,206.65	757.96	9,448.69	92.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,410.00	370.00	7,040.00	95.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,616.65	1,127.96	16,488.69	93.60
Approved Total (Overridden) (S\$)		900.00		
(S\$)	17,616.65	900.00	16,716.65	94.89
+ GST 7.00/7.00% (S\$)	1,233.17	63.00	1,170.17	94.89
Nett Amount (S\$)	18,849.82	963.00	17,886.82	94.89
+ Loss of Use (1.0 x S\$50.00/day) (S\$)		50.00		
+ Car Rental (1.0 x S\$101.46/day) (S\$)		101.46		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		1,121.95		
Global Sum Settlement (S\$)		1,121.00		

INSPECTION

Date of Assignment: 07/01/2019

Date Inspected: 07/01/2019 Inspected At:

Trans-cab Auto Services Pte Ltd (Ang Mo Kio)

2, Ang Mo Kio Street 63
Singapore 569111

Estimated Period of Repair: 1.5 days

Adjuster: KENNETH KONG

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR	Repair	1,108.46 FL	*- FL
2	1		*BUMPER LOWER REAR	Dented / Cut	768.84 FL	*768.84 FL
3	1		*BUMPER BRACKET CTR REAR	Serviceable	113.47 FL	*- FL
4	1		*BUMPER BRACKET SIDE RH REAR	Serviceable	135.97 FL	*- FL
5	1		*BUMPER RETAINER RH REAR	Serviceable	44.99 FL	*- FL
6	1		*BUMPER REFLECTOR RH	Serviceable	43.61 FL	*- FL
7	1		*BUMPER BRACKET SIDE LH REAR	Serviceable	135.97 FL	*- FL
8	1		*BUMPER RETAINER LH REAR	Serviceable	44.99 FL	*- FL
9	1		*BUMPER REFLECTOR LH	Serviceable	43.61 FL	*- FL
10	1		*BUMPER BEAM REAR	Repair	777.52 FL	*- FL
11	1		*BUMPER BEAM BRACKET LH REAR	Repair	225.95 FL	*- FL
12	1		*BUMPER BEAM BRACKET RH REAR	Repair	225.95 FL	*- FL
13	1		*OUTER PANEL REAR (END PANEL)	Repair	1,471.77 FL	*- FL
14	1		*OUTER PANEL REAR (END PANEL)TRIM	Serviceable	404.56 FL	*- FL
15	1		*TAILLAMP LH	Serviceable	552.55 FL	*- FL
16	1		*TAILLAMP PANEL LH	Serviceable	986.70 FL	*- FL
17	1		*BOOT REAR	Repair	2,872.68 FL	*- FL
18	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
19	1		*SET REAR BUMPER CLIP	Not Necessary	66.00 FS	*- FS
20	1		*SET BUMPER BRACKET CTR CLIP	Not Necessary	33.00 FS	*- FS
21	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*- FS
22	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*- FS
23	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*- FS
24	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*- FS
25	1		*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	*- FS
26	1		*SET BUMPER LOWER REAR CLIP	Necessary	66.00 FS	*66.00 FS
27	1		*EXHAUST MOUNTING REAR	Serviceable	17.82 FS	*- FS
28	2		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
29	1		*WINDSCREEN MOULDING	Not Necessary	100.00 FS	*- FS
30	1		*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,202.41	834.84
- List Item Discount on L Items 10.00/10.00% (\$\$)	995.76	76.88
Total Parts (\$\$)	10,206.65	757.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	3,000.00	220.00
2	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	3,000.00	150.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	0.00
4	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	0.00
5	TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
6	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	0.00
7	TO DROP REAR EXHAUST BOX ,RENEW THE SAME ,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE	New	170.00	0.00
8	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
9	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	0.00
10	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
Gross Labour Cost (S\$)			7,410.00	370.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >