

T & T Auto Services Pte Ltd

160 Sin Ming Drive
#08-14 Sin Ming AutoCity
Singapore 575722
Tel: 6266 6876 Fax: 6266 6861

KEE HUI TIANG
BLK 220 SERANGOON AVE 4
#09-234
SINGAPORE 550220

Not Notarized
6/1 by B?
Resurvey After Paint
5 days

ESTIMATE

DATE : 07/01/2019
VEHICLE NO : SKG 634 D
MAKE/MODEL : Toyota Altis
ACC DATE : 29/12/2018

PARTICULAR AMOUNT S\$

LIST ITEMS:				
1	1	BOOTLID	<i>Bt</i>	758.00 ✓
2	1	BOOTLID TOP LOCK	<i>Det</i>	85.10 ✓
3	1	BOOTLID LOWER LOCK	<i>R</i>	43.40 X
4	1	BOOTLID WEATHERSTRIP	<i>Det/Dir</i>	78.50 <i>508m</i>
5	1	BOOTLID OUTER GARNISH	<i>CM</i>	256.00 ✓
6	1	BOOTLID LOGO	<i>Mr</i>	38.50 ✓
7	1	BOOTLID EMBLEM - 1.6	<i>Mr</i>	31.60 ✓
8	1	BOOTLID EMBLEM - E	<i>Mr</i>	30.50 ✓
9	1	BOOTLID EMBLEM - VVTI	<i>Mr</i>	36.50 ✓
10	1	BOOTLID EMBLEM - COROLLA	<i>Mr</i>	47.40 ✓
11	1	BOOTLID EMBLEM - ALTIS	<i>Mr</i>	45.20 ✓
12	2	BOOTLID REFLECTOR	<i>n/stc</i>	179.90 <i>ols ?</i>
13	1	REAR BUMPER	<i>Bur</i>	475.80 ✓
14	2	REAR BUMPER BRACKET		57.20 114.40 7
15	2	REAR BUMPER SIDE RETAINER		28.90 57.80 X
16	2	REAR TAIL LAMP	<i>ols</i>	285.80 571.60 <i>LT</i>
17	1	REAR END PANEL		438.90 ?
18	1	REAR END PANEL TOP GARNISH		112.60 7
19	1	REAR FLOOR PANEL TOP BOARD	<i>Sm</i>	148.70 X
				3,730.30
Less Discount:			25%	932.58
				2,797.73

SPECIAL NETT ITEMS:	
1	1 REAR NUMBER PLATE
2	10 REAR BUMPER CLIP
3	2 REAR TAIL LAMP CLIP
4	2 REAR END PANEL TOP GARNISH CLIP
5	1 REAR REVERSE SENSOR

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

<i>Det</i>	50.00	<i>458m</i>
<i>Mr</i>	50.00	✓
<i>Mr</i>	10.00	X
<i>Mr</i>	10.00	✓
<i>Shan</i>	350.00	<i>2008m</i>
		470.00

LABOUR CHARGES:	
1	TO CHECK WIRING
2	TO TUFF KOTE
5	TO REMOVE/REFIX UPHOLSTERY, CUSHION SEAT & ROOF LINING
6	TO REMOVE/REFIX REVERSE SENSOR
7	TO PANEL BEATING, REMOVING & REPLACING OF NEW PARTS
8	TO SPRAY PAINTING ON AFFECTED AREA

	50.00	<i>201</i>
	250.00	<i>601</i>
	150.00	<i>601</i>
	100.00	<i>501</i>
	1,300.00	<i>601</i>
	1,200.00	<i>6401</i>
		3,050.00

GRAND TOTAL 6,317.73