

MBM WHEELPOWER PTE LTD

Your Ref: SLH9249G

Our Ref: SME2876X

To: LONPAC

CC

Fax

Not Notarized
Running B&P again
2 days

Date: 9/1/2019
From: Stephanie
Fax: 64525333
Contact: 86865188
Make / Model: HONDA FIT
Chassis No.: GK31045371
Engine No.: L13B1054176
Year of Make: 2014
Accident Date: 6 January 2019



ESTIMATE FOR VEHICLE NO. : SME2876X

DESCRIPTION

REAR BUMPER
REAR BUMPER BRACKET RH
REAR BUMPER CLIPS
REAR BUMPER GARNISH RH
REAR FENDER RH
REAR FENDER INNERSHEILD RH
REAR FENDER INNERSHIELD CLIPS RH
TAILLAMP RH
REAR ABSORBER RH
REAR KNUCKLE RH
REAR BEARING RH
REAR LOWER RH

QTY		List Price
1	\$	<i>Br 120</i> 690.00 ✓
1	\$	<i>SL</i> 60.00 X
10	\$	<i>nn</i> 50.00 ✓
1	\$	<i>SL</i> 70.00 X
1	\$	<i>AK</i> 1,050.00 }
1	\$	<i>SL</i> 165.00 }
10	\$	<i>nn</i> 50.00 }
1	\$	<i>SL</i> 420.00 }
1	\$	<i>SL</i> 550.00 }
1	\$	<i>SL</i> 250.00 }
1	\$	<i>nn</i> 200.00 }
1	\$	<i>SL</i> 320.00 }
Total: \$		3,875.00
LESS 20% \$		(775.00)
Parts Total: \$		3,100.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental item(s) must be resurveyed and is subject to approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

SPECIAL NETT

QUARTER GLASS	1	\$	<i>nn</i>	80.00 X
REAR RH RIM (14 INCH)	1	\$	<i>R</i>	250.00 X
REAR RH TYRE (185/60 R14)	1	\$	<i>nn</i>	180.00 X

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS. INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS.	\$	<i>2000</i>	1,000.00
TO DISMANTLE AND REPLACE REAR RH UNDERCARRIAGE	\$	<i>nn</i>	350.00 X
TO REMOVE, RENEW & REFIT REAR RH TYRE	\$	<i>nn</i>	30.00 X
TO CONDUCT ALL WHEEL COMPUTERISED ALIGNMENT	\$	<i>600</i>	100.00
TO CHECK & RECONNECT ALL NECESSARY WIRING	\$	<i>nn</i>	120.00 X
TO REMOVE & REFIT BUMPER SENSORS	\$	<i>500</i>	80.00 X
TO REMOVE & INSTALL REAR FENDER QUARTER GLASS	\$	<i>nn</i>	100.00 X
TO APPLY ANTI RUST COATING	\$	<i>nn</i>	150.00 X
TO SPRAY PAINT ON THE AFFECTED AREAS	\$	<i>2200</i>	800.00
Total:	\$		6,340.00
7% GST:	\$		443.80
Grand Total:	\$		6,783.80