


MBM WHEELPOWER PTE LTD



Your Ref: SLH9249G

Our Ref: SME2876X

To: LONPAC

CC

Fax

Not Notation
Recovery By painting
2 days

Date: 9/1/2019
 From: Stephanie
 Fax: 64525333
 Contact: 86865188
 Make / Model: HONDA FIT
 Chassis No.: GK31045371
 Engine No.: L13B1054176
 Year of Make: 2014
 Accident Date: 6 January 2019

ESTIMATE FOR VEHICLE NO. : SME2876X

DESCRIPTION

REAR BUMPER
 REAR BUMPER BRACKET RH
 REAR BUMPER CLIPS
 REAR BUMPER GARNISH RH
 REAR FENDER RH
 REAR FENDER INNERSHEILD RH
 REAR FENDER INNERSHIELD CLIPS RH
 TAILLAMP RH
 REAR ABSORBER RH
 REAR KNUCKLE RH
 REAR BEARING RH
 REAR LOWER RH

QTY

1
1
10
1
1
10
1
1
1
1
1
1

\$
\$
\$
\$
\$
\$
\$
\$
\$
\$
\$
\$

List Price

Br 120 690.00 ✓
Sn 60.00 X
nn 50.00 ✓
Sn 70.00 X
R 1,050.00 }
Sn 165.00 }
nn 50.00 }
Sn 420.00 } X
Sn 550.00 }
Sn 250.00 }
nn 200.00 }
Sn 320.00 }

Total: \$ 3,875.00

LESS 20% \$ (775.00)

Parts Total: \$ 3,100.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

SPECIAL NETT

QUARTER GLASS	1	\$	<i>na</i>	80.00 X
REAR RH RIM (14 INCH)	1	\$	<i>R</i>	250.00 X
REAR RH TYRE (185/60 R14)	1	\$	<i>na</i>	180.00 X

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS. INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS.		\$	<i>2001</i>	1,000.00
TO DISMANTLE AND REPLACE REAR RH UNDERCARRIAGE		\$	<i>na</i>	350.00 X
TO REMOVE, RENEW & REFIT REAR RH TYRE		\$	<i>na</i>	30.00 X
TO CONDUCT ALL WHEEL COMPUTERISED ALIGNMENT		\$	<i>601</i>	100.00
TO CHECK & RECONNECT ALL NECESSARY WIRING		\$	<i>na</i>	120.00 X
TO REMOVE & REFIT BUMPER SENSORS		\$	<i>501</i>	80.00 X
TO REMOVE & INSTALL REAR FENDER QUARTER GLASS		\$	<i>na</i>	100.00 X
TO APPLY ANTI RUST COATING		\$	<i>na</i>	150.00 X
TO SPRAY PAINT ON THE AFFECTED AREAS		\$	<i>2201</i>	800.00
Total:		\$		6,340.00
7% GST:		\$		443.80
Grand Total:		\$		6,783.80