

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

8-Jan-19

ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHD 1175 Z

1 pc	Tailgate	\$	2,292.30	bt
1 pc	Tailgate lower garnish	\$	362.61	an
1 pc	Tailgate weatherstrip	\$	276.98	X
1 pc	Rear windscreen moulding	\$	64.10	ne
1 pc	End panel top garnish	\$	90.00	X
1 pc	Emblem I30	\$	27.80	an
1 pc	Emblem CRDI	\$	29.40	ne
1 pc	Emblem Hyundai	\$	29.40	ne
1 pc	Rear bumper	\$	811.11	dt
1 pc	Rear bumper sponge	\$	79.20	?
1 pc	Rear bumper reinforcement	\$	815.64	?
1 pc	Rear bumper reinforcement centre	\$	79.20	?
2 pcs	Rear bumper n/s & o/s side bracket @ \$52.20	\$	104.40	ne
2 pcs	Rear bumper n/s & o/s reflector @\$107.50	\$	215.00	X
		\$	5,277.14	
		Less 20%	\$	1,055.43
			\$	4,221.71

S/NETT

1 set	Rear bumper clips	\$	48.00	ne
1 set	Reverse sensor	\$	280.00	200 an
1 set	Tailgate stickers	\$	100.00	ne
1 set	Tailgate lower garnish clips	\$	38.00	ne
1 set	Sealant	\$	50.00	an

8-Jan-19

ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHD 1175 Z

Sundry	\$	50.00	20.
Towing Fee	\$	50.00	? towing receipt
To dismantle / refit rear windscreen glass onto new tailgate	\$	120.00	✓
To dismantle and refit the inner components of wiper onto new tailgate, test wiper motor and water etc	\$	120.00	40
To dismantle and replace reverse sensor and test system	\$	80.00	30
To labour charge for dismantle and renew the accident damaged parts. Including to knock-out, straighten, repair, reshape of the end panel, etc	\$	950.00	400
To putty and spray painting on the rear bumper, tailgate, tailgate lower garnish, end panel	\$	800.00	500
To apply rustproofing on the repaired and replaced panels	\$	120.00	30.
Total	\$	7,027.71	

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Tanjilun 9749549
'up'
8/1/19 @ 240 pm

part by part
Resurvey before paint.
4 days

sure@lkkauto.com
tanjilun@lkkauto.com