

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: AXA	DATE	: 07/01/2019
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SJV4258M		
MODEL	: KIA RIO 1.4L MT 2WD 4DR		
CHASSIS NO			
<u>ACCIDENT DETAILS</u>		DATE	: 05/01/2019
		TIME	: 16:00HRS
THIRD PARTY REQUESTOR / CONTACT		:	MS HONG / SHARON

*NOT Affect
Lear
1/5 3400/-
5 day
Whip...
8/1/19*

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	BOOTLID 614.90 22/321	1	\$ 755.30	\$ 755.30
2	BOOTLID LOGO nll	1	\$ 55.00	\$ 55.00
3	BOOTLID EMBLEM 'C&C' nll	1	\$ 55.00	\$ 55.00
4	BOOTLID EMBLEM 'RIO' nll	1	\$ 50.00	\$ 50.00
5	BOOTLID KEYLOCK 8uc	1	\$ 158.00	\$ 158.00
6	BOOTLID LOCK 109 1w1	1	\$ 155.30	\$ 155.30
7	BOOTLID HINGE 17	2	\$ 89.00	\$ 178.00
8	BOOTLID WEATHERSTRIPE 1w1	1	\$ 166.00	\$ 166.00
9	REAR BUMPER 428.50 22/2e	1	\$ 580.00	\$ 580.00
10	REAR BUMPER LOWER LID 131.80 3w1	1	\$ 255.60	\$ 255.60
11	REAR BUMPER SIDE RETAINER 17	2	\$ 67.00	\$ 134.00
12	REAR BUMPER REINFORCEMENT 321	1	\$ 288.90	\$ 288.90
13	REAR BUMPER SPONGE 70.1	1	\$ 155.20	\$ 155.20
14	TAIL LAMP 260.80 2/50e	2	\$ 360.00	\$ 720.00
15	TAIL LAMP PANEL R	2	\$ 180.00	\$ 360.00
16	REAR NUMBER PLATE LAMP (SET) 17	1	\$ 124.00	\$ 124.00
17	REAR END PANEL 415.00 22	1	\$ 555.60	\$ 555.60
18	REAR END PANEL TOP GARNISH 101 Cle	1	\$ 177.50	\$ 177.50

19	SPARE TYPE TOOLS SPONGE	1	\$ 149.00	\$ 149.00
----	-------------------------	---	-----------	-----------

TOTAL PRICE \$ 5,072.40

LESS 10% \$ 507.24

SUB TOTAL PRICE \$ 4,565.16

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE	1	\$ 50.00	\$ 50.00
2	REAR BUMPER CLIPS(SET)	1	\$ 30.00	\$ 30.00
3	TAILLAMP CLIP(SET)	1	\$ 20.00	\$ 20.00
4	TAIL LAMP PANEL SEALANT	2	\$ 60.00	\$ 120.00
5	REAR END PANEL INSULATION SEAL	1	\$ 100.00	\$ 100.00
6	REAR END PANEL TOP GARNISH CLIP(SET)	1	\$ 20.00	\$ 20.00
7	REVERSE SENSOR	1	\$ 220.00	\$ 220.00
8	REVERSE CAMERA	1	\$ 380.00	\$ 380.00

TOTAL \$ 940.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, WELDING GRAZING, CUT, JOIN, STRAIGHTEN ALL AFFECTED PARTS	\$ 1,400.00	600	
2	TO PUTTY, POLISH, SPRAY PAINT, WAX ALL AFFECTED PANELS	\$ 1,200.00	800	
3	TUFF COAT	\$ 120.00	50	
4	WIRING CHECK	\$ 150.00	20	
5	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 100.00	50	
6	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 150.00	X	
7	CONDUCT WATER LEAKAGE TEST	\$ 150.00	11 X	

TOTAL

\$3,270.00

1520

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be consigned and is subject to final approval from Insurance Company

ESTIMATE REPORT

TOTAL PARTS COST : \$

Acknowledged by Repairer

Signature: TOTAL LABOUR COST :

Date:

5,505.16

#REF!

2831.10

10%

2547.99

230.00

1520.00

4297.99

20%

2028

P-2831.10

50%

1415.55

S.W 230.00

1520.00

3165.55

TOTAL REPAIR COST : #REF!

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

FAX :

PART BY PART / LUMP SUM :

NO OF DAYS :