



ESTIMATE

Date	: 08/01/2019	Reg No	: SKK4177J
To	: AIG ASIA PACIFIC INSURANCE PTE. LTD.	Model	: TOYOTA PREVIA 7 SEATER CVT
Attn.	:	Chassis No	: JTEGD54M40A038821
Office / Mobile	:	Engine No	: 2AZJ003339
Email Address	:	Quotation No.	: 79587
		Ref. No.	:
From	: GOLDBELL ENGINEERING PTE LTD	D.O.A.	: 04/01/2019
Attn.	: MELODYTEOHML	Policy No.	:
Office / Mobile	: +65 6484 3683	Claim Type	: TP CLAIM
Email / Fax No.	: MelodyTeohML@goldbell.com.sg	Workshop	: KAKI BUKIT

S/N	Part No	Description	Qty	U/Price	%	Net Price	Ext Price
1		FRONT BUMPER	1	609.15	-25	456.86	456.86
2		FRONT BUMPER RETAINER LH	1	66.20	-25	49.65	49.65
3		FRONT BUMPER RETAINER RH	1	66.20	-25	49.65	49.65
4		FRONT BUMPER CLIPS	10	5.00	-25	3.75	37.50
5		FRONT BUMPER BRACKET LH	1	68.20	-25	51.15	51.15
6		FRONT BUMPER BRACKET RH	1	68.20	-25	51.15	51.15
7		FOG LIGHT ASSEMBLY RH	1	280.15	-25	210.11	210.11
8		FRONT GRILLE WITH CHROME MOULDING	1	454.10	-25	340.58	340.58
9		FRONT GRILLE LOGO	1	75.30	-25	56.47	56.47
10		HEADLAMP WASHER MOTOR RH	1	455.90	-25	341.92	341.92
11		HEADLAMP WASHER COVER RH	1	45.30	-25	33.97	33.97
12		HEADLAMP ASSEMBLY RH	1	1,045.95	-25	784.46	784.46
13		FRONT SUPPORT PANEL	1	819.40	-25	614.55	614.55
14		FRONT SUPPORT TOP GARNISH CLIPS	10	5.00	-25	3.75	37.50
15		FRONT FENDER RH	1	706.10	-25	529.58	529.58
16		FRONT FENDER EMBLEM (VVT-I) RH	1	45.30	-25	33.97	33.97
17		FRONT FENDER INNER SHIELD RH	1	165.90	-25	124.43	124.43
18		FRONT FENDER INNER SHIELD CLIPS RH	10	5.00	-25	3.75	37.50
19		FRONT A-PILLAR RH	1	499.15	-25	374.36	374.36
20		FRONT A-PILLAR INNER GARNISH RH	1	65.10	-25	48.82	48.82
21		FRONT FENDER OUTER ROCKER GARNISH RH	1	145.10	-25	108.82	108.82
22		WINDMIRROR ASSEMBLY RH	1	987.15	-25	740.36	740.36
23		WINDMIRROR COVER RH	1	74.10	-25	55.57	55.57
24		FRONT DOOR RH	1	1,049.10	-25	786.82	786.82
25		FRONT DOOR TOP HINGE RH	1	74.10	-25	55.57	55.57
26		FRONT DOOR BOTTOM HINGE RH	1	74.20	-25	55.65	55.65
27		FRONT DOOR LOCK RH	1	509.10	-25	381.83	381.83
28		FRONT DOOR CHECKER RH	1	120.10	-25	90.07	90.07
29		FRONT DOOR LOWER OUTER ROCKER GARNISH RH	1	99.10	-25	74.32	74.32
30		ROCKER PANEL RH	1	549.10	-25	411.83	411.83
31		FRONT DOOR OUTER MOULDING RH	1	161.20	-25	120.90	120.90
32		FRONT DOOR WEATHERSTRIP RH	1	169.15	-25	126.86	126.86



ESTIMATE

Date	: 08/01/2019	Reg No	: SKK4177J
To	: AIG ASIA PACIFIC INSURANCE PTE. LTD.	Model	: TOYOTA PREVIA 7 SEATER CVT
Attn.	:	Chassis No	: JTEGD54M40A038821
Office / Mobile	:	Engine No	: 2AZJ003339
Email Address	:	Quotation No.	: 79587
		Ref. No.	:
From	: GOLDBELL ENGINEERING PTE LTD	D.O.A.	: 04/01/2019
Attn.	: MELODYTEOHML	Policy No.	:
Office / Mobile	: +65 6484 3683	Claim Type	: TP CLAIM
Email / Fax No.	: MelodyTeohML@goldbell.com.sg	Workshop	: KAKI BUKIT

S/N	Part No	Description	Qty	U/Price	%	Net Price	Ext Price
33		FRONT DOOR FRAME STICKER RH	2	76.10	-25	57.07	114.15
34		REAR DOOR RH	1	1,410.35	-25	1,057.76	1,057.76
35		REAR DOOR FRAME STICKER RH	2	76.10	-25	57.07	114.15
36		REAR DOOR FRONT OUTER WEATHERSTRIP RH	1	269.15	-25	201.86	201.86
37		REAR DOOR LOWER OUTER ROCKER GARNISH RH	1	110.25	-25	82.69	82.69
38		REAR FENDER OUTER ROCKER GARNISH RH	1	124.10	-25	93.07	93.07
39		REAR FENDER INNER SHIELD RH	1	165.10	-25	123.82	123.82
40		REAR FENDER INNER SHIELD CLIPS	3	5.00	-25	3.75	11.25
41		REAR BUMPER	1	617.15	-25	462.86	462.86
42		REAR BUMPER RETAINER LH	1	110.35	-25	82.76	82.76
43		REAR BUMPER RETAINER RH	1	65.10	-25	48.82	48.82
44		REAR BUMPER CLIPS	10	5.00	-25	3.75	37.50
45		REAR BUMPER REFLECTOR LH	1	66.20	-25	49.65	49.65
46		REAR BUMPER REFLECTOR RH	1	66.20	-25	49.65	49.65
47		FRONT FENDER INNER SHIELD LH	1	124.95	-25	93.71	93.71
48		FRONT FENDER INNER SHIELD CLIPS LH	10	5.00	-25	3.75	37.50
49		BONNET HINGE LH	1	54.10	-25	40.58	40.58
50		BONNET HINGE RH	1	54.10	-25	40.58	40.58
51		FRONT DRIVE SHAFT LH	1	1,045.10	-25	783.82	783.82
52		FRONT DRIVE SHAFT RH	1	1,245.35	-25	934.01	934.01
53		FRONT STEERING RACK AND PINON ASSEMBLY	1	5,403.10	-25	4,052.33	4,052.33
54		FRONT UNDERCARRIAGE COVER CENTRE	1	213.10	-25	159.83	159.83
55		FRONT UNDERCARRIAGE COVER LH	1	145.10	-25	108.82	108.82
56		FRONT UNDERCARRIAGE COVER RH	1	145.10	-25	108.82	108.82
57		FRONT UNDERCARRIAGE COVER CLIPS	10	5.00	-25	3.75	37.50
58		FRONT SHOCK ABSORBER LH	1	458.10	-25	343.58	343.58
59		FRONT SHOCK ABSORBER RH	1	458.10	-25	343.58	343.58
60		FRONT SHOCK ABSORBER TOP MOUNTING LH	1	210.10	-25	157.58	157.58
61		FRONT SHOCK ABSORBER TOP MOUNTING RH	1	210.10	-25	157.58	157.58
62		FRONT WHEEL HUB LH	1	435.10	-25	326.33	326.33
63		FRONT WHEEL HUB RH	1	435.10	-25	326.33	326.33



ESTIMATE

Date	: 08/01/2019	Reg No	: SKK4177J
To	: AIG ASIA PACIFIC INSURANCE PTE. LTD.	Model	: TOYOTA PREVIA 7 SEATER CVT
Attn.	:	Chassis No	: JTEGD54M40A038821
Office / Mobile	:	Engine No	: 2AZJ003339
Email Address	:	Quotation No.	: 79587
		Ref. No.	:
From	: GOLDBELL ENGINEERING PTE LTD	D.O.A.	: 04/01/2019
Attn.	: MELODYTEOHML	Policy No.	:
Office / Mobile	: +65 6484 3683	Claim Type	: TP CLAIM
Email / Fax No.	: MelodyTeohML@goldbell.com.sg	Workshop	: KAKI BUKIT

S/N	Part No	Description	Qty	U/Price	%	Net Price	Ext Price
64		FRONT WHEEL HUB BEARING LH	1	201.10	-25	150.83	150.83
65		FRONT WHEEL HUB BEARING RH	1	201.10	-25	150.83	150.83
66		FRONT KNUCKLE ARM LH	1	545.10	-25	408.83	408.83
67		FRONT KNUCKLE ARM RH	1	545.10	-25	408.83	408.83
68		FRONT KNUCKLE ARM BEARING LH	1	201.10	-25	150.83	150.83
69		FRONT KNUCKLE ARM BEARING RH	1	201.10	-25	150.83	150.83
70		FRONT LOWER ARM LH	1	569.10	-25	426.83	426.83
71		FRONT LOWER ARM RH	1	569.10	-25	426.83	426.83
72		FRONT STABILIZER LINK ROD LH	1	110.35	-25	82.76	82.76
73		FRONT STABILIZER LINK ROD RH	1	110.35	-25	82.76	82.76
74		FRONT STABILIZER BAR	1	458.10	-25	343.58	343.58
75		FRONT SUB FRAME	1	1,027.10	-25	770.32	770.32
76		FRONT ENGINE TOP MOUNTING RH	1	201.10	-25	150.83	150.83
77		FRONT DOOR WINDOW REGULATOR RH	1	269.10	-25	201.83	201.83
78		FRONT DOOR WINDOW REGULATOR MOTOR RH	1	509.10	-25	381.83	381.83
79		FRONT DOOR INNER TRIM BOARD RH	1	680.10	-25	510.08	510.08
80		REAR TAILGATE INNER DAMPER LH	1	299.10	-25	224.33	224.33
81		REAR ABSORBER LH	1	145.10	-25	108.82	108.82
82		REAR ABSORBER RH	1	145.10	-25	108.82	108.82
83		REAR AXLE BEAM	1	2,017.10	-25	1,512.82	1,512.82
84		FRONT SPORT RIM (17") LH	1	750.00	-25	562.50	562.50
85		FRONT SPORT RIM (17") RH	1	750.00	-25	562.50	562.50
86		REAR SPORT RIM (17") LH	1	750.00	-25	562.50	562.50
87		REAR SPORT RIM (17") RH	1	750.00	-25	562.50	562.50

PARTS TOTAL :

26,858.67



ESTIMATE

Date	: 08/01/2019	Reg No	: SKK4177J
To	: AIG ASIA PACIFIC INSURANCE PTE. LTD.	Model	: TOYOTA PREVIA 7 SEATER CVT
Attn.	:	Chassis No	: JTEGD54M40A038821
Office / Mobile	:	Engine No	: 2AZJ003339
Email Address	:	Quotation No.	: 79587
		Ref. No.	:
From	: GOLDBELL ENGINEERING PTE LTD	D.O.A.	: 04/01/2019
Attn.	: MELODYTEOHML	Policy No.	:
Office / Mobile	: +65 6484 3683	Claim Type	: TP CLAIM
Email / Fax No.	: MelodyTeohML@goldbell.com.sg	Workshop	: KAKI BUKIT

SPECIAL NETT ITEMS

1	FRONT TYRE LH (215/55 ZR17)	1	230.00
2	FRONT TYRE RH (215/55 ZR17)	1	230.00
3	REAR TYRE LH (215/55 ZR17)	1	230.00
4	REAR TYRE RH (215/55 ZR17)	1	230.00
5	COOLANT	1	40.00
6	POWER STEERING FLUID	1	50.00
7	SEALANT	1	50.00
8	AUTO-TRAN FLUID	1	50.00

PARTS TOTAL: 1110.00



ESTIMATE

Date	: 08/01/2019	Reg No	: SKK4177J
To	: AIG ASIA PACIFIC INSURANCE PTE. LTD.	Model	: TOYOTA PREVIA 7 SEATER CVT
Attn.	:	Chassis No	: JTEGD54M40A038821
Office / Mobile	:	Engine No	: 2AZJ003339
Email Address	:	Quotation No.	: 79587
		Ref. No.	:
From	: GOLDBELL ENGINEERING PTE LTD	D.O.A.	: 04/01/2019
Attn.	: MELODYTEOHML	Policy No.	:
Office / Mobile	: +65 6484 3683	Claim Type	: TP CLAIM
Email / Fax No.	: MelodyTeohML@goldbell.com.sg	Workshop	: KAKI BUKIT

LABOUR CHARGES

1	TO REMOVE AND REFIT AIR-CON SYSTEM AND TOP UP AIR-CON GAS	150.00
2	TO REMOVE AND REFIT FRONT RH DOOR COMPONENT	120.00
3	TO REMOVE AND REFIT REAR RH DOOR COMPONENT	120.00
4	TO REMOVE AND REFIT REAR TAILGATE LH DAMPER	50.00
5	TO REMOVE AND REFIT FRONT RH SUSPENSION SYSTEM	180.00
6	TO REMOVE AND REFIT FRONT LH SUSPENSION SYSTEM	180.00
7	TO REMOVE AND REFIT FRONT SUB FRAME	250.00
8	TO REMOVE AND REFIT REAR LH SUSPENSION SYSTEM	180.00
9	TO REMOVE AND REFIT REAR RH SUSPENSION SYSTEM	180.00
10	TO REMOVE AND REFIT REAR AXLE BEAM ASSEMBLY	250.00
11	TO REMOVE AND REFIT FRONT FLOOR CARPET AND SEATS TO ASSIST REPAIR	100.00
12	TO REMOVE AND REFIT FRONT WINDSCREEN GLASS TO ASSIST REPAIR OF A-PILLAR	180.00
13	TO REMOVE AND REFIT FRONT LH TYRE FOR BALANCING	20.00
14	TO REMOVE AND REFIT FRONT RH TYRE FOR BALANCING	20.00
15	TO REMOVE AND REFIT REAR LH TYRE FOR BALANCING	20.00
16	TO REMOVE AND REFIT REAR RH TYRE FOR BALANCING	20.00
17	TO SPRAY PAINT ON AFFECTED AREAS	3000.00
18	TO STRAIGHTEN AND PANEL BEAT	3000.00
19	TO CHECK WIRING SYSTEM	80.00
20	TO CONDUCT FULL WHEEL ALIGNMENT	150.00



ESTIMATE

Date	: 08/01/2019	Reg No	: SKK4177J
To	: AIG ASIA PACIFIC INSURANCE PTE. LTD.	Model	: TOYOTA PREVIA 7 SEATER CVT
Attn.	:	Chassis No	: JTEGD54M40A038821
Office / Mobile	:	Engine No	: 2AZJ003339
Email Address	:	Quotation No.	: 79587
		Ref. No.	:
From	: GOLDBELL ENGINEERING PTE LTD	D.O.A.	: 04/01/2019
Attn.	: MELODYTEOHML	Policy No.	:
Office / Mobile	: +65 6484 3683	Claim Type	: TP CLAIM
Email / Fax No.	: MelodyTeohML@goldbell.com.sg	Workshop	: KAKI BUKIT

LABOUR CHARGES

21	SUNDRIES	20.00
22	RUST PROOFING	100.00

LABOUR TOTAL : 8,370.00

SUB-TOTAL : 36,338.67

GST @ 7% for \$ 36,338.67 2,543.71

GRAND TOTAL (S\$) : 38,882.38

PREPARED BY : MELODYTEOHML

DATE / TIME :

SURVEYOR :

MOBILE NO :

OFFICE FAX NO :

EMAIL ADDRESS :

EXCESS AMOUNT :

REPAIR TYPE : PART-BY-PART / LUMP SUM

AUTHORISATION : AUTHORISED / NOT AUTHORISED

RE-SURVEY : BEFORE PAINT / AFTER PAINT

NO. OF DAYS :

REMARKS :