

孫亞弟汽車燒焊私人有限公司

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB. Reg. / GST Reg. No: 200810440N

EST/QUOTE NO. SQ004503

INDIA INTERNATIONAL INSURANCE PTE LTD

64 #05-05 CECIL STREET

IOB BUILDING SINGAPORE 049711

ATTENTION :

CONTACT : 62238122

FAX NO: 62244174

DATE : 08/01/2019
 ACCIDENT DATE : 01/11/2018
 VEHICLE NO : SLX3313J
 CHASSIS/ENG.NO : KMHD841CMJU630788
 VEHICLE MODEL : HYUNDAI ELANTRA
 CLAIM NO :
 POLICY NO :
 REMARK : 3313INDIA TP AGST SHC1752X

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
** LIST PRICE **							
1	1	PC	FRT BUMPER <i>repair</i>	443.40	20	354.72	354.72
2	10	PC	FRT BUMPER CLIPS <i>new</i>	15.90	20	12.72	127.20
3	1	PC	FRT BUMPER RETAINER LH <i>X</i>	28.00	20	22.40	22.40
4	1	PC	FRT HEADLAMP LH <i>X</i>	1,198.80	20	959.04	959.04
5	1	PC	FRT HEADLAMP BRACKET LH <i>X</i>	25.30	20	20.24	20.24
6	1	PC	FRT FENDER LH <i>Bt</i>	521.20	20	416.96	416.96
7	10	PC	FRT FENDER INNER SHIELD CLIP <i>new</i>	15.90	20	12.72	127.20

SUB-TOTAL: 2,027.76

** WORK LABOUR **

TO KNOCK, WELD, REMOVE & REMOVE ON ABOVE PARTS

TO PUTTY & SPARY PAINTING ON AFFECTED AREAS

TO CHECK WIRING

TO APPLY ANTI RUST COATING

700.00 *500* ~~700.00~~

1000.00 *900* ~~1,000.00~~

30.00 *X* ~~30.00~~

200.00 *80* ~~200.00~~

SUB-TOTAL 1,930.00

SAM

PAGE: 1 of 1

SUB-TOTAL : S\$ 3,957.76

ADD 7% GST. S\$ 277.04

GRAND TOTAL : S\$ 4,234.80

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD E & O E

Disclaimer clause:

The above estimate/quotation is meant for solely the intended party stated above and in any event, we are not liable to any other parties arising from the circumstances of this or any action taken in reliance on such estimates or quotations.

Quotation is only valid for 14 days.