

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Vicom Inspection Centre Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: AXA	DATE	: 08/01/2019
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
VEHICLE DETAILS			
VEHICLE NO	: YN4869P		
MODEL	: MIT CANTER		
CHASSIS NO			
ACCIDENT DETAILS		DATE	: 5-Jan-19
		TIME	: 14:20HRS
THIRD PARTY REQUESTOR / CONTACT		:	JACK LI

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAILGATE <i>Dented</i>	1	\$ 1,900.00	\$ 1,900.00 <i>1750</i>
2	TAILGATE HINGE <i>Neu</i>	2	\$ 150.00	\$ 300.00 <i>+</i>
3	REAR NUMBER PLATE LAMP <i>Neu</i>	1	\$ 60.00	\$ 60.00 <i>+</i>
4	REAR BUMPER CENTER BEAM <i>Neu</i>	1	\$ 430.00	\$ 430.00 <i>+</i>
5	REAR END PANEL <i>Repair</i>	1	\$ 1,600.00	\$ 1,600.00 <i>x</i>

1750 TOTAL PRICE \$ 4,290.00
1312.50 LESS 10% *25%* \$ 429.00
 SUB TOTAL PRICE \$ 3,861.00

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>Bent</i>	1	\$ 50.00	\$ 50.00 <i>30</i>
2	REAR NUMBER PLATE HOLDER <i>Bent</i>	1	\$ 188.80	\$ 188.80 <i>✓</i>
3	TAILGATE STICKER <i>Neu</i>	1	\$ 550.00	\$ 550.00 <i>250</i>
4	TAILGATE '60KM/H' <i>Neu</i>	1	\$ 40.00	\$ 40.00 <i>15</i>
5	TAILGATE '22 PAX' <i>Neu</i>	1	\$ 40.00	\$ 40.00 <i>15</i>
6	TAILGATE STEP PANEL <i>Bent</i>	1	\$ 650.00	\$ 650.00 <i>350</i>

848.80 TOTAL \$ 1,518.80

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	TO PANEL BEAT, KNOCK, WELD, CUT, ADJUST, STRAIGHTEN, GRAZE, ALIGN	\$ 2,200.00	200.	
2	TO PUTTY, SPRAY PAINT, POLISH, WAX	\$ 1,000.00	200.	
3	BULB CHECKING, WIRING	\$ 80.00	30.	
4	REMOVE AND REFIX TAILGATE	\$ 180.00	X.	

TOTAL

\$3,460.00

430

ESTIMATE REPORT

TOTAL PARTS COST : \$ 5,379.80

TOTAL LABOUR COST : \$ 3,460.00

TOTAL REPAIR COST : \$ 8,839.80

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

FAX :

PART BY PART / LUMP SUM :

NO OF DAYS :

Adrian Ling

09/01/19.

4/5 04 Days.

P/S. 4/5

total 2591.30

h/s: 2K.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: