

ASS. REC. BY:

REF:

CS/FCL19000526/Asbn2

Special Instruction:

Surveyor:

ASSIGNMENT (Office)From (Person): CWS Joanne Tong of FCL Date/Time: 09/01/2019 3:48pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJR 9377R Insured: SHA 877Lat Workshop m/s SW Werkz Tel: _____of 25 Kaki Bukit Rd 4 #03-67Policy No: _____ Claim No: D19000305MFSH

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 09/01/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS DS:

Date/Time: 09/01/2019 4:04pm Person Contacted: Chris H.O.D. Endorsement: _____Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SJR 9377R - X
	SHA 877L - CS/FCL17018340/Klbn2
10/01/19	@ 11:45 a.m. revert pending estimate from repairer to Joanne Tong via email.

DUT: 10/01/2019

2004/11/19

ASSIGNMENT

23/07/09.

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SJR9377R Yr Regn: 2009 July.

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or: _____

Make: Honda City C.C. 1497

Colour: Silver. A/C: Insured / Std / NI / NA

Sp Reading: 267832 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MRH6M265099020357

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 175/65R15

R: 175/65R15.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. D.O.I. 09/01/19

Survey held at SW wetke.

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP 1st Cap.
01/04/19	Confirmed HS \$ 5,000/- @ 6 days With Adrian (\$ 6,068.50 Red - 67%) MV : 16K PV : 10.1K. Nett: 5.9K. MV - \$16K LTA - \$10,083.00 } Nett - \$ 5,917.00

RECEIVED 01 APR 2019

Date/Time, File Pass to?

01/04/19

1) Typist

Date/Time, File Return to?

2) _____

☐ : Preli. Report☒ : Final Report

Days Of Repair: 6

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee:

Transportation:

) \$ + RS \$

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ 3,000/- HS)

170

50

50

47

317

MOTOR SURVEY ASSIGNMENT

Date	09-01-2019	Our Ref No. D19000305MFSH
Accident Date	07-01-2019	Claim Type. Third Party
Insured Vehicle	SHA0877L	Third Party Vehicle. SJR9377R
Survey Location	25 KAKI BUKIT ROAD 4 #03-67/68SYNERGY@KB	
Contact Person.	CHRIS CHAN PICK YUEN	
Contact No.	92712214/ 92712214	Fax No. 0
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	SW WERKZ PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 10 January 2019 11:45 AM
To: 'Joanne Yong Lai fong'; 'CWS Motor Claims'
Cc: 'SUR'; 'Admin-D (LKKAuto)'; 'assignments'
Subject: RE: SURVEY ASSESSMENT - D19000305MFSH/1

Dear Joanne,

Please be informed that we have inspected the vehicle SJR 9377R on 09/01/2019.

We are pending estimate from repairer.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Wednesday, 9 January 2019 4:04 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Joanne Yong Lai fong' <JoanneYong@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19000305MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Wednesday, 9 January, 2019 3:48 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Joanne Yong Lai fong <JoanneYong@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19000305MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



★ Posted: 04-Jan-2019 Tags: 2009 Honda City, 2009 honda city, Honda City, honda city, Honda, City, city, Used Honda



☐ **Honda City 1.5A VTEC (New 10-yr COE)** **\$43,800** **\$4,380 /yr** **05-Mar-2009** **1,497 cc** **127,000 km** **Sedan** **Available**

Depreciation Only \$365 Per Month! Option 5 Years COE At \$28800. Tip Top Condition! Very Well Maintained, Accident-Free, New Paintwork, No Repairs Needed, View To Believe! Up To 100% In House Loan/Bank...

★ Posted: 19-Dec-2018 Tags: 2009 Honda City, 2009 honda city, Honda City, honda city, Honda, City, city, Used Honda



☐ **Honda City 1.5A LX (New 5-yr COE)** **\$29,800** **\$5,960 /yr** **09-Mar-2009** **1,497 cc** **103,000 km** **Sedan** **Available**

Rare 1 Owner Only! Option For 10 Year COE At \$43800! Only! High Loan Available, Good Engine And Gearbox, Solid Undercarriage, No Accident, Trade In Available, No Repair Needed, Call Our Friendly Sales...

Creative Auto

★ Posted: 23-Dec-2018 Tags: 2009 Honda City, 2009 honda city, Honda City, honda city, Honda, City, city, Used Honda



☐ **Honda City 1.5A LX** **\$15,786** **N/A** **04-May-2009** **1,497 cc** **130,000 km** **Sedan** **Available**

Extended Warranty By Our Own Workshop, Test Drive To Feel The Engine And Gearbox.

★ Posted: 10-Nov-2018 Tags: 2009 Honda City, 2009 honda city, Honda City, honda city, Honda, City, city, Used Honda

Save this search criteria, to get email alerts whenever a match is found.

Save Search

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy Used Honda City, Honda City Singapore, used Honda City Singapore, used Honda City, used vehicles Singapore or even buy used Honda City Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow [sgCarMart.com](#)



[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2019 sgCarMart. All rights reserved.

SHORTLISTED HISTORY
Compare

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	5819E

Vehicle Details

Vehicle No.:	SJR9377R
Vehicle to be Exported:	Yes
Intended Deregistration Date:	08 Jan 2019
Vehicle Make:	HONDA
Vehicle Model:	CITY 1.5L I-VTEC AUTO
Primary Colour:	Silver
Manufacturing Year:	2009
Engine No.:	L15A71809048
Chassis No.:	MRHGM26509P020357
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$18,628.00
Original Registration Date:	23 Jul 2009
First Registration Date:	23 Jul 2009
Transfer Count:	2
Actual ARF Paid:	\$18,628.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Jul 2019
PARF Rebate Amount:	\$9,314.00

Intended COE Rebate Details

COE Expiry Date:	22 Jul 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$14,310.00
COE Rebate Amount:	\$769.00
Total Rebate Amount:	\$10,083.00

The information contained herein is correct as at 08 Jan 2019

OK

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company
Owner ID: 5R19E

Vehicle Details

Vehicle No.: SJR9377R
Vehicle to be Exported: Yes
Intended Deregistration Date: 08 Jan 2019
Vehicle Make: HONDA
Vehicle Model: CITY 1.5L I-VTEC AUTO
Primary Colour: Silver
Manufacturing Year: 2009
Engine No.: L15A71809048
Chassis No.: MRHGM26509P020357
Maximum Power Output: 88.0 kW (118 bhp)
Open Market Value: \$18,628.00
Original Registration Date: 23 Jul 2009
First Registration Date: 23 Jul 2009
Transfer Count: 2
Actual ARF Paid: \$18,628.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 22 Jul 2019
PARF Rebate Amount: \$9,314.00

Intended COE Rebate Details

COE Expiry Date: 22 Jul 2019
COE Category: A - Car (1600cc & below)
COE Period (Years): 10
QP Paid: \$14,310.00
COE Rebate Amount: \$769.00
Total Rebate Amount: \$10,083.00

The information is as at 08 Jan 2019

OK

SW WERKZ PTE LTD

BLOCK 25 KAKI BUKIT ROAD 4 #03-65/67/68 SYNERGY @ KB Singapore 417800

HP: 92712214 TEL: (65) 63844844 FAX: (65) 63834944

SW WERKZ LEASING PTE LTD
25 KAKI BUKIT ROAD 54
03-65/67/68 SYNERGY @KB
Singapore 417800

09th January 2019

TP 1st Cap
Shirley

Accident date: 07th JAN 2019

Estimated repair cost for vehicle no: SJR9377R HONDA CITY 1.5L '09

S/n	Qty	Items	U/price	Amount
1	1	Rear Boot Lid <i>Dented</i>		\$565.20 ✓
2	2	Rear Boot Lid Hinges <i>New</i>	\$81.20	\$162.40 ✓
3	1	Rear boot lid city logo <i>New</i>		\$35.00 ✓
4	1	Rear boot lid center moulding <i>New</i>		\$168.20 ✓
5	1	Rear boot lid emble logo <i>New</i>		\$35.00 ✓
6	1	Rear boot lid i-dsi logo <i>New</i>		\$35.10 ✓
7	1	Rear Boot Lid Number Plate <i>Green</i>		\$50.00 ✓
8	2	Rear Boot Lid Number Plate Lamp	\$58.10	\$116.20 ✓
9	1	Rear Boot Lid Inner Lock <i>Dented</i>		\$115.20 ✓
10	1	Rear boot lid inner rubber <i>Lat</i>		\$105.20 ✓
11	1	Rear boot lid key lock <i>New</i>		\$135.40 ✓
12	2	Rear tail lamp <i>RA cracked</i>	\$315.00	\$630.00 <i>315</i>
13	4	Rear tail lamp clips <i>New</i>	\$5.00	\$20.00 <i>10</i>
14	2	Rear tail lamp panel <i>Ry</i>	\$115.20	\$230.40 ✓
15	2	Rear tail lamp inner sponge <i>New</i>	\$58.20	\$116.40 <i>20</i>
16	1	Rear Bumper <i>Dishd</i>		\$491.20 ✓
17	2	Rear Bumper Side Bracket <i>New</i>	\$25.50	\$51.00 ✓
18	8	Rear bumper clips <i>New</i>	\$5.00	\$40.00 <i>30</i>
19	2	Rear bumper mud shield <i>Green</i>	\$65.20	\$130.40 ✓
20	8	Rear bumper mud shield clips	\$5.00	\$40.00 ✓
21	1	Rear end panel <i>Dented</i>		\$419.60 ✓
22	1	Rear End Panel Top Garnish <i>Dented</i>		\$155.20 ✓
23	1	Rear windscreen moulding <i>New</i>		\$102.50 ✓
24	2	Rear fender inner trim board <i>Green</i>	\$250.40	\$500.80 ✓
25	10	Rear fender inner trim board clips	\$5.00	\$50.00 ✓
26		Rear Spare tire panel top cover <i>to be</i>		\$225.00 ✓

1	Rear spare tire panel sealant		\$250.00	x
28	1 rear spare tire lock		\$125.00	x
29	2 Rear spare tire panel side panel	\$188.70	\$377.40	x
30	1 Rear Exhaust		\$685.00	x
31	2 rear exhaust mounting	\$48.50	\$97.00	x
32	1 rear exhaust aluminium cover		\$88.70	x

2607.70

Subtotal :- \$6,348.50

2086.16.

Labour charges

To remove & re-fix cushion

~~\$120.00~~ 60.

To remove & re-fix rear windscreen

~~\$120.00~~ x

Gum

~~\$50.00~~ x m

To remove & re-fix rear exhaust

~~\$250.00~~ x

To Check Wiring system

1750. ~~\$60.00~~ 30.

Tuff Kote

~~\$120.00~~ 60.

Panel beating

~~\$1,000.00~~ 800

Spray painting

~~\$1,000.00~~ 800.

Subtotal :- \$2,720.00

Total :- \$9,068.50

total. 3836.16

L/S: 3K

06 Aug

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI19000526/Asbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 03-04-2019	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 877L	Veh. Inspected	SJR 9377R	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19000305MFSH	Excess (\$)	0.00	
Assign From	JOANNE YONG	Assign Date	09/01/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA CITY	c.c	1497	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	MRHGM26509P020357	Colour	SILVER	
Odometer	267832	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	175/65 R15	BRIDGESTONE	6 mm	
L/H Front Tyre	175/65 R15	BRIDGESTONE	6 mm	
R/H Rear Tyre	175/65 R15	BRIDGESTONE	6 mm	
L/H Rear Tyre	175/65 R15	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	07/01/2019	Inspection Date	09/01/2019	
Survey held at	SW WERKZ PTE LTD BLK 25 KAKI BUKIT ROAD 4 #03-67/68 SYNERGY @ KB SINGAPORE 417800			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJR 9377R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BOOT LID	DENTED	565.20	565.20
2	REAR BOOT LID HINGES @\$81.20	NOT NECESSARY	162.40	-
1	REAR BOOT LID CITY LOGO	NECESSARY	35.00	35.00
1	REAR BOOT LID CENTER MOULDING	NOT NECESSARY	168.20	-
1	REAR BOOT LID EMBLEM LOGO	NECESSARY	35.00	35.00
1	REAR BOOT LID I-DSI LOGO	NECESSARY	35.10	35.10
1	REAR BOOT LID NUMBER PLATE	NOT NECESSARY	50.00	-
2	REAR BOOT LID NUMBER PLATE LAMP @\$58.10	NOT NECESSARY	116.20	-
1	REAR BOOT LID INNER LOCK	DAMAGED	115.20	115.20
1	REAR BOOT LID INNER RUBBER	CUT	105.20	105.20
1	REAR BOOT LID KEY LOCK	NOT NECESSARY	135.40	-
2	REAR TAIL LAMP @\$315.00	O/S CRACKED	630.00	315.00
4	REAR TAIL LAMP CLIPS @\$5.00	NECESSARY	20.00	10.00
2	REAR TAIL LAMP PANEL @\$115.20	TO REPAIR SEE LABOUR	230.40	-
2	REAR TAIL LAMP INNER SPONGE @\$58.20	NECESSARY	116.40	20.00
1	REAR BUMPER	DISTORTED	491.20	491.20
2	REAR BUMPER SIDE BRACKET @\$25.50	NECESSARY	51.00	51.00
8	REAR BUMPER CLIPS @\$5.00	NECESSARY	40.00	30.00
2	REAR BUMPER MUD SHIELD @\$65.20	NOT NECESSARY	130.40	-
8	REAR BUMPER MUD SHIELD CLIPS @\$5.00	NOT NECESSARY	40.00	-
1	REAR END PANEL	DENTED	419.60	419.60
1	REAR END PANEL TOP GARNISH	DEFORMED	155.20	155.20
1	REAR WINDSCREEN MOULDING	NOT NECESSARY	102.50	-
2	REAR FENDER INNER TRIM BOARD @\$250.40	NOT NECESSARY	500.80	-
10	REAR FENDER INNER TRIM BOARD CLIPS @\$5.00	NOT NECESSARY	50.00	-
1	REAR SPARE TIRE PANEL TOP COVER	TORN	225.00	225.00
1	REAR SPARE TIRE PANEL SEALANT	NOT NECESSARY	250.00	-
1	REAR SPARE TIRE LOCK	NOT NECESSARY	125.00	-
2	REAR SPARE TIRE PANEL SIDE PANEL @\$188.70	NOT NECESSARY	377.40	-
1	REAR EXHAUST	NOT NECESSARY	685.00	-

Report Ref No. CS/FCI19000526/Asbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR EXHAUST MOUNTING @\$48.50	NOT NECESSARY	97.00	-
1	REAR EXHAUST ALUMINIUM COVER	NOT NECESSARY	88.70	-
	LESS 20% DISCOUNT		-	-521.54
			6,348.50	2,086.16
	<u>SPECIAL NETT ITEMS</u>			
1	GUM (SN)	NOT NECESSARY	50.00	-
			50.00	-
	<u>LABOUR</u>			
	TO REMOVE & RE-FIX CUSHION.		120.00	60.00
	TO REMOVE & RE-FIX REAR WINDSCREEN.	NOT NECESSARY	120.00	-
	TO REMOVE & RE-FIX REAR EXHAUST.	NOT NECESSARY	250.00	-
	TO CHECK WIRING SYSTEM.		60.00	30.00
	TUFF KOTE.		120.00	60.00
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR TAIL LAMP PANEL.		1,000.00	800.00
	SPRAY PAINTING.		1,000.00	800.00
			2,670.00	1,750.00
	GRAND TOTAL		9,068.50	3,836.16
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,000.00

Report Ref No. CS/FCI19000526/Asbn2

MARKET VALUE: \$16,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$10,083.00=NETT VALUE: \$5,917.00

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.