

ASS. REC. BY

REP

FCI19000627/uvd3

n2

Special Instruction:

Surveyor

CWS

Marius

ASSIGNMENT (Office)

From (Person):

Serene fer

of

PEI

Date/Time:

11:39am 9/1/19

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLC9528C

Insured:

SHA 23197

at Workshop m/s

Trans Euro cars

Tel:

8128 9802

of

No-S ubric lose

Policy No:

Claim No:

D19000244MF8H

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

04/01/2019

CA / REV / REP. / REV 24 HRS (Ds)

H.O.D. Endorsement:

Date/Time:

11:57am 9/1/19

Person Contacted:

Ronald

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLC9528C-X

SHA 23197-X

14/1/19

Email preli revised to FCI

Submarine Marcus

REF: FCL

ASSIGNMENT

From: Date: 11-01-2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLC 9528C

at Workshop m/s Trans Eurocars

of 5 Ubi Close

Insured

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:


Tommy

4:30pm

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection

78



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'DS'

41A52861

Vehicle: IN / OUT

Date: Person Contacted:

Veh No. SLC 9528C Yr Regn. 5 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA /

Make: Mazda 6 C.C. 1998

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 5-5351 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JM 64 J107240237798

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/55-R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 5 mm

R/Bal. 5 mm

L/Bal. 5 mm

L/Bal. 5 mm

D.O.A. 4/1/19

D.O.I. 11/1/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear 1/5.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

27-2-19 informed Jess heading etc etc.

20/3/19 @ 7858.36 confirmed with Catherine. (Red)

RECEIVED 21 MAR 2019

Date/Time, File Pass to?



: Preli. Report

DOB Typist



: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: 2

Survey Fee:

Transportation

) S + PS \$

) Photos

) Others

4 TOTAL

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Invs (\$

☐ Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

3x15 = 45

170 + 45
50
30 + 50
54

419



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D19000244MFSH

Our ref: CS/FCI19000527/Uvd3

DATE: 14/1/2019

The Motor Claims Department
MS FIRST CAPITAL INSURANCE LTD

WITHOUT PREJUDICE

Dear Sir/Madam

INITIAL INSPECTION REPORT OF VEHICLE NO. SLC 9528C


We thank for your instruction on 9/1/2019

Please be informed that we had conducted the inspection of the above mentioned vehicle on vehicle on 11/1/2019 at the premises of M/s TRANS EUROKARS PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$10,654.34
Revised Estimate Amount	: S\$7,550.92
"Check" Items Amount	: S\$1,263.42
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the front n/s portion



Comments/Present Status:

Damages Consistent

Yours faithfully,

MARCUS CHUA
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	08-01-2019	Our Ref No. D19000244MFSH
Accident Date	04-01-2019	Claim Type. Third Party
Insured Vehicle	SHA2319T	Third Party Vehicle. SLC9528C
Survey Location	NO.5 UBI CLOSE	
Contact Person.	JESS FRANCIS CARLOS	
Contact No.	81289802/ 81289802	Fax No. 0
Survey Type	DIRECT SETTLEMENT: QUANTUM TO BE AGREED (EST. COR \$10,654.34)	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TRANS EUOKARS PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 14 January 2019 11:03 AM
To: 'CWS Motor Claims'
Cc: 'Serene Ler'; SUR
Subject: RE: SURVEY ASSESSMENT - D19000244MFSH/1, SLC 9528C
Attachments: SLC 9528C PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SLC 9528C
Date of survey: 11/1/2019
Number of days : 4 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 9 January 2019 3:23 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Serene Ler' <Serener@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19000244MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 9 January 2019 11:39 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Serene Ler <Serener@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19000244MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



AVG

This email has been checked for viruses by AVG antivirus software.

www.avg.com

Veron Chen (LKKAUTO)

From: catherinechua@eurokars.com.sg
Sent: Friday, 15 March 2019 1:51 PM
To: Marcus Chua (LKKAUTO); jess.francis@eurokars.com.sg
Cc: CS A Team; Admin A
Subject: SLC9528C - FINALIZATION OF COR
Attachments: 4326_001.pdf

Dear Marcus

Our COR computation is attached for your agreement.

COR: \$7858.36 before GST

5 repair days (not including preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)

Kindly confirm the above as soon as possible.

Aside to Jess:- please send before-paint photos to Marcus

Thanks n Regards



Driving luxury experiences since 1985

Catherine Chua

Insurance Claims Executive

23 Leng Kee Road Singapore 159095

T: (65) 6603 6128 D: (65) 6603 6121 F: (65) 6476 7417

E: catherinechua@mazda.com.sg

This email, including any attachment, is intended for the sole use of the recipient(s) named above and may contain information that is confidential and/or proprietary to the Eurokars Group. If you have received it in error, please notify us immediately by reply email and then delete this message from your system. Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

From: mazdacan@mazda.com.sg <mazdacan@mazda.com.sg>

Sent: 15 March 2019 10:33 AM

To: Catherine Chua <catherinechua@eurokars.com.sg>

Subject: Attached Image

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

F

SUPREME

CLICK HERE OR CALL
64

Post an Advertisement

Sell it yourself! Advertise it at just

\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New 5 Years Coe Renewal Toyota Altis 1.6A



2.88%p.a Lowest Interest@GV
Cars Financing \$1800
Downpayment Monthly From
\$568
GV Credit Pte Ltd StarAd



Browse by Category ▼

Sort by Date Posted

15 vehicles

mazda 6

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	V
Search Selection	mazda 6		Any	Any	2016	Any	Any	
	Mazda 6 2.0A Executive		\$87,800	\$9,340 /yr	30-Dec-2016	1,998 cc	60,126 km	
Highest Specs, Executive Model! Serviced At Eurokars With Proof/Warranty, Last Done Sept 18. Totally Brand New. 1 Doctor Owner. Nic Number. 100% Accident Free. Price Negotiable. Call Now!								
Lake View Credit Pte Ltd								
Posted: 13-Jan-2019 Tags: 2016 Mazda 6, 2016 mazda 6, Mazda 6, mazda 6, Mazda, 6, Used Mazda								
	Mazda 6 2.5A Luxury		\$110,000	\$13,570 /yr	29-Feb-2016	2,488 cc	58,000 km	
Christmas Offer! Free Insurance For NCD 40% And Above! Just 1 Owner. Full Agent Service. Still Under Warranty. Getting A Safety, Sup Comfortable Luxury Sedan With Good Fuel Efficient Car ...								
Posted: 11-Jan-2019 Tags: 2016 Mazda 6, 2016 mazda 6, Mazda 6, mazda 6, Mazda, 6, Used Mazda								
	Mazda 6 2.0A		\$78,888	\$9,120 /yr	17-Jun-2016	1,998 cc	35,000 km	
Up To 90% Loan! From \$1,130/Month. Guaranteed Non Private Hire Unit! Fully Agent Maintained, Valid Agent Warranty Till 2019! Last 5 Only. New Battery. Drive With Peace Of Mind: 1 Owner U...								
Cars 88 Pte Ltd								
Posted: 10-Jan-2019 Tags: 2016 Mazda 6, 2016 mazda 6, Mazda 6, mazda 6, Mazda, 6, Used Mazda								
	Mazda 6 2.0A Executive		\$78,800	\$9,650 /yr	18-Feb-2016	1,998 cc	15,656 km	
Low Depreciation For A Luxury Japan Made Sedan Loaded With Features. Full Servicing Done At Mazda. Higher Grade Executive Model V Display, Premium Bose Audio System With Multi Speakers, Ad...								
Posted: 09-Jan-2019 Tags: 2016 Mazda 6, 2016 mazda 6, Mazda 6, mazda 6, Mazda, 6, Used Mazda								
	Mazda to Unveil Updated Mazda6 Wagon							
Mazda Japan will showcase the world premiere of the updated Mazda6 wagon at the 88th Geneva International Motor Show.								
Read this article								
	Mazda 6 2.0A Executive		\$85,800	\$9,230 /yr	30-Dec-2016	1,998 cc	42,855 km	
One Of Mazda Most Elegant Model With Its Stylish Bold Curves On The Outside, Coupled With Generous Cabin Space For Families On Tri Equipped With A 2.0 SkyActiv-G Engine Coupled To A 6 Speed Au...								
Performance Premium Selection								
ad: 08-Jan-2019 Tags: 2016 Mazda 6, 2016 mazda 6, Mazda 6, mazda 6, Mazda, 6, Used Mazda								

Compare

Compare

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4358E
Vehicle Details	
Vehicle No.:	SLC9528C
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Jan 2019
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA6 4-DOOR SEDAN 2.0L SP.6EAT
Primary Colour:	Grey
Manufacturing Year:	2016
Engine No.:	PE20778584
Chassis No.:	JM6GJ1072G0237798
Maximum Power Output:	121.0 kW (162 bhp)
Open Market Value:	\$21,634.00
Original Registration Date:	30 May 2016
First Registration Date:	30 May 2016
Transfer Count:	0
Actual ARF Paid:	\$22,288.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 May 2026
PARF Rebate Amount:	\$16,716.00
Intended COE Rebate Details	
COE Expiry Date:	29 May 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$49,156.00
COE Rebate Amount:	\$36,245.00
Total Rebate Amount:	\$52,961.00

The information contained herein is correct as at 14 Jan 2019

OK



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
ESTIMATE COST OF REPAIRS

EUROKARS GROUP

11/1/19 5:47
Taken into before pa. reg.
Not Authorized

First Capital Insurance Ltd		NAME : Mr Gwee Aik Chiong	WIP : 39755	
		ADDRESS : 23 Highland Road Singapore 549114	EXCESS : DATE : 7-Jan-19	
ATTN. : MOTOR CLAIMS	TEL : 97855198			
FAX :				
VEH NO : SLC9528C	DATE IN :	CONTACT PERSON :	TOMMY/JESS	
CHASSIS NO : JM6GJ1072G0237798	MILEAGE :	TYPE OF CLAIM :	THIRD PARTY CLAIM	
MODEL : MAZDA6	DATE REG.: 30-May-16	POLICY NO. :		
NATURE OF WORKS				
Parts Description				
NO	QTY		REVISED	PRICES
1	1	MGMN3-50-031CBB	7-1	\$ 1,154.10
2	1	MGHP9-50-0U1C	3-1	\$ 14.00
3	1	MG46L-50-C22	11 X	\$ 97.00
4	1	MG46L-50-C21A	11 X	\$ 21.60
5	1	MG46L-50-A11 BB	11-1	\$ 31.80
6	1	MG46L-50-1T1A	11	\$ 73.30
7	1	MGHP9-50-111	7-1	\$ 73.30
8	2	MFD01-68-AC3	11 X	\$ 11.80
9	1	MGHP9-50-070A	11 X	\$ 552.00
10	6	MC274-50-133	11	\$ 21.00
11	2	MB45A-56-146A	11	\$ 5.60
12	2	MGHP9-50-0Z5	11	\$ 5.40
13	6	MGHP9-50-355	11	\$ 27.60
14	8	MS51S-51-833	11	\$ 30.40
15	6	MGD7A-50-EA1	11	\$ 18.00
16	1	MG46L-50-7K1	11	\$ 137.70
17	1	MG46L-50-161	11 X	\$ 35.40
18	1	MGHP9-50-EB1A	11 X	\$ 3.20
19	1	MG46L-50-B51	11	\$ 50.10
20	1	MGHP9-52-211A	11/3-1	\$ 365.40
21	1	MGHP9-52-240D	11 X	\$ 46.00
22	1	MGHP9-56-140J	11 X	\$ 98.00
23	17	MB45A-56-146A	11	\$ 47.60
24	1	MGM18-51-041E	11	\$ 3,209.30
25	1	MGMG9-51-0K6	11 X	\$ 201.30
26	2	MFB01-50-133C	11	\$ 7.60
27	1	MB092-51-833	11	\$ 3.30
28	1	MG46L-50-712A	11	\$ 114.80
29	2	MKD45-50-1K5A	11	\$ 5.40
30	2	MKD45-50-ES1	11	\$ 5.40

31	RIVET, FRONT GRILLE	2	MEA01-50-037	711	\$ 15.20
TOTAL PARTS					\$ 6,482.60
LESS 10%					\$ 648.26
TOTAL PARTS COST					\$ 5,834.34

Labour Description

1	MZ-BR-FRONT7	TO REPLACE FRONT BUMPER AND FRONT FENDER LH. TO REPAIR PANEL SHROUD LH AND ALL AREAS AFFECTED BY THE ACCIDENT.	1320	\$ 1,980.00
2	MZ-SP-SFRT07	TO RESPRAY FRONT BUMPER, PANEL SHROUD LH AND FRONT FENDER LH.	1260	\$ 1,890.00
3	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	100	\$ 250.00
4	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	120	\$ 250.00
5	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	150	\$ 350.00
6	MZ-BR-SUNDRI	SUNDRIES.	30	NETT \$ 100.00

TOTAL LABOUR	\$ -	\$ 4,820.00
TOTAL PARTS	\$ -	\$ 5,834.34
TOTAL	\$ -	\$ 10,654.34
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	\$ -
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

13635-77

Authorised Signature

I/We hereby acknowledge and certify that the following:

- The above information is true and correct.
- The above information is true and correct.
- The above information is true and correct.
- The above information is true and correct.
- The above information is true and correct.
- The above information is true and correct.
- The above information is true and correct.

Acknowledged by Transport

Signature

Date



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
SUPPLEMENTARY ESTIMATE COST OF REPAIRS



FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSE SINGAPORE 068877 ATTN : MOTOR CLAIMS FAX :		NAME : Mr Gwee Aik Chiong ADDRESS : 23 Highland Road Singapore 549114 TEL : 97855198		WIP : 39755 EXCESS : DATE: 7-Jan-19	
VEH NO :	SLC9528C	DATE IN :		CONTACT PERSON :	TOMMY/JESS
CHASSIS NO :	JM6GJ1072G0237798	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA6	DATE REG.:	30-May-16	POLICY NO. :	
NATURE OF WORKS					
Parts Description					
NO	QTY			REVISED	PRICES
1	PLATE(L), SEAL	1	GHP9 56 253	che	\$ 30.70
2	PLATE, SET	1	G46L 50 1C0A	che	\$ 72.70
3	UNIT (R) , HEADLAMP	1	GML8 51 031E	n/c che	\$ 3,209.30
TOTAL PARTS					\$ 3,312.70
LESS 10%					\$ 331.27
TOTAL PARTS COST					\$ 2,981.43
Labour Description					
TOTAL LABOUR					\$ - \$ -
TOTAL PARTS					\$ - \$ 2,981.43
TOTAL					\$ - \$ 2,981.43
LESS EXCESS					\$ - \$ -
TOTAL AFTER EXCESS					\$ - \$ -
GST 7%					\$ - \$ -
GRAND TOTAL					\$ - \$ -

REMARKS:
THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD
THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF
REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING
CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED
WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED
ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS
PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

Authorised Signature



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
FINALISED COST OF REPAIRS



FIRST CAPITAL INSURANCE LIMITED		NAME : Mr Gwee Aik Chiong		WIP : 39755	
		ADDRESS : 23 Highland Road		EXCESS :	
		Singapore 549114		DATE: 7-Jan-19	
ATTN : MOTOR CLAIMS		TEL : 97855198			
FAX :					
VEH NO :	SLC9528C	DATE IN :		CONTACT PERSON :	TOMMY/JESS
CHASSIS NO :	JM6GJ1072G0237798	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA6	DATE REG.:	30-May-16	POLICY NO. :	
NATURE OF WORKS					
Parts Description					
NO	QTY		REVISED	PRICES	
1	FRONT BUMPER	1	MGMN3-50-031CBB	\$ 1,154.10	\$ 1,154.10
2	RETAINER LHS	1	MGHP9-50-0U1C	\$ 14.00	\$ 14.00
3	CHROME LHS, FOGLAMP	1	MG46L-50-C22		\$ 97.00
4	COVER(L),HOLE-LAMP GJ/GL	1	MG46L-50-C21A		\$ 21.60
5	TOWING COVER	1	MG46L-50-A11 BB	\$ 31.80	\$ 31.80
6	MESH, FRONT BUMPER	1	MG46L-50-1T1A		\$ 73.30
7	FOAM, FRONT REINFORCEMENT	1	MGHP9-50-111	\$ 73.30	\$ 73.30
8	FASTENER, FOAM	2	MFD01-68-AC3		\$ 11.80
9	FRONT REINFORCEMENT	1	MGHP9-50-070A		\$ 552.00
10	CLIP, FRONT BUMPER	6	MC274-50-133	\$ 21.00	\$ 21.00
11	FASTENER, FRONT BUMPER	2	MB45A-56-146A	\$ 5.60	\$ 5.60
12	GROMMET, FRONT BUMPER	2	MGHP9-50-0Z5	\$ 5.40	\$ 5.40
13	RIVET, FRONT BUMPER	6	MGHP9-50-355	\$ 27.60	\$ 27.60
14	RIVET, FRONT BUMPER	8	MS51S-51-833	\$ 30.40	\$ 30.40
15	FASTENER, FRONT BUMPER	6	MGD7A-50-EA1	\$ 18.00	\$ 18.00
16	CHROME LHS	1	MG46L-50-7K1	\$ 137.70	\$ 137.70
17	BRACKET LHS, CHROME	1	MG46L-50-161		\$ 35.40
18	CLIP, CHROME	1	MGHP9-50-EB1A		\$ 3.20
19	PROTECTOR LHS, CHROME	1	MG46L-50-B51	\$ 50.10	\$ 50.10
20	FRONT FENDER LHS	1	MGHP9-52-211A	\$ 365.40	\$ 365.40
21	STAY LHS, FENDER	1	MGHP9-52-240D		\$ 46.00
22	MUDGUARD LHS	1	MGHP9-56-140J		\$ 98.00
23	FASTENER, MUDGUARD	17	MB45A-56-146A	\$ 47.60	\$ 47.60
24	HEADLAMP LHS	1	MGML8-51-041E	\$ 3,209.30	\$ 3,209.30
25	CORD SHORT, HEADLAMP	1	MGMG9-51-0K6		\$ 201.30
26	CLIP, HEADLAMP	2	MFB01-50-133C	\$ 7.60	\$ 7.60
27	RIVET, HEADLAMP	1	MB092-51-833	\$ 3.30	\$ 3.30
28	FRONT GRILLE	1	MG46L-50-712A	\$ 114.80	\$ 114.80
29	PIN LOCATOR, FRONT GRILLE	2	MKD45-50-1K5A		\$ 5.40
30	GROMMET, FRONT GRILLE	2	MKD45-50-ES1		\$ 5.40
31	RIVET, FRONT GRILLE	2	MEA01-50-037		\$ 15.20

SUPPLEMENTARY ITEMS				
1	PLATE(L), SEAL	1	GHP9 56 253	\$ 30.70 \$ 30.70
2	PLATE, SET	1	G46L 50 1C0A	\$ 72.70 \$ 72.70
3	UNIT (R) , HEADLAMP	1	GML8 51 031E	\$ 3,209.30
			TOTAL PARTS	\$ 5,420.40 \$ 9,795.30
			LESS 10%	\$ 542.04 \$ 979.53
			TOTAL PARTS COST	\$ 4,878.36 \$ 8,815.77
Labour Description				
1	MZ-BR-FRONT7	TO REPLACE FRONT BUMPER AND FRONT FENDER LH. TO REPAIR PANEL SHROUD LH AND ALL AREAS AFFECTED BY THE ACCIDENT.		\$ 1,320.00 \$ 1,980.00
2	MZ-SP-SFRTO7	TO RESPRAY FRONT BUMPER, PANEL SHROUD LH AND FRONT FENDER LH.		\$ 1,260.00 \$ 1,890.00
3	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.		\$ 100.00 \$ 250.00
4	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		\$ 120.00 \$ 250.00
5	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		\$ 150.00 \$ 350.00
6	MZ-BR-SUNDRI	SUNDRIES.		\$ 30.00 \$ 100.00
			TOTAL LABOUR	\$ 2,980.00 \$ 4,820.00
			TOTAL PARTS	\$ 4,878.36 \$ 8,815.77
			TOTAL	\$ 7,858.36 \$ 13,635.77
			LESS EXCESS	\$ - \$ -
			TOTAL AFTER EXCESS	\$ 7,858.36
			GST 7%	\$ 550.09 \$ -
			GRAND TOTAL	\$ 8,408.45 \$ -

REMARKS:

5 REPAIR DAYS (exclude preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI19000527/Uvd3n2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 26-03-2019



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 2319T	Veh. Inspected	SLC 9528C
Policy No.		Coverage (\$)	0.00
Claim No.	D19000244MFSH	Excess (\$)	0.00
Assign From	SERENE	Assign Date	09/01/2019

2. Vehicle Particulars & Condition

Make & Model	MAZDA 6 (A)	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JM6GJ1072G0237798	Colour	GREY
Odometer	55351	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/55 R17	BRIDGESTONE	5 mm
L/H Front Tyre	225/55 R17	BRIDGESTONE	5 mm
R/H Rear Tyre	225/55 R17	BRIDGESTONE	5 mm
L/H Rear Tyre	225/55 R17	BRIDGESTONE	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	04/01/2019	Inspection Date	11/01/2019
Survey held at	TRANS EUROKARS PTE LTD NO 5 UBI CLOSE SINGAPORE 408605		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLC 9528C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	DISTORTED	1,154.10	1,154.10
1	RETAINER LHS	BENT	14.00	14.00
1	CHROME LHS,FOGLAMP	NOT NECESSARY	97.00	-
1	COVER (L),HOLE-LAMP GJ/GL	NOT NECESSARY	21.60	-
1	TOWING COVER	MISSING	31.80	31.80
1	MESH,FRONT BUMPER	NOT NECESSARY	73.30	-
1	FOAM,FRONT REINFORCEMENT	TORN	73.30	73.30
2	FASTENER,FOAM	NOT NECESSARY	11.80	-
1	FRONT REINFORCEMENT	NOT NECESSARY	552.00	-
6	CLIP,FRONT BUMPER	NECESSARY	21.00	21.00
2	FASTENER,FRONT BUMPER	NECESSARY	5.60	5.60
2	GROMMET,FRONT BUMPER	NECESSARY	5.40	5.40
6	RIVET,FRONT BUMPER	NECESSARY	27.60	27.60
8	RIVET,FRONT BUMPER	NECESSARY	30.40	30.40
6	FASTENER,FRONT BUMPER	NECESSARY	18.00	18.00
1	CHROME LHS	CRACKED	137.70	137.70
1	BRACKET LHS,CHROME	NOT NECESSARY	35.40	-
1	CLIP,CHROME	NOT NECESSARY	3.20	-
1	PROTECTOR LHS.CHROME	CRACKED	50.10	50.10
1	FRONT FENDER LHS	DENTED / BUCKLED	365.40	365.40
1	STAY LHS,FENDER	NOT NECESSARY	46.00	-
1	MUDGUARD LHS	NOT NECESSARY	98.00	-
17	FASTENER,MUDGUARD	NECESSARY	47.60	47.60
1	HEADLAMP LHS	CRACKED	3,209.30	3,209.30
1	CORD SHORT,HEADLAMP	NOT NECESSARY	201.30	-
2	CLIP,HEADLAMP	NECESSARY	7.60	7.60
1	RIVET,HEADLAMP	NECESSARY	3.30	3.30
1	FRONT GRILLE	CRACKED	114.80	114.80
2	PIN LOCATOR,FRONT GRILLE	NOT NECESSARY	5.40	-
2	GROMMET,FRONT GRILLE	NOT NECESSARY	5.40	-

Report Ref No. CS/FCI19000527/Uvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	RIVET,FRONT GRILLE	NOT NECESSARY	15.20	-
1	PLATE (L),SEAL (ADDITIONAL)	CRACKED	30.70	30.70
1	PLATE,SET (ADDITIONAL)	CRACKED	72.70	72.70
1	UNIT (R),HEADLAMP (ADDITIONAL)(CRACKED)	NOT CONSISTENT WITH THE IMPACT	3,209.30	-
	LESS 10% DISCOUNT		-979.53	-542.04
			8,815.77	4,878.36
	<u>SPECIAL NETT ITEMS</u>			
1	SUNDRIES (SN)	NECESSARY	100.00	30.00
			100.00	30.00
	<u>LABOUR</u>			
	TO REPLACE FRONT BUMPER AND FRONT FENDER LH.TO REPAIR PANEL SHROUD LH AND ALL AREAS AFFECTED BY THE ACCIDENT.		1,980.00	1,320.00
	TO RESPRAY FRONT BUMPER,PANEL SHROUD LH AND FRONT FENDER LH.		1,890.00	1,260.00
	TO CARRY-OUT BODY CAVITY PRESERVATION.		250.00	100.00
	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		250.00	120.00
	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		350.00	150.00
			4,720.00	2,950.00
	GRAND TOTAL		13,635.77	7,858.36
RECOMMENDED COST OF REPAIRS				7,858.36

Report Ref No. CS/FCI19000527/Uvd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.