

Surround

REF: CC3 / AL719000536 / Atber

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured _____
 Policy No. _____
 Claims No. _____
 Sum Insured _____ Excess: **\$700k**
 (Client's Record) _____
 Make of Veh: _____

(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: **100k**
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: **04 1/2** days Res: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS _____
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: **SLG48905** Yr Regn: **2016 Sept**
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: **Audi Q3** c.c. **1395**
 Colour: **Gold** A/C: Insured / Std / NI / NA
 Sp. Reading: **8924** T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: **WAUZZZ848HR017206**
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: **235/55R17**
 R: **235/55R17**
BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front: _____ Rear: _____
 R/Bal. **06** mm R/Bal. **06** mm
 L/Bal. **06** mm L/Bal. **06** mm
 D.O.A. _____ D.O.I. **09/01/19**
 Survey held at **Premium**
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Front N/S
 The U/C / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction
	OD ALG.

Part by part \$5312 (Led: 5225! 49%)

RECEIVED 03 APR 2019

Date/Time, File Pass to? : Prel. Report
 : Final Report
 1) **314 Typst**

Days Of Repair: **4**
 Resurvey No. of Trip: **-**

Report Format: **OD**
 Lump Sum / I.P. (\$) **5312**

Add Fee: Site Insp (\$) Interview (\$) Tech. Invs (\$) Weekend (\$)

Survey Fee:	700
Transportation:	
Photos	
Other	10
TOTAL	710

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/01/2019 14:26
Date Of Accident	31/12/2018 13:50
Exact Location Of Accident	INTERSECTION OF TIONG BAHRU RD & ZION RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLG4890S
Insured/Policyholder	
Name Of Registered Owner	NEWMARK ANDREW PAUL
Passport No/FIN	G3295073L
Email Address	ANDREW.NEWMARK@MARRIOTT.COM
Mobile Phone No	(LOCAL) +65-93366787
Alternative Phone No	HOME-64003554

Vehicle Particulars

Manufacturer	AUDI
Model	Q3 1.4 TFSI
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100484847-02
Cover Note Number	

Driver

Name of Driver	NEWMARK ANDREW PAUL
Passport No/FIN	G3295073L
Date Of Birth	11/08/1970
Occupation	INDOOR
Date Of Driving Pass	27/06/2017
Driving Experience	1 YEAR AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93366787
Fax Number	
Contact Number	HOME-64003554
Email Address	ANDREW.NEWMARK@MARRIOTT.COM

Address	12 CUSCADEN WALK FOUR SEASONS PARK #05-04
Postcode	249694
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

AT APPLIES 1.50PM ON 31TH OF DEC MY CAR STOPPED AT RED LIGHT AT INTERSECTION OF TIONG BAHRU ROAD AND ZION ROAD. I WAS TURNING RIGHT. WHEN LIGHTS TURNED GREEN THE CAR ON MY LEFT SIDE / LANE CAME INTO MY LANE AND HIT THE LEFT SIDE OF MY CAR.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SDB11K
Vehicle Make/Model/Colour	WHITE / BENTLEY
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	NEO KWEE ENG
NRIC/Passport Number	S1218510C
Contact Number	96239909
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN


IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time: 2/1/19 9:54am



Driver's Signature
(If driver is not the policyholder)
Date & Time: 2/1/19 9:54am


Reporting Centre Personnel's Signature
Name: WONG KAREN SENG
NRIC/TIN No: G9871234



Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

at approx 1.50pm 12/31 my car stopped at red light at intersection of Truong Binh Road and Zion Road. I was turning right. When lights turned green the car on my left side/lane came into my lane and hit the left side of my car.

DECLARATION

I/We declare the foregoing particulars are true in every respect

Cheng Chuan
Policyholder's Signature
Date & Time
2/1/19 10am

Cheng Chuan
Driver's Signature
(If driver is not the policyholder)
Date & Time
2/1/19 10am

[Signature]
Reporting Centre Personnel's Signature
Name: *WANG JIAN JIAN*
NRIC/IN No: *670987145X*

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo





EMPLOYMENT PASS
Employment of Foreign Manpower Act (Chapter 91A)
Republic of Singapore

Employer
STARWOOD ASIA PACIFIC HOTELS & RESORTS PTE. LTD.



Name
NEWMARK ANDREW PAUL
Occupation
VICE PRESIDENT, HUMAN RESOURCES

Fin G3295073L	Date of Application 08-10-2017
	Date of Issue 11-12-2017
	Date of Expiry 11-12-2019



L8500312



REPUBLIC OF SINGAPORE DRIVING LICENCE

License Number: **G8295073L**

Name: **NEWMARK ANDREW PAUL**

Date of Birth: **11 Aug 1970**

Issue Date: **27 Jun 2017**

Valid Till: **25/06/2019**

002697702A

VISIT PASS

Immigration Regulations

Name
NEWMARK ANDREW PAUL



Date of Birth 11-08-1970	Sex M	Nationality AUSTRALIAN
Fin G3295073L	Date of Issue 11-12-2017	Date of Expiry 11-12-2019

YOU ARE TO SURRENDER THIS CARD WHEN IT IS CANCELLED OR HAS EXPIRED, OR WHEN A NEW CARD IS ISSUED TO YOU.



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3 Motor cars with unladen weight <= 3000kg with <= 7 passengers, exclusive of driver; and other motor vehicles with unladen weight <= 2500kg 27 Jun 2017

NP 426A





CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : Newmark Andrew Paul
 Period of Insurance : 30 Sep 2018 To 29 Sep 2019
 Engine No. : CZD248713
 Chassis No. : WAUZZZ8U8HR017206

Vehicle No. : SLG4890S
 Policy No. : 2100484847-02
 Endorsement No. :
 Issued Date : 18 Aug 2018

ABOUT THE COVER

Make/Model : AUDI Q3 1.4 TFSI (150BHP) DESIGN
 Engine Capacity/Tonnage : 1,395.00 CC Sum Insured : Market Value First Year of Registration : 2016
 Driver Restriction : NA Off Peak Car : No Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive* :

- a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YEDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 186) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$800 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

Newmark Andrew Paul - \$800 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1 Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408599 E3662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

We hereby certify that the policy in which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 186), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1958 (Malaysia).

0504125251

PREMIUM LEASING -LES

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE

SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.

AUTHORISED REPRESENTATIVE

AIGSGMOBEAPP

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0036/2019/GW
Date : 9-Jan-19

Vehicle NOT in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Newmark Andrew Paul
Address : 12 Cuscaden Walk Four Seasons Park
#05-04
Singapore 249694
Telephone : 93366787
Type of Claim : Own Damage Claims
Policy No. : 2100484847-02
Vehicle No : **SLG 4890 S**
Model Code : Audi Q3 1.4 TFSI
Model / Year : Sep-16
Engine No : CZD 248713
Chassis No : WAUZZZ8UBHR017206
Mileage : -
Date In :
Liability : -
Excess Cost : -
Estimated By : Allan Wu
Accident Date : 31-Dec-18
Place of Accident : Intersection of Tiong Bahru Rd & Zion Rd

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLG 4890 S

S/N	Nature of Jobs	Estimated Charges
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓
2	To dismantle and renew front bumper and lhs front fender. Re-organise crash management components. Reinstall all parts removed.	\$ 2,100.00 1000 ✓
3	To respray front bumper, lhs front fender and front lh door.	\$ 2,500.00 1650 ✓
4	To replacement tyre rim and carry out alignment test.	S/N \$ 280.00 ✓
5	To carry out diagnostic check.	S/N \$ 192.00 ✓
TOTAL LABOUR CHARGES		: \$ <u>5,432.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLG 4890 S

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>Repair</i>	\$ 1,788.00	*. ?X
2	FRONT BUMPER AIR GUIDE GRILLE-LH <i>Not on</i>	\$ 139.00	*
3	FRONT BUMPER SPOILER <i>cut</i>	\$ 349.00	✓ 279.20
4	FRONT FENDER-LH <i>Dented</i>	\$ 824.00	✓ 658.80
5	FRONT FENDER BRACKET-LH <i>Not on</i>	\$ 75.00	?
6	FRONT FENDER BRACE-LH <i>Not on</i>	\$ 96.00	?
7	FRONT WHEEL HOUSING LINER-LH <i>Not on</i>	\$ 223.00	* ✓
8	FRONT WHEEL HOUSING LINET ATTACHMENT PARTS-LH <i>Not on</i>	\$ 139.00	* ✓
9	FRONT WHEEL SPOILER-LH <i>Not on</i>	\$ 66.00	* ✓
11	FRONT WHEEL COVER -LH/RH <i>LH cut, RH not</i>	2 \$ 472.00	✓ 371.60
12	FRONT RIM - LH <i>cut</i>	TBC	✓ 555.20
13	SUNDRIES <i>Not on</i>	\$ 300.00	? 19.20
TOTAL SPARE PARTS		\$ 4,471.00	
TOTAL LABOUR CHARGES		\$ 5,432.00	
GRAND TOTAL		\$ 9,903.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

10058.10

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : *Adrian Ling.*
Surveyed Date : *09/01/19.*
Authorised Date :
Excess Cost :
Liability :
Remarks : *Authorised Repairs, 04 Days.*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0036/2019/GW
Date : 9-Jan-19

Vehicle NOT in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian

4 days - ok - jb - 4 Mar.19

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Newmark Andrew Paul
Address : 12 Cuscaden Walk Four Seasons Park
#05-04
Singapore 249694
Telephone : 93366787
Type of Claim : Own Damage Claims
Policy No. : 2100484847-02
Vehicle No : **SLG 4890 S**
Model Code : Audi Q3 1.4 TFSI
Model / Year : Sep-16
Engine No : CZD 248713
Chassis No : WAUZZZ8U8HR017206
Mileage : -
Date In :
Liability : -
Excess Cost : -
Estimated By : Allan Wu
Accident Date : 31-Dec-18
Place of Accident : Intersection of Tiong Bahru Rd & Zion Rd

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLG 4890 S

S/N	Nature of Jobs	Estimated Charges	
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N \$ 360.00	\$ 360.00
2	To dismantle and renew front bumper and lhs front fender. Re-organise crash management components. Reinstall all parts removed.	\$ 2,100.00	\$ 1,000.00
3	To respray front bumper, lhs front fender and front lh door.	\$ 2,500.00	\$ 1,650.00
4	To replacement tyre rim and carry out alignment test.	S/N \$ 280.00	\$ 280.00
5	To carry out diagnostic check.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		\$ 5,432.00	\$ 3,482.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLG 4890 S

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER	\$ 1,788.00	
2	FRONT BUMPER AIR GUIDE GRILLE-LH	\$ 139.00	
3	FRONT BUMPER SPOILER	\$ 349.00	\$ 279.20
4	FRONT FENDER-LH	\$ 824.00	\$ 658.80
5	FRONT FENDER BRACKET-LH	\$ 75.00	
6	FRONT FENDER BRACE-LH	\$ 96.00	
7	FRONT WHEEL HOUSING LINER-LH	\$ 223.00	
8	FRONT WHEEL HOUSING LINET ATTACHMENT PARTS-LH	\$ 139.00	
9	FRONT WHEEL SPOILER-LH	\$ 66.00	
11	FRONT WHEEL COVER -LH/RH	2 \$ 472.00	\$ 377.60
12	FRONT RIM - LH	\$ 694.00	\$ 555.20
13	SUNDRIES	\$ 300.00	\$ 19.20
	TOTAL SPARE PARTS	\$ 5,165.00	\$ 1,890.00
	TOTAL LABOUR CHARGES	\$ 5,432.00	\$ 3,482.00
	GRAND TOTAL	\$ 10,597.00	\$ 5,372.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SLG 4890 S

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PAOD/0036/2019/MAS

1 April 2019

Dear Sir,

RE: INSURANCE CLAIM FOR SLG 4890 S, Audi Q3 1.4 TFSI S-Tro

With reference to the above-mentioned vehicle, no. **SLG 4890 S**, claimant, **Mr. Newmark Andrew Paul**, please find the related document per attached.

1. A copy of the Original invoice no. 85013626 – S\$4,892.04
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SLG 4890 S

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183



Premium Automobiles Pte Ltd

Acad Centre Singapore
281 Alexandra Road
Singapore 119938
Main Telephone: 6342 2223
Fax: 6471 3233
Page 2 13128

Alexandra Service Centre
281 Alexandra Road
Singapore 119938
Telephone: 6342 2223
Telex: 6471 1022

Ubi Service Centre
55 Ubi Road 1
Singapore 408722
Telephone: 6889 3889
Telex: 6881 1181
GST Reg. No. 195902271W

Customer Service
Service Appointment
24 Hour Breakdown Service
5346 2323
9828 1223
customer.care@premiumauto.com.sg

INSURANCE INVOICE

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoices: 85013625 Date: 25/03/2019 Order: SL64890S Term: 30	Account: A0006 IT 01 AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SL64890S (V 31233) Regn Date: 30/09/2016 Mileage: 9145 WIP No.: 30580
 Model: Q3 1.4 TFSI S tronic BUGAIX Chassis: WAUZZT8UBH017206 Engine: CZD 246713 Dept: U
 USB No.:
 You have been assisted by :- UB-Jiayee (33)

		Details		Qty	Unit Price	Amount
X	ABU0821105	FENDER	Less 020%	1.00	623.50	658.80
X	ABU0807061N 4UB	FR. SPOILER	Less 020%	1.00	343.00	279.20
X	ABU0801025S	(R) SKIRTM 17" C2M 1	Less 020%	1.00	694.00	555.20
X	AN 0161857	POP-RIVET	Less 020%	8.00	3.00	19.20
X	ABU0853717 4UB	COVER	Less 020%	1.00	236.00	188.80
X	ABU0853718 4UB	COVER	Less 020%	1.00	236.00	188.80

Parts	1,890.00		Sub-Total	4,572.00
Labour	0.00			
Sublet	3,482.00		7% GST	320.04
Menus	0.00			
Lubricant	0.00		Grand Total	4,892.04



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Customer



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 119938
Main Telephone: 6838 2221
Main Telefax: 6471 2731
Page 1 13:38

Alexandra Service Centre
281 Alexandra Road
Singapore 119938
Telephone: 6588 2221
Fax: 6475 1021

Ubi Service Centre
55 Ubi Road 1
Singapore 408722
Telephone: 6189 2221
Fax: 6471 7127
GST Reg. No. 199902271W

Customer Service
Service Appointment: 6386 2333
24 Hour Breakdown Service: 9628 1233
Email: customer.care@premiumauto.com.sg

INSURANCE INVOICE

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079128 079128	Invoices: 85812626 Date: 25/03/2015 Order: SLS48905 Term: 30	Accounts: 00006 IT 01 AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079128
---	---	---

Regn No.: SLS48905 (V 31233)	Regn Date: 30/09/2016	Mileage: 9145	WIP No.: 38580
Model: Q3 1.4 TFSI S tronic SUBARI	Chassis: WAUZZZ78U8HR017206	Engine: CZD 246713	Dept: U
WSB No.: You have been assisted by :- UB-Jiayee (33)			

		Details	Qty	Unit Price	Amount
0	EXC	M: 8888 Insurance Excess/Liability	-888.00	1.00	-888.00
S	BODYWORK	M: TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	358.00	1.00	358.00
S	BODYWORK	M: TO DISMANTLE AND RENEW FRONT FENDER, REPAIR FRONT BUMPER, REORGANISE CRASH MANAGEMENT COMPONENTS, REINSTALL ALL PARTS REMOVED	1000.00	1.00	1,000.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER, LHS FRONT FENDER AND LHS FRONT DOOR	1658.00	1.00	1,658.00
S	BODYWORK	M: TO REPLACEMENT LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	288.00	1.00	288.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
Sub-Total					
7% GST					
Grand Total					

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SLG 4890 S

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0036/2019/SM
14TH January 2019

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

total pages

RE : CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER


Make & Model : Audi Q3 1.4 TFSI S TRONIC
Vehicle Chassis No. : WAUZZZ8U8HR017206
Vehicle Regn No. : **SLG 4890 S**
Vehicle Mileage : 9140 KM
Vehicle Owner : Mr. Newmark Andrew Paul
Certificate No : 2100484847-02
Own Damage Excess : S\$ 856.00 (Inclusive 7% GST)
Accident Date : 31/12/2018
Place : Tiong Bahru Road
Repair Cost : \$ 4,892.04
WIP No. : 38580
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature :



Time :

5pm

Date :

14/2/19



EMPLOYMENT PASS
Employment of Foreign Manpower Act (Chapter 91A)
Republic of Singapore

Employer
STARWOOD ASIA PACIFIC HOTELS & RESORTS PTE. LTD.



Name
NEWMARK ANDREW PAUL
Occupation
VICE PRESIDENT, HUMAN RESOURCES

FIN
G3295073L Date of Application
08-10-2017
Date of Issue
11-12-2017
Date of Expiry
11-12-2019



L8500312

REPUBLIC OF SINGAPORE DRIVING LICENCE



License Number **G3295073L**

NEWMARK ANDREW PAUL

Date of Birth **11 Aug 1970**

Issue Date **27 Jun 2017**

Valid Until **25/06/2019**



VISIT PASS

Immigration Regulations

Name
NEWMARK ANDREW PAUL



Date of Birth	Sex	Nationality
11-08-1970	M	AUSTRALIAN
FIN	Date of Issue	Date of Expiry
G3295073L	11-12-2017	11-12-2019

YOU ARE TO SURRENDER THIS CARD WHEN IT IS CANCELLED OR HAS EXPIRED, OR WHEN A NEW CARD IS ISSUED TO YOU.



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class	Motor cars with unladen weight \leq 3000kg with \leq 7 passengers, exclusive of driver; and other motor vehicles with unladen weight \leq 2500kg	EFFECTIVE DATE
Class 3		27 Jun 2017

NP 425A



License No: G3295073L



CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : Newmark Andrew Paul
Period of Insurance : 30 Sep 2018 To 29 Sep 2019
Engine No. : CZD248713
Chassis No. : WAUZZZ8U8HR017206

Vehicle No. : SLG4890S
Policy No. : 2100484847-02
Endorsement No. :
Issued Date : 18 Aug 2018

ABOUT THE COVER

Make/Model : AUDI Q3 1.4 TFSI (150BHP) DESIGN
Engine Capacity/Tonnage : 1,395.00 CC
Driver Restriction : NA
Person or Classes of Persons Entitled to Drive* :
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2016
Insuring with COE/PARF : Yes

a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$800 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

Newmark Andrew Paul - \$800 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662333

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125251

PREMIUM LEASING -LES

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE
SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

M. Anile

AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

AIGSGMOBLEAPP

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 Jan 2019		09 Jan 2019 16:37 Edit Adj Rpt	S\$5,372.00 Edit Estimates	S\$5,372.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	NEWMARK ANDREW PAUL , ID: G3295073L, Tel: +6593366787, Email: ANDREW.NEWMARK@MARRIOTT.COM								
Vehicle Reg. No.:	SLG4890S	Date of Loss:	31/12/2018 13:00 - :59 [27 Months and 1 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 6407837567SG	Policy/Cover Note No.:	2100484847-02 (Comprehensive)						
		Excess:	S\$800.00						
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Dally Amri, Mimi Zarina] MimiZarina.DallyAmri@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 18/01/2019]								
Driver/Custodian:	NEWMARK ANDREW PAUL (48 / Male), NRIC: G3295073L, Tel: +6593366787 Email: ANDREW.NEWMARK@MARRIOTT.COM								
ASSOCIATED MAIL RECEIVED				View All	Compose Case Mail				
• AIG_SG (17/01/2019): SLG4890S / OD / 31/12/2018 / Coverage & Excess update									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLG4890S (6407837567SG)
OD
Dec 31 2018 1:50PM
[NEWMARK ANDREW PAUL]
Premium Automobiles Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View View in Browser <input type="button" value="v"/>	
Photos/Images												3 per page <input type="button" value="v"/>		<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print											
1	21/03/19 17:03	General View		Load JPG	<input checked="" type="checkbox"/>											
2	21/03/19 17:03	General View		Load JPG	<input checked="" type="checkbox"/>											
3	21/03/19 17:03	General View		Load JPG	<input checked="" type="checkbox"/>											
4	21/03/19 17:03	General View		Load JPG	<input checked="" type="checkbox"/>											
5	21/03/19 17:03	General View		Load JPG	<input checked="" type="checkbox"/>											
6	21/03/19 17:03	General View		Load JPG	<input checked="" type="checkbox"/>											
7	21/03/19 17:03	General View		Load JPG	<input checked="" type="checkbox"/>											
8	21/03/19 17:03	General View		Load JPG	<input checked="" type="checkbox"/>											
9	21/03/19 17:03	General View		Load JPG	<input checked="" type="checkbox"/>											
10	21/03/19 17:03	General View		Load JPG	<input checked="" type="checkbox"/>											
11	21/03/19 17:03	General View		Load JPG	<input checked="" type="checkbox"/>											
12	21/03/19 17:03	General View		Load JPG	<input checked="" type="checkbox"/>											
13	21/03/19 17:03	General View		Load JPG	<input checked="" type="checkbox"/>											
14	21/03/19 17:03	General View		Load JPG	<input checked="" type="checkbox"/>											
15	21/03/19 17:03	General View		Load JPG	<input checked="" type="checkbox"/>											
16	21/03/19 17:03	General View		Load JPG	<input checked="" type="checkbox"/>											
17	21/03/19 17:03	General View		Load JPG	<input checked="" type="checkbox"/>											
18	21/03/19 17:03	General View		Load JPG	<input checked="" type="checkbox"/>											
Documentation												1 per page <input type="button" value="v"/>		<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print											
1	11/01/19 09:02	estimate		Load PDF												
2	11/01/19 09:02	Certificate of Insurance		Load PDF												
3	11/01/19 09:02	Driver's Driving License and NIRC		Load PDF												
4	11/01/19 09:02	Singapore Accident Statement		Load PDF												
5	16/01/19 16:51	Foreign Driving License		Load PDF												

Linked Accident Report Documents

												View View in Browser <input type="button" value="v"/>			
Assessment Reports												1 per page <input type="button" value="v"/>		<input checked="" type="checkbox"/>	
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print										
1	02/01/19 15:51	Accident Statement		Load HTM											
2	03/01/19 17:36	Addendum Sheet		Load JPG	<input checked="" type="checkbox"/>										
3	03/01/19 17:37	Accident Statement Addm. #1		Load HTM											
Photos/Images												3 per page <input type="button" value="v"/>		<input checked="" type="checkbox"/>	
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print										
1	02/01/19 14:44	Accident Photo		Load JPG	<input checked="" type="checkbox"/>										
2	02/01/19 14:44	Accident Photo		Load JPG	<input checked="" type="checkbox"/>										
3	02/01/19 14:44	Accident Photo		Load JPG											

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
				<input checked="" type="checkbox"/>
4	02/01/19 14:44	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	02/01/19 14:44	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	02/01/19 14:44	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
7	02/01/19 14:44	Accident Photo	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	02/01/19 14:38	Sketch Plan	Load JPG	<input checked="" type="checkbox"/>
2	02/01/19 14:38	Sketch Plan #2	Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG19000538/ATBQ2

Date: 05/04/2019

REFERENCE

Insured/Claimant: NEWMARK ANDREW PAUL Policy No: 2100484847-02
Date of Loss: 31/12/2018 Nature of Claim: OD Claim No: 6407837567SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLG4890S**
Make & Model: AUDI Q3, 1.4 TFSI (A) Engine No: CZD248713
Reg. Date: 30/09/2016 (Man. Year: 2016) Chassis No: WAUZZZ8U8HR017206
Colour: Gold Odometer: 8924 km
Engine Capacity: 1395 cc
Market Value/New Car Price: S\$100,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55 R17 Rear Tyre Size: 235/55 R17
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,026.20	1,890.00	3,136.20	62.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,432.00	3,482.00	1,950.00	35.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,458.20	5,372.00	5,086.20	48.63
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	9,658.20	4,572.00	5,086.20	52.66
+ GST 7.00/7.00% (S\$)	676.07	320.04	356.03	52.66
Nett Amount (S\$)	10,334.27	4,892.04	5,442.23	52.66

INSPECTION

Date of Assignment: 09/01/2019
Date Inspected: 09/01/2019 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	1,788.00 FS	*- FS
2	1		*FRONT BUMPER AIR GUIDE GRILLE -LH	Not Necessary	139.00 FS	*- FS
3	1		*FRONT BUMPER SPONGE	Cut	349.00 FS	*279.20 FS
4	1		*FRONT FENDER-LH	Dented	824.00 FS	*658.80 FS
5	1		*FRONT FENDER BRACKET-LH	Not Necessary	75.00 FS	*- FS
6	1		*FRONT FENDER BRACE-LH	Not Necessary	96.00 FS	*- FS
7	1		*FRONT WHEEL HOUSING LINER-LH	Not Necessary	223.00 FS	*- FS
8	1		*FRONT WHEEL HOUSING LINET ATTACHMENT PARTS-LH	Not Necessary	139.00 FS	*- FS
9	1		*FRONT WHEEL SPOILER-LH	Not Necessary	66.00 FS	*- FS
10	2		*FRONT WHEEL COVER-LH/RH	N/S Cut / O/S Necessary	472.00 FS	*377.60 FS
11	1		*FRONT RIM -LH	Cut	555.20 FS	*555.20 FS
12	1		*SUNDRIES	Necessary	300.00 FS	*19.20 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 5,026.20 1,890.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS ,HORNS ,FOG LAMPS ,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO DISMANTLE AND RENEW FRONT BUMPER AND LHS FRONT FENDER.RE-ORGANISE CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	New	2,100.00	1,000.00
3	TO RESPRAY FRONT BUMPER ,LHS FRONT FENDER AND FRONT LH DOOR	New	2,500.00	1,650.00
4	TO REPLACEMENT TYRE RIM AND CARRY OUT ALIGNMENT TEST	New	280.00	280.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			5,432.00	3,482.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >