

Veron Chen (LKKAUTO)

From: glory.tan@premiumauto.com.sg
Sent: Tuesday, 29 January 2019 11:52 AM
To: SUR
Cc: Adrian Ling (LKKAUTO); 'Claims'
Subject: Check item photos for SLZ 1749 M
Attachments: WhatsApp Image 2019-01-29 at 11.04.53 AM.jpeg; WhatsApp Image 2019-01-29 at 11.05.01 AM.jpeg; WhatsApp Image 2019-01-29 at 11.05.07 AM.jpeg; WhatsApp Image 2019-01-29 at 11.05.13 AM.jpeg; WhatsApp Image 2019-01-29 at 11.05.25 AM.jpeg; WhatsApp Image 2019-01-29 at 11.05.34 AM.jpeg; WhatsApp Image 2019-01-29 at 11.05.45 AM.jpeg; WhatsApp Image 2019-01-29 at 11.05.58 AM.jpeg; WhatsApp Image 2019-01-29 at 11.06.05 AM.jpeg; WhatsApp Image 2019-01-29 at 11.06.21 AM.jpeg; WhatsApp Image 2019-01-29 at 11.06.30 AM.jpeg; WhatsApp Image 2019-01-29 at 11.06.36 AM.jpeg; WhatsApp Image 2019-01-29 at 11.06.43 AM.jpeg; WhatsApp Image 2019-01-29 at 11.06.51 AM.jpeg; WhatsApp Image 2019-01-29 at 11.08.56 AM.jpeg; WhatsApp Image 2019-01-29 at 11.09.06 AM.jpeg; WhatsApp Image 2019-01-29 at 11.09.22 AM.jpeg

Dear all,

Please refer to the attached for SLZ 1749 M check item photos.

Item number in marked estimate,

- 3. Front bumper securing strip
- 5. Front bumper air guide-rh
- 7. Front bumper guide section-rh
- 15. Front fender closing element-rh
- 16. Front fender bracket-rh
- 17. Front fender brace -rh
- 22. Front wheel spoiler-rh

Thank you.

Glory Tan

Bodyworks Department

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 f. +65 6841 1183

e. glory.tan@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223