

REF: CC3/ALH19000538 / Avber

ASSIGNMENT

From _____ Date: _____

Estimated Cost: _____

☒ OD / ☐ TP / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV

To inspect Vehicle No: _____

at Workshop mis _____

of _____

Insured: _____

Policy No. 1800042831

Claims No. _____

Sum Insured: _____ Excess: 600

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 160K.

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 5 ^{hrs} days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLZ1749M Yr Regn: 2018 / Apr

Type: ☒ M/Car / ☐ M/Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or _____

Make: Audi A4 sedan. cc 1984

Colour: Grey. A/C: Insured / Std / NI / NA

Sp Reading: 10136. T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAU222F43JA137437

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt orModl: Nil / ☒ S/Rim / ☐ STD A/Rim or

Tyre Size: F: 225/50R17.

R: 225/50R17.

BS / DUN / EXNOVA ☒ GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. 22/12/18 D.O.I. 09/01/19

Survey held at Premium.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front O/S.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

OD AIG.

10/1/19 Revert via merimen

11/1/19 Rece approved \$12,903 from Victor by merimen

11/1/19 Informed Tony c/a ex \$600 by email

25/3/19 final fig \$11,221.76 (Red 6628.24, 3792) confirmed by email

RECEIVED 05 APR 2019

Date/Time, File Pass to?

☐ : Prel. Report

Days Of Repair: 5

1) _____

☐ : Final Report

Resurvey No. of Trip: 1

Date/Time, File Return to?

Survey Fee

2) 5/4 - typist

Add Fee: ☐ : Site Insp (\$

Transportation

☐ : Interview (\$

Photos

☐ : Tech. Invs (\$

Others

☐ : Weekend (\$

Report Format: merimen

Lump Sum / I.B.I: (\$ 11,221.76

TOTAL

200

10

210

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 11 January 2019 4:04 PM
To: Claims Dept
Cc: SUR; (nora.khai@premiumauto.com.sg)
Subject: SLZ 1749M-DOA: 22/12/2018 (AIG OD)

Dear Tony,

As instructed by our client , please proceed to repair the **insured vehicle SLZ 1749M (Excess S600/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

***SLZ1749M (2366897869SG)**

OD

Dec 22 2018 1:10PM

[NG ING-YONG BRIAN (HUANG YINGRONG BRIAN)]

Premium Automobiles Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 11/01/2019 15:32 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$12903.00) - SLZ1749M - Claim Handler: Dally Amri, Mimi Zarina

Approved:12903.00:Re-inspection to be done for damage check and supplementary items / labour.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Loh, Chee-Heng

Date: 10 Jan 2019

Preliminary Advice

Vehicle No	: SLZ1749M	Accident Date	: 22/12/2018
Make	: AUDI A4	Policy No.	: 1800042831
Assignment Date	: 09/01/2019	Excess	: S\$0.00
Date of Inspection	: 09/01/2019	Est. Duration of Repair	: 5.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	17,850.00
Revised Amount	:S\$	12,903.00
Check Items (Estimated)	:S\$	754.00
Total	:S\$	13,657.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	160,000.00
COE / PARF Rebate	:S\$	63,777.00
Salvage Value	:S\$	
Margin for Repair	:S\$	96,223.00

Remarks

(X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

() Other comments :

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9521F
Vehicle Details	
Vehicle No.:	SLZ1749M
Vehicle to be Exported:	No
Intended Deregistration Date:	09 Jan 2019
Vehicle Make:	AUDI
Vehicle Model:	A4 SEDAN 2.0 TFSI S TRONIC (NAV)
Primary Colour:	Grey
Manufacturing Year:	2018
Engine No.:	CVK057562
Chassis No.:	WAUZZZF43JA137437
Maximum Power Output:	140.0 kW (187 bhp)
Open Market Value:	\$33,421.00
Original Registration Date:	25 Apr 2018
First Registration Date:	25 Apr 2018
Transfer Count:	0
Actual ARF Paid:	\$38,790.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Apr 2028
PARF Rebate Amount:	\$29,092.00
Intended COE Rebate Details	
COE Expiry Date:	24 Apr 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$37,330.00
COE Rebate Amount:	\$34,685.00
Total Rebate Amount:	\$63,777.00

The information contained herein is correct as at 09 Jan 2019

OK



CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : NG ING-YONG BRIAN (HUANG YINGRONG BRIAN)
Period of Insurance : 25 Apr 2018 To 25 Apr 2020
Engine No. : CVK 057562
Chassis No. : WAUZZZF43JA137437

Vehicle No. : SLZ1749M
Policy No. : 1800042831
Endorsement No. :
Issued Date : 22 May 2018

ABOUT THE COVER

Make/Model : AUDI A4 Sedan 2.0 TFSI S tronic
Engine Capacity/Tonnage : 1,984.00 CC
Driver Restriction : NA
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2018
Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive*

a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.
You have to pay an additional sum of \$3,000 as "Inexperienced Driver Excess" ("IDR") if You are or Your Authorised Driver (named or unnamed) has less than 2 years' driving experience.

Age Condition : 40 years old and above

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
This Policy does not cover use for hire or reward, driving tuition, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 85 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
Fire - \$0 Own Damage - \$1600 Theft - \$0 Flood Cover - \$0

Section 2
Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

NG ING-YONG BRIAN (HUANG YINGRONG BRIAN) - \$1600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles(Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1958 (Malaysia).

0604125261

PREMIUM LEASING -CYS

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE

SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

M. Anik

AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

Stephany Lee

IMPORTANT: KEEP THIS DOCUMENT IN YOUR CAR AT ALL TIMES.

What can the 24-hour AIG Auto Emergency Hotline provide for you?

- Immediate assistance after an accident
- Emergency breakdown service
- Towing service (accident or non-accident related)
- Advice on Motor Claims procedures
- Medical Referral Assistance

If no one is injured in the accident:

- You are not required to make any police report.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s).
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

If the accident involves injuries or damage to government property & vehicles, foreign registered vehicles or non-injury hit & run case:

- Report the accident to the police, providing full details of the circumstances of the accident.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s), if applicable.
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

What should I do in the event of an accident?

- Keep calm and move your car to a safe place.
- Do not admit or discuss fault or blame with the other party(ies).
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.
- Submit Writ/Summons/Correspondences from third party(ies) to AIG immediately.

LOSS OF USE CAR REPLACEMENT BENEFIT

Applicable only if this benefit is included in your motor insurance. Please refer to your Policy Schedule for details. Policy terms and conditions apply. Please call our customer service hotline number **(65) 6419-3000** for assistance.

The Certificate of Insurance (CI) should be produced without demand when collecting the Rental Car and the Rental Car Company reserves the right to verify the identity of the holder. The CI is the property of AIG and its use is subject to the terms and conditions contained in the Loss of Use Endorsement under the policy issued to the policyholder.

Steps to activate Loss of Use Car Replacement Benefit and Important Information

1. To activate your loss of use car replacement, please contact the Rental Car Company (listed below) after filing/reporting your accident claim.
2. Your rental car will be made available within **5** working hours of activation with the Rental Car Company.
3. At the time of collection of the Rental Car, the **original** insurance policy and schedule issued by AIG, a copy of the Accident Report from **Audi Customer Service Centre** must be produced.
4. The number of days is based on the period your vehicle is in the repair workshop unless the number of days of loss of use entitlement is stated in the Policy.
5. Rental cars are strictly for use in Singapore only.
6. Extension of rental beyond repair period approved by AIG surveyor will be chargeable by the Rental Car Company on per day basis.
7. Upgrade of Rental Car is available upon request subject to additional charges by the Rental Car Company.

Rental Car Company: Popular Rent A Car Pte. Ltd.

Activation Hotline: 67428888

501 Gulleimard Road Singapore 399840

Operation Hours: Monday to Friday: 9am to 6pm Saturday (Half Day): 9am to 4pm

*The Rental Car Company's Terms & Conditions apply (i.e., refundable security deposit, excess liability for the Rental Car, Collision Damage Waiver, etc.)

IMPORTANT NOTICE

If you sell your motor vehicle, this Notice is **IMPORTANT** and **MUST** be complied with. Policyholders are hereby warned that under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.99), it shall be unlawful for any person to use or cause or permit any other person to use a motor vehicle without a valid policy of insurance under the Act.

The Policyholder is further warned that on the sale of a motor vehicle, they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.88).

This Policy will cease to be valid once the motor vehicle has been sold to another person unless the transfer of interest has been duly notified to and agreed to by the insurance company concerned. If the insurance company agrees to cover the new owner, they will issue a new Certificate of Insurance in the new owner's name. The premium chargeable may vary according to the new owner's profile.

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number: **57729521F**

Name

NG ING-YONG BRIAN
(HUANG YINGRONG BRIAN)

Birth Date: **10 Oct 1977**

Issue Date: **30 Aug 2005**



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES

PASS DATE

Class 3 Motor Cars and Motor Tractors the weight of
which unladen does not exceed 2500 kilograms

25 Oct 1995

NP 429A



Licence No: 57729521F

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/01/2019 18:18
Date Of Accident	22/12/2018 13:10
Exact Location Of Accident	CAR PARK AT APT BLK 313 SHUNFU ROAD # 08-295
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLZ1749M
Insured/Policyholder	
Name Of Registered Owner	NG ING-YONG BRIAN (HUANG YINGRONG BRIAN)
NRIC No	S7729521F
Email Address	BRIAN.NG.INGYONG@GMAIL.COM
Mobile Phone No	(LOCAL) +65-91278078
Alternative Phone No	OFFICE-97123649

Vehicle Particulars

Manufacturer	AUDI
Model	A4 SEDAN 2.0 TFSI
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1800042831
Cover Note Number	

Driver

Name of Driver	NG ING-YONG BRIAN (HUANG YINGRONG BRIAN)
NRIC No	S7729521F
Date Of Birth	10/10/1977
Occupation	INDOOR
Date Of Driving Pass	25/10/1995
Driving Experience	23 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-91278078
Fax Number	
Contact Number	OFFICE-97123649
Email Address	BRIAN.NG.INGYONG@GMAIL.COM

Address	313 SHUNFU ROAD #08-295
Postcode	570313
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	POLICE STATION OF ORIGIN : TANGLIN VISION HQ 21 KAMPONG JAVA ROAD SINGAPORE 228892
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO THE SKETCH PLAN AND POLICE REPORT : E/20181223/7021

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLX6622Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

1. The first group of authors (e.g., Berman et al., 1986; Berman &
 2.
 3.
 4.
 5.
 6.
 7.
 8.
 9.
 10.
 11.
 12.
 13.
 14.
 15.
 16.
 17.
 18.
 19.
 20.
 21.
 22.
 23.
 24.
 25.
 26.
 27.
 28.
 29.
 30.
 31.
 32.
 33.
 34.
 35.
 36.
 37.
 38.
 39.
 40.
 41.
 42.
 43.
 44.
 45.
 46.
 47.
 48.
 49.
 50.
 51.
 52.
 53.
 54.
 55.
 56.
 57.
 58.
 59.
 60.
 61.
 62.
 63.
 64.
 65.
 66.
 67.
 68.
 69.
 70.
 71.
 72.
 73.
 74.
 75.
 76.
 77.
 78.
 79.
 80.
 81.
 82.
 83.
 84.
 85.
 86.
 87.
 88.
 89.
 90.
 91.
 92.
 93.
 94.
 95.
 96.
 97.
 98.
 99.
 100.
 101.
 102.
 103.
 104.
 105.
 106.
 107.
 108.
 109.
 110.
 111.
 112.
 113.
 114.
 115.
 116.
 117.
 118.
 119.
 120.
 121.
 122.
 123.
 124.
 125.
 126.
 127.
 128.
 129.
 130.
 131.
 132.
 133.
 134.
 135.
 136.
 137.
 138.
 139.
 140.
 141.
 142.
 143.
 144.
 145.
 146.
 147.
 148.
 149.
 150.
 151.
 152.
 153.
 154.
 155.
 156.
 157.
 158.
 159.
 160.
 161.
 162.
 163.
 164.
 165.
 166.
 167.
 168.
 169.
 170.
 171.
 172.
 173.
 174.
 175.
 176.
 177.
 178.
 179.
 180.
 181.
 182.
 183.
 184.
 185.
 186.
 187.
 188.
 189.
 190.
 191.
 192.
 193.
 194.
 195.
 196.
 197.
 198.
 199.
 200.
 201.
 202.
 203.
 204.
 205.
 206.
 207.
 208.
 209.
 210.
 211.
 212.
 213.
 214.
 215.
 216.
 217.
 218.
 219.
 220.
 221.
 222.
 223.
 224.
 225.
 226.
 227.
 228.
 229.
 230.
 231.
 232.
 233.
 234.
 235.
 236.
 237.
 238.
 239.
 240.
 241.
 242.
 243.
 244.
 245.
 246.
 247.
 248.
 249.
 250.
 251.
 252.
 253.
 254.
 255.
 256.
 257.
 258.
 259.
 260.
 261.
 262.
 263.
 264.
 265.
 266.
 267.
 268.
 269.
 270.
 271.
 272.
 273.
 274.
 275.
 276.
 277.
 278.
 279.
 280.
 281.
 282.
 283.
 284.
 285.
 286.
 287.
 288.
 289.
 290.
 291.
 292.
 293.
 294.
 295.
 296.
 297.
 298.
 299.
 300.
 301.
 302.
 303.
 304.
 305.
 306.
 307.
 308.
 309.
 310.
 311.
 312.
 313.
 314.
 315.
 316.
 317.
 318.
 319.
 320.
 321.
 322.
 323.
 324.
 325.
 326.
 327.
 328.
 329.
 330.
 331.
 332.
 333.
 334.
 335.
 336.
 337.
 338.
 339.
 340.
 341.
 342.
 343.
 344.
 345.
 346.
 347.
 348.
 349.
 350.
 351.
 352.
 353.
 354.
 355.
 356.
 357.
 358.
 359.
 360.
 361.
 362.
 363.
 364.
 365.
 366.
 367.
 368.
 369.
 370.
 371.
 372.
 373.
 374.
 375.
 376.
 377.
 378.
 379.
 380.
 381.
 382.
 383.
 384.
 385.
 386.
 387.
 388.
 389.
 390.
 391.
 392.
 393.
 394.
 395.
 396.
 397.
 398.
 399.
 400.
 401.
 402.
 403.
 404.
 405.
 406.
 407.
 408.
 409.
 410.
 411.
 412.
 413.
 414.
 415.
 416.
 417.
 418.
 419.
 420.
 421.
 422.
 423.
 424.
 425.
 426.
 427.
 428.
 429.
 430.
 431.
 432.
 433.
 434.
 435.
 436.
 437.
 438.
 439.
 440.
 441.
 442.
 443.
 444.
 445.
 446.
 447.
 448.
 449.
 450.
 451.
 452.
 453.
 454.
 455.
 456.
 457.
 458.
 459.
 460.
 461.
 462.
 463.
 464.
 465.
 466.
 467.
 468.
 469.
 470.
 471.
 472.
 473.
 474.
 475.
 476.
 477.
 478.
 479.
 480.
 481.
 482.
 483.
 484.
 485.
 486.
 487.
 488.
 489.
 490.
 491.
 492.
 493.
 494.
 495.
 496.
 497.
 498.
 499.
 500.
 501.
 502.
 503.
 504.
 505.
 506.
 507.
 508.
 509.
 510.
 511.
 512.
 513.
 514.
 515.
 516.
 517.
 518.
 519.
 520.
 521.
 522.
 523.
 524.
 525.
 526.
 527.
 528.
 529.
 530.
 531.
 532.
 533.
 534.
 535.
 536.
 537.
 538.
 539.
 540.
 541.
 542.
 543.
 544.
 545.
 546.
 547.
 548.
 549.
 550.
 551.
 552.
 553.
 554.
 555.
 556.
 557.
 558.
 559.
 560.
 561.
 562.
 563.
 564.
 565.
 566.
 567.
 568.
 569.
 570.
 571.
 572.
 573.
 574.
 575.
 576.
 577.
 578.
 579.
 580.
 581.
 582.
 583.
 584.
 585.
 586.
 587.
 588.
 589.
 590.
 591.
 592.
 593.
 594.
 595.
 596.
 59


- IMPORTANT NOTICE**
1. Please report promptly the details of the accident to your local County coroner.
 2. This report must be completed by the Police Officer and by the Authorized Driver.
 3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or falsification of material facts may cause insurance companies to **deny future policy claims**.
 4. The actual and completion of this form by a motorist constitutes a true and voluntary act of policy liability and each of the statements contained.
 5. **Any false statement may be referred to the Police for prosecution.**
 6. This report will be furnished by the issuing of the full accident report agreement. Copy published by the Governor Insurance Association of Virginia (VAIR) and the Motor Vehicle Insurance Association of Virginia (MVAIA) are available upon application to the relevant parties.
 7. By the completion of this report by the motorist, you hereby consent to the issuing of this report and the giving of a copy of the report along with any available information.

8. Covered under the Personal Data Protection Act (PDPA)

³² We thank the authorizing and the German economic association of companies (VDA) for providing a dataset with information on the activities of the German manufacturing sector and for their kind support and other personal contributions.

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Handwritten text across the accident description area:

no car order to the police
Report: E/2018/223/2021

DECLARATION

(I/We declare that the foregoing is a true and correct statement of the facts.)

Officer B. Jones

Officer A. Smith

Officer C. Brown

Police Department

Police Report



**SINGAPORE
POLICE FORCE**



8/20181223/7021

1 of 2

POLICE REPORT (NP299)

Report No. E/20181223/7021

Police Station Of Origin
Tanglin Division HQ
21 Kampong Java Road SINGAPORE
228502
Tel No: 1800-3910000

Date/Time Report Made 23/12/2018 21:30	Video Report No.	Station Diary No.
Name Of Informant NG ING-YONG BRIAN	Address APT BLK 313 SHUNFU ROAD #06-296 SINGAPORE 570313	
ID Type / ID No NRIC NO / S7729521F	Contact No. Home/Office: Mobile: 91278076	
Nationality SINGAPORE CITIZEN	Email Address brian.ng.ingyong@gmail.com	
Occupation	Sex Male	Age 41
Financial/Investment adviser	Date of Birth 10/10/1977	Race Chinese
Institution/School Name	Language English	
Date/Time Of Incident 22/12/2018 13:05 - 22/12/2018 13:10	Location Of Incident APT BLK 313 SHUNFU ROAD #06-296 SINGAPORE 570313	

Brief details.

My car, an Audi A4, license plate no. SLZ 1649 M, was parked (facing out) at Shunfu Mart (MBCP SH2), where I have season parking for this car. On the evening of 22 Dec 2018 (Saturday), I went to my car to drive out for dinner. I discovered the front right-hand side of my car had been badly damaged - including the front side panel, front headlamp and front bumper. Fortunately the car comes with incident-recording front in-car camera which activates when there is movement of the car when it is parked, such as was the case here. The video shows recording of a silver mercedes C-class sedan, license plate no. SLX 6622 Y,

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 23/12/2018 21:30
Officer In-Charge Of Case	Classification Of Case:

Authentication Stamp

Police Report



**SINGAPORE
POLICE FORCE**



E/20181223/7021

2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. E/20181223/7021

driving away from the parking lot next to my car, with scratch marks and a visible dent on its rear left-hand side door and rear left-hand side bumper, at exactly 1.06pm on 22 Dec 2018. From this recording appearance of the dents on his car, and fact that the camera only activates during such incidents, I have strong reason to suspect that the driver of this car had, knowingly or unknowingly, made a miscalculation in his turning radius when exiting the lot on the right hand side of my car resulting in the damage. I am leaving on a family holiday to Japan tomorrow morning for a week but intend to follow up with action against the owner of this car to claim for the damage, after I return to Singapore on 1 Jan 2019.

Subjects Involved			
Victim			
Person Name	NG ING-YONG BRIAN		
ID Type	NRIC NO	ID No	S7729521F
Gender	Male	Age	41
Race	Chinese	Language	English
Occupation	Financial/Investment adviser	Address Type	
Address	APT BLK 313 SHUNFU ROAD		Mobile No
	#08-295 SINGAPORE 570313		91278078
Is Informant A	Yes		
Victim?			
Person Name NG ING-YONG BRIAN (Informant)			

Signature Of Officer Recording The Report:	Signature Of Informant:
Not applicable	The identity of the person making this report has been authenticated by SingPass. No signature is required.
Signature Of Interpreter:	Date/Time:
Not applicable	23/12/2018 21:30
Officer In-Charge Of Case:	Classification Of Case:

Authentication Stamp

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khal@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0024/2019/GW
Date : 8-Jan-19

Vehicle not IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Ng-Yong Brian (Huang Yingrong Brian)
Address : Blk 313 Shunfu Road
#08-295
Singapore 570313
Telephone : HP +6591278078
Type of Claim : Own Damage Claims
Policy No. : 1800042831
Vehicle No : **SLZ 1749 M**
Model Code : Audi A4 Sedan 2.0 TFSI
Model / Year : Apr-18
Engine No : CVK 057562
Chassis No : WAUZZZF43JA137437
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 22-Dec-18
Place of Accident : Car park at Apt Blk 313 ShunFu Road #08-295

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLZ 1749 M

S/N	Nature of Jobs	Estimated Charges
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 ✓ ✓
2	To dismantle and renew front bumper, rhs front fender and rhs headlight. Re-organise crash management components. Reinstall all parts removed.	\$ 2,100.00 1250 ✓
3	To respray front bumper and rhs front fender.	\$ 1,500.00 1100 ✓
4	To renew rhs front rim and carry out wheel alignment.	S/N \$ 280.00 ✗
5	To carry out diagnostic check.	S/N \$ 192.00 ✓ ✓
TOTAL LABOUR CHARGES		: <u>\$ 4,552.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SLZ 1749 M

S/N	Parts Description		Damage Parts & Prices	
			S/NETT	REMARKS
1	FRONT BUMPER <i>Rehanded</i>	S	1,999.00 ✓	1599.20
2	FRONT BUMPER FIXING PARTS <i>Not nec</i>	S	258.00 X	
3	FRONT BUMPER SECURING STRIP <i>Not nec</i>	S	32.00 X ✓	25.44
4	FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE <i>Not nec</i>	S	191.00 X	
5	FRONT BUMPER AIR GUIDE -RH <i>Not nec</i>	S	56.00 X ✓	44.40
6	FRONT BUMPER AIR GUIDE GRILLE -RH <i>Not nec</i>	S	123.00 X	
7	FRONT BUMPER GUIDE SECTION-RH <i>Not nec</i>	S	34.00 ? ✓	27.12
8	FRONT BUMPER FOAM FILLIER PIECE <i>Not nec</i>	S	113.00 X	
9	FRONT BUMPER CARRIER <i>Not nec</i>	S	733.00 X	
10	FRONT BUMPER SUPPORT-RH <i>Not nec</i>	S	26.00 X	
11	FRONT SENSOR <i>Not nec</i>	2 S	462.00 X	
12	FRONT SENSOR SEAL RING <i>Not nec</i>	4 S	123.00 X	
13	FRONT FENDER-RH <i>Dented</i>	S	700.00 ✓	559.60
14	FRONT FENDER ATTACHMENT PARTS-RH <i>Not nec</i>	S	48.00 ? X	
15	FRONT FENDER CLOSING ELEMENT-RH <i>Not nec</i>	S	45.00 X ✓	36.00
16	FRONT FENDER BRACKET-RH <i>Not nec</i>	S	32.00 ? X	
17	FRONT FENDER BRACE-RH <i>Bent</i>	S	107.00 ? ✓	85.60
18	FRONT FENDER COVER-RH <i>Not nec</i>	S	28.00 ✓	22.24
19	FRONT FENDER TOP COVER-RH <i>Not nec</i>	S	21.00 ✓	16.16
20	FRONT WHEEL HOUSING LINER-RH <i>Not nec</i>	S	220.00 X	
SUB-TOTAL SPARE PARTS			\$ 5,351.00	

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SLZ 1749 M

S/N	Parts Description	Damage Pa S/NETT
21	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS-RH <i>not nec</i>	\$ 82.00+
22	FRONT WHEEL SPOILER-RH <i>not nec torn</i>	\$ 66.00+ ✓ <i>52.32</i>
23	FRONT FENDER LEDGE-RH <i>not nec</i>	\$ 33.00? X
24	FRONT STONE CHIP GUARD-RH <i>nec</i>	\$ 46.00 ✓ <i>36.64</i>
25	LED HEADLIGHT-RH <i>cut</i>	\$ 7,087.00 ✓ <i>5669.60</i>
26	HEADLIGHT LIFT CYLINDER-RH <i>not nec</i>	\$ 120.00 +
27	RUBBER VALVE <i>not nec</i>	4 \$ 13.00+
28	FRONT RIM-RH <i>nec</i>	TBC ✓
29	SUNDRIES <i>nec</i>	\$ 500.00 ? ✓ <i>25.44</i>
TOTAL SPARE PARTS		\$ 13,298.00
TOTAL LABOUR CHARGES		\$ 4,552.00
GRAND TOTAL		\$ 17,850.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lim
Surveyed Date : 09/01/19
Authorised Date :
Excess Cost :
Liability :
Remarks : not Authorised, 05 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0024/2019/GW
Date	:	8-Jan-19

Vehicle not IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian
5 days - ok - 18 Mar 19

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr. Ng-Yong Brian (Huang Yingrong Brian)
Address	:	Blk 313 Shunfu Road #08-295 Singapore 570313
Telephone	:	HP +6591278078
Type of Claim	:	Own Damage Claims
Policy No.	:	1800042831
Vehicle No	:	SLZ 1749 M
Model Code	:	Audi A4 Sedan 2.0 TFSI
Model / Year	:	Apr-18
Engine No	:	CVK 057562
Chassis No	:	WAUZZZF43JA137437
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	22-Dec-18
Place of Accident	:	Car park at Apt Blk 313 ShunFu Road #08-295

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLZ 1749 M

S/N	Nature of Jobs	Estimated Charges			
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N	\$ 480.00	\$	480.00
2	To dismantle and renew front bumper, rhs front fender and rhs headlight. Re-organise crash management components. Reinstall all parts removed.		\$ 2,100.00	\$	1,250.00
3	To respray front bumper and rhs front fender.		\$ 1,500.00	\$	1,100.00
4	To renew rhs front rim and carry out wheel alignment.	S/N	\$ 280.00		
5	To carry out diagnostic check.	S/N	\$ 192.00	\$	192.00
TOTAL LABOUR CHARGES		:	<u>\$ 4,552.00</u>	<u>\$</u>	<u>3,022.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SLZ 1749 M

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER	\$ 1,999.00	\$ 1,599.20
2	FRONT BUMPER FIXING PARTS	\$ 258.00	
3	FRONT BUMPER SECURING STRIP	\$ 32.00	\$ 25.44
4	FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE	\$ 191.00	
5	FRONT BUMPER AIR GUIDE -RH	\$ 56.00	\$ 44.40
6	FRONT BUMPER AIR GUIDE GRILLE -RH	\$ 123.00	
7	FRONT BUMPER GUIDE SECTION-RH	\$ 34.00	\$ 27.12
8	FRONT BUMPER FOAM FILLIER PIECE	\$ 113.00	
9	FRONT BUMPER CARRIER	\$ 733.00	
10	FRONT BUMPER SUPPORT-RH	\$ 26.00	
11	FRONT SENSOR	2 \$ 462.00	
12	FRONT SENSOR SEAL RING	4 \$ 123.00	
13	FRONT FENDER-RH	\$ 700.00	\$ 559.60
14	FRONT FENDER ATTACHMENT PARTS-RH	\$ 48.00	
15	FRONT FENDER CLOSING ELEMENT-RH	\$ 45.00	\$ 36.00
16	FRONT FENDER BRACKET-RH	\$ 32.00	
17	FRONT FENDER BRACE-RH	\$ 107.00	\$ 85.60
18	FRONT FENDER COVER-RH	\$ 28.00	\$ 22.24
19	FRONT FENDER TOP COVER-RH	\$ 21.00	\$ 16.16
20	FRONT WHEEL HOUSING LINER-RH	\$ 220.00	
SUB-TOTAL SPARE PARTS		\$ 5,351.00	\$ 2,415.76

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Material List for Accident Vehicle Regn No.SLZ 1749 M

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Shirley Hiew (LKK Auto)

From: Boo seng yak <boojohnny@gmail.com>
Sent: Monday, 18 March 2019 2:41 PM
To: Adrian Ling; Veron Chen; sur@lkkauto.com; Carrine Leong; jiajee.yap@premiumauto.com.sg; Chang Chee Sing
Subject: FINAL REVISION - SLZ1749M - OD AIG - SURVEYED 9 JAN 19
Attachments: WhatsApp Image 2019-01-29 at 11.04.53 AM (resize).jpeg; WhatsApp Image 2019-01-29 at 11.05.01 AM (resize).jpeg; WhatsApp Image 2019-01-29 at 11.05.07 AM (resize).jpeg; WhatsApp Image 2019-01-29 at 11.05.13 AM (resize).jpeg; WhatsApp Image 2019-01-29 at 11.05.25 AM (resize).jpeg; WhatsApp Image 2019-01-29 at 11.05.34 AM (resize).jpeg; WhatsApp Image 2019-01-29 at 11.05.45 AM (resize).jpeg; WhatsApp Image 2019-01-29 at 11.05.58 AM (resize).jpeg; WhatsApp Image 2019-01-29 at 11.06.05 AM (resize).jpeg; WhatsApp Image 2019-01-29 at 11.06.21 AM (resize).jpeg; WhatsApp Image 2019-01-29 at 11.06.30 AM (resize).jpeg; WhatsApp Image 2019-01-29 at 11.06.36 AM (resize).jpeg; WhatsApp Image 2019-01-29 at 11.06.43 AM (resize).jpeg; WhatsApp Image 2019-01-29 at 11.06.51 AM (resize).jpeg; WhatsApp Image 2019-01-29 at 11.08.56 AM (resize).jpeg; WhatsApp Image 2019-01-29 at 11.09.06 AM (resize).jpeg; WhatsApp Image 2019-01-29 at 11.09.22 AM (resize).jpeg; WhatsApp Image 2019-01-30 at 11.39.27 AM (resize).jpeg; PA00242019 - SLZ 1749 M - A4 Sedan 2.0 TFSI - FRONT RHS (AIG).xls

Hi Adrian and all,

Revised estimate and checked item's photographs is attached.

Please confirm repair cost of \$11,221.76 @ 5 days of repairs.

Your early closure is well appreciated.

Best regards - jb

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 25 March 2019 1:15 PM
To: 'Boo seng yak'; Carrine Leong; jiajee.yap@premiumauto.com.sg; Chang Chee Sing; SUR
Subject: RE: FINAL REVISION - SLZ1749M - OD AIG - SURVEYED 9 JAN 19

Dear Mr Boo,

Confirm repair cost of \$11,221.76 before excess \$600 and GST @ 5 days of repairs.

Kindly send us invoice and discharge voucher for us to close file.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak <boojohnny@gmail.com>
Sent: Monday, 18 March 2019 2:41 PM
To: Adrian Ling (LKKAUTO) <adrianling@lkkauto.com>; Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; SUR <sur@lkkauto.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>; jiajee.yap@premiumauto.com.sg; Chang Chee Sing <claims@premiumauto.com.sg>
Subject: FINAL REVISION - SLZ1749M - OD AIG - SURVEYED 9 JAN 19

Hi Adrian and all,

Revised estimate and checked item's photographs is attached.

Please confirm repair cost of \$11,221.76 @ 5 days of repairs.

Your early closure is well appreciated.

Best regards - jlb

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SLZ 1749 M

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0024/2019/MAS

3 April 2019

Dear Sir,

RE: INSURANCE CLAIM FOR SLZ 1749 M, Audi A4 Sedan 2.0 TFSI

With reference to the above-mentioned vehicle, no. **SLZ 1749 M**, claimant, **Mr. Ng Ing-Yong Brian**, please find the related document per attached.

1. A copy of the Original invoice no. 85013637 – S\$11,365.28
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SLZ 1749 M

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183



INS-24 INVOICE
Company No. 159982271W
GST Reg. No. 159982271W

GST Rec. No. 19990271W

Grand Total

Customer



Premium Automobiles Pte Ltd

Add Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone: 6366 2222
Main Telex: 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone: 6366 2221
Telex: 6475 1921

Ubi Service Centre
55 Ubi Road 1
Singapore 408721
Telephone: 6366 2221
Telex: 6475 1921

Customer Service
Service Appointment
Hour breakdown Service
Email: customer.care@premiumauto.com.sg

6366 2222
6475 1921

INSURANCE INVOICE
Company: AIG
GST Reg. No. 199982271W

Page 2 15:21

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-15 SINGAPORE 079120 079120	Invoice: 05013637 Date: 27/03/2019 Order: SLZ1743M Term: 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-15 SINGAPORE 079120
---	--	--

Regn No.: SLZ1743M (V 37379) Regn Date: 25/04/2018 Mileage: 10677 WIP No.: 36385
Model: A4 SEDAN 2.0 TFSI 8M2AD6 (NRV) Chassis: WAUZZZF43JA137437 Engine: CVK 057562 Dept: U
VSB No.:
You have been assisted by :- UB-Jiayer (46)

		Details	Qty	Unit Price	Amount
X	ABW0621106A	FENDER	1.00	599.50	599.50
X	ABW08070650 BRU	COVER	1.00	1999.00	1,999.00
X	ABW0807284	GUIDE	1.00	27.12	27.12
X	ABW0621092	PLATE	1.00	36.00	36.00
X	ABW0621136C	ISU SUPPORT	1.00	85.60	85.60
X	ABW0121754	AIR DUCT	1.00	44.40	44.40
X	ABW0823746	COVER	1.00	16.16	16.16
X	ABW0807277	STRIP	1.00	25.44	25.44
X	ABW0620582C	COVER	1.00	22.24	22.24
X	ABW0653624B 909	STONEGUARD	1.00	36.54	36.54
X	AK 0161857	POP-RIVET	6.00	2.40	14.40
X	AK 0385853	RIVET	6.00	2.40	14.40
X	AK 91244001	STUD	3.00	6.54	19.62

Parts 8,199.76
Labour 0.00
Sublet 3,822.00
Menus 0.00
Lubricant 0.00

Sub-Total 10,621.76
7% GST 743.52
Grand Total 11,365.28

Received by

For & on behalf of
Premium Automobiles Pte Ltd

Customer

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SLZ1749M

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0024/2019/TF
1 February 2019

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

1 total pages

RE : CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A4 SEDAN 2.0 TFSI
Vehicle Chassis No. : WAUZZZF43JA137437
Vehicle Regn No. : SLZ1749M
Vehicle Mileage : 10677KM
Vehicle Owner : Mr. Ng Ing- Yong Brian
Certificate No : 1800042831
Own Damage Excess : \$642.00 (Inclusive GST)
Accident Date : 22 December 2018
Place : Blk 313 Shunfu Road Carpark
Repair Cost : S 11,365.28
WIP No. : 38385
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature :

Time :

Date :


1/2/19

REPUBLIC OF SINGAPORE DRIVING LICENCE

Vehicle Number: 87728521F

Male

NG SING-YONG BRIAN
(Huang Yingrong Brian)

Birth Date: 10 Oct 1977

Issue Date: 30 Aug 2009

0087871347



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES

	VALID DATE
Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms	25 Oct 1995

NP 420A

0087871347

0087871347



CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : NG ING-YONG BRIAN (HUANG YINGRONG BRIAN)
Period of Insurance : 25 Apr 2018 To 25 Apr 2020
Engine No. : CVK 057562
Chassis No. : WAUZZZF43JA137437

Vehicle No. : SLZ1749M
Policy No. : 1800042831
Endorsement No. :
Issued Date : 22 May 2018

ABOUT THE COVER

Make/Model : AUDI A4 Sedan 2.0 TFSI S tronic
Engine Capacity/Tonnage : 1,984.00 CC
Driver Restriction : NA
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2018
Insuring with COE/PAF : Yes

Person or Classes of Persons Entitled to Drive*

a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Inexperienced Driver Excess" ("IDR") if You are or Your Authorised Driver (named or unnamed) has less than 2 years' driving experience.

Age Condition : 40 years old and above

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
 This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered imperative by Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189) and Section 85 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
Fire - \$0 Own Damage - \$1600 Theft - \$0 Flood Cover - \$0

Section 2
Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

NG ING-YONG BRIAN (HUANG YINGRONG BRIAN) - \$1600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63962323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6336 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125261

PREMIUM LEASING -CYS
 281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE
 SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

Stefany Loh

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

Stefany Loh

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	07 Jan 2019		09 Jan 2019 16:42 Edit Adj Rpt	S\$11,221.76 Edit Estimates	S\$11,221.76 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	NG ING-YONG BRIAN (HUANG YINGRONG BRIAN), ID: S7729521F, Tel: +6591278078, Email: BRIAN.NG.INGYONG@GMAIL.COM								
Vehicle Reg. No.:	SLZ1749M	Date of Loss:	22/12/2018 13:00 - :59 [7 Months and 27 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 2366897869SG	Policy/Cover Note No.:	(Comprehensive)						
		Excess:	S\$600.00						
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Dally Amri, Mimi Zarina] MimiZarina.DallyAmri@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 18/01/2019]								
Driver/Custodian:	NG ING-YONG BRIAN (HUANG YINGRONG BRIAN) (41 / Male), NRIC: S7729521F, Tel: +6591278078 Email: BRIAN.NG.INGYONG@GMAIL.COM								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG (11/01/2019): Alert - Adj Mandate Approved (S\$12903.00) - SLZ1749M - Claim Handler: Dally Amri... - AIG_SG (11/01/2019): SLZ1749M / OD / 22/12/2018 / Coverage & Excess update									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLZ1749M (2366897869SG)
OD

Dec 22 2018 1:10PM
[NG ING-YONG BRIAN (HUANG YINGRONG BRIAN)]
Premium Automobiles Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Assessment Reports															1 per page		☒			
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail		Print			
1	10/01/19 10:00	Adjuster Immediate Advice													 Load HTM					
Photos/Images															3 per page		☒			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail		Print			
1	09/01/19 16:48	General View													 Load JPG		☒			
2	09/01/19 16:48	General View													 Load JPG		☒			
3	09/01/19 16:48	General View													 Load JPG		☒			
4	09/01/19 16:48	General View													 Load JPG		☒			
5	09/01/19 16:48	General View													 Load JPG		☒			
6	09/01/19 16:48	General View													 Load JPG		☒			
7	09/01/19 16:48	General View													 Load JPG		☒			
8	09/01/19 16:48	General View													 Load JPG		☒			
9	09/01/19 16:48	General View													 Load JPG		☒			
10	09/01/19 16:48	General View													 Load JPG		☒			
11	09/01/19 16:48	General View													 Load JPG		☒			
12	09/01/19 16:48	General View													 Load JPG		☒			
13	09/01/19 16:48	General View													 Load JPG		☒			
14	09/01/19 16:48	General View													 Load JPG		☒			
15	09/01/19 16:48	General View													 Load JPG		☒			
16	09/01/19 16:48	General View													 Load JPG		☒			
17	09/01/19 16:48	General View													 Load JPG		☒			
18	09/01/19 16:48	General View													 Load JPG		☒			
19	09/01/19 16:48	General View													 Load JPG		☒			
20	25/03/19 09:43	Reinspection Photo													 Load JPG		☒			
21	25/03/19 09:43	Reinspection Photo													 Load JPG		☒			
22	25/03/19 09:43	Reinspection Photo													 Load JPG		☒			
23	25/03/19 09:43	Reinspection Photo													 Load JPG		☒			
24	25/03/19 09:43	Reinspection Photo													 Load JPG		☒			
25	25/03/19 09:43	Reinspection Photo													 Load JPG		☒			
26	25/03/19 09:43	Reinspection Photo													 Load JPG		☒			
27	25/03/19 09:43	Reinspection Photo													 Load JPG		☒			
28	25/03/19 09:43	Reinspection Photo													 Load JPG		☒			
29	25/03/19 09:43	Reinspection Photo													 Load JPG		☒			
30	25/03/19 09:43	Reinspection Photo													 Load JPG		☒			
31	25/03/19 09:43	Reinspection Photo													 Load JPG		☒			
32	25/03/19 09:43	Reinspection Photo													 Load JPG		☒			
33	25/03/19 09:43	Reinspection Photo													 Load JPG		☒			
34	25/03/19 09:43	Reinspection Photo													 Load JPG		☒			
35	25/03/19 09:43	Reinspection Photo													 Load JPG		☒			

Assessment Reports				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
36	25/03/19 09:43	Reinspection Photo	 Load JPG	☒	
37	25/03/19 09:43	Reinspection Photo	 Load JPG	☒	
Documentation				1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	10/01/19 10:04	Singapore Accident Statement	 Load PDF		
2	10/01/19 10:04	Police Report	 Load PDF		
3	10/01/19 10:05	Certificate of Insurance	 Load PDF		
4	10/01/19 10:05	Driver's Driving License	 Load PDF		
5	10/01/19 10:05	MARK ESTIMATE	 Load PDF		
6	29/04/19 16:18	Workshop Invoice	 Load PDF		
7	29/04/19 16:18	Discharge Voucher	 Load PDF		

Linked Accident Report Documents

				View	View in Browser
Video				1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print	
1	05/01/19 10:08	Video - Accident	 Load AVI		
Assessment Reports				1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print	
1	02/01/19 18:46	Accident Statement	 Load HTM		
2	05/01/19 10:34	Addendum Sheet	 Load JPG	☒	
3	05/01/19 10:35	Accident Statement Addm. #1	 Load HTM		
Photos/Images				3 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print	
1	02/01/19 18:41	Police Report	 Load JPG	☒	
2	02/01/19 18:41	Police Report	 Load JPG	☒	
3	02/01/19 18:41	Accident Photo	 Load JPG	☒	
4	02/01/19 18:41	Accident Photo	 Load JPG	☒	
5	02/01/19 18:41	Accident Photo	 Load JPG	☒	
6	02/01/19 18:41	Accident Photo	 Load JPG	☒	
7	02/01/19 18:41	Accident Photo	 Load JPG	☒	
8	02/01/19 18:41	Accident Photo	 Load JPG	☒	
9	02/01/19 18:41	Accident Photo	 Load JPG	☒	
10	02/01/19 18:41	Accident Photo	 Load JPG	☒	
11	05/01/19 10:08	Accident Photo	 Load JPG	☒	
12	05/01/19 10:08	Accident Photo	 Load JPG	☒	
13	05/01/19 10:08	Accident Photo	 Load JPG	☒	
Documentation				1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print	
1	05/01/19 10:32	Sketch Plan	 Load JPG	☒	
2	05/01/19 10:32	Sketch Plan #2	 Load JPG	☒	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG19000538/AVBE2

Date: 29/04/2019

REFERENCE

Insured/Claimant: NG ING-YONG BRIAN (HUANG YINGRONG BRIAN)

Policy No:

Date of Loss: 22/12/2018

Nature of Claim: OD Claim No: 2366897869SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLZ1749M	Engine No:	CVK057562
Make & Model:	AUDI A4, 2.0 (A)	Chassis No:	WAUZZZF43JA137437
Reg. Date:	25/04/2018 (Man. Year: 2018)	Odometer:	10136 km
Colour:	Grey		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$160,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,298.00	8,199.76	5,098.24	38.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,552.00	3,022.00	1,530.00	33.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,850.00	11,221.76	6,628.24	37.13
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	17,250.00	10,621.76	6,628.24	38.42
+ GST 7.00/7.00% (S\$)	1,207.50	743.52	463.98	38.42
Nett Amount (S\$)	18,457.50	11,365.28	7,092.22	38.42

INSPECTION

Date of Assignment: 09/01/2019

Date Inspected: 09/01/2019 Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,999.00 FS	*1,599.20 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	258.00 FS	*- FS
3	1		*FRONT BUMPER SECURING STRIP	Necessary	32.00 FS	*25.44 FS
4	1		*FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE	Not Necessary	191.00 FS	*- FS
5	1		*FRONT BUMPER AIR GUIDE -RH	Deformed	56.00 FS	*44.40 FS
6	1		*FRONT BUMPER AIR GUIDE GRILLE -RH	Not Necessary	123.00 FS	*- FS
7	1		*FRONT BUMPER GUIDE SECTION -RH	Damaged	34.00 FS	*27.12 FS
8	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	113.00 FS	*- FS
9	1		*FRONT BUMPER CARRIER	Not Necessary	733.00 FS	*- FS
10	1		*FRONT BUMPER SUPPORT-RH	Not Necessary	26.00 FS	*- FS
11	2		*FRONT SENSOR	Not Necessary	462.00 FS	*- FS
12	4		*FRONT SENSOR SEAL RING	Not Necessary	123.00 FS	*- FS
13	1		*FRONT FENDER -RH	Dented	700.00 FS	*559.60 FS
14	1		*FRONT FENDER ATTACHMENT PARTS-RH	Not Necessary	48.00 FS	*- FS
15	1		*FRONT FENDER CLOSING ELEMENT -RH	Necessary	45.00 FS	*36.00 FS
16	1		*FRONT FENDER BRACKET -RH	Not Necessary	32.00 FS	*- FS
17	1		*FRONT FENDER BRACE -RH	Bent	107.00 FS	*85.60 FS
18	1		*FRONT FENDER COVER-RH	Necessary	28.00 FS	*22.24 FS
19	1		*FRONT FENDER TOP COVER-RH	Necessary	21.00 FS	*16.16 FS
20	1		*FRONT WHEEL HOUSING LINER-RH	Not Necessary	220.00 FS	*- FS
21	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS-RH	Not Necessary	82.00 FS	*- FS
22	1		*FRONT WHEEL SPOILER-RH	Torn	66.00 FS	*52.32 FS
23	1		*FRONT FENDER LEDGE -RH	Not Necessary	33.00 FS	*- FS
24	1		*FRONT STONE CHIP GUARD-RH	Necessary	46.00 FS	*36.64 FS
25	1		*LED HEADLIGHT-RH	Cut	7,087.00 FS	*5,669.60 FS
26	1		*HEADLIGHT LIFT CYLINDER -RH	Not Necessary	120.00 FS	*- FS
27	4		*RUBBER VALVE	Not Necessary	13.00 FS	*- FS
28	1		*FRONT RIM -RH (NPA)	Not Necessary	0.00 FS	*- FS
29	1		*SUNDRIES	Necessary	500.00 FS	*25.44 FS
F=Franchise part. S=SpcNett.						
Total Parts (\$\$)					13,298.00	8,199.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO DISMANTLE AND RENEW FRONT BUMPER ,RHS FRONT FENDER AND RHS HEADLIGHT.RE-ORGANISE CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	New	2,100.00	1,250.00
3	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER	New	1,500.00	1,100.00
4	TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	0.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			4,552.00	3,022.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >