

INSURANCE

INS. CASE OWNER:

Chin Kiat

CC b/CTI1900

0544, K. F. 6/19

LKK:

IDAC:

Surveyor:

K. F. 6/19

DOI:

ASSIGNMENT

8/1/19

Date / Time:

8/1/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

YN 7390H

Claim No.:

Name of Insured:

FAS NEW ENTERPRISE CONSULTING

Policy No.:

DMLR SN 2001245800

Insured Tel No.:

HP:

D.O.A.:

1/1/19

Make / Model:

ISUZU

Excess Sec II :SS

D.O.A.:

Place of Accident:

PIE TOWNS (Mamb)

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

M. ANDREW SATHIYAN KUMAR

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability:

Final ? Yes / No

SME 12794



INSRS:

WSP:

Tel:

Liability:

RMKS:

WEL
LL

INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

16/1/19
PK.

SME 12794

YN 7390H

BOLA 27, 100%, OLD rear ended TP vehicle.
Send letter to OLPIC call back, confirmed BOLA 27, Agree to
settle and waive HED issue.

SPM 170 200 / 62

After point photo

STAGE

DATE / PIC

Non-Reporting Itr (1st)

Non-Reporting Itr (2nd)

Non-Reporting Itr (Final)

Notification Itr (if non-pickup)

Call OI: 1/5/2019

After call Itr to OI: 1/5/2019

Documentation Check List: Handler Typist

Notification Itr (if non-pickup)

After call Itr to OI

Authorisation To Act

Release Voucher

Final Repair Bill

Car Rental Invoice

Towing Invoice

LTA / GIA

Medical Bill

PIR

Mandate/Reject Instruction

LOD

Payment Breakdown Form

Post-Repair Photos

Others:

PRELIMINARY ADVICE Date/Time:

9/1/2019

Sent By:

LSP

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$ 2,500.00

(5 days)

Reduction:

S\$ 45

%

Email:

Call:

FINAL SETTLEMENT

Date/Time:

28/5/2019

Confirm with:

Karen

Email:

Call:

Final Liability:

%

100

(Agreed / Assigned)

BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost:

S\$ 2,568.00

Loss of Rental (LOR):

S\$ -

(days)

Loss of Use (LOU):

S\$ 400.00

(S 80.00 x 5 days)

Loss of Income (LOI):

S\$ -

(S x days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

S\$ 7.45

Medical:

S\$ -

Disbursement:

S\$ -

(e.g. Tow/Independent)

Legal Cost

S\$ -

1) Claim status: Normal/Reject/Private Settle

2) Report Format: TP

3) Survey fee: 4400.00

Total:

S\$ 2,975.45

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email:

Call:

Payee 1:

S\$ 2,975.45

Name 1:

Wei Lee Motor works

Payee 2: (Strike if N.A.)

S\$ -

Name 2:

Payee 3: (Strike if N.A.)

S\$ -

Name 3:

ASS. REC. BY:

REF: C72 /

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

QD / TP / WS / TP RES / QD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

9/11 File pass to

451 x 2,400.00 (Redi \$ 3,592.16 / 59.95 %)

Veh No:

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STO A/Rlm or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS, SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC6/CTI19000544/Kfb3

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 09-01-2019



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YN 7390N	Veh. Inspected	SME 1729U
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	09/01/2019

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	02/01/2019	Inspection Date	08/01/2019
Survey held at	WEI LEE MOTOR WORKS BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32 SINGAPORE 575644.		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC6/CTI19000544/Kfb3

Date: 09.01.2019

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SME1729U

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 08.01.2019 at the premises of M/s Wei Lee Motor Works and have the following to report:-

Workshop Estimate Amount	: S\$	5,992.16
Revised Estimate Amount	: S\$	3,005.92
"Check" Items Amount	: S\$	293.44
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 5 days

Yours faithfully,

KENNETH KONG
Licensed Appraiser

K.F 威利摩哆WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.

TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: welleemotorworks@gmail.com
Business Regn No: 269438/00J

4, Jan 2019

China Taiping Insurance (S)PL
105 Cecil Street #18-00
The Octagon S 069534

Attn: Motor claim dept-3rd party claim
Claiming against your insured vehicle no: YN7390H
Accident involving vehicle no: SME1729U/YN7390H
DOA: 02/01/2019 AT PIE twds City On left lane twds PIE

Dear officer incharge

Re: Estimate cost of repair for vehicle no: SME1729U

Description	Qty	Amount
Lid	1	610.40
Lid reflector @202.30	2	404.60
Lid-1.8 emblem	1	24.50
Lid-H logo	1	24.70
Lid-I VTec emblem	1	33.50
Lid lock	1	194.00
Lid hinge @62.60	2	125.20
End panel	1	300.80
End panel top garnish	1	66.00
Boot weatherstrip	1	107.00
Exhaust tailpipe	1	656.00
Exhaust mounting @42	2	84.00
Taillamp @308	2	616.00
Spare tyre panel	1	536.50
Tool compartment	1	194.00
Spare tyre board	1	172.00
Rear bumper	1	635.00
Rear bumper retainer @28	2	56.00
Parts		4,840.20
Parts less 20%		968.04
		3,872.16

Not within
6/1/19 &?
Money After Paint
5 days

Parts
603-30 1866.90
SN 1493-12 373-28
Lab 1470- 53-50
3016-62
603-32 4600
#2413-30

Vehicle no: SME1729U

Reverse sensor

SL 220.00 X

To remove damaged parts and attachments.

Cut n weld damaged panel.

Straighten rear chassis .

Repair/reshape dented/damaged areas.

1,100.00 75d

To replace/realign all parts into position.

800.00 72d

To spray paint.

5,992.16

威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.
TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com
Business Regn No: 269436/00J

4, Jan 2019

China Taiping Insurance (S)PL
105 Cecil Street #18-00
The Octagon S 069534

Attn: Motor claim dept-3rd party claim
Claiming against your insured vehicle no: YN7390H
Accident involving vehicle no: SME1729U/YN7390H
DOA: 02/01/2019 AT PIE twds City On left lane twds PIE

Dear officer incharge

Re: Estimate cost of repair for vehicle no: SME1729U

Not Withheld
1/1/19 &?
Money After Paint
5 days

Description	Qty	Amount	
Lid	1	610.40	✓
Lid reflector @202.30	2	404.60	✓
Lid-1.8 emblem	1	24.50	✓
Lid-H logo	1	24.70	✓
Lid-I VTec emblem	1	33.50	✓
Lid lock	1	194.00	X
Lid hinge @62.60	2	125.20	X
End panel	1	300.80	✓
End panel top garnish	1	66.00	✓
Boot weatherstrip	1	107.00	50% @ 53.50
Exhaust tailpipe	1	656.00	X
Exhaust mounting @42	2	84.00	X
Taillamp @308	2	616.00	✓
Spare tyre panel	1	536.50	X
Tool compartment	1	194.00	X
Spare tyre board	1	172.00	X
Rear bumper	1	635.00	✓
Rear bumper retainer @28	2	56.00	✓
Parts		4,840.20	
Parts less 20%		968.04	
		3,872.16	

LKK Auto Consultants hereby notify the Repairer of the following:

- To reserve any estimate after spray painting
- To display damaged parts during survey
- Parts prices are subject to confirmation

- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be reserved and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Vehicle no: SME1729U

Reverse sensor

52 220.00 X

To remove damaged parts and attachments.

Cut n weld damaged panel.

Straighten rear chassis .

Repair/reshape dented/damaged areas.

To replace/realign all parts into position.

1,100.00 7501

To spray paint.

800.00 7201

5,992.16

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Company

Owner ID: 1813C

Vehicle Details

Vehicle No.: SME1729U

Vehicle to be Exported: Yes

Intended Deregistration Date: 30 Jan 2019

Vehicle Make: HONDA

Vehicle Model: HONDA CIVIC 1.8L 5AT

Primary Colour: Black

Manufacturing Year: 2008

Engine No.: R18A14014535

Chassis No.: JHMF163095202627

Maximum Power Output: 103.0 kW (138 bhp)

Open Market Value: \$26,619.00

Original Registration Date: 01 Dec 2009

First Registration Date: 01 Dec 2009

Transfer Count: 1

Actual ARF Paid: \$26,619.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 30 Nov 2019

PARF Rebate Amount: \$13,309.00

Intended COE Rebate Details

COE Expiry Date: 30 Nov 2019

COE Category: B - Car (1601cc & above)

COE Period(Years): 10

QP Paid: \$18,002.00

COE Rebate Amount: \$1,500.00

Total Rebate Amount: \$14,809.00

The information contained herein is correct as at 04 Jan 2019

OK

Shu Pei (LKKAUTO)

From: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Sent: Monday, 14 January 2019 5:44 PM
To: Shu Pei (LKKAUTO)
Cc: Poh Kin (LKKAUTO); Admin A; Ong Chin Kiat
Subject: RE: Direct Settlement - Accident Involving YN7390H (OI : CTI - TBA) and SME1729U (TP : LKK REF - CC6/CTI19000544/Kfb3) on 02.01.2019
Attachments: YN7390H.pdf

Dear Shu Pei,

Attached our insured's GIA report.

Thank you.

Regards,

Ong Chin Kiat
Assistant Claims Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
Direct (65) 6389 6174
Fax (65) 6224 7174 / 6224 7478
www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Claims Dept of CTI
Sent: Thursday, 10 January, 2019 9:26 AM
To: 'Shu Pei (LKKAUTO)' <shupeil@lkkauto.com>
Cc: Poh Kin (LKKAUTO) <pohkin@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Ong Chin Kiat <chinkiat.ong@sg.cntaiping.com>
Subject: RE: Direct Settlement - Accident Involving YN7390N (OI : CTI - TBA) and SME1729U (TP : LKK REF - CC6/CTI19000544/Kfb3) on 02.01.2019

Dear Shu Pei,

Our insured has not file a report.

We shall inform our insured to file a report and keep you updated.

Thank you.

Regards,

Ong Chin Kiat

Assistant Claims Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

Direct (65) 6389 6174

Fax (65) 6224 7174 / 6224 7478

www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Shu Pei (LKKAUTO) [<mailto:shupe@lkkauto.com>]

Sent: Wednesday, 9 January, 2019 6:10 PM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Cc: Lucas Lee <lucas.lee@sg.cntaiping.com>; Ong Chin Kiat <chinkiat.ong@sg.cntaiping.com>; Poh Kin (LKKAUTO) <pohkin@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Subject: Direct Settlement - Accident Involving YN7390N (OI : CTI - TBA) and SME1729U (TP : LKK REF - CC6/CTI19000544/Kfb3) on 02.01.2019

WITHOUT PREJUDICE

Dear Chin Kiat,

We refer to the above matter.

We have inspected TP vehicle SME 1729U at M/s Wei Lee Motor Works on a WP basis and TP repairer proposed for a direct settlement.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Enclosed for your perusal is:

- TP's GIA report
- Estimated cost of repair
- Preliminary advice

Our case handler in-charge is Poh Kin and he can be contacted at DID: 6841-2132.

Thank You.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.

TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com
Business Regn No: 269436/00J

15, FEB 2019

China Taiping Insurance (S) PL

Attn: Motor claim dept-3rd party claim

Claiming against your insured vehicle no: YN7390H

Accident involving vehicle no: SME1729U/YN7390H

ON 02/01/2019 AT PIE twds City On Left Lane twds PIE

Dear officer incharge

We are the workshop for the owner of vehicle no: SME1729U

Regarding the claim for the case above, this is a liability clear case considering that your client's vehicle collided into the rear portion of our client's vehicle.

The claim for vehicle No: SME1729U as follow:-

Cost of repair to SME1729U	\$ 2,568.00	finalised with your surveyor
Loss of use	\$ 400.00	\$80x5d
LTA search fee	\$ 7.45	


\$ 2,975.45

Enclosed with all the necessary document for your reference.

Kindly let us have your reply soonest possible.

Thank you.





Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC6/CTI19000544/Kfb3

16 MAY 2019

M/S FASTWELD ENGINEERING CONSTRUCTION PTE LTD
2 KRANJI LINK
SINGAPORE 728648

Dear Sir/Madam,

**ACCIDENT INVOLVING YN 7390H AND SME 1729U ALONG/AT PIE
TOWARDS CHANGI BEFORE BKE EXIT ON 02/01/2019**

We refer to the above accident where we are acting for China Taiping Insurance (Singapore) Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please call us if you have further queries.

Yours faithfully,

Poh Kin, Chong
Case Handler
DID: 6841 2132
FAX: 6741 4108
Email: pohkin@lkkauto.com

c.c. *China Taiping Insurance (Singapore) Pte Ltd*
(Motor Claims Dept)

AUTHORIZATION TO ACT

I, KH Kasing PL ("the third party claimant")
of 261 A UPP Thomson Road (address),
owner of SME 17294 (vehicle no.) hereby authorize
Wei Lee Motor Works
("the workshop") to act for me with respect to my claim for repair costs and/or
rental and/or loss of use ("claim") for my vehicle no. SME 17294 that was
damaged pursuant to the accident which occurred on 21/2019 (date) along
PE (towards city) on left lane towards PE (location)
involving vehicle no/s YN 7390 N ("the accident").


I further authorize the workshop to settle the above mentioned claim in a
manner that they deem fit and the workshop is further authorized to receive
payment further to settlement of my claim with payment cheque/s being made in
favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my
behalf is on a without prejudice and without admission of liability basis insofar
as the driver/owner/insurers of the other vehicle/s is concerned.

Date this 4 day of Jan (month) 20 19 (year)



Signed by "the third party claimant"



Signed by "the workshop"

MOTOR CLAIMS DISCHARGE VOUCHER

Policy No : DMCVSN3001341800

Claim No : SNM19D 200162

Claimant : KH LEASING PTE LTD

Amount : S\$2,975.45
DOLLARS TWO THOUSAND NINE HUNDRED SEVENTY FIVE AND CENTS
FORTY FIVE ONLY

I/We agree to accept the above mentioned amount to be paid to me/us in full & final settlement of all claims, costs & disbursements for injuries / damages sustained by me/us through an accident involving

Claimant Vehicle No. : SME 1729U
Insured Vehicle No. : YN 7390H

Date of Loss : 02/01/2019
Place of Accident : PIE

IN CONSIDERATION of the payment made to me/us of the aforementioned sum by CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD., I/We agree absolutely to discharge CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD. and/or

Insured Name : FASTWELD ENGINEERING CONSTRUCTION PTE LTD
Driver Name : CHANDRAN SENTHIL KUMAR

from all claims, present or future in respect of all loss, injury or damage sustained by me/us arising out of the said accident.

I acknowledge that this payment is made without admission of liability on the part of CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

(1) General Damages	S\$	-
(2) Cost of Repair/ Excess	S\$	2,568.00
(3) Loss of Use/ Rental/Earning	S\$	400.00
(4) GIA/Police Reports/ Investigation Results/Search Fees	S\$	7.45
(5) Medical Reports/Expenses	S\$	-
(6) Survey Fees/P.T. Fees	S\$	-
(7) Cost including Disbursement	S\$	-
TOTAL	S\$	2,975.45

Claimant Name :

KH Leasing PL

NRIC No : 2016118136

Signature :



Date :

17-6-2019

威利摩托 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-28,
SINGAPORE 575644.
TEL: 6459 9830 FAX: 6458 0128
Business Regn No: 269436/00J
GST Regn No: 26-943600-J

TAX INVOICE

M/S : China Taiping Insurance (S) PL

NO : WL03722
Vehicle No : SME1729U
Date : 15-FEB-2019

<u>Quantity</u>	<u>Particulars</u>	<u>Unit Price</u>	<u>Amount Incl. GST</u>
SME1729U			
1.00	Your insured vehicle no: YN7390H Accident involving vehicle no: SME1729U/YN7390H DOA: 02/01/2019		
1.00	Cost of repair for vehicle no: SME1729U Lump sum repaired as recommended by LKK Auto Consultants	\$2,400.00	\$2,400.00
1.00	GST	\$168.00	\$168.00
			\$2,568.00
Total Amount Incl. GST		\$168.00	
Standard Rate GST Amount (7.00%)		\$2,400.00	
Total Amount Before GST			

Receipt

> Back to OneMotoring



Land Transport Authority
10 Sin Ming Drive
Singapore 575701
GST Registration No. : M4-0006529-2

Print Date/Time : 04 Jan 2019 / 16:50:28

Receipt Date/Time : 04 Jan 2019 / 16:50:28

Tax Invoice/Receipt

Receipt No. : ITNET-00000-190104-003592

Previous Receipt No. :

S/N Item Description/
Business Transaction Reference
No.

Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
-------------------------------	------------------------	------------------------------

Result of Insurance Enquiry - YN7390H

As at 02 Jan 2019/18:45:00

Insurance Co: CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

1 Insurance Enquiry - YN7390H

Enquiry Fee

20190104164935847429

Sub-Total

Total Before Rounding

Rounding Difference

Total Amount Payable

Paid By

20190104164947544

Direct Debit: eNETS Debit
(Internet Banking)

Total

Cash Change

Tendered Amount

Excess Refundable Amount

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD			Ref : CC6/CTI19000544/Kfb3q2	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Date : 26-06-2019	
			Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YN 7390H	Veh. Inspected	SME 1729U	
Policy No.	DMCVSN3001341800	Coverage (\$)	0.00	
Claim No.	SNM19D200162	Excess (\$)	0.00	
Assign From		Assign Date	08/01/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA CIVIC (A)	c.c	1799	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	JHMFD16309S202627	Colour	METALLIC BLACK	
Odometer	175823	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	DUNLOP	4 mm	
L/H Front Tyre	205/55 R16	DUNLOP	4 mm	
R/H Rear Tyre	205/55 R16	DUNLOP	4 mm	
L/H Rear Tyre	205/55 R16	DUNLOP	4 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	02/01/2019	Inspection Date	08/01/2019	
Survey held at	WEI LEE MOTOR WORKS BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32 SINGAPORE 575644.			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SME 1729U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	LID	BENT	610.40	610.40
1	LID REFLECTOR @\$202.30	N/S CRACKED	404.60	202.30
1	LID -1.8 EMBLEM	NECESSARY	24.50	24.50
1	LID -H LOGO	NECESSARY	24.70	24.70
1	LID -I VTEC EMBLEM	NECESSARY	33.50	33.50
1	LID LOCK	TO REPAIR SEE LABOUR	194.00	-
2	LID HINGE @\$62.60	TO REPAIR SEE LABOUR	125.20	-
1	END PANEL	NOT NECESSARY	300.80	-
1	END PANEL TOP GARNISH	NOT NECESSARY	66.00	-
1	EXHAUST TAILPIPE	TO REPAIR SEE LABOUR	656.00	-
2	EXHAUST MOUNTING @\$42.00	SERVICEABLE	84.00	-
2	TAILLAMP @\$308.00	N/S CRACKED	616.00	308.00
1	SPARE TYRE PANEL	TO REPAIR SEE LABOUR	536.50	-
1	TOOL COMPARTMENT	SERVICEABLE	194.00	-
1	SPARE TYRE BOARD	SERVICEABLE	172.00	-
1	REAR BUMPER	BUCKLED	635.00	635.00
2	REAR BUMPER RETAINER @\$28.00	N/S DISTORTED	56.00	28.00
	LESS 20% DISCOUNT		-946.64	-373.28
			3,786.56	1,493.12
1	BOOT WEATHERSTRIP (50%) (SN)	DISTORTED / DENTED	107.00	53.50
	LESS 20% DISCOUNT		-21.40	-
			85.60	53.50
SPECIAL NETT ITEMS				
1	REVERSE SENSOR (SN)	SERVICEABLE	220.00	-
			220.00	-

Report Ref No. CC6/CTI19000544/Kfb3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR TO REMOVE DAMAGED PARTS AND ATTACHMENTS.CUT N WELD DAMAGED PANEL.STRAIGHTEN REAR CHASSIS.REPAIR /RESHAPE DENTED /DAMAGED AREAS.TO REPLACE/REALIGN ALL PARTS INTO POSITION.INCLUSIVE OF THE REPAIR OF LID LOCK,LID HINGE,EXHAUST TAILPIPE AND SPARE TYRE PANEL . TO SPRAY PAINT.		1,100.00	750.00
			800.00	720.00
			1,900.00	1,470.00
GRAND TOTAL			5,992.16	3,016.62
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,400.00

Report Ref No. CC6/CT119000544/Kfb3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.