

ASS. REC. BY:

REF

es/amol9000592/R19d3

n2

Special Instruction:

Survivor:

Rasul

ASSIGNMENT (Office)

From (Person):

Hun Cheung Yung Bernard

SMO

Date/Time:

10/11/19 @ 1:47pm

Estimated Cost:

Bill to:

OD/TT/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SGF 324B

Insured:

FBM 9108Y

at Workshop m/s

Falcon - Air Auto

Tel:

6779 5665

of

No 8 pandan loop

Policy No:

D18MTMC01002648

Claim No:

CMTD1805510

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

11/12/2018

CA / REV / REP. / REV 24 HRS

up

4/01/2019

H.O.D. Endorsement:

Date/Time:

15Gpm@10/11/19

Person Contacted:

Andy

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SGF 324B-X
	FBM 9108Y-X
14/01/19 @ 1:34pm	visited to Bernard team via Meinman.
24/11/19 @ 4:37pm	Confirmed with Andy. US to 400, 7 days, (Ref to 3488.40, 47%)

REF:

ASSIGNMENT

117014

COG 19/04/2021/MAL

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SGF 324B

at Workshop n/s FALCON - AIR

of BLU, Pannan Loop

Insured: SMU

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 15K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 7 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SGF 324B

Yr Regn: 2006 / MAL

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

MITSUBISHI LANCER 1.6^M C.C. : 1584

Colour:

BLACK

A/C: Insured / Std / NI / NA

Sp. Reading:

149356

T/Radio: Insured / Std / NI / NA

Eng/No:

CrNo:

JMY3NCS3A6U004986

Gen. Cond: Good / ☒ Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size:

F:

195/60R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

FALKEN

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

11/12/18

D.O.I.

11/01/19

Survey held at

FALCON - AIR

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Repair 1hr 4K. ref to and

Date/Time, File Pass to?

☐

: Prel. Report

Date/Time, File Return to?

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 7

Resurvey No. of Trip: 1

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Insp (\$)

☐

Weekend (\$)

Survey Fee:

Transportation:

) S + PS. SI

) Photos:

) Others:

) TOTAL

250
10

260

Report Format:

MER-TA

Lump Sum / LBA: (\$)

4000

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Somp Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: HAN CHEUNG YONG BERNARD

Date: 14 Jan 2019

Preliminary Advice

Insured Vehicle No	: FBM9108Y	Accident Date	: 11/12/2018
TP Vehicle No	: SGF324B	Assignment Date	: 10/01/2019
Make	: MITSUBISHI LANCER	Est. Duration of Repair	: 7.00
Date of Inspection	: 11/01/2019		
Inspection At	: FALCON-AIR AUTO SERVICES PTE LTD (PANDAN) NO 8 PANDAN LOOP SINGAPORE		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,488.40
Revised Amount	:S\$	6,426.80
Check Items (Estimated)	:S\$	641.60
Total	:S\$	7,068.40

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Dec 2018 Sendback Est	13 Dec 2018 09:52 \$7,488.40	10 Jan 2019 13:47 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	NA, ID: NA			
Main Claimant:	TAM KIM SENG, ID: S2501170H			
Vehicle Reg. No.:	SGF324B	Date of Loss:	11/12/2018 11:00 - :59 [152 Months and 11 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / CMTD1805510	Policy/Cover Note No.:	D18MTMC01002648	
Vehicle Reg. No. (Insured):	FBM9108Y	Policy No. (Claimant):	18-MV005700-R01	
		Excess:		
Repairer:	Falcon-Air Auto Services Pte Ltd (Pandan) No 8 Pandan Loop, Clementi - Tel:			
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by HAN CHEUNG YONG BERNARD - 6322 4659]			
Claimant's Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 21/01/2019]			

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Rasul (LKKAuto)

From: Rasul (LKKAuto)
Sent: Monday, 14 January, 2019 9:17 AM
To: 'ANDY'
Subject: SGF 324B doa : 11/12/18

Hi Andy,

Repair limit to repair this vehicle is 4K


Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 24 January 2019 4:22 PM
To: ANDY; Rasul (LKKAUTO)
Cc: SUR; Admin A
Subject: RE: SGF 324B doa : 11/12/18

Dear Andy,

WITHOUT PREJUDICE

Confirm Lump Sum \$4,000.00 before GST and 7 repair days.

Kindly send the relevant documents to SOMPO Insurance company.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ANDY <andy@falconair.com.sg>
Sent: Tuesday, 22 January 2019 10:54 AM
To: Rasul (LKKAUTO) <Rasul@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: RE: SGF 324B doa : 11/12/18

Dear Sir

Finalised repair limit @ \$4000.00 7 working days

Please submit your surveyor report, after one week we will send the LOD to Somp

Best Regards

Andy

Falcon-Air Auto Services Pte Ltd

Add : No. 8 Pandan Loop (Blk K / Blk 1) Singapore 128226 Tel No : +65 6779 5665 Fax No : +65 6779 1110

From: Rasul (LKKAUTO) [<mailto:Rasul@lkkauto.com>]
Sent: Monday, January 14, 2019 9:17 AM
To: ANDY <andy@falconair.com.sg>
Subject: SGF 324B doa : 11/12/18

Hi Andy,

Repair limit to repair this vehicle is 4K

Best Regards,

Shiau Chan (LKKAUTO)

From: ANDY <andy@falconair.com.sg>
Sent: Tuesday, 22 January 2019 10:54 AM
To: Rasul (LKKAUTO)
Cc: SUR; Admin A
Subject: RE: SGF 324B doa : 11/12/18
Attachments: after repair (1).JPG; after repair (2).JPG; after repair (3).JPG; after repair (4).JPG; after repair (5).JPG; after repair (6).JPG

Dear Sir

Finalised repair limit @ \$4000.00 7 working days
Please submit your surveyor report, after one week we will send the LOD to Somp

Best Regards

Andy

Falcon-Air Auto Services Pte Ltd

Add : No. 8 Pandan Loop (Blk K / Blk 1) Singapore 128226 Tel No : +65 6779 5665 Fax No : +65 6779 1110

From: Rasul (LKKAUTO) [mailto:Rasul@lkkauto.com]
Sent: Monday, January 14, 2019 9:17 AM
To: ANDY <andy@falconair.com.sg>
Subject: SGF 324B doa : 11/12/18

Hi Andy,

Repair limit to repair this vehicle is 4K


Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.



Mitsubishi Lancer

Price Range

Depreciation

> 10 year

Vehicle Type

Advanced Search

Home » Used Cars » Monster Motors Pte Ltd » Mitsubishi Lancer 1.6M GLX (COE till 05/2021)

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Mitsubishi Lancer 1.6M GLX (COE till 05/2021)

Overview

Financial

Accessories

Similar

Research

Photos

Map

PREMIUM AD



CONSIGNMENT / BUY / SELL / SCRAP / EXPORT

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

Car Details

Price \$17,000

Depreciation \$7,120 /yr

Reg Date 10-Jul-2006
(2yrs 4mths 21days COE left)

Manufactured 2006

Mileage -

Transmission Manual

Engine Cap 1,584 cc

Road Tax \$954 /yr

Power 79.0 kW (105 bhp)
View specs of the Mitsubishi Lancer (2006-2008)

Curb Weight 1,162 kg

Features Reliable And Powerful Single Cam 1.6 Engine. 4 Cylinder 16 Valves Engine. Fuel Efficient Running At 580Km To 620Km Per Tank.

Accessories Original Black Leather Seat, Factory Fitted Sports Rims, Audio System, Parking/Rear Sensors. Spaco Steering.

Description Cheap And Modded Lancer. S90 Throttle Body, Open Pod Hurricane Filter, Drift Racing Exhaust. Mods Will Go With The Car. Whatsapp Or Call To Book An Appointment For Viewing! High Loans And Trade-ins Available.

COE \$22,789

OMV \$11,671

ARF \$12,839

Dereg Value \$10,889 as of today (change)

No. of Owners 6

Type of Veh Mid-Sized Sedan

Category COE Car, Premium Ad Car

Availability Available

PREMIUM AD


Add to Shortlist

Add to Compare

Add a Note

Posted on: 08-Nov-2018 | Last Updated on: 09-Jan-2019

Tags: Mitsubishi Lancer, mitsubishi lancer, 2006 Mitsubishi Lancer, 2006 mitsubishi lancer, Mitsubishi, Lancer, lancer, Used Mitsubishi



Location Map

Seller Information

Company	Monster Motors Pte Ltd	
	» dealer's price list » 73 vehs sold 124 vehs available	
Address	453 Tagore Industrial Avenue #01-02 Search cars nearby this location	
Location	Sindo Industrial Estate	
Website	www.monstermotors.com.sg	
Contact Person(s)	Althan	92718770
	Enzo	97598881



TRADE

This ad has a review
Monetary Singapore trading losses
invest

Compare

Upfront Payment

» more Financial info

Transfer Fee	\$25	?
Down Payment	\$5,100 (change)	Maximum 70% Loan ?
1st Instalment	\$462	?
Total Upfront Payment	\$5,587 (excluding insurance)	?

Estimates based on 70% loan at 3.75% interest rate. Check with seller for exact figure.

Items for Mitsubishi Lancer

» View All



Scuff Plate
\$50



3D Royal MAXpider
Car Mat
\$310



Sport Seat
\$350



Evolution 10 ABS
Spoiler
\$280



Evo X Front Grill (With
Side Number...
\$300



Bidded Carplate
For Sale
\$30,888

Showing 6 out of 301 suitable items for Mitsubishi Lancer View All

Pro-Jex V2D Auto Pte Ltd is a specialist workshop for Mitsubishi cars.



Afraid of lemons? Request to have
this car evaluated professionally.

Recommended for you

1-6 of 18



New Mitsubishi Lancer EX
is here! Prices, Pictures...



Mitsubishi Motors
announces special edition
Evo



Mitsubishi Lancer - EOL



MINI Connected and new
MINI Lifestyle



Lamborghini unveils new
Huracan EVO



Easy audio upgrades with
Dimension Audio

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Audi, Kia, Hyundai, Volkswagen, Mitsubishi & BMW. There are plenty of cars for sale, even for COE cars, OPC cars, vans, luxury cars, sports cars, SUV, MPV, hatchback or stationwagons. You can also buy from a car auction and look up car loans, financial services, low mileage cars, car brands, car insurance, carpark rates, car audio, car grooming, car rental, vehicle insurance, car insurance quotation, car blog, car accessories, car workshop & car sticker. Visit our partners for job openings, Singapore jobs, real estate properties for sale, facebook marketing, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2019 sgCarMart. All rights reserved.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1170H
Vehicle Details	
Vehicle No.:	SGF324B
Vehicle to be Exported:	Yes
Intended Deregistration Date:	10 Jan 2019
Vehicle Make:	MITSUBISHI
Vehicle Model:	LANCER 1.6 M
Primary Colour:	Black
Manufacturing Year:	2006
Engine No.:	4G18HC3201
Chassis No.:	JMYSNCS3A6U004956
Maximum Power Output:	79.0 kW (105 bhp)
Open Market Value:	\$11,261.00
Original Registration Date:	30 Mar 2006
First Registration Date:	30 Mar 2006
Transfer Count:	1
Actual ARF Paid:	\$12,388.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	29 Mar 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$24,771.00
COE Rebate Amount:	\$10,987.00
Total Rebate Amount:	\$10,987.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 10 Jan 2019

OK

15,000
10,987

4013



bernard 6322 4659

TP INSURER: Sampo Insurance Singapore Pte. Ltd. (HQ)
NA

Claimant Insurer: Tokio Marine Insurance Singapore Ltd

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	11/12/2018
Vehicle Reg. No.:	SGF324B	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	TAM KIM SENG		
Make/Model:	mitsubishi LANCER, 1.6 (M)	Vehicle Reg. Date:	30/03/2006
Vehicle Colour:	BLACK		
Engine No:	4G18HC3201	Chassis No:	JMYSNCS3A6U004956
Odometer:	5 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	6		
Description of Accident/Loss	REFER SKETCH PLAN		
Remarks:	VEHICLE WITH OWNER KINDLY ADVISE LIABILITY		
Present Location:	FALCON-AIR AUTO SERVICES PTE LTD (PANDAN)		

COST OF CLAIMS	Amount
Parts	5,438.40
Miscellaneous Items	0.00
Labour	2,050.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	7,488.40
+ GST 7.00% (S\$)	524.19
Nett Amount (S\$)	8,012.59

This claim is handled by: ANDY

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 13 Dec 2018)

Parts: 143 MITSUBISHI LANCER 1.6 (M) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Falcon-Air Auto Services Pte Ltd/SGF324B/13/12/2018 09:52

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*BONNET PA/	20.00	0.00	*751.00 FL
2	1		*BONNET LOCK PA/	20.00	0.00	*48.00 FL
3	1		*RADIATOR SUPPORT PANEL PA/	20.00	0.00	*693.00 FL
4	2		*HEADLAMP LH/RH CA/	20.00	0.00	*1,144.00 FL
5	1		*RADIATOR TO CHECK ? PA/	20.00	0.00	*802.00 FL
6	1		*AIRCON CONDENSER PA/	20.00	0.00	*1,121.00 FL
7	2		*FRONT GRILLE LH/RH CA/	20.00	0.00	*256.00 FL
8	1		*FRONT BUMPER DE/	20.00	0.00	*862.00 FL
9	1		*FRONT BUMPER REINFORCEMENT B+/	20.00	0.00	*139.00 FL
10	1		*FRONT BUMPER LOGO re -	20.00	0.00	*44.00 FL
11	1		*FRONT NUMBER PLATE BASE CA/	20.00	0.00	*45.00 FL
12	1		*FRONT NUMBER PLATE PA/	0	0.00	*36.00 FS
13	1		*FRONT BUMPER LOWER GARNISH mis/	20.00	0.00	*75.00 FL
14	1		*FRONT BUMPER SIDE RETAINER RH re -	20.00	0.00	*50.00 FL
15	1		*RH FRONT FENDER PA/	20.00	0.00	*573.00 FL
16	18		*RIVETS re -	20.00	0.00	*90.00 FL
17	1		*BRACE PANEL PA/	20.00	0.00	*60.00 FL

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (S\$)	6,789.00
- List Item Discount on L Items (S\$)	1,350.60
Total Parts (S\$)	5,438.40

Falcon-Air Auto Services Pte Ltd/SGF324B/13/12/2018 09:52. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO FOCUS HEADLAMP/CHECK LIGHT SYSTEM	New	30.00
2	TO REMOVE/REPLACE AIRCON CONDENSER VACUUM & REGAS	New	100 120.00
3	TO CUT OUT/REWELD RADIATOR SUPPORT PANEL, REPAIR FRONT CHASSIS , LH FRONT FENDER , RH FRONT DOOR INCLUDES KNOCKING & REPLACEMENT OF PARTS	New	600 700.00
4	SPRAY PAINTING ON ACCIDENT DAMAGED AREAS INNER/OUTER	New	900 1,200.00
Gross Labour Cost (\$\$)			2,050.00

Falcon-Air Auto Services Pte Ltd/SGF324B/13/12/2018 09:52. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office : Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862
Branches : Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop S(128226) Tel: 6779-6665 Fax: 6779-1110
Website: www.falconair.com.sg Email: email@falconair.com.sg

5438.40

1630.00

7068.40

20%

5,654.72

4/3-5,650

Repair limit 4k

Rasul

HP 90010068

7days

4/3

11/01/19 @ 1445

7days

Reguy after repair

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19000592/R1QD3N2

Date: 25/01/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTMC01002648
Claimant Vehicle No :	SGF324B	Insured Vehicle No :	FBM9108Y
Date of Loss:	11/12/2018	Nature of Claim:	TP
		Claim No:	CMTD1805510

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGF324B	Engine No:	4G18HC3201
Make & Model:	MITSUBISHI LANCER, 1.6 (M)	Chassis No:	JMYSNCS3A6U004956
Reg. Date:	30/03/2006 (Man. Year: 2006)	Odometer:	149556 km
Colour:	Black		
Engine Capacity:	1584 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60 R15	Rear Tyre Size:	195/60 R15
Front Left Side:	Falken 5 mm	Rear Left Side:	Falken 5 mm
Front Right Side:	Falken 5 mm	Rear Right Side:	Falken 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	5,438.40	5,438.40	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,050.00	1,630.00	420.00	20.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	7,488.40	7,068.40	420.00	5.61
Approved Total (Overridden) (\$\$)		4,000.00		
(\$\$)	7,488.40	4,000.00	3,488.40	46.58
+ GST 7.00/7.00% (\$\$)	524.19	280.00	244.19	46.58
Nett Amount (\$\$)	8,012.59	4,280.00	3,732.59	46.58

INSPECTION

Date of Assignment:	10/01/2019	Present Location:	Falcon-Air Auto Services Pte Ltd (Pandan)
Date Inspected:	11/01/2019	Inspected At:	Falcon-Air Auto Services Pte Ltd (Pandan) No 8 Pandan Loop Singapore
Estimated Period of Repair:	7.0 days		

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 25 Jan 2019)
Parts: 143	MITSUBISHI LANCER 1.6 (M) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SGF324B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Bent	751.00 FL	*751.00 FL
2	1		*BONNET LOCK	Bent	48.00 FL	*48.00 FL
3	1		*RADIATOR SUPPORT PANEL	Bent	693.00 FL	*693.00 FL
4	2		*HEADLAMP LH/RH	Cracked	1,144.00 FL	*1,144.00 FL
5	1		*RADIATOR TO CHECK	Bent	802.00 FL	*802.00 FL
6	1		*AIRCON CONDENSER	Bent	1,121.00 FL	*1,121.00 FL
7	2		*FRONT GRILLE LH/RH	Cracked	256.00 FL	*256.00 FL
8	1		*FRONT BUMPER	Deformed	862.00 FL	*862.00 FL
9	1		*FRONT BUMPER REINFORCEMENT	Bent	139.00 FL	*139.00 FL
10	1		*FRONT BUMPER LOGO	Necessary	44.00 FL	*44.00 FL
11	1		*FRONT NUMBER PLATE BASE	Cracked	45.00 FL	*45.00 FL
12	1		*FRONT NUMBER PLATE	Bent	36.00 FS	*36.00 FS
13	1		*FRONT BUMPER LOWER GARNISH	Missing	75.00 FL	*75.00 FL
14	1		*FRONT BUMPER SIDE RETAINER RH	Necessary	50.00 FL	*50.00 FL
15	1		*RH FRONT FENDER	Bent	573.00 FL	*573.00 FL
16	18		*RIVETS	Necessary	90.00 FL	*90.00 FL
17	1		*BRACE PANEL	Bent	60.00 FL	*60.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,789.00	6,789.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,350.60	1,350.60
Total Parts (\$\$)	5,438.40	5,438.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO FOCUS HEADLAMP/CHECK LIGHT SYSTEM	New	30.00	30.00
2	TO REMOVE/REPLACE AIRCON CONDENSER VACUUM & REGAS	New	120.00	100.00
3	TO CUT OUT/REWELD RADIATOR SUPPORT PANEL, REPAIR FRONT CHASSIS , LH FRONT FENDER , RH FRONT DOOR INCLUDES KNOCKING & REPLACEMENT OF PARTS	New	700.00	600.00
4	SPRAY PAINTING ON ACCIDENT DAMAGED AREAS INNER/OUTER	New	1,200.00	900.00
Gross Labour Cost (\$\$)			2,050.00	1,630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >