

Ke
Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SKR5939J

TP/AIG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department \ MR YAP

Estimate No: ES1991028/YISHUN

Date: 10 Jan 2019

Policy No: D18MTPV01000127

Veh Reg No: SKR5939J

Make/Model: NISSAN NOTE 1.2 DIG-S
CVT 2WD LED

Chassis No: JN1TBAE12Z0981016

Engine No: HR12057459B

Reg. Date: 23/02/2015

WS Ref: TP/AIG/YS

Claim Type: Third Party

Accident Date: 08/01/2019

TP Veh Reg No: SDJ6080D

Estimate Repair Cost to Vehicle No :SKR5939J

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
Net Price				
1 REAR BUMPER	414.00	1 PC	414.00	✓
2 REAR BUMPER BRACKETS	68.00	2 PCS	136.00	✓
3 REAR BUMPER SPONGE	111.00	1 PC	111.00	✓
4 REAR BUMPER CLIPS	5.00	6 PCS	30.00	✓
5 REAR BUMPER RH SIDE RETAINERS	44.00	2 PCS	88.00	✓
6 REAR TAILGATE	976.00	1 PC	976.00	✓
7 TAILGATE LOGO	59.70	1 PC	59.70	✓
8 TAILGATE EMBLEM (NOTE)	73.90	1 PC	73.90	✓
9 TAILGATE EMBLEM (DIGS)	55.10	1 PC	55.10	✓
10 TAILGATE INNER LOCK	155.00	1 PC	155.00	✓
11 TAILGATE INNER RUBBER	68.40	1 PC	68.40	✓
12 REAR END PANEL	552.80	1 PC	552.80	✓
13 REAR END PANEL TOP GARNISH	76.50	1 PC	76.50	✓
14 REAR SPARE TYRE TOP BOARD	528.00	1 PC	528.00	✓
15 REAR WINDSCREEN GLASS MOULDING	125.00	1 PC	125.00	✓
16 TAILLAMPS	268.80	2 PCS	537.60	✓
			3,987.00	
			Less 10%	398.70
				3,588.30
Special Net				
17 REVERSE SENSOR	200.00	1 SET	200.00	✓
18 REAR WINDSCREEN GLASS GUM	40.00	1 ROLL	40.00	✓
19 SMART KEY SENSOR	51.50	1 PC	51.50	✓
			291.50	291.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Cheng Hoe Motor Pte Ltd

Bik 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
TEL: 64193000 FAX: 64153727
ATTN: Motor Claim Department \ MR YAP

WS Ref: TP/AIG/YS
Claim Type: Third Party
Accident Date: 08/01/2019
TP Veh Reg No: SDJ6080D

Estimate No: ES1991028/YISHUN
Date: 10 Jan 2019
Policy No: D18MTPV01000127
Veh Reg No: SKR5939J
Make/Model: NISSAN NOTE 1.2 DIG-S
CVT 2WD LED
Chassis No: JN1TB AE12Z0981016
Engine No: HR12057459B
Reg. Date: 23/02/2015

Estimate Repair Cost to Vehicle No :SKR5939J

Description	U/Price	Quantity	List Price	Amount
			S\$	S\$
Labour				
20 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	✓
21 REMOVE & REFIX REAR BUMPER ASSY, TAILLAMPS, TAILGATE & ATTACHMENT, CUT, WELD & RENEW REAR PANEL, KNOCK & REPAIR REAR SPARE TYRE COMPARTMENT & REALIGN THE SAME	950.00	1 LA	950.00	800
22 PUTTY & RESPRAY ON REAR SPARE TYRE COMPARTMENT, REAR FENDERS, REAR BUMPER, TAILGATE, REAR PANEL & AFFECTED AREAS	950.00	1 LA	950.00	800
23 RUSTPROOFING	60.00	1 LA	60.00	✓
24 REMOVE & REFIX REVERSE CAMERA & RESET SYSTEM	60.00	1 LA	60.00	✓
			2,140.00	2,140.00
			Total	S\$ 6,019.80
			Add GST @ 7%	421.39
			Total Amount Payable	S\$ 6,441.19

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

Cor -
Lam 6+1=7x60=420
L7A-8