

INS. CASE OWNER:

Peter

CC Y, ASM 1900

ASSIGNMENT

DOI:

10-1-19

Date / Time:

Registered in Meriment:

10-1-19

Pre-assign / CCU / FTE

Claim No.:

SAMP1991

Policy No.:

Make / Model:

Place of Accident:

KIE

Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :\$5

Is driver the owner?

If NO, Driver Name / Age:

Driver Tel No.:

HP:

D.O.A.:

Nature of Accident:

(YES / NO)

Guth Sock lei, Pearl
925 2087 (V/L YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No

SKP 2360H

INSRS:
WSP:
Tel:
Liability:
RMKS:Alan's
UnitedINSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date / Time

STAGE

DATE / PIC

15-1

SKP 2360H x SKT 8997K x

Non-Reporting ltr (1st):
Non-Reporting ltr (2nd):
Non-Reporting ltr (Final):
Notification ltr (if non-pickup):
Call GI:
After call ltr to OI:

CPU

25/4/2019

OIO

HIO

pre-claim

Spoke to OIO, confirmed BOLA 27, OIO rear ended TP,
informed TP claim and Hep issue. OIO agree to settle
and mention have HIO protection. Sent letter to OI.

19/8

20/8

21/8

26/8

pending finalise LOR

to get supp inst from KSC & get KSC to fill up
parts condition & to finalise.

to seek mandate.

Pending mandate approval.

offer G/S \$7950 (Pending acceptance).

TP reject offer. seek AXA instruction. TP propose
\$9106.00.

Settle @ \$9106, DV send (Pending DV).

HIO print photo

Documentation Check List: Handler Typist
Notification ltr (if non-pickup) ☒ ☐
After call ltr to OI: ☒ ☐
Authorisation To Act: ☒ ☐
Release Voucher: ☒ ☐
Final Repair Bill: ☒ ☐
Car Rental Invoice: ☒ ☐
Towing Invoice: ☒ ☐
LTA / GIA: ☒ ☐
Medical Bill: ☒ ☐
PIR: ☒ ☐
Mandate/Reject Instruction: ☒ ☐
LOD: ☒ ☐
Payment Breakdown Form: ☒ ☐
Post-Repair Photos: ☒ ☐
Others: ☒ ☐

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: Kenneth

Repair Cost:

\$5 7200.00

(6 days)

Reduction:

\$2944.69

% 29

Email ☐Call ☐

FINAL SETTLEMENT

Date/Time:

26/8/19 5pm

Confirm with:

Kenneth

Email ☒Call ☐

Final Liability:

% 100

(Agreed / Assessed)

BOLA S/N No.:

27

Repair Cost:

\$7704.00

Loss of Rental (LOR):

\$5 1400.00

(10 days)

x

140.00

Loss of Use (LOU):

\$5 -

(3 x days)

x

days)

Loss of Income (LOI):

\$5 -

(3 x days)

x

days)

LOR only ☒LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

\$5 2.00

Medical:

\$5 -

Disbursement:

\$5 -

(e.g. Tow / Independent)

x

Legal Cost

\$5 -

Total:

\$5 9106.00

Global Sum \$5:

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☒Call ☐

Payee 1:

\$5 9106.00

Name 1:

Alan's United Auto Pte Ltd

Payee 2: (Only if N.A.)

\$5 -

Name 2:

Payee 3: (Strike if N.A.)

\$5 -

Name 3:

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 05904

Vehicle Insured : SKT8997K
Accident Date : 05-Jan-2019

Date : 09-Jan-2019

Our Ref : 219003 (AXA) / CHAN

PAGE : 1

CROWN PACIFIC BIOTECHNOLOGY PTE LTD
38 PENJURU LANE
Singapore 609204

Not withair
11 by 8?

5-6 days

ESTIMATED COST OF REPAIR FOR VOLKSWAGEN MULTIVAN 2.0 TDI SKP2360H

1 pc	Tail gate			Ry	2,880.00	—
1 pc	Tail gate rubber			As	160.00	—
1 pc	Tail gate inner lock			Tr	290.00	—
1 pc	Tail gate wiper motor			Tr	280.00	✓
1 pc	Tail gate glass moulding	INNER SIDE		nn	550.00	✓ X
1 pc	Tail gate inner trim			my	720.00	✓
1 pc	Tail gate logo			Tr	75.00	—
1 pc	Tail gate "MULTIVAN" emblem			Tr	55.00	—
1 pc	Tail gate "TDI" emblem			Tr	45.00	—
1 pc	Tail gate outer garnish			wrap	270.00	—
1 pc	Tail gate lower outer handle			Tr	230.00	X
1 pc	Rear bumper fascia			Bu	1,200.00	—
2 pcs	Rear bumper reflector	@ S\$ 50.00		CM	100.00	—
1 pc	Rear bumper reinforcement			By	600.00	—
1 pc	Rear bumper inner parts			CM	95.00	—
2 pcs	Rear bumper side retainer	@ S\$ 40.00		Tr	80.00	X
					7,630.00	
				Less 10% :	763.00	

- 1 pc Tail gate lower chrome mouldig
- 1 pc Tail gate sealnt
- 1 pc Rear no. plate with box
- 1 pc Rear bumper reverse sensor (4pc) *2*

6770.00
677.00
6093.00
6,867.00
CM 180.00 sn
Tr 60.00 sn
Tr 50.00 sn
5407 400.00 sn

To remove & renew rear windscreen
glass and conduct water leak test.

150.00 1201

Con't Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SKT8997K

Page : 2

To remove roof lining, front and rear seats, trim board and carpet

120.00 ⁶⁰¹

To apply undersealing

80.00 ? X

To putty and spray replaced parts

750.00 ⁶⁰⁰¹

To remove, cut-out damaged parts, panel beating, welding, align, refix and to renew above parts

800.00 ⁵⁴⁰¹

Total : S\$ 9,457.00

Singapore Dollars Nine Thousand Four Hundred and Fifty Seven Only

L/SUM
~~7500~~ 7200
④
6 DAYS

REMOVED PUS GUPH
7ks.

P 6093.00
SN 270.00
S.P 687.69
L 1320.00
8370.69
837.06
- 10%
7533.63

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SKT8997K (AXA)

Date : 12-01-2019

Accident Date : 05-01-2019

Our Ref : 219003 / CHAN

CROWN PACIFIC BIOTECHNOLOGY PTE LTD

C/O ALAN'S UNITED AUTO PTE LTD

SUPPLEMENTARY ITEM PRICE FOR VOLKSWAGEN MULTIVAN 2.0 TDI SKP2360H

1 PC	END PANEL TOP GARNISH	<i>mgcm</i>	\$175.00	—
1 PC	END PANEL TOP GARNISH CHROME	<i>nd</i>	\$415.00	—
1 PC	TAIL GATE EVPORATOR CONTROL BOX	<i>nd</i>	\$112.00	—
1 PC	TAIL GATE EVPORATOR CONTROL BOX SWITCH	<i>cm</i>	\$62.10	—
			\$764.10	
		LESS 10%	\$76.41	
			<u>\$687.69</u>	

Singapore Dollars Six Hundred Eighty Seven And Cents Sixty Nine Only

10,144.69

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 05904

Vehicle Insured : SKT8997K
Accident Date : 05-Jan-2019

Date : 09-Jan-2019

Our Ref : 219003 (AXA) / CHAN

PAGE : 1

CROWN PACIFIC BIOTECHNOLOGY PTE LTD
38 PENJURU LANE
Singapore 609204

Not Withheld

11 by 8?

5-6 days

ESTIMATED COST OF REPAIR FOR VOLKSWAGEN MULTIVAN 2.0 TDI SKP2360H

1 pc	Tail gate	
1 pc	Tail gate rubber	
1 pc	Tail gate inner lock	
1 pc	Tail gate wiper motor	
1 pc	Tail gate glass moulding	INNER SIDE
1 pc	Tail gate inner trim	
1 pc	Tail gate logo	
1 pc	Tail gate "MULTIVAN" emblem	
1 pc	Tail gate "TDI" emblem	
1 pc	Tail gate outer garnish	
1 pc	Tail gate lower outer handle	
1 pc	Rear bumper fascia	
2 pcs	Rear bumper reflector	@ S\$ 50.00
1 pc	Rear bumper reinforcement	
1 pc	Rear bumper inner parts	
2 pcs	Rear bumper side retainer	@ S\$ 40.00

R	2,880.00	—
G	160.00	—
T	290.00	—
	280.00	? ✓
M	550.00	? X
	720.00	? ✓
M	75.00	—
M	55.00	—
M	45.00	—
M	270.00	—
	230.00	X
A	1,200.00	—
C	100.00	—
	600.00	? ✓
	95.00	? ✓
	80.00	X

Less 10% : 7,630.00

6770.00
677.00
6093.00

1 pc	Tail gate lower chrome moulding	
1 pc	Tail gate sealant	
1 pc	Rear no. plate with box	
1 pc	Rear bumper reverse sensor	(4pc 2)

M	180.00	sn ✓
M	60.00	sn
M	50.00	sn
X	400.00	sn 47

To remove & renew rear windscreen
glass and conduct water leak test.

150.00 1201

Con't Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SKT8997K

Page : 2

To remove roof lining, front and rear seats, trim board and carpet

120.00

To apply undersealing

80.00 ? X

To putty and spray replaced parts

750.00 600

To remove, cut-out damaged parts, panel beating, welding, align, refix and to renew above parts

800.00 540

Total : S\$ 9,457.00

Singapore Dollars Nine Thousand Four Hundred and Fifty Seven Only

L/SUM

7500

@

6 DAYS

REMARK: PUS GUTTER
YES.

P 6093.00

SN 270.00

S.P 687.69

L 1320.00

8370.69

837.06

- 10%

7533.63

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 05904

Vehicle Insured : SKT8997K
Accident Date : 05-Jan-2019

Date : 09-Jan-2019

Our Ref : 219003 (AXA) / CHAN

PAGE : 1

CROWN PACIFIC BIOTECHNOLOGY PTE LTD
38 PENJURU LANE
Singapore 609204

*Not Withain
61 Rm 8?*

5-6 days

ESTIMATED COST OF REPAIR FOR VOLKSWAGEN MULTIVAN 2.0 TDI SKP2360H

1 pc	Tail gate			<i>Rs</i>	2,880.00	✓
1 pc	Tail gate rubber			<i>Rs</i>	160.00	✓
1 pc	Tail gate inner lock			<i>Rs</i>	290.00	✓
1 pc	Tail gate wiper motor				280.00	?
1 pc	Tail gate glass moulding			<i>Rs</i>	550.00	<i>sur?</i>
1 pc	Tail gate inner trim				720.00	?
1 pc	Tail gate logo			<i>Rs</i>	75.00	✓
1 pc	Tail gate "MULTIVAN" emblem			<i>Rs</i>	55.00	✓
1 pc	Tail gate "TDI" emblem			<i>Rs</i>	45.00	✓
1 pc	Tail gate outer garnish			<i>wrap</i>	270.00	✓
1 pc	Tail gate lower outer handle				230.00	✓
1 pc	Rear bumper fascia			<i>Bu</i>	1,200.00	✓
2 pcs	Rear bumper reflector	@ S\$ 50.00		<i>cm</i>	100.00	✓
1 pc	Rear bumper reinforcement				600.00	?
1 pc	Rear bumper inner parts				95.00	?
2 pcs	Rear bumper side retainer	@ S\$ 40.00		<i>Rs</i>	80.00	X
					7,630.00	
Less 10% :					763.00	

1 pc Tail gate lower chrome mouldig
1 pc Tail gate sealnt
1 pc Rear no. plate with box
1 pc Rear bumper reverse sensor(*4pc* 2

6,867.00
cm 180.00 *sn* ✓
40sn 60.00 *sn* ✓
Rs 50.00 *sn* ✓
400.00 *sn* 4r

To remove & renew rear windscreen
glass and conduct water leak test.

150.00 *12cl*

UKK Auto Consultants hence notify
the Repairer of the following:
• To survey & estimate spray painting
• To display damaged parts during survey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be surveyed and
is subject to final approval from Insurance Company

Authorised by: *Signature*

Con't Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SKT8997K

Page : 2

To remove roof lining, front and
rear seats, trim board and carpet

120.00 *601*

To apply undersealing

80.00 ?

To putty and spray replaced parts

750.00 *6001*

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

800.00 *5401*

Total : S\$ 9,457.00

=====

Singapore Dollars Nine Thousand Four Hundred
and Fifty Seven Only

Enquire Vehicle Registration Details**Owner Particulars**

NRIC/Passport
/Company Cert No.: 200301188H

Owner ID Type: Company

Owner Name: CROWN PACIFIC BIOTECHNOLOGY PTE. LTD.

Registered Address: 38 PENJURU LANE SINGAPORE 609204

Mailing Address: -

Birth Date: -

Vehicle Particulars

Vehicle No.: SKP2360H

Previous Vehicle No.: SKD1689E

Effective Date of Ownership: 31 Oct 2011

Original Regn Date: 31 Oct 2011

Registration Date: 31 Oct 2011

Year of Manufacture: 2011

Vehicle Type: Passenger (Co) Company Station Wagon (Single Rate)

Vehicle Scheme: -

Vehicle Attachment 1: With Sun Roof

Vehicle Attachment 2: -

Vehicle Attachment 3: -

Vehicle Make: VOLKSWAGEN

Vehicle Model: MULTIVAN 2.0 TDI AT 7EMH47

Primary Colour: Silver

Secondary Colour: -

Passenger Capacity: 6

Chassis No.: WV2ZZZ7HZCH033224

Engine No.: CFC047554

Engine Capacity /Power Rating: 1968 cc / -

Maximum Power Output: 132.0 kW (177 bhp)

Propellant: Diesel



Service Request Details

Claim

S9M0199D

Reference

None

Loss Date

5 January 2019

Request Date

10 January 2019

Due Date

17 January 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Incident Only

Services

Pending verification - Direct Settlement

10.01.2019 @ 908am

Kenny veh in.

Kenneth

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SKP2360H

Make

TPVD



Service Address

Primary Contact/Insured

POH CHEY HUAT
BLK 224 #10-98, SIMEI STREET 4, 520224, Singapore
92252087
DOGAvenue@YAOO.COM

Claim Handler

Owner Default

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

Catherine Chong (LKK Auto)

From: kennychan@alanutd.com
Sent: Wednesday, 9 January, 2019 11:51 AM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Subject: ATTACHED SKP2360H REPAIR ESTIMATE GIA REPORT TO REQUEST JOINT EXPERT SURVEYOR LIST FOR CONDUCT PRE SURVEY
Attachments: SKM_284e19010911320.pdf
Categories: Mateen

Dear Motor Claims Dept.

Attached our client vehicle SKP2360H repair estimate , GIA report to request joint expert surveyor list for us to choose surveyor to conduct pre repair survey , claiming your insured vehicle SKT8997K accident on 05-01-2019
Thank you .

Regards
Kenny
Alan's United Auto Pte Ltd
64538686



Auto
Consultants
Pte Ltd

Company Registration No. 199607188R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 20/8/2019

Survey Details:

Date of loss	5-Jan-19
Date of appointment	10-Jan-19
Date of survey	10-Jan-19
Location of survey	ALAN'S UNITED AUTO PTE LTD

Vehicle Details:

Claim Type:	THIRD PARTY CLAIM
Vehicle number	SKP 2360H
Make and Model	VOLKSWAGEN MULTIVAN 2.0 TDI
Date of registration	31-Oct-11
Parf Rebate	
Market Value	\$ 61,000.00
Parf Rebate	\$ 53,833.00
Nett Loss	\$ 7,167.00

Repair details:

Initial Estimate	9,457.00
------------------	----------

Proposed/Revised repair cost:

Parts	\$ 7,050.69
Check items (estimate)	\$ -
Labour	\$ 1,320.00
Total	\$ 8,370.69
Lump Sum(if applicable)	\$ 7,200.00

Number of days for repair	6DAYS
---------------------------	--------------



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

06 RECOMMENDED REPAIR DAYS + 3 PRS + 2 SUNDAYS = 11 DAYS

Mandate:

Liability(TP)	100%	
Proposed repair cost	\$ 7,704.00	W/GST
Loss of use	\$ -	
Loss of rental	\$ 1,980.00	11days x \$180
Loss of income	\$ -	
LTA search fees	\$ 2.00	
Others	-	
Proposed Total	9686	



<MANDATE IA> -S9M0199D {ACCIDENT INVOLVING SKT 8997K(OI) & SKP 2360H(TP) ON 05/01/2019}

Type

🔗 Question

Message

LIABILITY: 100% BOLA 527: INFORMED OI ABOUT TP CLAIM AND NCD ISSUE. AGREED TO SETTLE AT BEST. WE SEEK YOUR MANDATE AT \$9686.00 (CLAIMING LOR). MANDATE IA HAS BEEN UPLOADED IN SMARTCLAIM. KINDLY LET US HAVE YOUR APPROVAL/INSTRUCTION. THANKS - CECILIA

Reply



Pls proceed DS with below revised quantum

Type

🔗 Question

Message

COR: \$6696.55 (-20% lump-sum repair from \$8370.69); LOR: \$1260 (\$140/day for 9 days - 1d PRS, 2d weekends and 6d repair); LTA: \$2.00. Total: \$7958.55. If TP rejects, you have global sum settlement mandate up to \$8000 (all-in)

Reply



Pls revise our offer with below quantum

Type

🔗 Question

Message

COR: \$6696.55 (-20% lump-sum repair from \$8370.69); LOR: \$2520 (\$140/day for the requested 18 days from LOD, including the delay caused by part sourcing); LTA: \$2.00. Total: \$9218.55. If TP rejects, you have global sum settlement mandate up to \$9250 (all-in)

Reply

CROWN PACIFIC BIOTECHNOLOGY PTE LTD

c/o Blk 7 Sin Ming Industrial Estate

#01-76

Singapore 575642

Date: 15-2-2019

AXA INSURANCE SINGAPORE PTE LTD
MOTOR CLAIMS DEPT.

8 STANTON WAY

#27-01 AXA TOWER

SINGAPORE 068811

Dear Sir / Madam

ACCIDENT INVOLVING MOTOR VEHICLES SKP 2360 H AND SKT 8997 K
ALONG KPE EXIT TO PIE (TUN) ON 5-1-2019

I / We, the owner of Vehicle No. SKP 2360 H which was involved in the above accident.

My / Our vehicle sustained damages as a result of the above said accident and I / we are now claiming against you for the followings:-

- | | | |
|--|---|------------|
| 1. Costs of repair | - | \$7704.00 |
| 2. Loss of Use /Rental fees 18 Days | - | \$4320.00 |
| 3. Police / GIA report / LTA fees | - | \$1.00 |
| 4. Surveyor report fees | - | |
| 5. Others | - | |
| Total: | | \$12026.00 |

Please advise whether you are now prepare to settle my claims as outlined above.

I / We hereby authorise my / our repairers, M/s Alan's United Auto Pte. Ltd. and/or their representatives to negotiate/compromise settlement of my / our above claim on my / our behalf. If there is a settlement I / we further authorise you to pay whatever settlement sum to my / our repairers being the outstanding repair bill and incidentals due to them.

Your kind attention and prompt settlement is much appreciated.

Yours faithfully,







KIAN HUA

KIAN HUA MOTOR CO. PTE LTD
7 Jalan Lembah Kallang Singapore 339563
Tel: 62933850 Fax: 63551800
Email: Sales@Kianhuamotor.Com
Co. Reg No. / GST Reg No: 200106569G

Customer's Copy

Customer: ALAN'S UNITED AUTO PTE LTD

Address: BLK 7 SIN MING IND EST
#01-76
SINGAPORE 575642

Tax Invoice No: SRI2692475

Date: 24/01/2019

Area Code: 1 DELIVER

Credit Terms: 30Days

Kian Hua Sales: TEY

SKP2360

P/O No: SOR1012027

SOR1012027

WWW.KIANHUAMOTOR.COM

No.	Description	Qty	Unit Price	Amount
1	BOOT LOCK VW TPT3 12> OPERATING	1		
2	CHILD CATCH TRIM VW TPT 12> LONG	1		

Products received and checked to be in good condition

Sub-Total:

G.S.T(7%):

Total :

Customer's Signature / Company Stamp
Products sold are not returnable.

Page: 1 of 1

FOR KIAN HUA OFFICIAL USE:

PAID / AMOUNT:

TIME:

TEY - 24/01/2019 4:09:30 PM

Authorised Signature

M/S: ALAN'S UNITED AUTO PTE LTD

BLK 7 SIN MING IND EST

#01-76

SINGAPORE 575642

TEL: 6453-8686

ATTN: WAH

FAX: 6459-6550

Delivery Time: 25-Jan-19

SKP2360

SALES ORDER

NO: SORI011967

PAGE: 1/1

DATE: 10 Jan 2019

A/C CODE: KALANS

TERM: 30Days

Part No	Due Dat	Description	Quantity	Unit Price	Amount
				<u>SGD</u>	<u>SGD</u>
1	7H5864585A-30T	BUMPER TOP GARNISH VW TPT 12> COVER	1 PC		

Total Qty: 1 PC

Add GST @ 7%

Alan'S United Auto Pte Ltd

For Kian Hua Motor Co. Pte Ltd

CONFIRMED & ACCEPTED BY

Once the order is confirmed, it cannot be cancelled. Goods sold are not returnable.

AUTHORISED SIGNATURE

TEY



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

30 APRIL 2019

POH CHEY HUAT
BLK 168C SIMEI LANE
#06-56
SINGAPORE 523168

Dear Sir/Madam,

OUR REF : CC4/ASM19000606/Kfa3
YOUR REF : SKT 8997K
ACCIDENT INVOLVING SKT 8997K AND SKP 2360H ALONG KPE > PIE KALLANG
BAHRU FLYOVER ON 05/01/2019

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from ALAN'S UNITED AUTO PTE LTD, acting on behalf of the owner of SKP 2360H against your motor insurance policy.

Based on the accident report, accident scenario, it was reported that your vehicle had rear-ended the Third Party vehicle SKP 2360H. As such, liability is down against us.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter.

Your full co-operation in the handling of the claim is required and kindly submit the following to pohkin@lkkauto.com within 7 days from the date of this letter **if not provided at AXA's reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at pohkin@lkkauto.com

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,

Poh Kin Chong
Case Handler
DID: 6841 2132
FAX: 6741 4108
Email: pohkin@lkkauto.com

c.c. AXA Insurance Pte Ltd (AXA)
(Motor Claims Dept)

LETTER OF AUTHORITY

ACCIDENT INVOLVING SKP2360H And SKT 8997K
ALONG KPE Exit To PIE (Tuas)
ON 5-1-2019

BY THE LETTER OF AUTHORITY, I / We, CROWN PACIFIC BIOTECHNOLOGY PTE LTD
NRIC NO. 200301188H The owner of Vehicle No. SKP2360H

Hereby irrevocably appoint Messrs **Alan's United Auto Pte. Ltd.** at Block 7, Sin Ming Industrial Estate, Sector C, #01-76, Singapore 575642, and/or their representative to process the Third Party claim on my/our behalf and to do all and/or any of the followings:-

1. To submit, negotiate/compromise and to resolve settlements of my/our above mentioned claim.
2. To collect payment(s) due in respect of any such claim(s) for the loss and damage, such payment to be made by way of Cheque in favor of **Alan's United Auto Pte. Ltd.**
3. For any of the purpose aforesaid, to execute, sign and deliver all documents whatsoever as they deem necessary for the purpose of settling my/our said claim.

I / We hereby declare that all the processing and documents done by virtue of this letter of authority on my/our behalf by my/our repairers or any person authorized by them shall be as good valid and effectual to all intends and purposes whatsoever as if the same had been done or executed by me/us in person.

I / We further confirm that the acceptance by Messrs **Alan's United Auto Pte. Ltd.** of the settlement amount constitute the full discharge of my/our claim(s) in respect of the above accident.

Signed on the 07 (day) 01 (month) 2019 (year)

Acknowledged by Owner
(company stamp if applicable)





AXA THIRD PARTY DIRECT SETTLEMENT

Vehicle No:	BKT 8997K	(Insd veh)	Model: VOLKSWAGEN MULTIVAN
	SKP 2360H	(TP veh)	
Date of Accident/ Time:	05/01/2019 / 09:40		

Repair Estimate	: \$	10,854.82	
Final Repair Cost	: \$	7,704.00	(WG&T)
Loss of Use	: \$		days at \$ per day
Rental (if any)	: \$	1,400.00	10 days at \$ 140.00 per day
LTA / GIA Search Fee	: \$	2.00	
Others:	: \$		
Final Settlement Sum	: \$	9,106.00	
Payee Name : ALAN'S UNITED AUTO PTE LTD			
Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)			
A)	For Non GIA Registered Workshop:		Agreed Liability 100 (%)
B)	For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____
	BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks:			


NOTE:

- PLEASE EXPRESSLY RESERVE YOUR CLIENT'S RIGHTS IF SO REQUIRED IN THIS SETTLEMENT DOCUMENT.
- THIS SETTLEMENT IS ON A WITHOUT PREJUDICE BASIS AND SHOULD NOT CONSTRUED AS AN ADMISSION OF LIABILITY ON AXA AND THEIR CLIENT/TORTFEASOR IN ANY MANNER WHATSOEVER.
- AXA RESERVES THEIR RIGHTS UNDER THE POLICY TERMS & CONDITIONS AS WELL AS THEIR RIGHTS IN LAW.

Only applicable to rental claim - All document are to be submitted with this settlement confirmation. In the event, rental agreement / invoices are not received within 7 days of this signed confirmation, we will automatically revert to loss of use claim per the NIMA rates.

We/I confirmed that this is a full and final settlement that we and or our client have/had/has against you (AXA and their policyholder/authorised driver/tortfeasor) for any and all losses (past/present/future) arising from this accident.

We confirmed that we have the authority of our client to act for and on their behalf in this accident.

  Signature of workshop representative / Workshop stamp Name of Representative: KENNY Date: 26-8-2019	 Signature of Witness / Workshop stamp (if applicable) Name of Witness: Date: 26-8-19
  Signature of AXA's surveyor/representative: Name of AXA's surveyor /Representative: Date: 29/8/19	

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 15683

Vehicle Insured : SKT8997K

Accident Date : 05-Jan-2019

Date : 14-Feb-2019

Our Ref : 219003 (AXA) / CHAN

PAGE : 1

CROWN PACIFIC BIOTECHNOLOGY PTE LTD

38 PENJURU LANE

Singapore 609204

FINAL REPAIR COST FOR VOLKSWAGEN MULTIVAN 2.0 TDI SKP2360H

To supply spare parts

To remove & renew rear windscreen
glass and conduct water leak test.

To remove roof lining, front and
rear seats, trim board and carpet

To apply undersealing

To putty and spray replaced parts

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

	7,200.00
Add 7% GST :	504.00
Total :	S\$ 7,704.00

Singapore Dollars Seven Thousand Seven Hundred
and Four Only

HUI SHOON CAR RENTAL

#BLK 4, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-125,
SINGAPORE 575636, TEL: 6453 1473
REGN. NO.: 53013461J

VRA NO:

16954

VEHICLE RENTAL AGREEMENT

HIRER'S PARTICULAR		Vehicle No: SDK1334		Mileage Out: 68874	
Hire: CROWN PACIFIC BIOTECHNOLOGY P.L		Make & Model: TOYOTA ESTIMA		Auto/Manual: ☒ Auto	
NRIC / Passport No: 38 PENJURAN LONG		OUT Date: 7-1-2019		OUT Time: 11.50 A.M.	
Address: S 609214		Replace Veh No:		Mileage Out:	
Driving Licence No: 96589485		OUT Date:		OUT Time:	
Contact Number:					
DRIVERS PARTICULARS (If different from Hirer)		CHARGES			
Appointed Driver: LONG TIEN SENG		Daily 18 @ \$240/- per day 4320.00			
NRIC / Passport No: S1651429B		Weekly @ \$ per week			
Date of Birth: 5-1-1964		Monthly @ \$ per month			
Address: 30 SEGBAN ROAD		Hours @ \$ per hour			
# U5-03 S 677723		Others @ \$			
Driving Licence No: 96589485					
Pass Date: 12-10-1982					
Contact Number:		SUB-TOTAL \$ 4320.00			
New Insurance Policy Terms & Conditions as at 08-12-2010		PETROL LEVEL			
1. NOT PERMITTED TO DRIVE - Not Covered		Out E 1/4 1/2 3/4 F			
Driver Age 22 years old and below		In E 1/4 1/2 3/4 F			
Driver above Age 70 years old		TOTAL CHARGES \$ 4320.00			
Driver less than 2 years Driving Experience					
2. ADDITIONAL EXCESS - S\$3000.00		IMPORTANT! FOR SINGAPORE USE ONLY			
Driver Age 23 to 25 years old with 2 years driving experience		Excess Liability: S\$2500.00			
Driver Age 65 to 70 years old with 2 years driving experience		Malaysia Excess (With Prior Consent): NOT ALLOWED.			
REMARKS		Hirer's Signature: 			
SKP 2360 H		Addition Driver's Signature: 			
					

I have read and agree to the terms and condition on both sides of this agreement. If I have presented a charge/credit card for payment, I agree that all amounts payable under this agreement and for parking and traffic infringements may be billed to that account and my signature above will be considered to have been made on the charge/credit card voucher. All information I have given HUI SHOON CAR RENTAL, in connection with this agreement is true.

* IMPORTANT

- ONLY PERSONS ABOVE 25 TO BE BELOW 65 YEARS OLD WITH MORE THAN 3 YEARS DRIVING EXPERIENCE. AUTHORISED, LICENSED AND SIGNING THIS AGREEMENT MAY DRIVE THE VEHICLE. OTHERWISE ADDITIONAL S\$3000.00 EXCESS IS APPLICABLE.
- ALL PARKING AND TRAFFIC VIOLATIONS ARE THE RESPONSIBILITY OF THE HIRER, AND ADMINISTRATIVE CHARGE WILL BE LEVIED ON ANY TRAFFIC VIOLATIONS REDIRECTED.
- THE HIRER SHALL BE LIABLE FOR EXCESS CHARGES FOR ANY LATE RETURN AT THE RATE SHOWN PER HOUR OR PER DAY, INCLUSIVE OF CDW AND/OR PAI WHERE APPLICABLE.
- VEHICLE IS STRICTLY FOR SINGAPORE USE ONLY, AND MAY NOT BE DRIVEN OUT OF SINGAPORE WITHOUT PRIOR CONSENT OF THE COMPANY HUI SHOON CAR RENTAL.
- IN CASE OF ACCIDENT, THE HIRER SHALL REPORT TO RENTAL OFFICE IMMEDIATELY, IF THERE IS BODILY INJURIES, A POLICE REPORT MUST BE MADE WITHIN 24 HOURS.

RETURN OF VEHICLE. THE HIRER / DRIVER IS REQUIRED TO SIGN IN THE COLUMN "SIGNATURE OF HIRER / DRIVER" FAILING WHICH THE DAY AND TIME INSERTED BELOW SHALL BE DEEMED TO BE THE DAY AND TIME THE VEHICLE IS RETURNED TO HUI SHOON CAR RENTAL AND THE SAME SHALL BE ACCEPTED AS CONCLUSIVE EVIDENCE OF THE SAME AND SHALL NOT BE CHALLENGED OR QUESTIONED ON ANY ACCOUNT WHATSOEVER.

DATE IN	TIME IN	MILEAGE	CHECKED BY	SIGNATURE OF HIRER / DRIVER
25/1/19	2.50 PM	70120		

HUI SHOON CAR RENTAL

BLK 1, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-125, SINGAPORE 575636. TEL: 6453 1473

INVOICE NO. **29024**

CUSTOMER

CROWN PACIFIC BIOTECHNOLOGY
PTE LTD.
C/O ALAN'S UNITED AUTO PTE LTD

BLK 7 SIN MING IND. ESTATE
SECTOR C, #01-76
SINGAPORE 575642.

ATTN: MR. ALAN KHONG

DATE : 25.01.2019

REF.NO : --

TERM : CASH

RENTAL FEES FOR :-

s/no.	vehicle no.	vra no.	yr reference	no. of day/s	unit pr	amount
1	SDK 133U	16954	SKP 2360H	18	\$ 240.00	\$ 4,320.00
		***	*****	***		

TOTAL : **\$ 4,320.00**

PLEASE LET US HAVE YOUR CHEQUE MADE IN FAVOR
OF **HUI SHOON CAR RENTAL**

YOUR EARLY REMITTANCE IS MUCH APPRECIATED.



HUI SHOON CAR RENTAL


**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
 Phone: +65 6224 0010 Fax: +65 6224 0030
 Operating Hours: Monday to Friday 9am to 5pm
 GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-19-002802

Date of Request: 07/01/2019

Your Ref No: Online Purchase

Alan's United Auto Pte Ltd
 Blk 7 Sin Ming Industrial Estate
 #01-76
 Singapore 575642

Dear Sir/Madam,

Enquiry Date: 07/01/2019
 Enquiry By: Chan Yew Siah
 TP Vehicle No: SKT8997K
 Accident Date: 05/01/2019

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-19-002802

Date of Request: 07/01/2019

Your Ref No: Online Purchase

Alan's United Auto Pte Ltd
Blk 7 Sin Ming Industrial Estate
#01-76
Singapore 575642

Dear Sir/Madam,

Enquiry Date 07/01/2019
Enquiry By Chan Yew Siah
TP Vehicle No. SKT8997K
Accident Date 05/01/2019

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SKT8997K	AXA Insurance Pte Ltd	25/06/2018-24/06/2019	6338 7288

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM19000606/Kga3q2	
8 SHENTON WAY #24-01 AXA TOWERS SINGAPORE 068811 ATTN: PETER		Date : 03-09-2019 Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKT 8997K	Veh. Inspected	SKP 2360H
Policy No.	GA359665/1	Coverage (\$)	0.00
Claim No.	S9M0199D	Excess (\$)	0.00
Assign From		Assign Date	10/01/2019
2. Vehicle Particulars & Condition			
Make & Model	VOLKSWAGEN MULTIVAN	c.c	1968
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	WV2ZZZ7HZCH033224	Colour	METALLIC SILVER
Odometer	73340	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	255/45 R18	PIRELLI	8 mm
L/H Front Tyre	255/45 R18	PIRELLI	8 mm
R/H Rear Tyre	255/45 R18	PIRELLI	8 mm
L/H Rear Tyre	255/45 R18	PIRELLI	8 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	05/01/2019	Inspection Date	10/01/2019
Survey held at	ALAN'S UNITED AUTO PTE LTD BLK 7 SIN MING INDUSTRIAL ESTATE #01-76 SINGAPORE 575642		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKP 2360H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	TAIL GATE (CONSISTENT)	BENT	2,880.00	2,880.00
1	TAIL GATE RUBBER (CONSISTENT)	CUT	160.00	160.00
1	TAIL GATE INNER LOCK (CONSISTENT)	JAMMED	290.00	290.00
1	TAIL GATE WIPER MOTOR (CONSISTENT)	JAMMED	280.00	280.00
1	TAIL GATE GLASS MOULDING (CONSISTENT)	NOT NECESSARY	550.00	-
1	TAIL GATE INNER TRIM (CONSISTENT)	MTG DISTORTED	720.00	720.00
1	TAIL GATE LOGO (CONSISTENT)	NECESSARY	75.00	75.00
1	TAIL GATE 'MULTIVAN' EMBLEM (CONSISTENT)	NECESSARY	55.00	55.00
1	TAIL GATE 'TDI' EMBLEM (CONSISTENT)	NECESSARY	45.00	45.00
1	TAIL GATE OUTER GARNISH (CONSISTENT)	WARPED	270.00	270.00
1	TAIL GATE LOWER OUTER HANDLE (CONSISTENT)	SERVICEABLE	230.00	-
1	REAR BUMPER FASCIA (CONSISTENT)	BUCKLED	1,200.00	1,200.00
2	REAR BUMPER REFLECTOR @\$50.00 (CONSISTENT)	CRACKED	100.00	100.00
1	REAR BUMPER REINFORCEMENT (CONSISTENT)	BENT	600.00	600.00
1	REAR BUMPER INNER PARTS (CONSISTENT)	CRACKED	95.00	95.00
2	REAR BUMPER SIDE RETAINER @\$40.00 (CONSISTENT)	SERVICEABLE	80.00	-
1	END PANEL TOP GARNISH (ADDITIONAL)(CONSISTENT)	MTG CRACKED	175.00	175.00
1	END PANEL TOP GARNISH CHROME (ADDITIONAL) (CONSISTENT)	DENTED	415.00	415.00
1	TAIL GATE EVAPORATOR CONTROL BOX (ADDITIONAL) (CONSISTENT)	DENTED	112.00	112.00
1	TAIL GATE EVAPORATOR CONTROL BOX SWITCH (ADDITIONAL)(CONSISTENT)	CRACKED	62.10	62.10
	LESS 10% DISCOUNT		-839.41	-753.41
			7,554.69	6,780.69
SPECIAL NETT ITEMS				
1	TAIL GATE LOWER CHROME MOULDING (SN) (CONSISTENT)	CRACKED	180.00	180.00
1	TAIL GATE SEALANT (SN) (CONSISTENT)	NECESSARY	60.00	40.00
1	REAR NO.PLATE WITH BOX (SN) (CONSISTENT)	DENTED	50.00	50.00

Report Ref No. CC4/ASM19000606/Kga3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
4	REAR BUMPER REVERSE SENSOR (SN) (CONSISTENT)	SHORTED (2 PCS ONLY)	✓ 400.00	200.00
			690.00	470.00
	LABOUR			
	TO REMOVE & RENEW REAR WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.		150.00	✓ 120.00
	TO REMOVE ROOF LINING ,FRONT AND REAR SEATS ,TRIM BOARD AND CARPET .		120.00	✓ 60.00
	TO APPLY UNDERSEALING.	NOT NECESSARY	80.00	-
	TO PUTTY AND SPRAY REPLACED PARTS .		750.00	✓ 600.00
	TO REMOVE,CUT -OUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN ,REFIX AND TO RENEW ABOVE PARTS.		800.00	✓ 540.00
			1,900.00	1,320.00
GRAND TOTAL			10,144.69	8,570.69
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				7,200.00

Report Ref No. CC4/ASM19000606/Kga3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Service Request Details

Claim

59M01990

Reference

CCN/ASM19000606/Kga3a2

Loss Date

5 January 2019

Report Date

6 Jan 2019 9:19:00 AM

Request Date

21 May 2019

Due Date

Vehicle Information

Incident Vehicle Registration #

SKP2360H

Make

TPVD

Model

VOLKSWAGEN MULTIVAN

Service Address

Actions

Next Step

Wait for Approve Invoice

Next Step

Wait for Approve Invoice

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Primary Contact/Insured

POH CHEY HUAT

BLK 224 #10-98, SIMEI STREET 4, S20224, Singapore

92252087

DOGAVENTUE@YAGOO.COM

Claim Handler

WANG Peter

prefer.wang@axa.com.sg

Additional Instructions

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

Document Type

Document SubType

+ Upload Documents

NAME

TYPE

SUB-TYPE

AUTHOR

DATE UPLOADED

LKKInvoice1 (2).pdf

Invoice

Surveyor/ Assessor expense

LKK AUTO CONSULTANTS PTE LTD (TP)

5 September 2019

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 RENTAL RECEIPT.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	5 September 2019
 LKK Inspection.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	5 September 2019
 LKK Adjustment 1a (1).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	5 September 2019
 GIA SEARCH.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	5 September 2019
 PAYMENT BREAKDOWN EXPRESS SETTLEMENT FORM.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	5 September 2019
 AUTHORISATION TO ACT FORM.pdf	Forms / Claim Documents	POA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	5 September 2019
 WORKSHOP INVOICE.pdf	Invoice	Requirer	LKK AUTO CONSULTANTS PTE LTD (TP)	5 September 2019
 LETTER TO CL.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	5 September 2019
 MANDATE IA DIO 20082019.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 August 2019
 LOD AND OTHER DOCUMENTS.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 August 2019
 PARF CODE REBATE.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 August 2019
 TP EST LIST MARKED.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 August 2019
 LKK RESURVEY PHOTO 2.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 August 2019
 LKK SURVEY PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 August 2019

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 LKK RESURVEY PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 August 2019
 TP ESTIMATE - MARKED.pdf	Forms / Claim Documents	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	14 January 2019
 GIA REPORT OF SKT8997K (INSOL).PDF	Reports & Statement	GIA Report	KADRI Matien	10 January 2019
 EMAIL.mug	Letters and Correspondence	Others	KADRI Matien	10 January 2019
 EMAIL FROM WORKSHOP (THIRD PARTY PSI).mug	Letters and Correspondence	Workshop	KADRI Matien	9 January 2019
 SKP2363H TP.PDF	Reports & Statement	GIA Report	KUMAR Shalindra	8 January 2019