

Cecilia

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29
Kaki Bukit Autohub, Singapore 417921
Tel No. : 67461515 / 67471787 Fax No. : 67485015
Website : www.successunited.com.sg
Buss. Reg. No. : GST No. 200402570G

AIG Asia Pacific Insurance Pte Ltd
AIG Building
78 Shenton Way, #07-16
Singapore 079120
Attention : Motor Claim Department
Contact : 64191053 Fax No. : 68357416

Xiao Tony

Estimate : TP19-009

Date : 10/01/2019
Vehicle Num. : GBF8113A
Make/Model : Toyota Dyna-2016
Chassis/Eng# : JTFAT35Y70K207606/1KD2686731
Accident Date : 11/12/2018
Claim No. :
Reference :
Policy No. : (22/05/2019)

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1	LIST ITEMS :		
2.	1	Fuel Tank <i>Revised</i>		1,085.45
3.	2	Fuel Tank Bracket Holder <i>Best</i>		311.00
		Side Gate Hinge <i>new</i>	211.55	423.10

List Total S\$:
25.00% Discount S\$:

1396.45
1047.33

1,819.55
454.89
1,364.66

LABOUR :
To remove, repair and replaced damaged bodyparts,
realign bodyworks & where consistent to the accident
To putty and respray painting on affected area.

500

450.00 *200*
400.00 *300*
850.00

Labour Total S\$:

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian Lj

10/01/19. 03 Days

~~450~~, P/P ??
Total 1547.33 (P/P) ✓

E. & O.E.

Total S\$: 2,214.66

=====

Signature

for SUCCESS UNITED PTE LTD