



CROWN ASIA BUS BUILDER PTE. LTD. (UEN:201023449R)

44 Sungei Kadut Avenue Singapore 729667

Tel: (65) 6469 3319, Fax: (65) 6902 6758

GST ID No : 201023449R

PC595U

Repair Estimate

No. : QT-000025

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Your Ref. :

C/O LKK AUTO CONSULTANTS PTE LTD

Our D/O No. :

Terms : C.O.D.

Date : 24-01-2019

Page : 1 of 2

TEL :

FAX :

Item	Tax Code	Description	Qty	UOM	U/ Price S\$	Disc.	Total S\$
OS		THIRD PARTY CLAIM - REPAIR ESTIMATE FOR PC595U Traffic accident on 24/12/2018 involving PC 595 U and YL 3072M at Forth Chin Bee Road (Heavy Vehicle Carpark)					
Parts Required:							
1.	OS	REAR RIGHT BOTTOM BUMPER X	1.00		2650 1,500.00		1,500.00 X
2.	OS	REAR RIGHT BUMPER STRUCTURAL FRAME ASSY X	1.00		1000 1,000.00		1,000.00 X
3.	OS	REAR RIGHT LID COVER ASSY LH-Repair (RH-B) ✓	1.00		2385 2,650.00	700? ✓	5,300.00
4.	OS	LESS: 10% TRADE DISCOUNT	1.00		-780.00		-780.00
5.	OS	LABOUR CHARGES - TO SPRAY FOAM, KNOCK AND REPAIR ALL NECESSARY PARTS INCLUDING CHANGING OF ALL DAMAGED PARTS	1.00		2,450.00		2,450.00
6.	OS	LABOUR CHARGES TO PUTTY AND SPRAY PAINTING FOR REAR BUMPER, REAR STRUCTURE ASSY AND TWO REAR RIGHT LID COVER, RIGHT BODY STRUCTURE	1.00		2,800.00		2,800.00

NOTE: THIS ESTIMATE IS BASED ON VISIBLE DAMAGE ONLY. SHOULD ANY HIDDEN PARTS AND/OR LABOUR CHARGES REQUIRED DURING WORKS IN PROGRESS, IT WILL BE NOTIFIED ACCORDINGLY.

PRICE QUOTED IS SUBJECT TO 7% GST.

claims@crownasia.com.sg

**CROWN ASIA BUS BUILDER PTE. LTD.** (UEN:201023449R)

44 Sungei Kadut Avenue Singapore 729667

Tel: (65) 6469 3319, Fax: (65) 6902 6758

GST ID No : 201023449R

Repair Estimate**No. : QT-000025**

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

C/O LKK AUTO CONSULTANTS PTE LTD

Your Ref. :

Our D/O No. :

Terms : C.O.D.

Date : 24-01-2019

Page : 2 of 2

TEL :

FAX :

Item	Tax Code	Description	Qty	UOM	U/ Price	Disc.	Total
					S\$		S\$

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Resul

Ap 90010068

7 days
P/H 4/s

24/01/19 @ 1110

Resurvey 64 parts

2385

2400

4785

20%

3828

43-\$3,800

7 days

SINGAPORE DOLLAR TWELVE THOUSAND TWO HUNDRED SEVENTY ONLY

Sub Total (Excluding GST) **12,270.00**GST payable @ 7% on 0.00 **0.00**Total (Inclusive of GST) **12,270.00**

Notes :

1. All cheques should be crossed and made payable to CROWN ASIA BUS BUILDER PTE. LTD.
2. Goods sold are neither returnable nor refundable. Otherwise a cancellation fee of 20% on purchase price will be imposed.

GST Summary

Amount(S\$)

Tax(S\$)

Authorised Signature