

 $51\; UBI\; AVE\; 1, \#02-25\; PAYA\; UBI\; INDUSTRIAL\; PARK, SINGAPORE\; 408933\;\; TEL: (065)\; 62563561\;\; FAX: (065)\; 62564315\;\; FAX: (065)\; 6256415\;\; FAX: (065)\; F$

Immediate Advice

To: AXA Insurance Pte Ltd Date: 17/06/2019

Survey Details:

Date of loss	09.01.2019
Date of appointment	11.01.2019
Date of survey	10.01.2019
Location of survey	TORQUE 5 PTE LTD

Vehicle Details:

Claim Type:	Third part	Third party	
Vehicle number	SLT3177G	SLT3177G	
Make and Model	Honda Ve	zel Hybrid (1496cc)	
Date of registration	25.10.201	25.10.2017	
Excess	NIL		
Market Value/ Book Value	\$	88,000.00	(est)
Parf/COE Rebate	\$	46,704.00	(est)
Nett Value/ ERV	\$	41,296.00	(est)

Repair details:

Initial Estimate	Ś	72,033.78

Proposed/Revised repair cost:

Total Lump Sum(if applicable)	\$ \$	42,270.49 33,000.00
Supplementary	\$	1,286.00
Labour	\$	5,990.00
Check items (estimate)		NIL
Parts	\$	34,994.49

Number of days for repair	<u>20</u>
---------------------------	-----------



 $51\ UBI\ AVE\ 1,\#02-25\ PAYA\ UBI\ INDUSTRIAL\ PARK, SINGAPORE\ 408933\ \ TEL: (065)\ 62563561\ \ FAX: (065)\ 62564315$

Remarks:

Will seek mandate after confirm liability.	

Mandate:

Liability(TP)	ТВА	
Proposed repair cost (w/GST)		
Loss of use		
Loss of rental		
Loss of income		
LTA/GIA search fees		
Others		
Proposed Total		