

Please arrange to survey vehicle at
8 KAKI BUKIT AVENUE 4 - GATE 2
#07-48 PREMIER @ KAKI BUKIT
SINGAPORE 415875

ABWIN 諭輝

Date : 14/01/2019
TP Vehicle No. : GBB-1377-Y
To : EQ INSURANCE COMPANY LTD
Attn : Motor Claim Department

LINDA LIAO
ABWIN SERVICE PTE LTD
DID: 67139417
Fax: 67139415
HP: 97519596

Owner : HI-GLITZ PTE LTD
NTUC INCOME INSURANCE CO-OPERATIVE LTD
Certificate No. : 5069802656-03
Vehicle No. : GU -4477-M
Make & Model : VOLKSWAGEN CADDY 1.6 TDI AT 2CAA85

Accident Date: 08/01/2019

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
-----	-------------	---------------	---------------

List Item

1	TAILGATE	\$2,678.35	α
1	TAILGATE LOCK CATCH	\$76.65	α
1	RH TAILLAMP	\$254.65	α
1	LH TAILLAMP	\$254.65	α
1	RH TAILAMP CORNER PANEL	\$95.60	α
1	LH TAILAMP CORNER PANEL	\$95.60	α
1	REAR BUMPER	\$788.60	—
1	REAR BUMPER BRACKET RH	\$55.60	—
1	REAR BUMPER BRACKET LH	\$55.60	—
1	REAR END PANEL	\$385.55	α
1	REAR END PANEL TOP GARNISH	\$195.65	α
1	REAR BUMPER REINFORCEMENT	\$780.40	?
1	REAR BUMPER SPONGE CENTRE	\$295.60	?
Sub Total		\$6,012.50	
Discount 10% on Parts		(\$601.25)	
		\$5,411.25	

Special Nett

1	REAR BUMPER REVERSE SENSOR	\$350.00	200
1	REAR BUMPER REVERSE CAMERA	\$450.00	α
10	REAR BUMPER CLIPS	\$50.00	✓
Sub Total		\$850.00	

Labour & Misc

TO STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	\$1,200.00	300
TO SPRAY PAINT ON AFFECTED AREAS	\$1,200.00	250
TO CHECK ALL NECESSARY WIRINGS	\$250.00	20
TO APPLY TUFF KOTE	\$150.00	α
TO DETACH & RENEW REVERSE SENSOR	\$250.00	50
Sub Total	\$3,050.00	

Date : 14/01/2019
TP Vehicle No. : GBB-1377-Y
To : **EQ INSURANCE COMPANY LTD**
Attn : **Motor Claim Department**

LINDA LIAO
ABWIN SERVICE PTE LTD
DID: 67139417
Fax: 67139415
HP: 97519596

Owner : HI-GLITZ PTE LTD
NTUC INCOME INSURANCE CO-OPERATIVE LTD
Certificate No. : 5069802656-03
Vehicle No. : GU -4477-M
Make & Model : VOLKSWAGEN CADDY 1.6 TDI AT 2CAA85

Accident Date: 08/01/2019

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
-----	-------------	---------------	---------------

Sub Total	\$9,311.25
GST 7%	\$651.79
Total	\$9,963.04

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: