



吉维利企业

KIVILE ENTERPRISE

BLK 3007 UBI RD 1 #01-408, SINGAPORE 408701

TEL: 6748 8645 FAX: 6748 2553

EMAIL: KIVILEPC@GMAIL.COM WEBSITE: KIVILEPC.COM

ROC NO.: 53114844X GST REG NO.: M90370110N

Acknowledged by Repairer

Signature:

Date:

Vehicle No. : JQH593

Model: Yamaha T35LC (T135)

HANDLE BAR / BT	75 /
HANDLE BAR HOLDER X NN	45
BALANCE / Cut	30 /
GRIP / cut	28 /
BRAKE LEVER / cut	38 /
MIRROR / cut	40 /
HEAD LAMP / cut	220 /
TOP COWLING(?) / cut	145 /
FRONT FAIRING / CFA	110 /
FRONT FAIRING STAY X Repair	60
FRONT FAIRING GUARD X Cut NN	85
SIDE FAIRING RH / cut	155 /
SIGNAL LIGHT RH / BR	35 /
SIDE FAIRING GUARD RH X NN	95
SIDE FAIRING LH / cut	155 /
SIGNAL LIGHT LH / CFA	35 /
SIDE FAIRING GUARD LH / cut	95 /
FRONT MUDGUARD / cut	75 /
METER X NN	260
METER CABLE / BR	30 /
FRONT FORK / BT	330 /
STEERING STAY / AC	75 /
RIM / cut	220
DISC X NN	75
WHEEL SHAFT / BT	65 /
CENTER GUARD X NN	80
CENTER BOX X NN	75
SEAT BAR / cut NN	65 /
SIDE COMB LH X	80
FRONT FOOTREST / BT	38 /
FOOTREST RUBBER / cut	35 /
REAR BOX / cut	155 /
REAR MUDGUARD / cut	80 /
IU UNIT / cut	165 /
IU HOLDER X NN	35
FRONT BODY FRAME REPAIR X NN	250
FRONT NUMBER PLATE / CFA	20 / 10
TRANSPORT	50 / 30
spray	250 X NN
labour	300 150.
2284	4254

Gmo Qiang (UKK)

11/1/19 3Days. After repair photos.