

✓
in 160119

SERVICE ESTIMATE

96286 - C00001 SL: SERVICE SALES - PC

Ms Polly Ning Li-Hsiung

32 Chai Chee Avenue

#14-198

Singapore 461032

Closed by : Derek Oh Siong Wee

Svc Consultant :

Remarks : Ms Polly Ning Li-Hsi

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 1

Inv.date. : 11/01/2019

WIP No. . : 47159

Veh.In/Out: 11/01/2019

*Tel.No. . : Mobile: 94510036

Reg.No. . : SLA3022U

Reg.date . : 29/03/2018

Mileage .. : 0

Chassis No: YV1FS28L0J2462477

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

802	TO REPLACE FRT HEADLAMP,FRT RH GRILL,FRT RH FOG LAMP & FRT BUMPER,ETC	0	3200.00	0		3,200.00	S
-----	---	---	---------	---	--	----------	---

1200.

800	TO PUTTY SPRAY PAINT ON FRT BUMPER,ETC	0	1400.00	0		1,400.00	S
-----	--	---	---------	---	--	----------	---

700.

280	TO CHECK WIRING INCLUDE RESETING OF ALL ELECTRICAL MODULES	0	450.00	0		450.00	S ✓
-----	--	---	--------	---	--	--------	-----

BUMPER COVER FRT SV6	1.0 EA	1519.90				1,519.90	S de ✓
BUMPER AIR COVER FRT	1.0 EA	634.60				634.60	S X an
BUMPER FOAM FRT SV60	1.0 EA	345.20				345.20	S ?
BUMPER BRACKET LHF S	1.0 EA	88.70				88.70	S X an
BUMPER BRACKET RH F V	1.0 EA	88.70				88.70	S de ✓
BUMPER BRACKET LHF S	1.0 EA	88.70				88.70	S X an
BUMPER BRACKET RH F S	1.0 EA	88.70				88.70	S de ✓
TOW COVER FRT S60 14	1.0 EA	73.90				73.90	S cut ✓
RADIATOR GRILLE T2 D	1.0 EA	605.00				605.00	S X an

* Frt RH Headlamp - cut ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanpin 97495749
WP 16/11/2019
3 days
Resurvey before paint
sur E/Wearnes.com.

SERVICE ESTIMATE

96286 - C00001 SL: SERVICE SALES - PC

Ms Polly Ning Li-Hsiung
32 Chai Chee Avenue
#14-198

Singapore 461032

Closed by : Derek Oh Siong Wee
Svc Consultant :
Remarks : Ms Polly Ning Li-Hsi

GST Reg.No:M28920628X
Inv.No. : B&P 0 Page 2
Inv.date. : 11/01/2019
WIP No. : 47159
Veh.In/Out: 11/01/2019
*Tel.No. : Mobile: 94510036
Reg.No. : SLA3022U
Reg.date. : 29/03/2018
Mileage : 0
Chassis No: YV1FS28L0J2462477

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	BUMPER COVER LHF BLA	1.0 EA	105.80			105.80	SX ^{ny}
	BUMPER COVER RHF BLA	1.0 EA	105.80			105.80	SX ^{ny} <i>ct</i>
	BUMPER CASING COVER <i>LH</i>	1.0 EA	80.40			80.40	SX ^{ny}
	BUMPER CASING COVER <i>RH</i>	1.0 EA	76.90			76.90	SX ^{ny}
	BUMPER GRILLE LOWER	1.0 EA	119.50			119.50	SX ^{ny}
	BUMPER UNDERTRAY FRT	1.0 EA	173.80			173.80	SX ^{ny}
	BUMPER TRAY AIR GUID	1.0 EA	173.80			173.80	SX ^{ny}
	BUMPER CLIP S80 07-	10.0 EA	4.80			48.00	SX ^{ny}
	BUMPER AIR GUIDE LHF	1.0 EA	35.70			35.70	SX ^{ny}
	BUMPER AIR GUIDE RHF	1.0 EA	35.70			35.70	SX ^{ny}
	BLIND RIVET 4.0*21 P	10.0 EA	3.00			30.00	SX ^{ny}
	BUMPER CLIP GREEN S6	10.0 EA	4.80			48.00	SX ^{ny}
	BUMPER RAIL (BEAM) F	1.0 EA	1158.80			1,158.80	SX ^{ny}
	FRAME PANEL FRT SV60	1.0 EA	1707.10			1,707.10	SX ^{ny}
	EXTERIOR ADHESIVE GL	1.0 EA	142.20			142.20	SX ^{ny}

Gross Total. 12,624.90

Labour Total 5,050.00
Parts Total 7,574.90
Package Total 0.00

Net..... 12,624.90
GST @ 7.0% 883.74
Total..... 13,508.65
Paid..... 0.00
Please Pay.. 13,508.65

GST: S=StdRated; O=OutOfScope; Z=ZeroRated