


Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 17:54

Company Reg. No. 199902271W
GST Reg. No. 199902271W

Customer

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013935 Date : 18/06/2019 Order : SKF4852U Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No: SKF4852U (V 39078)	Regn Date: 09/10/2018	Mileage: 34735	WIP No.: 38913
Model: A5 SPORTBACK 2.0 TFSI S tronic	Chassis: WAUZZZF56JA124271	Engine: CVK 066242	Dept: U
You have been assisted by :- UB-Tony Foong (33)			

		Details	Qty	Unit Price	Amount
Q	EXC	M: 8888 Insurance Excess/Liability	-800.00	1.00	-800.00
S	BODYWORK	M: TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	480.00	1.00	480.00
S	BODYWORK	M: TO DISMANTLE AND RENEW FRONT BUMPER AND RHS FRONT FENDER. REORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	1000.00	1.00	1,000.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER	1100.00	1.00	1,100.00
S	BODYWORK	M: TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT. INSPECT FRONT SUSPENSION FOR FURTHER DAMAGES	280.00	1.00	280.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
X	A8W6821106B	FENDER	Less 020%	1.00	968.00
X	A8W6821172C	WHEEL HOUS	Less 020%	1.00	256.00
X	A8W6807065D GRU	COVER	Less 020%	1.00	2073.00
X	A8W0601025BH	(A) (G) RIM 18 " CV8(1	Less 020%	1.00	943.00
X	A8W6853824B 9B9	STONEGUARD	Less 020%	1.00	45.80
X	A8W6853602A PUZ	TRIM	Less 020%	1.00	144.50
X	A8W6820582E	COVER	Less 020%	1.00	31.80

Parts 3,569.68
Labour 0.00
Sublet 3,052.00
Menus 0.00
Lubricant 0.00

Sub-Total 5,821.68

7% GST 407.52

Grand Total 6,229.20



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SKF 4852 U

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0043/2019/JE
22 February 2019

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

RE : CLAIM – OWNER’S SATISFACTION/DISCHARGE VOUCHER

1

total pages

Make & Model : AUDI A5 SB 2.0 TFSI
Vehicle Chassis No. : WAUZZZF56JA124271
Vehicle Regn No. : **SKF 4852 U**
Vehicle Mileage : 34735 KM
Vehicle Owner : Mr. Liu Bin
Certificate No : 1800119799
Own Damage Excess : S\$ 856.00 (Inclusive GST)
Accident Date : 9 January 2019
Place : Along AMK AVE 1
Repair Cost : \$ 6,229.20
WIP No. : 38913

Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733


Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature :

Time :

Date :



22/2