

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Chhia Nyuk Pui

Date: 16 Jan 2019

**Preliminary Advice**

Insured Vehicle No	:	SKG4865C			
TP Vehicle No	:	SMB1615E	Accident Date	:	28/11/2018
Make	:	MAN NL320F (A22)	Assignment Date	:	15/01/2019
Date of Inspection	:	10/01/2019	Est. Duration of Repair	:	4 days
Inspection At	:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705			

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:	S\$ 7,650.00
Revised Amount	:	S\$ 6,611.08
Check Items (Estimated)	:	S\$ 0.00
Total	:	S\$ 6,611.08
Lump Sum Repair		:S\$

**Total Loss Consideration**

New for Old Value	:	S\$
Pre-Accident Value	:	S\$
COE / PARF Rebate	:	S\$
Salvage Value	:	S\$
Margin for Repair	:	S\$

**Remarks**

- (      ) The vehicle is economical/not economical for repair.  
( X ) The above survey was conducted on a 'without prejudice' basis.