

(08/11/13) wef

REF:

CC3/M8G19000785/Utd302

ASS. REC. BY: Maria

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKS7311at Workshop m/s SP

of _____

Insured: SKV1790A

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 100%

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or NoLum Sum: 2 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SKS7311 Yr Regn: 3,15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CAMake: Toyota Alphard c.c. 2362Colour: white A/C: Insured / Std / NI / NASp. Reading: 134604 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTEGDD1H708355053

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO orFront 6 mm Rear 6 mmR/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 10/1/19 D.O.I. 14/1/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

7:15pm at the workshop 21/2/1916/1/2019 - Report GIA Report to Chen Hui & Margaret.21/2/19 2/3 #4500 conf. and with Alu.22/2/2019

RECEIVED 22 FEB 2019

Date/Time, File Pass to?

☐ : Preli. Report☒ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

20010210Report Format: TPLump Sum / I.B.I. (\$ 4500)

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Wednesday, 16 January 2019 11:47 AM
To: 'chenhow_ng@sg.msig-asia.com'; 'margaret_loh@sg.msig-asia.com'
Cc: SUR; KKLau; Accounts (LKKAuto)
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP - FASTECH AUTO PTE LTD, DOA: 10/01/2019, SKS 7311B (TP VEHICLE), SKV 1790A (OI VEHICLE)
Attachments: TP GIA REPORT.pdf

Dear Cheng How/Margaret,

Please be informed that we had inspected the vehicle SKS 7311B at M/s: FASTECH AUTO PTE LTD, 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883

Enclosed herewith a copy of TP's GIA report. The estimated cost of repair will forward to you shortly.

Meanwhile, kindly provide us the claim reference number for our necessary action.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	1366N
Vehicle Details	
Vehicle No.:	SKS7311B
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Jan 2019
Vehicle Make:	TOYOTA
Vehicle Model:	ALPHARD 2.4 CVT
Primary Colour:	White
Manufacturing Year:	2014
Engine No.:	2AZJ126183
Chassis No.:	JTEGD21H708355053
Maximum Power Output:	125.0 kW (167 bhp)
Open Market Value:	\$41,542.00
Original Registration Date:	09 Mar 2015
First Registration Date:	09 Mar 2015
Transfer Count:	0
Actual ARF Paid:	\$50,159.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	08 Mar 2025
PARF Rebate Amount:	\$37,619.00
Intended COE Rebate Details	
COE Expiry Date:	08 Mar 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$66,751.00
COE Rebate Amount:	\$41,008.00
Total Rebate Amount:	\$78,627.00

The information contained herein is correct as at 14 Jan 2019

OK

Cheap Car Insurance Renewal

Is your car insurance expiring soon?
Receive best quotations from multiple insurers in as little as 2 hours.

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

New 5 Years Coe Renewal Toyota Vios 1.5a



2.88%p.a Lowest Interest@Gv
Cars Financing \$1500
Downpayment Monthly From
\$468
GV Credit Pte Ltd StarAd



Browse by Category

Sort by Date Posted 20 results/page

7 vehicles

Alphard

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Alphard		Any	Any	2015	Any	Any	Any	Available
	Toyota	Alphard 2.5A S Moonroof	\$128,800	\$16,190 /yr	06-Oct-2015	2,493 cc	-	MPV	Available
Elegant White MPV, "G" Model, With Twin Moonroof, One Owner Only, Very Well Maintained, Flexible In-house Loan Packages Available. Prime Motor & Leasing Posted: 12-Jan-2019 Tags: 2015 Toyota Alphard, 2015 toyota alphard, Toyota Alphard, toyota alphard, Toyota, Alphard, alphard, Used Toyota									
	Toyota	Alphard 2.4A	\$106,800	\$13,650 /yr	08-Jan-2015	2,362 cc	60,348 km	MPV	Available
1 Owner, Low Mileage Done 60348 KM, Very Well Maintained. Posted: 10-Jan-2019 Tags: 2015 Toyota Alphard, 2015 toyota alphard, Toyota Alphard, toyota alphard, Toyota, Alphard, alphard, Used Toyota									
	Toyota	Alphard 2.4A Moonroof	\$108,888	\$13,330 /yr	12-Feb-2015	2,362 cc	58,050 km	MPV	Available
Low Mileage, Family 2nd Car And Under Utilize. Well Maintain By Owner. Fully Service By Borneo And Under Warranty Till Feb 2020. View To Believe. No Consignment Agents. Posted: 05-Jan-2019 Tags: 2015 Toyota Alphard, 2015 toyota alphard, Toyota Alphard, toyota alphard, Toyota, Alphard, alphard, Used Toyota									
	Toyota	Alphard 2.5A S Moonroof	\$154,800	\$20,350 /yr	02-Oct-2015	2,493 cc	57,000 km	MPV	Available
Best Buy 7 Seaters Luxury MPV Own By A Fussy Owner! 100% Accident Free! Zero Repair Needed, Original Flawless Paintwork And Interior! Loan And Trade In Available! Hurry Come For Deal Before Sold! Posted: 29-Dec-2018 Tags: 2015 Toyota Alphard, 2015 toyota alphard, Toyota Alphard, toyota alphard, Toyota, Alphard, alphard, Used Toyota									
	SMRT's Strides to offer fuel-cell cars SMRT Taxis' private-hire arm - Strides - is partnering Toyota Tsusho to offer Singapore's first hydrogen fuel cell cars by as early as the end of the year. Read this article								
	Toyota	Alphard 2.4A Moonroof	\$115,800	\$14,740 /yr	02-Jan-2015	2,362 cc	84,500 km	MPV	Available
Fully Service And Maintained By Borneo Agent And Under Warranty! Renewed Road Tax For 6 Months! Well Maintained By Very Careful Owner! Car Is Not A PHV Vehicle,Most Highly On Demand For Limousine/Busi... Car Buyers Automotive Pte Ltd Posted: 24-Dec-2018 Tags: 2015 Toyota Alphard, 2015 toyota alphard, Toyota Alphard, toyota alphard, Toyota, Alphard, alphard, Used Toyota									
	Toyota	Alphard 2.5A S	\$130,000	\$16,530 /yr	21-Oct-2015	2,493 cc	120,000 km	MPV	Available
Viewing By Appointment. Twin Power Door, Moonroof. Pristine Condition. Posted: 08-Dec-2018 Tags: 2015 Toyota Alphard, 2015 toyota alphard, Toyota Alphard, toyota alphard, Toyota, Alphard, alphard, Used Toyota									
Compare	Toyota	Alphard 2.5A S	\$129,800	\$15,810 /yr	23-Dec-2015	2,493 cc	42,200 km	MPV	Available

Date of Accident : 10/01/19 Accident Time: 6.04pm (24-HR-Format)
 Accident Place : Along telok Blangah towards CTE
 Vehicle. No. (Car Plate No.) : SKS7311B Make/Model: Toyota Alphard
 Insurance Company : OAC Policy No: 2018-VO10
 Owner or Company Name /IC No. : LHL International Pte Ltd (198401366N)
 Owner or Company Contact No. : Owner's Hp 90068338 Company Tel
 DRIVER'S Name / IC No. : See Kok Eng / S0709467A
 DRIVER'S Date Of Birth : 17/7/1945 DRIVER'S License Pass Date 26/2/1966
 Relationship of Owner & Driver : Spouse \ Parents \ Children \ Sibling \ Employee \ Others:
 DRIVER'S Address : 28 Lorong N Telok Kurau S 425153
 DRIVER'S Contact No./ Alt No. : 1) 2)
 DRIVER'S Occupation : INDOOR \ OUTDOOR (e.g. working inside or outside office)
 Email Address :
 Weather & Road Surface : CLEAR & DRY \ RAINING & WET \ AFTER RAIN & WET
 Reporting Type : Reporting Only \ Claim Other Party \ Claim Own Insurance
 Number of Passengers (Including Driver): 2 person
 Was there any video Captured by car camera: YES \ NO
 Exact purpose for which vehicle was being used at the time of accident: Private use \ Work purpose
 Any Injury (If YES, Pls state): NO

Other Party Driver's Particular (if any)

Vehicle. No: SKV1790A (ms16)	Vehicle. No: _____
Vehicle Make/Model: _____	Vehicle Make/Model: _____
Name Driver: _____	Name Driver: _____
IC No. Driver/Contact: _____	IC No. Driver/Contact: _____

* NEW - Passenger's name & gender:

Judy Ng cheo Tee. (F)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

on the stated date and time I was driving my vehicle
A along telok Blangah. I stop my car due to amber light
suddenly vehicle B hit on my rear portion.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

FASTECH AUTO PTE LTD
BLK1 KAKI BUKIT AVE 6
#01-46/48/50 AUTOBAY
SINGAPORE 417883

not Authorized.
n/a
n/s 4500/
14/1/19
4 day.

VEHICLE NO:SKS 7311B

QTY	PARTICULAR		
1 PCS	REAR WINDSCREEN SEALANT		acc \$50.00
1 PCS	REAR WINDSCREEN MOULDING	148.50	net \$248.10
1 PCS	TAILGATE	1901.10	20/54 \$2,450.10
1 PCS	TAILGATE REAR LOGO	78.10	net \$78.80
1 PCS	TAILGATE 'ALPHARD' EMBLEM	75.00	net \$78.50
2 PCS	TAILGATE REFLECTORS @\$650.10		acc net \$1,300.20
1 PCS	TAILGATE OUTER GARNISH		17 \$881.10
1 PCS	TAILGATE INNER LOCK		17 \$399.50
1 PCS	TAILGATE INNER TRIM BOARD		17 \$788.50
1 SET	TAILGATE INNER TRIM BOARD CLIPS		17 \$60.00
1 PCS	TAILGATE WEATHERSTRIP	311.10	4m \$388.20
1 PCS	REAR BUMPER	615.10	20/22 \$1,645.10
2 PCS	REAR BUMPER TOWING COVERS @\$60.00	45.00	15 torn \$120.00
2 PCS	REAR BUMPER SIDE RETAINERS @\$88.10	65.00	n/s but \$176.20
1 SET	REAR BUMPER CLIPS		net \$60.00
2 PCS	REAR BUMPER REFLECTORS @\$105.00	85.00	n/s cre \$210.00
2 PCS	TAILLAMPS @\$745.10		17 \$1,490.20
1 PCS	TAILLAMP LOWER GARNISH N/S	488.10	20/22 \$525.10
1 PCS	REAR END PANEL	690.10	20 \$820.10
1 PCS	REAR END PANEL TOP GARNISH	255.10	2w/ \$366.50
4 PCS	REAR BUMPER PDC SENSORS @\$388.00	265.00	shld \$1,525.00
1 PCS	REAR SPARE TYRE BRACKET		17 \$299.50
			\$13,960.70
	LABOUR CHARGES:		
	TO CHECK WIRING		\$50.00
	TO DISMANTLE & REPLACING PDC SENSOR		\$80.00
	TO DISMANTLE & REFIX REAR WINDSCREEN		\$150.00
	TO DISMANTLE & REFIX TAILGATE MECHANISM		\$150.00
	TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTREY		\$150.00
	TO SPRAY rust PROOFING		\$100.00
	LABOUR FOR PANEL BEATING & REPLACING PARTS		\$1,080.00
	TO PUTTY & SPRAY PAINTING		\$1,500.00
			TO \$17,220.70

257

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-51322

3849.15

2649.15



































...CLAIM SUBFOLDER...(Pending for Survey Report)



















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Jan 2019		31 Jan 2019 09:39 Edit Adj Rpt	S\$4,500.00 Edit Estimates	S\$4,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	CHONG TECK WENG , ID: S7385913A								
Main Claimant:	LHL INTERNATIONAL PTE LTD , Co. Reg. No.: -								
Vehicle Reg. No.:	SKS7311B	Date of Loss:	10/01/2019 18:00 - :59 [46 Months and 1 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 581867	Policy/Cover Note No.:	71625505 (Comprehensive) Coverage: 01/09/2018 - 31/08/2019						
Vehicle Reg. No. (Insured):	SKV1790A	Policy No. (Claimant):	2018-V0103663-VDP						
		Excess:	S\$700.00						
Repairer:	Kan Fook Sing Motor Workshop (Defu) No. 61 Defu Lane 12, 539147 Defu Lane - Tel: 67479560								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jowyn Tay Mei Ling - 6643 1307]								
Claimant's Insurer:	Great Eastern General Insurance Limited (HQ) - Tel: +65 248 2888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Imm.Advice due 01/02/2019]								
Adj Asg. Remarks:	Liability 100% on OI Survey done on 16/01/19								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKS7311B (581867)**
[SKV1790A]
TP
LHL INTERNATIONAL PTE LTD
Jan 10 2019 6:00PM
[CHONG TECK WENG]
Kan Fook Sing Motor Workshop

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	30/01/19 17:17	Accident Statement From: SC - Reg. No: SKV1790A, Claimant: CHONG TECK WENG	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	22/02/19 11:07	General View	 Load JPG	<input checked="" type="checkbox"/>
2	22/02/19 11:07	General View	 Load JPG	<input checked="" type="checkbox"/>
3	22/02/19 11:07	General View	 Load JPG	<input checked="" type="checkbox"/>
4	22/02/19 11:07	General View	 Load JPG	<input checked="" type="checkbox"/>
5	22/02/19 11:07	General View	 Load JPG	<input checked="" type="checkbox"/>
6	22/02/19 11:07	General View	 Load JPG	<input checked="" type="checkbox"/>
7	22/02/19 11:07	General View	 Load JPG	<input checked="" type="checkbox"/>
8	22/02/19 11:07	General View	 Load JPG	<input checked="" type="checkbox"/>
9	22/02/19 11:07	General View	 Load JPG	<input checked="" type="checkbox"/>
10	22/02/19 11:07	General View	 Load JPG	<input checked="" type="checkbox"/>
11	22/02/19 11:07	General View	 Load JPG	<input checked="" type="checkbox"/>
12	22/02/19 11:07	General View	 Load JPG	<input checked="" type="checkbox"/>
13	22/02/19 11:07	General View	 Load JPG	<input checked="" type="checkbox"/>
14	22/02/19 11:07	General View	 Load JPG	<input checked="" type="checkbox"/>
15	22/02/19 11:07	General View	 Load JPG	<input checked="" type="checkbox"/>
16	22/02/19 11:07	General View	 Load JPG	<input checked="" type="checkbox"/>
17	22/02/19 11:07	General View	 Load JPG	<input checked="" type="checkbox"/>
18	22/02/19 11:07	General View	 Load JPG	<input checked="" type="checkbox"/>
19	22/02/19 11:07	General View	 Load JPG	<input checked="" type="checkbox"/>
20	22/02/19 11:07	General View	 Load JPG	<input checked="" type="checkbox"/>
21	22/02/19 11:07	General View	 Load JPG	<input checked="" type="checkbox"/>
22	22/02/19 11:07	General View	 Load JPG	<input checked="" type="checkbox"/>
23	22/02/19 11:07	General View	 Load JPG	<input checked="" type="checkbox"/>
24	22/02/19 11:07	General View	 Load JPG	<input checked="" type="checkbox"/>
25	22/02/19 11:07	General View	 Load JPG	<input checked="" type="checkbox"/>
26	22/02/19 11:07	General View	 Load JPG	<input checked="" type="checkbox"/>
27	22/02/19 11:07	General View	 Load JPG	<input checked="" type="checkbox"/>
28	22/02/19 11:07	General View	 Load JPG	<input checked="" type="checkbox"/>
29	22/02/19 11:07	General View	 Load JPG	<input checked="" type="checkbox"/>
30	22/02/19 11:07	General View	 Load JPG	<input checked="" type="checkbox"/>
31	22/02/19 11:07	General View	 Load JPG	<input checked="" type="checkbox"/>
32	22/02/19 11:07	General View	 Load JPG	<input checked="" type="checkbox"/>
33	22/02/19 11:07	General View	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	22/02/19 11:07	General View	 Load JPG	<input checked="" type="checkbox"/>
35	22/02/19 11:07	General View	 Load JPG	<input checked="" type="checkbox"/>
36	22/02/19 11:07	General View	 Load JPG	<input checked="" type="checkbox"/>
37	22/02/19 11:07	General View	 Load JPG	<input checked="" type="checkbox"/>
38	22/02/19 11:07	General View	 Load JPG	<input checked="" type="checkbox"/>
39	22/02/19 11:07	General View	 Load JPG	<input checked="" type="checkbox"/>
40	22/02/19 11:07	General View	 Load JPG	<input checked="" type="checkbox"/>
41	22/02/19 11:07	General View	 Load JPG	<input checked="" type="checkbox"/>
42	22/02/19 11:07	General View	 Load JPG	<input checked="" type="checkbox"/>
43	22/02/19 11:07	General View	 Load JPG	<input checked="" type="checkbox"/>
44	22/02/19 11:07	General View	 Load JPG	<input checked="" type="checkbox"/>
45	22/02/19 11:07	General View	 Load JPG	<input checked="" type="checkbox"/>
46	22/02/19 11:07	General View	 Load JPG	<input checked="" type="checkbox"/>
47	22/02/19 11:07	General View	 Load JPG	<input checked="" type="checkbox"/>
48	22/02/19 11:07	General View	 Load JPG	<input checked="" type="checkbox"/>
49	22/02/19 11:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	22/02/19 11:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	22/02/19 11:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	22/02/19 11:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	22/02/19 11:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	22/02/19 11:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	22/02/19 11:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	22/02/19 11:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	22/02/19 11:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	22/02/19 11:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	22/02/19 11:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	22/02/19 11:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	22/02/19 11:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	22/02/19 11:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	22/02/19 11:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	22/02/19 11:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	22/02/19 11:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	22/02/19 11:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	22/02/19 11:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	22/02/19 11:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	22/02/19 11:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	22/02/19 11:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	22/02/19 11:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	22/02/19 11:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	22/02/19 11:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	22/02/19 11:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	22/02/19 11:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	22/02/19 11:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	22/02/19 11:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	22/02/19 11:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	22/02/19 11:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	22/02/19 11:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	22/02/19 11:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	22/02/19 11:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	22/02/19 11:07	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
84	22/02/19 11:07	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
85	22/02/19 11:07	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
86	22/02/19 11:07	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
87	22/02/19 11:07	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
88	22/02/19 11:07	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
89	22/02/19 11:07	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
90	22/02/19 11:07	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
91	22/02/19 11:07	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
92	22/02/19 11:07	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
93	22/02/19 11:07	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
94	22/02/19 11:07	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
1	11/01/19 16:08	Accident Statement	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
1	11/01/19 16:02	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	11/01/19 16:02	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	11/01/19 16:02	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	11/01/19 16:02	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	11/01/19 16:02	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	11/01/19 16:02	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
7	11/01/19 16:03	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
8	11/01/19 16:03	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
9	11/01/19 16:03	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kan Fook Sing Motor Workshop (Defu)	Thumbnail	Print
1	11/01/19 16:04	Accident Sketch Plan	Load JPG	<input checked="" type="checkbox"/>
2	11/01/19 16:04	Accident Sketch Plan	Load JPG	<input checked="" type="checkbox"/>
3	11/01/19 16:05	Driver IC & Licence	Load JPG	<input checked="" type="checkbox"/>
4	11/01/19 16:05	Cert Ins	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG19000785/UTD3E2

Date: 25/02/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 71625505

Claimant Vehicle No: SKS7311B

Insured Vehicle No: SKV1790A

Date of Loss: 10/01/2019

Nature of Claim: TP

Claim No: 581867

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKS7311B

Make & Model: TOYOTA ALPHARD, 2.4 CVT (A)

Engine No: 2AZJ126183

Reg. Date: 09/03/2015 (Man. Year: 2014)

Chassis No: JTEGD21H708355053

Colour: White

Odometer: 134604 km

Engine Capacity: 2362 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R17

Rear Tyre Size: 215/60 R17

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,960.70	3,849.15	10,111.55	72.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,260.00	1,800.00	1,460.00	44.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,220.70	5,649.15	11,571.55	67.20
Approved Total (Overridden) (S\$)		4,500.00		
(S\$)	17,220.70	4,500.00	12,720.70	73.87
+ GST 7.00/7.00% (S\$)	1,205.45	315.00	890.45	73.87
Nett Amount (S\$)	18,426.15	4,815.00	13,611.15	73.87

INSPECTION

Date of Assignment: 31/01/2019

Date Inspected: 14/01/2019

Inspected At:

FASTECH AUTO PTE LTD
1 KAKI BUKIT AVENUE 6
#01-46/48/50 AUTOBAY
SINGAPORE 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Feb 2019)
Parts:	M1-MPV	TOYOTA ALPHARD 2.4 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKS7311B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 F	*50.00 FL
2	1		*REAR WINDSCREEN MOULDING	Necessary	248.10 F	*148.50 FL
3	1		*TAILGATE	Dented / Bent	2,450.10 F	*1,901.10 FL
4	1		*TAILGATE REAR LOGO	Necessary	78.80 F	*78.10 FL
5	1		*TAILGATE ALPHARD EMBLEM	Necessary	78.50 F	*75.00 FL
6	2		*TAILGATE REFLECTORS (CRACKED)	Not Consistent With The Impact	1,300.20 F	*- FL
7	1		*TAILGATE OUTER GARNISH	Not Necessary	881.10 F	*- FL
8	1		*TAILGATE INNER LOCK	Not Necessary	399.50 F	*- FL
9	1		*TAILGATE INNER TRIM BOARD	Not Necessary	788.50 F	*- FL
10	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	60.00 F	*- FL
11	1		*TAILGATE WEATHERSTRIP	Twisted	388.20 F	*311.10 FL
12	1		*REAR BUMPER	Dented / Deformed	1,645.10 F	*615.10 FL
13	1		*REAR BUMPER TOWING COVERS	N/S Torn	120.00 F	*45.00 FL
14	1		*REAR BUMPER SIDE RETAINERS	N/S Bent	176.20 F	*65.00 FL
15	1		*SET REAR BUMPER CLIPS	Necessary	60.00 F	*60.00 FL
16	1		*REAR BUMPER REFLECTORS	N/S Cracked	210.00 F	*85.00 FL
17	2		*TAILLAMPS	Not Necessary	1,490.20 F	*- FL
18	1		*REAR END PANEL	Dented	820.10 F	*690.10 FL
19	1		*REAR END PANEL TOP GARNISH	Twisted	366.50 F	*255.10 FL
20	1		*REAR BUMPER PDC SENSORS (4PCS)	Shorted-1pc only	1,525.00 F	*265.00 FL
21	1		*REAR SPARE TYRE BRACKET	Not Necessary	299.50 F	*- FL
22	1		*TAILLAMP LOWER GARNISH N/S	Dented / Deformed	525.10 F	*488.10 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$) 13,960.70 5,132.20
 - List Item Discount on L Items 0.00/25.00% (\$\$) 0.00 1,283.05

Total Parts (\$\$) 13,960.70 3,849.15

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	50.00	30.00
2	TO DISMANTLE & REPLACING PDC SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	120.00
4	TO DISMANTLE & REFIX TAILGATE MECHANISM	New	150.00	60.00
5	TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTREY	New	150.00	80.00
6	TO SPRAY RUST PROOFING	New	100.00	60.00
7	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	1,080.00	600.00
8	TO PUTTY & SPRAY PAINTING	New	1,500.00	800.00
Gross Labour Cost (\$)			3,260.00	1,800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >