

QUAN DE MOTOR TRADING

1 KAKI BUKIT AVENUE 6, #01-67

AUTOBAY, SINGAPORE 417883

HP: 96709191 FAX: 66840767

AXA Insurance Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811
Attn: Motor Claims Department

Not Authorised
Hale
1/5 #8022/
14/1/19
Attn: Mr. Marcos (Surveyor)
12/1/19

Date: 9 January 2019

**Accident on 08/01/2019 involving vehicles SJV2984M, GBE8519T, SLW3877D
along PIE towards Tuas**

Estimate cost of repair to vehicle SJV2984M Proton Persona

1 pc.	bootlid	2D/3uc	\$	580.00	✓
1 pc.	bootlid outer handle	cr	\$	116.00	✓
2 pcs.	bootlid hinges @\$105.00	cr	\$	210.00	X
1 pc.	bootlid inner lock	twl	\$	108.00	✓
1 pc.	bootlid weatherstrip	twl	\$	146.00	✓
1 pc.	bootlid inner trim	cr	\$	166.00	X
1 set	bootlid inner trim clips	cr	\$	35.00	✓
1 pc.	rear bumper	2D	\$	550.00	✓
2 pcs.	rear bumper reflectors @\$38.00	cr	\$	76.00	✓
1 pc.	rear bumper reinforcement	3rd	\$	360.00	✓
1 set	rear bumper clips	cr	\$	40.00	✓
2 pcs.	taillamps @\$355.00	cr	\$	710.00	✓
1 pc.	rear end panel	Body	\$	480.00	✓
1 pc.	rear end panel top garnish	cr	\$	180.00	✓
1 pc.	rear floor panel	cr	\$	965.00	✓
1 pc.	rear floor panel top board	cr	\$	210.00	✓
2 pcs.	rear fender inner trims @\$215.00	cr	\$	430.00	X
1 pc.	bonnet	Buc	\$	590.00	✓
1 pc.	bonnet outer chrome	cr	\$	110.00	✓
1 pc.	bonnet lock	twl	\$	68.00	✓
1 pc.	front bumper	2D	\$	490.00	✓
1 pc.	front bumper reinforcement	3rd	\$	290.00	✓
2 pcs.	front bumper slide retainers @\$35.00	3rd	\$	70.00	✓
1 set	front bumper clips	cr	\$	40.00	✓
1 pc.	front bumper centre grille	3rd	\$	75.00	✓
1 pc.	front grille	cr	\$	105.00	✓
1 pc.	front grille logo	cr	\$	45.00	✓
2 pcs.	headlamps @\$510.00	cr	\$	1,020.00	✓
1 pc.	front support panel	2D/2uc	\$	588.00	✓
			\$	8,853.00	
Less 10%			\$	885.30	8047
			\$	7,967.70	7242.3

8047
507
4023.50

S. Nett Items:

1 set rear bumper reverse sensor
 1 pc rear license plate w/holder
 1 pc. rear exhaust chrome
 1 pc. front license plate w/holder

Bal c/f \$ 7,967.70

Shwld \$ 280.00 *200*
Bert \$ 50.00 *40*
Sic \$ 80.00 *X*
Bert \$ 50.00 *40*

Labour Charges:

To check wiring
 To remove & refix reverse sensor
 To remove & refix interior seat, cushion upholstery
 To remove & refix rear exhaust
 To transfer bootlid mechanism
 To spray rust proofing
 To remove & refix air-con & refill gas
 Labour for panel beating, welding & renew parts
 Spray painting

\$ 80.00 *30*
 \$ 100.00 *50*
 \$ 120.00 *80*
 \$ 100.00 *60*
 \$ 100.00 *60*
 \$ 200.00 *120*
 \$ 120.00 *100*
 \$ 1,800.00 *1600*
 \$ 1,800.00 *1600*

Total: \$ 12,847.70

3980 *112223*
8977

KK/ Please notify the Police of the following:

- Repairs before spray painting
- To replace damaged part(s) during resurvey
- Prices quoted are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: