

2/03/2002

ASS. REC. BY:

REF:

C8MSG1900087 / K1031

Special Instruction:

Surveyor
Merimen

Kenneth

ASSIGNMENT (Office)

From (Person):

Vene Tan

of

MS19

Date/Time:

14/11/19 @ 3:51pm

Estimated Cost:

Bill to:

OD ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

EK90Y

Insured:

XB2160M

at Workshop m/s

Chew Goun Motor

Tel:

64841626

of

Blk 10, Amk Ind. Park 2A #01-15/16

Policy No:

B28720308Mkf

Claim No:

581946

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

09/01/2019

CA / REV / REP. / REV 24 HRS

lup

15/11/19

H.O.D. Endorsement:

Date/Time:

5:06pm 9/11/19

Person Contacted:

Grace

Vehicle:

IN OUT

Date/Time

Action/Instruction (✓) Estimate

EK90Y - NBA / MSG19000509 / Y

Dof: 9/1/19

XB2160M - NBA / MSG19000509 / Y

JVA: 9/1/19

16/11-

Revised preli advise via merimen

3/1/1

1/1 Lm 8580d email & confirm (Red: 5710.23!49%)

REF: MSLG

ASSIGNMENT

From: Date: 15/01/19

Veh No: EK 90Y Yr Regn: 08 09

Estimated Cost:

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /OD / ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No:

EK 90Y

Make:

Mit Lancer

C.C.

1499

at Workshop m/s

chew Goon Motor

Colour:

M. Black

A/C: Insured / Std / NI / NA

of Blk 10, Tmk Ind. Park 2A #01-15/16

Sp. Reading

266325

T/Radio: Insured / Std / NI / NA

Insured

Eng/No:

Policy No.

C/No:

JMY SACY 2A94004423

Claims No.

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: ☒ In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: ☒ In order / Jammed / Leaked / Burnt or

Make of Veh:

Modi: Nil / S/Rim / STD Air Rim or

Tyre Size: F:


F:

215/60R16

R:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Falken

Bal. or Market Value:

S/BK

Front

Rear

IDAC Accident Rpt:

Consistent? : Yes or No

R/Bal.

4 mm

R/Bal.

4 mm

GIA / PR Seen:

Consistent? : Yes or No

L/Bal.

4 mm

L/Bal.

4 mm

Est. Repairs:

08 days

Res.: Yes or No

D.O.A.

9/1/19

D.O.I.

15/1/19

Lum Sum:

20 %

3 Val.: Yes or No

Survey held at

CA / REV / REP. / 24 HRS (up)

Vehicle: IN / OUT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rear body

Date:

Person Contacted:

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

16/1 File pass to Car

RECEIVED 01 FEB 2019.

[Signature]
1/2/2019

Date/Time: File Pass to?



Preli. Report

Days Of Repair: 8

1) 1/2 Typist



Final Report

Resurvey No. of Trip: 1

Date/Time: File Return to?

Survey Fee:

200

2)

Add Fee:



Site Insp (\$)

Transportation

) \$ + RS \$



Interview (\$)

) Photos



Tech Invs (\$)

) Other:



Weekend (\$)

) ...

Report Format: TP

Lum Sum / I.B.I: (\$

58007

TOTAL

210

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	09 Jan 2019		14 Jan 2019 15:51 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	SINSEMOH TRANSPORTATION PTE LTD, Co. Reg. No.: NA			
Main Claimant:	TAN BROTHERS INSURANCE AGENCIES PTE LTD, Co. Reg. No.: 197500491N			
Vehicle Reg. No.:	EK90Y	Date of Loss:	09/01/2019 12:00 - :59 [112 Months and 16 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / 581946	Policy/Cover Note No.:	B28720308MKF (Third Party Only) Coverage: 01/04/2018 - 31/03/2019	
Vehicle Reg. No. (Insured):	XB2160M	Policy No. (Claimant):		
		Excess:		
Repairer:	Chew Goon Motor (AMK) Blk 10 Ang Mo Kio Industrial Park 2A, #01-15/16 & 17, AMK Autopoint, 568047 Ang Mo Kio - Tel: 64841626			
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 15/01/2019]			
Driver/Custodian (Insured):	MOGANAVAL S/O ARIAPPAN (), NRIC: S6931748J, Tel: +6598931562			
Adj Asg. Remarks:	Liability 50/50 Assign LKK Auto Consultants Pte Ltd Vehicle in workshop Contact 6484 1626			

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tan Gek Ing

Date: 16 Jan 2019

Preliminary Advice

Insured Vehicle No	: XB2160M	Accident Date	: 09/01/2019
TP Vehicle No	: EK90Y	Assignment Date	: 14/01/2019
Make	: MITSUBISHI LANCER	Est. Duration of Repair	: 8.00
Date of Inspection	: 15/01/2019		
Inspection At	: CHEW GOON MOTOR (AMK) BLK 10 ANG MO KIO INDUSTRIAL PARK 2A, #01-15/16 & 17, AMK AUTOPOINT SINGAPORE 568047		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s rear body portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,510.23
Revised Amount	:S\$	5,747.65
Check Items (Estimated)	:S\$	3,558.88
Total	:S\$	9,306.53

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical/not economical for repair.
- (x) The above survey was conducted on a 'without prejudice' basis.



ANNOUNCING BENEFIT AUTO

as sgCarMart Premium Dealer for the 5th Consecutive Year

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New 5 Years Coe Renewal Toyota Altis 1.6A



2.88% P.A. Lowest Interest @ GV
Cars Financing \$1800
Downpayment Monthly From
\$568
GV Credit Pte Ltd StarAde

• Free VICOM evaluation
• Free grooming and 6 months maintenance
• In-house workshop ensures quality service
• Member of SVTA and hire purchase association
• 100% deposit refund for unapproved loan

YONG LEE SENG MOTOR PTE LTD

Browse by Category ▼

Sort by Date Posted ▼

20 results/page ▼

6 vehicles

mitsubishi lancer 1.5

Advanced Search



Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	mitsubishi lancer 1.5	Any	Any	2010	Any	Any	Any	Available
	Mitsubishi Lancer EX 1.5A Sports	\$24,800	\$9,030 /yr	14-Oct-2010	1,499 cc	-	Sedan	Available
Sporty Red Lancer 1.5A (Sports Edition) Of Excellent Condition. Maintained At C&C With History. Fussy Malay Owner. New Paintwork. Road Tax Till Apr 19. 100% Accident Free. Price Negotiable. Call Now! Lake View Credit Pte Ltd Posted: 12-Jan-2019 Tags: 2010 Mitsubishi Lancer, 2010 mitsubishi lancer, Mitsubishi Lancer, mitsubishi lancer, Mitsubishi, Lancer, lancer, Used Mitsubishi								
	Mitsubishi Lancer EX 1.5A GLS	\$18,800	\$8,700 /yr	21-Apr-2010	1,499 cc	-	Sedan	Available
1 Owner Only. Road Tax Till 20 April 2019. 100% Accident Free. Original Paintwork. STA/ VICOM Inspection Welcome. No Repairs Needed. Flexible Bank And In-House High Loan Available At Low Interest Rate... Imperium Car Motor Pte Ltd Posted: 12-Jan-2019 Tags: 2010 Mitsubishi Lancer, 2010 mitsubishi lancer, Mitsubishi Lancer, mitsubishi lancer, Mitsubishi, Lancer, lancer, Used Mitsubishi								
	Mitsubishi Lancer EX 1.5A Elegance	\$18,300	\$9,590 /yr	05-Jan-2010	1,499 cc	102,664 km	Sedan	Available
Road Tax Till 04 Jul 2019. 100% Accident Free. Original Paintwork. Geninue Low Mileage. STA/VICOM Inspection Welcome. No Repairs Needed. Flexible Bank And In House High Loan Available At Low Interest ... Imperium Car Motor Pte Ltd Posted: 10-Jan-2019 Tags: 2010 Mitsubishi Lancer, 2010 mitsubishi lancer, Mitsubishi Lancer, mitsubishi lancer, Mitsubishi, Lancer, lancer, Used Mitsubishi								
	Mitsubishi Lancer EX 1.5A Sports	\$19,000	\$9,750 /yr	07-Jan-2010	1,499 cc	150,000 km	Sedan	Available
Balloon Scheme Available. Regular Servicing. Well Maintained. Posted: 07-Jan-2019 Tags: 2010 Mitsubishi Lancer, 2010 mitsubishi lancer, Mitsubishi Lancer, mitsubishi lancer, Mitsubishi, Lancer, lancer, Used Mitsubishi								
GET YOUR COE RENEWAL LOAN Is your COE expiring? Let us help you renew it! Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.								
	Mitsubishi Lancer EX 1.5A Elegance	\$23,333	\$8,680 /yr	05-Oct-2010	1,499 cc	89,559 km	Sedan	Available
Cheapest In Town. Car In Full Working Condition. Superb Condition Inside Out, Well Taken Care By A Car Passion Owner, View To Believe. Call Now To View. Posted: 05-Jan-2019 Tags: 2010 Mitsubishi Lancer, 2010 mitsubishi lancer, Mitsubishi Lancer, mitsubishi lancer, Mitsubishi, Lancer, lancer, Used Mitsubishi								
	Mitsubishi Lancer EX 1.5A Sports	\$20,800	\$11,000 /yr	29-Jan-2010	1,499 cc	-	Sedan	Available
Don't Miss Out Best Unit In Town! Original Condition Since Day 1 And Fully Maintain By Agent C&C With One Lady Owner. Low Maintiance And Reliable Sedan, Ample Boot Space. Loan Application Available! W... Posted: 19-Nov-2018 Tags: 2010 Mitsubishi Lancer, 2010 mitsubishi lancer, Mitsubishi Lancer, mitsubishi lancer, Mitsubishi, Lancer, lancer, Used Mitsubishi								

Compare

Save this search criteria, to get email alerts whenever a match is found.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	0491N
Vehicle Details	
Vehicle No.:	EK90Y
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Jan 2019
Vehicle Make:	MITSUBISHI
Vehicle Model:	LANCER 1.5 MIVEC GLS 4A/T
Primary Colour:	Black
Manufacturing Year:	2009
Engine No.:	4A910125975
Chassis No.:	JMYSRCY2A9U004423
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$18,142.00
Original Registration Date:	24 Aug 2009
First Registration Date:	24 Aug 2009
Transfer Count:	0
Actual ARF Paid:	\$18,142.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Aug 2019
PARF Rebate Amount:	\$9,071.00
Intended COE Rebate Details	
COE Expiry Date:	23 Aug 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$15,019.00
COE Rebate Amount:	\$928.00
Total Rebate Amount:	\$9,999.00

The information contained herein is correct as at 10 Jan 2019

OK



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	09/01/2019 12:34
Date Of Accident	09/01/2019 11:30
Exact Location Of Accident	JUNCTION OF JALAN BUROH AND PENJURU ROAD
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	EK90Y
Insured/Policyholder	
Name Of Registered Owner	TAN BROTHERS INSURANCE AGENCIES PTE LTD
Co Reg No	197500491N
Email Address	EDWIN.TAN@TPSGROUP.COM.SG
Mobile Phone No	(LOCAL) +65-93388201
Alternative Phone No	OFFICE-62201822
Vehicle Particulars	
Manufacturer	MITSUBISHI
Model	LANCER
Exact Purpose for which vehicle was being used at time of accident	TRAVELLING TO CUSTOMER OFFICE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	A 29092842 MCX
Cover Note Number	
Driver	
Name of Driver	EDWIN TAN YEW HOCK (EDWIN CHEN YOUFU)
NRIC No	S8201531J
Date Of Birth	01/01/1982
Occupation	INDOOR
Date Of Driving Pass	25/04/2003
Driving Experience	15 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93388201
Fax Number	
Contact Number	OFFICE-62201822
EEmail Address	EDWIN.TAN@TPSGROUP.COM.SG

Address	BLK 338 HOUGANG AVENUE 7 #01-405
Postcode	530338
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ - SINGAPORE CITY
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN AND POLICE REPORT T/20190110/7014

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XB2610M
Vehicle Make/Model/Colour	MITSUBISHI
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	MOGNAVALL S/O ARIAPPAN
NRIC/Passport Number	S6931748J
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	EDWIN TAN YEW HOCK (EDWIN CHEN YOUFU)
Approximate Age	
Injuries Sustain	SLIGHT INJURY
Injured person in which vehicle?	EK90Y
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I WAS TURNING RIGHT INTO PENJURU ROAD FROM JALAN BURUH WHEN I FELT A HARD IMPACT ON MY LEFT. THE VEHICLE JERKED & I NEARLY LOST CONTROL OF IT.



DECLARATION
I/We declare that the particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



SINGAPORE POLICE FORCE



T/20190110/7014

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 4
Report No. T/20190110/7014

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 10/01/2019 14:36	Vide Report No.:	Station Diary No.:
--	------------------	--------------------

Informant's Particulars

Name of Informant: EDWIN TAN YEW HOCK			Address: APT BLK 338 HOUGANG AVENUE 7 #01-405 SINGAPORE 530338		
ID Type / ID No.: NRIC NO / S8201531J			Contact No.: Home/Office: Mobile: 93388201		
Nationality: SINGAPORE CITIZEN			Email: edwinyh.tan@gmail.com		
Sex: Male	Age: 37	Date of Birth: 01/01/1982	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: MARKETING AND SALES REPRESENTATIVE (ICT)			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 09/01/2019 11:30	Type of Location: X-Junction
Location: JALAN BUROH				
Weather: Clear		Road Surface: Dry		Road Speed Limit: 50 Km/h
Traffic Flow: Dual Carriage Way		Traffic Control: Traffic Light - Working		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
EK90Y	Car					0
XB2610M	Container Truck	MITSUBISHI	Unsure	Blue	Slightly Damaged	0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
-------------	-------------------	--------------	-----------	-------------



**SINGAPORE
POLICE FORCE**



T/20190110/7014

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 4

Report No. T/20190110/7014

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
EK90Y	MSIG INSURANCE (SINGAPORE) PTE. LTD.			
XB2610M	MSIG INSURANCE (SINGAPORE) PTE. LTD.	Not provided		

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL			Use of Pedestrian Crossing: NA	
Driver				
Name	EDWIN TAN YEW HOCK		ID No.	S8201531J
Related Vehicle	EK90Y (Car)		Contact No.	93388201
Hospital/Clinic	SINGHEALTH POLYCLINICS - OUTRAM		Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	09/01/2019		Date Discharge	09/01/2019
No. of Days granted Medical Leave		02	Degree of Injury	Slight
Driver				
Name	Moganavall S/O Ariappan		ID No.	S6931748J
Related Vehicle	XB2610M (Container Truck)		Contact No.	NIL
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: 3,4,5 Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave		NIL	Degree of Injury	NIL

Brief Details.

I intended to make a right turn from Jalan Buroh onto Penjuru Road. The traffic light was in my favour. Suddenly, I felt a strong impact to the left side of my car and nearly lost control of my vehicle to the point that instead of turning right I went straight and cleared the junction.

When I exited the vehicle, I realised that the rear left passenger door was badly damaged. I walked back towards the junction and found a stationary container truck XB2610M which was on the lane to my left with some damages. The driver moved his vehicle from the junction to avoid congesting the flow of traffic. We exchanged particulars & went our separate ways because I felt ok.

However, later during the day, after I'd filed the accident report at IDAC, I experienced discomfort in my lower back and right shoulder and went to Outram Polyclinic to seek consultation from a doctor. I was requested to do some stretching and movement actions and was prescribed painkillers and given 2 days medical leave. I was also advised that I might experience more pain in the following days. Today, my



**SINGAPORE
POLICE FORCE**



T/20190110/7014

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

3 of 4

Report No. T/20190110/7014

CONTINUATION OF REPORT

neck began to hurt.

The uploaded report shows that the truck's registration number is keyed in incorrectly but shown to be correct on the sketch. I'm working with IDAC to amend that now.



**SINGAPORE
POLICE FORCE**



T/20190110/7014

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

4 of 4

Report No. T/20190110/7014

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / TPHQ /
YEO GEAK ENG CECILIA
Contact No.: 65476404

Authentication Stamp
NP168

Signature Of Informant:
The identity of the person making this report has
been authenticated by SingPass. No signature is
required.

Date/Time:
10/01/2019 14:36

Classification Of Case:

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S8201531J



Name

EDWIN TAN YEW HOCK
(EDWIN CHEN YOUFU)

陈有福

Race

CHINESE

Date of birth

01-01-1982

Sex

M

Country of birth
SINGAPORE

S8201531J

REPUBLIC OF SINGAPORE DRIVING LICENCE



License Number: S8201531J
Name

EDWIN TAN YEW HOCK
(EDWIN CHEN YOUFU)

Birth Date: 01 Jan 1982

Issue Date: 25 Apr 2003



000416390B



5048613

NRIC No. S8201531J



Date of issue

13-06-2012

Address

APT BLK 338 HOUGANG AVENUE 7
#01-405
SINGAPORE 530338


YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3

Motor Cars and Motor Tractors the weight of
which unladen does not exceed 2500 kilograms

PASS DATE

25 Apr 2003



License No: S8201531J

NP 428A

Addendum Sheet



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
 5 Raffles Quay #18-00 Singapore 048580
 Tel (65) 6224 0010 Fax (65) 6224 0030
 Operating Hours: Monday to Friday, 09:00 - 17:00
 UEN: S66550020 / GST Reg. No.: M400017135

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No: MAY19003807 Vehicle Registration No: EK904
 Name (as shown in NRIC): EDWIN TAN YEW HOCK NRIC/FIN/Passport No: S820153LT
 (*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
 Address: _____ Singapore ()
 Contact (Tel): _____ Mobile No.: 93388201
 Email Address: _____
 Date of Accident: 09/01/2019 Time of Accident: 11:30
 Place of Accident: JUNCTION OF JALAN PUEH AND PANGKAP KOND
 Insurance Company: melh

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

- WAS ANYBODY INJURED IN THE ACCIDENT - YE
- WAS THE ACCIDENT REPORTED TO THE POLICE - YES, REPORT ONLINE
- DETAILS OF OTHER VEHICLE PROPERTY 1 - VEHICLE REGISTRATION
NUMBER: XB2610M

Policyholder / Driver's Signature

Date: 10/01/2019



Reporting Centre Personnel's Signature

Name: Poh Yee Hoon
 NRIC/FIN No: _____
 Date: 10/01/2019

趙源摩哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

*Not Withheld
U/Ping @ \$800 max
Penny After Paint
8clays*

To: MSIG Insurance (S) Pte Ltd

Policy No: THIRD PARTY

Date: 11.01.2019

Accident Date : 09.01.2019

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost of Repair "Mitsubishi Lancer" Reg. No. EK90Y Claiming Against Your Insured Veh. No. XB2160M			
1pc	Front Door Outer Handle		R 216.00 N X
1pc	Front Door Outer Handle End Cover		CU 25.00 N ✓
1pc	Rear Door LH 828		B 936.00 N ✓
1pc	Rear Door Top Hinge		R 97.00 N X
1pc	Rear Door Weatherstrip		CU 140.00 N 501
1pc	Rear Door Inner Lock		Del 310.50 N —
1pc	Rear Door Outer Handle		CU 144.00 N ✓
1pc	Rear Door Glass Guide		DIT 145.00 N Z
1pc	Rear Door Trim Board 589		MZ 625.00 N ✓
10pcs	Rear Door Trim Board Clips	4.00	M 40.00 N —
1pc	Rear Door Glass Outer Moulding		B 185.00 N —
1pc	Rear Door Glass Regulator		DIT 142.00 N Z
1pc	Rear Door Glass Motor		M 399.00 N Z
1pc	Rocker Panel Skirt		CMA 565.00 N —
10pcs	Rocker Panel Skirt Clips	4.00	M 40.00 N ✓
1pc	Rear Fender LH		M 978.00 N ✓
1pc	Rear Fender Inner Panel		R 889.00 N X
1pc	Rear Shock Absorber		S 213.50 N X
1pc	Rear Knuckle Arm 414		B 496.00 N Z
1pc	Rear Knuckle Arm Bearing		M 189.00 N Z
1pc	Rear Lower Arm		DIT 238.70 N Z
1pc	Rear Upper Arm		S 315.00 N X
1pc	Rear Trailing Arm 402		B 516.00 N Z
			7,844.70
	Less 10%		784.47
			7,060.23
1pc	Rear Door Visor		M 180.00 SN
1pc	Rear Door Sound Insulation Mat (Sound System)		M 100SN 150.00 SN
1pc	Rear Windscreen Glass Sealant		M 40SN 50.00 SN
1pc	Rear Windscreen Glass Sealer		M 30.00 SN
1pc	Rear Windscreen Glass Fastener		M 50.00 SN 30
1pc	Rear Wheel Rim		Del 350.00 SN Z
	To Dismantle / Transfer Rear Door Fittings / Ancillary Accessories		120.00 60L
	To Dismantle / Refit Rear Windscreen Glass		160.00 120
	To Dismantle / Refit Fuel Tank Inlet Pipe and House		100.00 60L
		C/F	8,250.23

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: MSIG Insurance (S) Pte Ltd

Policy No: THIRD PARTY

Date: 11.01.2019

Accident Date : 09.01.2019

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost of Repair "Mitsubishi Lancer" Reg. No. EK90Y Claiming Against Your Insured Veh. No. XB2160M		
		B/F	8,250.23
	To Dismantle / Transfer Rear Spare Tyre Panel Inner Trims Boards / Garnish and Rear Fenders Inner Trims Boards / Garnish to Facilitate Repair		80.00 ✓
	To Dismantle / Replace Rear Under Carriage to Facilitate Repair		220.00 742
	To Conduct Computerize Wheel Alignment Test		80.00 601
	To Supply Rear Fender Panel Joint Sealant		60.00 301
	To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replaced / Repair Panel		100.00 601
	To Dismantle / Refit Roof Upholstery		120.00 601
	Labour Charge - Panel Beating , Repairing Of Front Door, Door "B" Pillar, Rocker Panel, Rear Fender Inner Panel, Rear Bumper etc. Cnt, Weld Rear Fender and Parts Replacement		1,200.00 800
	To Spray Painting Affected Areas		1,400.00 11001
		Total :	<u>11,510.23</u>

WHEEL ALIGNMENT SYSTEM

Customer: CHEW GOON MOTOR
 Description: MITSUBISHI LANCER
 Reference Diameter: 16"
 Working Notes: *
 Date: 15/01/2019
 Operator:

Reg. N.: EK 90 Y
 Repair order no.:
 Mileage: km

Time: 11.45.54

FRONT AXLE

	Databank				Previous Values		Final Values	
	Data		- Tolerance	+ Tolerance	LH	RH	LH	RH
Total toe	LH	RH						
Half-toe								
Max Dif.								
Camber								
Max Dif.								
Caster								
Max Dif.								
King-pin angle								
Max Dif.								
Included angle								
Steering angle diff. at 20°								
Max Int. Steering Angle								
Max Ext. Steering Angle								
Set Back								
Tyre								
Pressure measured								
Tread depth (mm)								

REAR AXLE

	Databank				Previous Values		Final Values	
	Data		- Tolerance	+ Tolerance	LH	RH	LH	RH
Total toe	LH	RH						
Half-toe								
Max Dif.								
Camber								
Max Dif.								
Set Back								
Thrust angle								
Track difference								
Tyre								
Pressure measured								
Tread depth (mm)								

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

Not Authorized
16/1/19
U/Sing B?
Penalty After Paint
8clays

To: MSIG Insurance (S) Pte Ltd

Policy No: THIRD PARTY

Date: 11.01.2019

Accident Date : 09.01.2019

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost of Repair "Mitsubishi Lancer" Reg. No. EK90Y Claiming Against Your Insured Veh. No. XB2160M			
1pc	Front Door Outer Handle		R 216.00 N X
1pc	Front Door Outer Handle End Cover		Cur 25.00 N ✓
1pc	Rear Door LH		Bt 936.00 N ✓
1pc	Rear Door Top Hinge		R 97.00 N X
1pc	Rear Door Weatherstrip		To Cur 140.00 N 501
1pc	Rear Door Inner Lock		Ref 310.50 N ✓
1pc	Rear Door Outer Handle		CMA 144.00 N ✓
1pc	Rear Door Glass Guide		145.00 N 7
1pc	Rear Door Trim Board		M3CMA 625.00 N ✓
10pcs	Rear Door Trim Board Clips	4.00	NA 40.00 N ✓
1pc	Rear Door Glass Outer Moulding		Alu 185.00 N ✓
1pc	Rear Door Glass Regulator		142.00 N 7
1pc	Rear Door Glass Motor		399.00 N 7
1pc	Rocker Panel Skirt		CMA 565.00 N ✓
10pcs	Rocker Panel Skirt Clips	4.00	NA 40.00 N ✓
1pc	Rear Fender LH		Alu 978.00 N ✓
1pc	Rear Fender Inner Panel		889.00 N 7
1pc	Rear Shock Absorber		213.50 N 7
1pc	Rear Knuckle Arm		496.00 N 7
1pc	Rear Knuckle Arm Bearing		189.00 N 7
1pc	Rear Lower Arm		238.70 N 7
1pc	Rear Upper Arm		315.00 N 7
1pc	Rear Trailing Arm		516.00 N 7
Less 10%			7,844.70
			784.47
			7,060.23
1pc	Rear Door Visor		NA 180.00 SN
1pc	Rear Door Sound Insulation Mat (Sound System)		150.00 SN
1pc	Rear Windscreen Glass Sealant		40SN 50.00 SN
1pc	Rear Windscreen Glass Sealer		NA 30.00 SN
1pc	Rear Windscreen Glass Fastener		NA 50.00 SN 30
1pc	Rear Wheel Rim		Ref 350.00 SN ✓
To Dismantle / Transfer Rear Door Fittings / Ancillary Accessories			120.00 60L
To Dismantle / Refit Rear Windscreen Glass			160.00 120L
To Dismantle / Refit Fuel Tank Inlet Pipe and House			100.00 60L
			8,250.23

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged car during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company.

Acknowledged by Repairer
Signature:
Date:

C/F

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: MSIG Insurance (S) Pte Ltd

Policy No: THIRD PARTY

Date: 11.01.2019

Accident Date : 09.01.2019

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost of Repair "Mitsubishi Lancer" Reg. No. EK90Y Claiming Against Your Insured Veh. No. XB2160M		
		B/F	8,250.23
	To Dismantle / Transfer Rear Spare Tyre Panel Inner Trims Boards / Garnish and Rear Fenders Inner Trims Boards / Garnish to Facilitate Repair		80.00 ✓
	To Dismantle / Replace Rear Under Carriage to Facilitate Repair		220.00 ?
	To Conduct Computerize Wheel Alignment Test		80.00 600
	To Supply Rear Fender Panel Joint Sealant		60.00 300
	To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replaced / Repair Panel		100.00 600
	To Dismantle / Refit Roof Upholstery		120.00 600
	Labour Charge - Panel Beating , Repairing Of Front Door, Door "B" Pillar, Rocker Panel, Rear Fender Inner Panel, Rear Bumper etc. Cnt, Weld Rear Fender and Parts Replacement		1,200.00 800
	To Spray Painting Affected Areas		1,400.00 1100
		Total :	<u>11,510.23</u>

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	09 Jan 2019		14 Jan 2019 15:51 Edit Adj Rpt	S\$5,800.00 Edit Estimates	S\$5,800.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	SINSEMOH TRANSPORTATION PTE LTD , Co. Reg. No.: NA								
Main Claimant:	TAN BROTHERS INSURANCE AGENCIES PTE LTD , Co. Reg. No.: 197500491N								
Vehicle Reg. No.:	EK90Y	Date of Loss:	09/01/2019 12:00 - :59 [112 Months and 16 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 581946	Policy/Cover Note No.:	B28720308MKF (Third Party Only) Coverage: 01/04/2018 - 31/03/2019						
Vehicle Reg. No. (Insured):	XB2160M	Policy No. (Claimant):							
		Excess:							
Repairer:	Chew Goon Motor (AMK) Blk 10 Ang Mo Kio Industrial Park 2A, #01-15/16 & 17, AMK Autopoint, 568047 Ang Mo Kio - Tel: 64841626								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 13/02/2019]								
Driver/Custodian (Insured):	MOGANAVAL S/O ARIAPPAN (), NRIC: S6931748J, Tel: +6598931562								
Adj Asg. Remarks:	Liability 50/50 Assign LKK Auto Consultants Pte Ltd Vehicle in workshop Contact 6484 1626								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*EK90Y (581946)
[XB2160M]

TP

TAN BROTHERS INSURANCE AGENCIES PTE LTD

Jan 9 2019 12:00PM

[SINSENMOH TRANSPORTATION PTE LTD]

Chew Goon Motor

Upload Documents			Upload Photos			Compose New Letter			View			View in Browser		
Assessment Reports									1 per page			<input checked="" type="checkbox"/>		
No	Finalized On		MSIG Insurance (Singapore) Pte. Ltd. (HQ)							Thumbnail		Print		
1	14/01/19 09:45		Accident Statement From: SC - Reg. No: XB2160M, Claimant: SINSENMOH TRANSPORTATION PTE LTD							Load HTM				
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)							Thumbnail		Print		
1	16/01/19 15:59		Adjuster Immediate Advice							Load HTM				
Photos/Images									3 per page			<input checked="" type="checkbox"/>		
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)							Thumbnail		Print		
1	01/02/19 10:51		General View							Load JPG		<input checked="" type="checkbox"/>		
2	01/02/19 10:51		General View							Load JPG		<input checked="" type="checkbox"/>		
3	01/02/19 10:51		General View							Load JPG		<input checked="" type="checkbox"/>		
4	01/02/19 10:51		General View							Load JPG		<input checked="" type="checkbox"/>		
5	01/02/19 10:51		General View							Load JPG		<input checked="" type="checkbox"/>		
6	01/02/19 10:51		General View							Load JPG		<input checked="" type="checkbox"/>		
7	01/02/19 10:51		General View							Load JPG		<input checked="" type="checkbox"/>		
8	01/02/19 10:51		General View							Load JPG		<input checked="" type="checkbox"/>		
9	01/02/19 10:51		General View							Load JPG		<input checked="" type="checkbox"/>		
10	01/02/19 10:51		General View							Load JPG		<input checked="" type="checkbox"/>		
11	01/02/19 10:51		General View							Load JPG		<input checked="" type="checkbox"/>		
12	01/02/19 10:51		General View							Load JPG		<input checked="" type="checkbox"/>		
13	01/02/19 10:51		General View							Load JPG		<input checked="" type="checkbox"/>		
14	01/02/19 10:51		General View							Load JPG		<input checked="" type="checkbox"/>		
15	01/02/19 10:51		General View							Load JPG		<input checked="" type="checkbox"/>		
16	01/02/19 10:51		General View							Load JPG		<input checked="" type="checkbox"/>		
17	01/02/19 10:51		General View							Load JPG		<input checked="" type="checkbox"/>		
18	01/02/19 10:51		General View							Load JPG		<input checked="" type="checkbox"/>		
19	01/02/19 10:51		General View							Load JPG		<input checked="" type="checkbox"/>		
20	01/02/19 10:51		General View							Load JPG		<input checked="" type="checkbox"/>		
21	01/02/19 10:51		General View							Load JPG		<input checked="" type="checkbox"/>		
22	01/02/19 10:51		General View							Load JPG		<input checked="" type="checkbox"/>		
23	01/02/19 10:51		General View							Load JPG		<input checked="" type="checkbox"/>		
24	01/02/19 10:51		General View							Load JPG		<input checked="" type="checkbox"/>		
25	01/02/19 10:51		General View							Load JPG		<input checked="" type="checkbox"/>		
26	01/02/19 10:55		Reinspection Photo							Load JPG		<input checked="" type="checkbox"/>		
27	01/02/19 10:55		Reinspection Photo							Load JPG		<input checked="" type="checkbox"/>		
28	01/02/19 10:55		Reinspection Photo							Load JPG		<input checked="" type="checkbox"/>		
29	01/02/19 10:55		Reinspection Photo							Load JPG		<input checked="" type="checkbox"/>		
30	01/02/19 10:55		Reinspection Photo							Load JPG		<input checked="" type="checkbox"/>		
31	01/02/19 10:55		Reinspection Photo							Load JPG		<input checked="" type="checkbox"/>		
32	01/02/19 10:55		Reinspection Photo							Load JPG				

Assessment Reports			1 per page	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
				✓
33	01/02/19 10:55	Reinspection Photo	Load JPG	✓
34	01/02/19 10:56	Reinspection Photo	Load JPG	✓
35	01/02/19 10:56	Reinspection Photo	Load JPG	✓
Documentation			1 per page	✓
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	14/01/19 09:45	EK90Y GIA REPORT From: SC - Reg. No: XB2160M, Claimant: SINSEMOH TRANSPORTATION PTE LTD	Load PDF	
2	14/01/19 09:47	TP CHOOSE LKK CONSULTANCY	Load PDF	
3	14/01/19 09:47	RPI REQUEST	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19000821/KTD3E2

Date: 01/02/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No:

B28720308MKF

Claimant Vehicle
No : EK90Y

Insured Vehicle No :

XB2160M

Date of Loss: 09/01/2019

Nature of Claim:

TP

Claim No: 581946

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **EK90Y**

Make & Model: MITSUBISHI LANCER, 1.5 GLX (A)

Engine No: 4A910125975

Reg. Date: 24/08/2009 (Man. Year: 2009)

Chassis No: JMYSRCY2A9U004423

Colour: Metallic Black

Odometer: 266325 km

Engine Capacity: 1499 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size:

215/60 R16

Front Left Side: Falken 4 mm

Rear Left Side:

Falken 4 mm

Front Right Side: Falken 4 mm

Rear Right Side:

Falken 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,870.23	5,770.78	2,099.45	26.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,640.00	2,570.00	1,070.00	29.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,510.23	8,340.78	3,169.45	27.54
Approved Total (Overridden) (S\$)		5,800.00		
(S\$)	11,510.23	5,800.00	5,710.23	49.61
+ GST 7.00/7.00% (S\$)	805.72	406.00	399.72	49.61
Nett Amount (S\$)	12,315.95	6,206.00	6,109.95	49.61

INSPECTION

Date of Assignment: 14/01/2019

Date Inspected: 15/01/2019 Inspected At:

Chew Goon Motor (AMK)

Blk 10 Ang Mo Kio Industrial Park 2A, #01-

15/16 & 17, AMK Autopoint

Singapore 568047

Estimated Period of Repair: 8.0 days

Adjuster: KENNETH KONG**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Feb 2019)
Parts:	143	MITSUBISHI LANCER 1.5 GLX (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for EK90Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT DOOR OUTER HANDLE	Repair	216.00 FN	*- FN
2	1	*FRONT DOOR OUTER HANDLE END COVER	Cut	25.00 FN	*25.00 FN
3	1	*REAR DOOR LH	Bent	936.00 FN	*828.00 FN
4	1	*REAR DOOR TOP HINGE	Repair	97.00 FN	*- FN
5	1	*REAR DOOR WEATHERSTRIP (\$140.00) (50%)	Bent	126.00 FS	*70.00 FS
6	1	*REAR DOOR INNER LOCK	Dented	310.50 FN	*310.50 FN
7	1	*REAR DOOR OUTER HANDLE	Cracked	144.00 FN	*144.00 FN
8	1	*REAR DOOR GLASS GUIDE	Distorted	145.00 FN	*145.00 FN
9	1	*REAR DOOR TRIM BOARD	MTG Cracked	625.00 FN	*589.00 FN
10	10	*REAR DOOR TRIM BOARD CLIPS	Necessary	40.00 FN	*40.00 FN
11	1	*REAR DOOR GLASS OUTER MOULDING	Buckled	185.00 FN	*185.00 FN
12	1	*REAR DOOR GLASS REGULATOR	Distorted	142.00 FN	*142.00 FN
13	1	*REAR DOOR GLASS MOTOR	Jammed	399.00 FN	*399.00 FN
14	1	*ROCKER PANEL SKIRT	Cracked	565.00 FN	*565.00 FN
15	10	*ROCKER PANEL SKIRT CLIPS	Necessary	40.00 FN	*40.00 FN
16	1	*REAR FENDER LH	Bent	978.00 FN	*978.00 FN
17	1	*REAR FENDER INNER PANEL	Repair	889.00 FN	*- FN
18	1	*REAR SHOCK ABSORBER	Serviceable	213.50 FN	*- FN
19	1	*REAR KNUCKLE ARM	Bent	496.00 FN	*414.00 FN
20	1	*REAR KNUCKLE ARM BEARING	Necessary	189.00 FN	*189.00 FN
21	1	*REAR LOWER ARM	Distorted	238.70 FN	*238.70 FN
22	1	*REAR UPPER ARM	Serviceable	315.00 FN	*- FN
23	1	*REAR TRAILING ARM	Bent	516.00 FN	*402.00 FN
24	1	*REAR DOOR VISOR	Necessary	180.00 FS	*80.00 FS
25	1	*REAR DOOR SOUND INSULATION MAT (SOUND SYSTEM)	Necessary	150.00 FS	*100.00 FS
26	1	*REAR WINDSCREEN GLASS SEALANT	Necessary	50.00 FS	*40.00 FS
27	1	*REAR WINDSCREEN GLASS SEALER	Necessary	30.00 FS	*30.00 FS
28	1	*REAR WINDSCREEN GLASS FASTENER	Necessary	50.00 FS	*30.00 FS
29	1	*REAR WHEEL RIM	Dented	350.00 FS	*350.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$) **8,640.70** **6,334.20**
 - Nett Item Discount on N Items 10.00/10.00% (\$\$) **770.47** **563.42**

Total Parts (\$\$) 7,870.23 5,770.78

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE / TRANSFER REAR DOOR FITTINGS / ANCILLARY ACCESSORIES	New	120.00	60.00
2	TO DISMANTLE / REFIT REAR WINDSCREEN GLASS	New	160.00	120.00
3	TO DISMANTLE / REFIT FUEL TANK INLET PIPE AND HOUSE	New	100.00	60.00
4	TO DISMANTLE / TRANSFER REAR SPARE TYRE PANEL INNER TRIMS BOARDS / GARNISH AND REAR FENDERS INNER TRIMS BOARDS / GARNISH TO FACILITATE REPAIR	New	80.00	80.00
5	TO DISMANTLE / REPLACE REAR UNDER CARRIAGE TO FACILITATE REPAIR	New	220.00	140.00
6	TO CONDUCT COMPUTERIZE WHEEL ALIGNMENT TEST	New	80.00	60.00
7	TO SUPPLY REAR FENDER PANEL JOINT SEALANT	New	60.00	30.00
8	TO APPLY RUST PROOFING / RESEAL TUFF COATING TREATMENT TO RESPRAY / REPLACED / REPAIR PANEL	New	100.00	60.00
9	TO DISMANTLE / REFIT ROOF UPHOLSTERY	New	120.00	60.00
10	LABOUR CHARGE - PANEL BEATING, REPAIRING OF FRONT DOOR, DOOR B PILLAR, ROCKER PANEL, REAR FENDER INNER PANEL, REAR BUMPER ETC. CUT, WELD REAR FENDER AND PARTS REPLACEMENT	New	1,200.00	800.00
11	TO SPRAY PAINTING AFFECTED AREAS	New	1,400.00	1,100.00
Gross Labour Cost (S\$)			3,640.00	2,570.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >