

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Clara Li Zi Rong

Date: 21 Jan 2019

Preliminary Advice

Insured Vehicle No : SKL7315C

TP Vehicle No : SGZ7313G

Make : MITSUBISHI COLT PLUS

Date of Inspection : 18/01/2019

Inspection At : TORQUE 5 PTE LTD

Accident Date : 14/01/2019

Assignment Date : 15/01/2019

Est. Duration of Repair : 4/Days

Point of Impact / General Description of Damages

The vehicle sustained impact / damagesFront O/S... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	16,301.00
Revised Amount	:S\$	5,370.00
Check Items (Estimated)	:S\$	6,038.00
Total	:S\$	11,408.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments :We have not authorized repairs.