


Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 17:45

Company Reg. No. 199902271W
GST Reg. No. 199902271W

Customer

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013990 Date : 02/07/2019 Order : SKD0140C Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No: SKD0140C (V 32569) Regn Date: 27/02/2017 Mileage: 44873 WIP No.: 39278

Model: Q5 2.0 TFSI quattro (180 bhp) Chassis: WAUZZZ8RXHA080088 Engine: CNC 182052 Dept: U

You have been assisted by :- UB-Justin Ee (R) (46)

		Details	Qty	Unit Price	Amount
Q	EXC	M: 8888 Insurance Excess/Liability	-500.00	1.00	-500.00
S	BODYWORK	M: TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	480.00	1.00	480.00
S	BODYWORK	M: TO DISMANTLE AND RENEW FRONT BUMPER AND LHS FRONT FENDER. REORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	1200.00	1.00	1,200.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER, FRONT SPOILER AND LHS FRONT FENDER.	1375.00	1.00	1,375.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
X	A8R0821105A	FENDER Less 020%	1.00	912.50	730.00
X	A8R0821171K	WHEEL HOUS Less 020%	1.00	245.50	196.40
X	A8R0807065C GRU	(V) (SK) COVER 17/01/1 Less 020%	1.00	2353.00	1,882.40
X	A8R0807061F GRU	FR. SPOILER Less 020%	1.00	568.50	454.80
X	A8R0821135	SUPPORT Less 020%	1.00	78.30	62.64
X	A8R0098629	ATT. PARTS Less 020%	1.00	93.70	74.96
X	A8R0821467A	BRACKET Less 020%	1.00	48.20	38.56
X	A8R0807283C	GUIDE Less 020%	1.00	33.90	27.12
X	A8R0807277C	STRIP Less 020%	1.00	33.10	26.48
X	A8R0821469	BRACKET Less 020%	1.00	44.50	35.60
X	A8R0853887B	(A) (SK) SPOILER 17/01 Less 020%	1.00	59.50	47.60
X	A8R0854959G GRU	(A) (SK) LINING 17/01/ Less 020%	1.00	174.00	139.20
X	A8R0807681M BJI	(A) (SK) GRILL 17/01/1 Less 020%	1.00	319.00	255.20
X	A8T0941699B	FOG LAMP Less 020%	1.00	238.00	190.40
X	AN 0161857	POP-RIVET Less 020%	6.00	3.00	14.40

Parts 4,175.76
Labour 0.00
Sublet 3,247.00
Menus 0.00
Lubricant 0.00

Sub-Total 6,922.76

7% GST 484.59

Grand Total 7,407.35



Received by

For & on behalf of
Premium Automobiles Pte Ltd