

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chong Boon Sen

Date: 02 Apr 2019

Preliminary Advice

Vehicle No	: SKG7315D	Accident Date	: 08/01/2019
Make	: PORSCHE CAYENNE	Policy No.	: DMPCSN30927418022
Assignment Date	: 16/01/2019	Excess	: S\$3,500.00
Date of Inspection	: 16/01/2019	Est. Duration of Repair	: 12 days
Inspection At	: Trans Eurokars Pte Ltd (HQ) 5 Ubi Close Singapore 408605		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	72,481.41 (INCLUSIVE SUPPLEMENTARY)
Revised Amount	:S\$	46,860.22 (INCLUSIVE SUPPLEMENTARY)
Check Items (Estimated)	:S\$	10,148.67
Total	:S\$	57,008.89
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	140,000.00
COE / PARF Rebate	:S\$	81,994.00
Salvage Value	:S\$	
Margin for Repair	:S\$	58,006.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Supplemenatry amount is \$ 9,871.29