

Surveyor

Mr. Jim

ASSIGNMENT (Office)

Person (Person)

Catherine Thia

of

CTI

Date/Time 16/11/19 @ 2:28pm

Estimated Cost:

Bill to:

☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.

PC7619P

Insured:

at Workshop n/s

Best Auto

Tel:

6604 9883

of

2 kaki Bukit Ave 2 #01-11

Policy No.

Claim No:

SNM19D200281

Sum Insured:

Excess:

\$1,500.00

Make of Veh;

(Client's Record)

D.O.A 12/01/2019

CA / ☒ REV / REP. / REV 24 HRS

H.O.D. Endorsement

Date/Time:

2:48pm @ 16/11/19

Person Contacted:

Yan

Vehicle ☒ IN / ☐ OUT

Date/Time

Action/Instruction (✓) Estimate

PC7619P-CS3/CTI190009954/Gcd3

Dut: 12/01/2019

17/1/19

@ 1:15pm Yan said est not ready

17/1/19

Informed Catherine Thia pending est from repairer by merimen

21/1/19

Revert via merimen

22/1/19

Per approved \$6660 from Catherine by merimen

22/1/19

Informed Yan c/A & \$1500 by email

28/2/19

@ 11:48am Yan said still pending for spare parts

29/3/19

@ 3:13pm Yan said still pending for spare parts

14/5/19

@ 11:35am check with Eddie can mark up 10% on cost

17/5/19

@ 12:19pm Mr Lim confirmed \$6420 with Yan (Red 2675, 2990)

RECEIVED 17 MAY 2019

REF:

CT11

ASSIGNMENT

From: _____ Date: 16/1/19

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: PC 7619Pat Workshop n/s: BEST AUTOof 2 Kaki Bukit Ave 2 # 01-17

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____

Excess: 1500.00

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: PC 7619P Yt Regn: 15/10/18Type: M/Car / M/Cycle / Bus ☒ Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA HIACEC.G. 2782 2754Colour: WHITE

A/C: Insured / Std / NI / NA

Sp Reading: 11640

T/Radio: Insured / Std / NI / NA

Eng/No: 18D8299248Ctno: GDH2011009131Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/80/15R: 195/80/15BS: DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 7 mmR/Bal: 7 mmL/Bal: 7 mmU/Bal: 7 mmD.O.A: 12/1/19D.O.I: 16/1/19Survey held at: BEST AUTODes. of Damages: FR / Rear / O/S / MS / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time: _____ Action / Instruction: _____

NOT AUTHORISED

MV 68,000/-
PV 26,848/-
NV A1,152/-

Date/Time, File Pass to?

☐

: Proll. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

17/5 - typist

Days Of Repair: 5Resurvey No. of Trip: 2

Survey Fee:

Transportation

) S + RS \$

) Photos

) Others

) .

TOTAL

Report Format :

merimen

Lump Sum / I.B.I: (\$

6420/-

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

220



Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 22 January 2019 4:53 PM
To: 'Best Auto K'; SUR
Subject: RE: PC7619P - REPAIR ESTIMATE-DOA: 12/1/2019

Dear Yan,

Vehicle excess \$1500/-

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 22 January 2019 3:20 PM
To: 'Best Auto K' <bestautokpl@gmail.com>; SUR <sur@lkkauto.com>
Subject: RE: PC7619P - REPAIR ESTIMATE-DOA: 12/1/2019

Dear Yan,

As instructed by our client , please proceed to repair the **insured vehicle PC 7619P (Excess S0/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 22 January 2019 9:54 AM
To: 'Best Auto K' <bestautokpl@gmail.com>; SUR <sur@lkkauto.com>
Subject: RE: PC7619P - REPAIR ESTIMATE

Dear Yan,

Still pending approval from insurance.

You may check with OIC Catherine Thia.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Best Auto K <bestautokpl@gmail.com>

Sent: Tuesday, 22 January 2019 9:30 AM

To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>

Subject: Re: PC7619P - REPAIR ESTIMATE

Morning Veron Chen,

How long does it take time to know insurance answer ?

Thanks & Regards,

Yan

Best Auto K Pte Ltd

2 Kaki Bukit Ave 2 #01-11 Auto Hub Singapore 417921

T: 6604 9883 F: 6604 9823

On Mon, Jan 21, 2019 at 5:41 PM Veron Chen (LKKAuto) <veronchen@lkkauto.com> wrote:

Dear Yan,

Pending approval from insurance.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

From: Best Auto K <bestautokpl@gmail.com>
Sent: Monday, 21 January 2019 5:25 PM
To: Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Subject: Re: PC7619P - REPAIR ESTIMATE

Hi Nivitha,

May i know how about the latest status of the vehicle PC7619P od claim case.

Thanks & Regards,

Yan

Best Auto K Pte Ltd

2 Kaki Bukit Ave 2 #01-11 Auto Hub Singapore 417921

T: 6604 9883 F: 6604 9823

On Mon, Jan 21, 2019 at 5:22 PM Best Auto K <bestautokpl@gmail.com> wrote:

Hi Nivitha,

May i know how about lathe vehicle PC7619P od claim case latest status

Thanks & Regards,

Yan

Best Auto K Pte Ltd

2 Kaki Bukit Ave 2 #01-11 Auto Hub Singapore 417921

T: 6604 9883 F: 6604 9823

On Fri, Jan 18, 2019 at 3:50 PM Admin-D (LKKAuto) <admin-d@lkkauto.com> wrote:

Dear Yan,

Received, with thanks.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Best Auto K [<mailto:bestautokpl@gmail.com>]

Sent: Friday, 18 January 2019 3:45 PM

To: assignments@lkkauto.com

Cc: catherine.thia@sg.cntaiping.com

Subject: Re: PC7619P - REPAIR ESTIMATE

Hi Liminda,

Sorry for the inconvenience. Kindly refer to Amended attachment.

Thanks & Regards,

Yan

Best Auto K Pte Ltd

2 Kaki Bukit Ave 2 #01-11 Auto Hub Singapore 417921

T: 6604 9883 F: 6604 9823

On Fri, Jan 18, 2019 at 3:39 PM Best Auto K <bestautokpl@gmail.com> wrote:

Hi Liminda,

Kindly refer to attachment for this vehicle repair estimate amount.

Thanks & Regards,

Yan

Best Auto K Pte Ltd

2 Kaki Bukit Ave 2 #01-11 Auto Hub Singapore 417921

T: 6604 9883 F: 6604 9823



AVG

This email has been checked for viruses by AVG antivirus software.
www.avg.com

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Tuesday, 22 January 2019 3:20 PM
To: 'Best Auto K'; SUR
Subject: RE: PC7619P - REPAIR ESTIMATE-DOA: 12/1/2019
Attachments: MARK EST.pdf

Dear Yan,

As instructed by our client , please proceed to repair the **insured vehicle PC 7619P (Excess S0/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)
Sent: Tuesday, 22 January 2019 9:54 AM
To: 'Best Auto K' <bestautokpl@gmail.com>; SUR <sur@lkkauto.com>
Subject: RE: PC7619P - REPAIR ESTIMATE

Dear Yan,

Still pending approval from insurance.

You may check with OIC Catherine Thia.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Best Auto K <bestautokpl@gmail.com>
Sent: Tuesday, 22 January 2019 9:30 AM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Subject: Re: PC7619P - REPAIR ESTIMATE

Morning Veron Chen,

How long does it take time to know insurance answer ?

Thanks & Regards,

Yan

Best Auto K Pte Ltd

2 Kaki Bukit Ave 2 #01-11 Auto Hub Singapore 417921

T: 6604 9883 F: 6604 9823

On Mon, Jan 21, 2019 at 5:41 PM Veron Chen (LKKAuto) <veronchen@lkkauto.com> wrote:

Dear Yan,

Pending approval from insurance.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Best Auto K <bestautokpl@gmail.com>

Sent: Monday, 21 January 2019 5:25 PM

To: Admin-D (LKKAuto) <admin-d@lkkauto.com>

Subject: Re: PC7619P - REPAIR ESTIMATE

Hi Nivitha,

May i know how about the latest status of the vehicle PC7619P od claim case.

Thanks & Regards,

Yan

Best Auto K Pte Ltd

2 Kaki Bukit Ave 2 #01-11 Auto Hub Singapore 417921

T: 6604 9883 F: 6604 9823

On Mon, Jan 21, 2019 at 5:22 PM Best Auto K <bestautokpl@gmail.com> wrote:

Hi Nivitha,

May i know how about lathe vehicle PC7619P od claim case latest status

Thanks & Regards,

Yan

Best Auto K Pte Ltd

2 Kaki Bukit Ave 2 #01-11 Auto Hub Singapore 417921

T: 6604 9883 F: 6604 9823

On Fri, Jan 18, 2019 at 3:50 PM Admin-D (LKKAUTO) <admin-d@lkkauto.com> wrote:

Dear Yan,

Received, with thanks.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4345

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Best Auto K [<mailto:bestautokpl@gmail.com>]

Sent: Friday, 18 January 2019 3:45 PM

To: assignments@lkkauto.com

Cc: catherine.thia@sg.cntaiping.com

Subject: Re: PC7619P - REPAIR ESTIMATE

Hi Liminda,

Sorry for the inconvenience. Kindly refer to Amended attachment.

Thanks & Regards,

Yan

Best Auto K Pte Ltd

2 Kaki Bukit Ave 2 #01-11 Auto Hub Singapore 417921

T: 6604 9883 F: 6604 9823

On Fri, Jan 18, 2019 at 3:39 PM Best Auto K <bestautokpl@gmail.com> wrote:

Hi Liminda,

Kindly refer to attachment for this vehicle repair estimate amount.

Thanks & Regards,

Yan

Best Auto K Pte Ltd

2 Kaki Bukit Ave 2 #01-11 Auto Hub Singapore 417921

T: 6604 9883 F: 6604 9823



This email has been checked for viruses by AVG antivirus software.
www.avg.com

View Received Message

This mail is associated with :

***PC7619P (SNM19D0200281)**

OD

Jan 12 2019 12:00AM

[L.K.CONSTRUCTION PTE LTD]

Best Auto K Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA_TAIPING), sent on 22/01/2019 15:04 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$6660.00) - PC7619P - Claim Handler: Catherine Thia

Approved:6660.00:pls aifc.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199807198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd. 3 Anson Road #16-00 Springleaf Tower Singapore 079909	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Catherine Thia	Date: 21 Jan 2019

Preliminary Advice

Vehicle No	: PC7619P	Accident Date	: 12/01/2019
Make	: TOYOTA HIACE	Policy No.	: DMCVSN30670818000
Assignment Date	: 16/01/2019	Excess	: S\$0.00
Date of Inspection	: 16/01/2019	Est. Duration of Repair	: 0.00
Inspection At	: BEST AUTO K PTE LTD (HQ) 2 KAKI BUKIT AVENUE 2, #01-11 KAKI BUKIT AUTOHUB SINGAPORE 417921		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,795.00
Revised Amount	:S\$	5,320.00
Check Items (Estimated)	:S\$	1,340.00
Total	:S\$	6,660.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	68,000.00
COE / PARF Rebate	:S\$	26,848.00
Salvage Value	:S\$	
Margin for Repair	:S\$	41,152.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

View Sent Message

This mail is associated with :

***PC7619P (SNM19D0200281)**

OD

Jan 12 2019 12:00AM

[L.K.CONSTRUCTION PTE LTD]

Best Auto K Pte Ltd

[Resend](#)[View Recipients](#)[Print Message](#)[Delete Message](#)[Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 17/01/2019 13:27 PM.

To CHINA_TAIPIING

Subject OD SURVEY PC 7619P

Dear Catherine,

Please be informed that we have inspected the vehicle PC 7619P on 16/1/2019.

We are pending estimate from repairer.

Best Regards,
Veron Chen

DOCUMENTS SUMMARY

There are no documents.

Nivitha (LKK Auto)

From: Catherine Thia <catherine.thia@sg.cntaiping.com>
Sent: Wednesday, 16 January 2019 2:28 PM
To: assignments
Cc: bestautokpl@gmail.com
Subject: PC7619P OD claim
Attachments: 20190116141947.pdf

Dear LKK oic

Please assist to survey vehicle on urgent basis

We will create in Merimen shortly

Thanks

Catherine Thia
Senior Executive
Motor Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
Direct (65) 6389 6193
www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: slnx@sg.chinataiping.com [mailto:slnx@sg.chinataiping.com]
Sent: Wednesday, 16 January, 2019 2:23 PM
To: Catherine Thia <catherine.thia@sg.cntaiping.com>
Subject:

Evon Char

From: Best Auto K <bestautokpl@gmail.com>
Sent: Tuesday, January 15, 2019 10:13 AM
To: Claims Dept of CTI
Subject: PC 7619 P - GIA REPORT & PHOTOS
Attachments: SAS2535137.PDF

Hi,

Kindly refer to attached for insurance own damage claims.

Thanks & Regards,

Yan

Best Auto K Pte Ltd
2 Kaki Bukit Ave 2 #01-11 Auto Hub Singapore 417921
T: 6604 9883 F: 6604 9823

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

Excess \$1500/-

15 JAN 2019

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	0969E
Vehicle Details	
Vehicle No.:	PC7619P
Vehicle to be Exported:	No
Intended Deregistration Date:	16 Jan 2019
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE DX 2.8 AUTO
Primary Colour:	White
Manufacturing Year:	2018
Engine No.:	1GD8299248
Chassis No.:	GDH2011009131
Maximum Power Output:	-
Open Market Value:	\$37,567.00
Original Registration Date:	15 Oct 2018
First Registration Date:	15 Oct 2018
Transfer Count:	0
Actual ARF Paid:	\$1,879.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	14 Oct 2028
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$27,556.00
COE Rebate Amount:	\$26,848.00
Total Rebate Amount:	\$26,848.00

The information contained herein is correct as at 16 Jan 2019

OK

Dep 7/07/19

MV 68,000/2
PV 26,848/2
NV 41,152/2

16/1/19

FREE VALUATION

Let us tell you how much your car can sell for!

No obligations and it's FREE!

How much is my car worth?



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New 5 Years Coe Renewal Toyota Vios 1.5A



2.88%APR Lowest Interest Rate
Cars Financing \$1000
Downpayment Monthly From
\$418
GV Credit Pte Ltd

• Free VICOM evaluation
• Free grooming and 6 months maintenance
• In-house workshop ensures quality service
• Member of SVTA and hire purchase association
• 100% deposit refund for unapproved loan

YONG LEE SENG MOTOR PTE LTD

Browse by Category

Back (1 2 3) Next >

Sort by Date Posted

100 results/page

218 vehicles

Toyota Hiace

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Toyota Hiace		Any	Any	2018	Any	Any	Any	All
	Toyota Hiace		\$69,800	\$7,170 /yr	09-Oct-2018	2,982 cc	1 km	Van	Available
Fuel Type: Diesel Ready Stock. 100% Loan. Warranty & Servicing Included. GST, Admin Fee & Miscellaneous All Included. Many Free Accessories In This Deal. Don't Miss Out On This Special Deal. Full Cash Welcome. Cheapest I...									
Car (5) Pte Ltd									
Posted: 16-Jan-2019 Tags: 2018 Toyota Hiace, 2018 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota									
	Toyota Hiace		\$69,800	\$7,190 /yr	27-Sep-2018	2,982 cc	18 km	Van	Available
Fuel Type: Diesel GUARANTEED CHEAPEST IN MARKET. LOWEST DRIVEAWAY. UP TO 100% LOAN AVAILABLE. IMMEDIATE PACKAGE. YEAR END PROMOTION. Double Confirm Plus Chop No Gimmicks, Inclusive Of 3 Years/100,000km Warranty And Fre...									
Car (5) Pte Ltd									
Posted: 16-Jan-2019 Tags: 2018 Toyota Hiace, 2018 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota									
	Toyota Hiace		\$69,800	\$7,170 /yr	09-Oct-2018	2,982 cc	1 km	Van	Available
Fuel Type: Diesel Ready Stock. 100% Loan. Warranty & Servicing Included. GST, Admin Fee & Miscellaneous All Included. Many Free Accessories In This Deal. Don't Miss Out On This Special Deal. Full Cash Welcome. Cheapest I...									
Car (5) Pte Ltd									
Posted: 16-Jan-2019 Tags: 2018 Toyota Hiace, 2018 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota									
	Toyota Hiace		\$67,988	\$6,930 /yr	05-Nov-2018	2,982 cc	-	Van	Available
Fuel Type: Diesel Newly Registered Toyota Hiace Manual, Guarantee 1st Owner, Ready Stock, 100% Loan With Lowest Interest Rate. We Provide In House Finance Also, Super High Trade In, Call Now!									
ABWIN Bus Pte Ltd									
Posted: 16-Jan-2019 Tags: 2018 Toyota Hiace, 2018 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota									
	Roof Mount Monitor (With DVD Player) Roof Mount Monitor from \$360 Available size 10.2", 14.1" and 17" More info about this product								
	Toyota Hiace		\$68,988	\$7,070 /yr	16-Oct-2018	2,982 cc	-	Van	Available
Fuel Type: Diesel Monthly \$784 Only. The Lowest Price You Can Get In Town. Price Come With Guarantee 10 Year COE. Call Now Before COE Up Again!									
ABWIN Bus Pte Ltd									
Posted: 16-Jan-2019 Tags: 2018 Toyota Hiace, 2018 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota									
	Toyota Hiace		\$68,988	\$7,070 /yr	17-Oct-2018	2,982 cc	-	Van	Available
Fuel Type: Diesel									

Compare [1]

Select used cars to Compare or Add to Alert

Shortlist [1]

Add to Shortlist

Compare Now

Clear All

To compare cars,
select from the
search results.

To compare cars,
select from the
search results.

To compare cars,
select from the
search results.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	14/01/2019 13:45
Date Of Accident	12/01/2019 13:00
Exact Location Of Accident	TAGORE LANE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	PC7619P
Insured/Policyholder	
Name Of Registered Owner	L. K. ANG CONSTRUCTION PTE LTD
Co Reg No	198600969E
Email Address	LKANGCO@LKAC.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-64532689

Vehicle Particulars

Manufacturer	TOYOTA
Model	HIACE DX 2.8 AUTO
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMB1SN3067081800
Cover Note Number	15/10/18 - 14/10/19

Driver

Name of Driver	HAMZAH BIN MOHAMED SAID
NRIC No	S1240550B
Date Of Birth	26/09/1957
Occupation	OUTDOOR
Date Of Driving Pass	01/02/1978
Driving Experience	40 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96331921
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 101 BT. BATOK WEST AVE 6 #01-42
Postcode	650101
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	ANG MO KIO NORTH NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 51 ANG MO KIO AVE 9 , POSTCODE: 569784 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-4849999 - FAX NO: 62181399
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT ATTACHED. *OWN DAMAGE CLAIM BY BEST AUTO CARE*

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GV6435R
Vehicle Make/Model/Colour	PARKED
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	SAN WIN
NRIC/Passport Number	G6594477X
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver) 0

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SMC3324B
Vehicle Make/Model/Colour PARKED
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver TAN SOON HOW
NRIC/Passport Number S6875424J
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver) 0

Sketch Plan

SKETCH PLAN

VEHICLE NO.: PC 7619 P
INSURER: China Taiping
DATE & TIME: 12/1/19 @ 13:00

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

ajr

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name: YS
NRIC/EIN No.:

14/1/19

SKETCH PLAN

SKETCH PLAN

↑ ↓

Tagua lane

forward

A - PC 7619P
B - GV 6435R (Parked)
San Win
G 6394477X
C - SMC 3324B (Parked)
Tan Soon How
S 6895424J

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report No: F/2019 0112/2051

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature _____
Date & Time _____

Driver's Signature _____
(If driver is not the policyholder)
Date & Time _____

Reporting Centre Personnel's Signature
Name: *(YS)*
NRIC/FIN No: *(YS)*

() Claim Own Policy () Claim Third Party () Reporting Only
(✓) Claim ODTP at other workshop (by Best Auto (pre))



**SINGAPORE
POLICE FORCE**



F/20190112/2051

1 of 2

POLICE REPORT (NP299)

Report No. F/20190112/2051

Police Station Of Origin
Ang Mo Kio North N.P.C.
51 Ang Mo Kio Avenue 9 SINGAPORE
569784
Tel No: 1800-4849999

Date/Time Report Made 12/01/2019 15:03	Vide Report No.		Station Diary No. 47	
Name Of Informant HAMZAH BIN MOHAMED SAID	Address APT BLK 101 BUKIT BATOK WEST AVENUE 6 #01-42 SINGAPORE 650101			
ID Type / ID No. NRIC NO / S12405508	Contact No. Home/Office		Mobile 96331921	
Nationality SINGAPORE CITIZEN	Email Address			
Occupation PRIVATE DRIVER	Sex Male	Age 61	Date of Birth 26/09/1957	Race Boyanese
Institution/School Name	Language English			
Date/Time Of Incident 12/01/2019 13:00	Location Of Incident TAGORE LANE SINGAPORE			

Brief details.

On 12/1/2019 at about 1300hrs, I was travelling along Tagore Lane with my white Toyota Van with license plate number PC7819P, when I accidentally swerved to the left. As a result, I crashed onto a parked white Toyota Van bearing plate number GV6435R. Due to the impact, the said van moved forward and hit onto a white BMW car bearing plate number SMC3324B which was parked in front of it. I have an in-car camera which was on during the accident. The front right bumper of my van cracked and damaged and the logo fell out. The back of the Toyota van was badly damaged and dented and the BMW car suffered scratches and dents on the rear bumper. There was no injuries involved in the

Signature Of Officer Recording The Report.

F / Sgt 2 NUR FARAHIN BINTE RAHIM

Signature Of Interpreter:
Not applicableOfficer in-Charge Of Case:
F / Ang Mo Kio North N.P.C /
Staff Sgt ZED CHANG POH CHUAN
Contact No.: 64849999

Authentication Stamp

Signature Of Informant:

Date/Time:
12/01/2019 15:03

Classification Of Case:



**SINGAPORE
POLICE FORCE**



F/20190112/2051

2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. F/20190112/2051

accident. No cyclists or pedestrians was hurt and no government properties were damaged. I exchanged particulars with the involved parties.

The particulars of the drivers are as follows:

- 1) BMW car bearing plate number SMC3324B, Tan Soon How S6875424J HP:98896736
- 2) Toyota van bearing plate number GV6435R, San Win G6594477X

I am lodging this report for record purposes and for insurance claims.

Signature Of Officer Recording The Report:

F / Sgt 2 NUR FARAHIN BINTE RAHIM

Signature Of Interpreter:
Not applicable

Officer In-Charge Of Case:
F / Ang Mo Kio North N.P.C /
Staff Sgt ZED CHANG POH CHUAN
Contact No.: 64849999

Authentication Stamp

Signature Of Informant:

Ang

Date/Time
12/01/2019 15:03

Classification Of Case:

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S1240550B



HAMZAH BIN MOHAMED SAID

حمزة بن محمد سعيد

Name

BOYANESI

Date of Birth

26-09-1957

Sex

M

Date of Birth

SINGAPORE



REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number S1240550B

Name

HAMZAH BIN MOHAMED SAID



Date of Birth 26 Sep 1957

Issue Date 05 Sep 2003



1272418

Vehicle No. S1240550B

Motor Class: G+ Serial No: 08-07-1054

Vehicle No. S1240550B Date: 30-09-2002 No: 0210801

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

		PASS DATE
Class 2D	Motorcycles not exceeding 200 cc	18 Oct 1976
Class 2A	Motorcycles between 201 cc and 400 cc	18 Oct 1976
Class 2	Motorcycles exceeding 400 cc	18 Oct 1976
Class 7	Motor Cars and Motor Tractors the weight of which unladen does not exceed 2000 kilograms	01 Feb 1978
Class 4	Heavy Motor Cars and Motor Tractors the weight of which unladen exceeds 2000 kilograms	26 Mar 1987



SP 426A

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



SCENE



SCENE



SCENE



BEST AUTO K PTE LTD

Co. GST Reg. No.: 201211041G

2 KAKI BUKIT AVE 2 #01-11 AUTO HUB SINGAPORE 417921

Tel: 6604 9883

Fax: 6604 9823

Email: bestautokpl@gmail.com

REPAIR ESTIMATED

L.K. ANG CONSTRUCTION PTE LTD
459 TAGORE INDUSTRIAL AVENUE
#04-08 SINGAPORE 787828

Our Ref : RS2019/1801
Date : 18/01/2019
Vehicle No : PC 7619 P
Model : Toyota HiAceDX 2.8 Auto
Accident Date : 12/01/2019

INSURANCE CO :-

CHINA TAIPING INSURANCE (SINGAPORE) PTE .LTD.
3 ANSON ROAD, #16-00
SPRINGLEAF TOWER SINGAPORE 079909

TEL : 6389 6116

FAX : 6225 3592

Item	Description	Qty	U/Price	Amount
1.	RADIATOR	1	1,200.00	1,200.00 NN X
2.	RADIATOR SPARE TANK	1	285.00	285.00 NN X
3.	RADIATOR SUPPORT	1	380.00	380.00 ? BT
4.	FRONT LEFT HEAD LAMP	1	1,980.00	1,980.00 BR ✓
5.	FRONT BUMPER	1	450.00	450.00 BR ✓
6.	FRONT BORNET	1	580.00	580.00 DD ✓
7.	FRONT GRILLE	1	360.00	360.00 BR ✓
8.	BUMPER BRAKET (LEFT)	1	900.00	900.00 ? BR
9.	PANEL BEATING FRONT BODY	1	600.00	600.00 ✓
10.	ADD BLUE SPARE TANK	1	450.00	450.00 CR ✓
11.	AIRCOND CONDENSOR	1	960.00	960.00 ?
12.	WITH LABOUR TO REPLACE WIRING REPAIR ALIGN BONET FRONT BUMPER HEAD LAMP	1	650.00	650.00

- ALL ABOVE IS ORIGINAL PARTS.

The details and the estimate provided above are based on our first inspection and do not constitute a guarantee that no further work/parts will be required. The total bill of work will be as per the details available on completion of the work.

Other terms and conditions as applicable.

Yours faithfully,

Administrator

hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Sub Total 8,795.00

GST 7.0 % 615.65

Total 9,410.65

BEST AUTO K PTE LTD

Co. GST Reg. No.: 201211041G

2 KAKI BUKIT AVE 2 #01-11 AUTO HUB SINGAPORE 417921

Tel: 6604 9883

Fax: 6604 9823

Email: bestautokpi@gmail.com

REPAIR ESTIMATED

L.K. ANG CONSTRUCTION PTE LTD
459 TAGORE INDUSTRIAL AVENUE
#04-08 SINGAPORE 787828

Our Ref : RS2019/1801

Date : 18/01/2019

Vehicle No : PC 7619 P

Model : Toyota HiAceDX 2.8 Auto

Accident Date : 12/01/2019

INSURANCE CO :-

CHINA TAIPING INSURANCE (SINGAPORE) PTE .LTD.

3 ANSON ROAD, #16-00

SPRINGLEAF TOWER SINGAPORE 079909

TEL : 6389 6116

FAX : 6225 3592

Item	Description	Qty	U/Price	Amount
1.	FRONT LEFT HEAD LAMP	1	2,200.00	2,200.00 BR✓
2.	FRONT BUMPER	1	450.00	450.00 BR✓
3.	FRONT BARNET BONNET	1	680.00	680.00 DD✓
4.	FRONT BUMPER BRAKET (LEFT)	1	90.00	90.00 BR✓
5.	FRONT BUMPER GRILL INNER	1	320.00	320.00 BR✓
6.	FRONT BUMPER GRILL UPPER PANEL	1	280.00	280.00 DD✓
7.	FRONT BUMPER GRILL LOWER PANEL	1	240.00	240.00 DD✓
8.	FRONT BUMPER LOWER GRILL	1	150.00	150.00 CRA✓
9.	FRONT WIPER GARNISH	1	380.00	380.00 HAX BR✓
10.	FRONT BUMPER TOP BEAM	1	220.00	220.00 DD✓
11.	FRONT BUMPER SAFETY BAR SUPPORT	1	250.00	250.00 DD✓
12.	FRONT BUMPER GRILL SAMLL (LEFT)	1	90.00	90.00 CUT✓
13.	RADIATOR TOP PANEL	1	195.00	195.00 DD✓
14.	RADIATOR SPARE TANK	1	320.00	320.00 CRA✓
15.	RADIATOR SUPPORT (LEFT)	1	185.00	185.00 BT✓
16.	WIPER TANK	1	160.00	160.00 CRA✓
17.	ADD BLUE SPARE TANK	1	1600.00	1600.00 CUT✓
18.	WIRING BRACKET (LEFT)	1	85.00	85.00 BR✓
19.	WIRING REPAIR, HOLDER CONNECTOR	1	300.00	300.00 CRA✓
20.	WITH LABOUR TO REPLACE & REPAIR	1	900.00	900.00
	PANEL BEATING & SPRAY PAINTING			
	WIRING REPAIR			
	FRONT BUMPER			
	RADIATOR			
	COOLANT			
	BLEED COOLANT SYSTEM			

- ALL ABOVE IS ORIGINAL PARTS.

The details and the estimate provided above are based on our first inspection and do not constitute a guarantee that no further work/parts will be required. The total bill of work will be as per the details available on completion of the work.

Other terms and conditions as applicable.

Yours faithfully,

Yan
(Administrator)



Sub Total 9,095.00

GST 7.0 % 636.65

Total 9,731.65

Parts 5720.00
LN 700.00
NET 6420.00
30/4/19

Veron Chen (LKKAUTO)

From: Best Auto K <bestautokpl@gmail.com>
Sent: Thursday, 24 January 2019 2:39 PM
To: Catherine Thia; Veron Chen (LKKAUTO)
Cc: L. K. Ang Construction Pte Ltd
Subject: PC7619P - Surveyor Form
Attachments: Scan_0002.pdf

Hi Catherine and Veron,

Kindly refer to attached pre-repair surveyor form.

Thanks & Regards,

Yan

Best Auto K Pte Ltd
2 Kaki Bukit Ave 2 #01-11 Auto Hub Singapore 417921
T: 6604 9883 F: 6604 9823

BEST AUTO K PTE LTD

Co. GST Reg. No.: 201211041G

2 KAKI BUKIT AVE 2 #01-11 AUTO HUB SINGAPORE 417921

Tel: 6604 9883

Fax: 6604 9823

Email: bestautokpl@gmail.com

PRE-REPAIR SURVEYOR FORM

L.K. ANG CONSTRUCTION PTE LTD
459 TAGORE INDUSTRIAL AVENUE
#04-08 SINGAPORE 787828

Our Ref : RS2019/1801
Date : 24/01/2019
Reg No : PC 7619 P
Model : Toyota HiAceDX 2.8 Auto
Accident Date : 12/01/2019

INSURANCE CO :-
CHINA TAIPING INSURANCE (SINGAPORE) PTE .LTD.
3 ANSON ROAD, #16-00
SPRINGLEAF TOWER SINGAPORE
079909

Inspected At : BEST AUTO K PTE LTD
2 Kaki Bukit Avenue 2, #01-11
Kaki Bukit AutoHub Singapore 417921

Estimated Period of Repair : 8 Days

FOR SURVEYOR

Please initial here after completion of pre-repair inspection. Thank you.

Appointed surveyor
(Name & Signature)

LIM TEOW GUAN



Resurvey

Date & Time of Inspection : 24/1/19 1345

Yours faithfully

Yan
Administrator


26/2/19.

YUNG SOON AUTO SUPPLY CO.

24, Upper World Road Singapore 207181
TEL: 62960824 Lines FAX: 62968711 Email: yung_soon2003@yahoo.com.sg
GST REG NO: S48-0002705-X BOC REG NO: 218060000M

QUOTATION

TO: BEST AUTO K PTE LTD

2 KAKI BUKIT AVENUE 2
#01-11 AUTO HUB
SINGAPORE 417921

TEL: 6604 9883 (98438331 ah FAX: 6604 9823
(xsb)

ATTN: LHHONG

NO: YSQT19050001

PAGE: 1/2

DATE: 25 Jan 2019

A/C CODE: B0004

TERM: 30 DAYS

YOUR REF:

Part No	Due Dat	Description	Quantity	Unit Price SIN	Amount SIN
TOYOTA		KDH200 FRONT LEFT HEAD LAMP	1 PCE	1,760.00	1,760.00
TOYOTA		KDH200 FRONT BUMPER	1 PCE	360.00	360.00
TOYOTA		KDH200 FRONT BORNET	1 PCE	544.00	544.00
TOYOTA		KDH200 FRONT BUMPER BRACKET LEFT	1 PCE	72.00	72.00
TOYOTA		KDH200 FRONT BUMPER GRILLE INNER	1 PCE	256.00	256.00
TOYOTA		KDH200 FRONT BUMPER UPPER PANEL	1 PCE	224.00	224.00
TOYOTA		KDH200 FRONT BUMPER LOWER PANEL	1 PCE	192.00	192.00
TOYOTA		KD200 FRONT BUMPER LOWER GRILLE	1 PCE	120.00	120.00
TOYOTA		KDH200 FRONT WIPER GARNISH	1 PCE	304.00	304.00
TOYOTA		KDH200 FRONT BUMPER TOP BEAM	1 PCE	176.00	176.00
TOYOTA		KDH200 FRONT BUMPER SAFETY BAR SUPPORT	1 PCE	200.00	200.00
TOYOTA		KDH200 FRONT BUMPER GRILLE SMALL LEFT	1 PCE	72.00	72.00
TOYOTA		KDH200 RADIATOR TOP PANEL	1 PCE	156.00	156.00
TOYOTA		KDH200 RADIATOR SPARE TANK	1 PCE	256.00	256.00
TOYOTA		KDH200 RADIATOR SUPPORT LEFT	1 PCE	148.00	148.00
TOYOTA		KDH200 WIPER TANK	1 PCE	128.00	128.00
TOYOTA		KDH200 ADD BLUE SPARE TANK	1 PCE	760.00	760.00
TOYOTA		KDH200 WIRING BARCKET LEFT	1 PCE	68.00	68.00

YUNG SOON AUTO SUPPLY CO.

24 Upper World Road Singapore 207181
TEL: 62960088 (4 Lines) FAX: 62968731 Email: yung_soon2003@yahoo.com.sg
GST REG NO: S456 8002700-N, UIC NO: 963218000004

TO: BEST AUTO K PTE LTD

QUOTATION

NO: YSQT19050001
PAGE: 2/2

Total	SIN 5,796.00
Add GST @ 7%	405.72
Grand Total	SIN 6,201.72

GAPORE DOLLAR SIX THOUSAND TWO HUNDRED AND ONE AND CENTS SEVENTY TWO ONLY

Auto K Pte Ltd

For Yung Soon Auto Supply Co.

FIRMED & ACCEPTED BY

AUTHORISED SIGNATURE
SULIN



SL AUTO PARTS TRADING

#05-136 Veerasani

Singapore - 200633

E-mail :slautoparts2018@gmail.com

No. 22948

Date: 29. 1. 2019

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99	100
---	---	---	---	---	---	---	---	---	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	-----

1997

100

Messrs: Best Auto & Pte Ltd

Item	Description	Quantity	Unit Price	Amount
1	Bolt 20 Front Bumper Bracket LH	1 pc		\$70.00
2	Bolt 20 Front Bumper Grille Inner	1 pc		230.00
3	KD H 20 Bumper Upper Panel	1 pc		200.00
4	Bolt 20 Bumper Lower Panel	1 pc		160.00
5	Bolt 20 Front Bumper Top Beam	1 pc		180.00
6	Bolt 20 Front Bumper Safety Support	1 pc		150.00
7	Bolt 20 Radiator Top panel	1 pc		150.00
8	Bolt 20 Radiator Spare Tank	1 pc		280.00
	E. & O. E.			
			Sub Total	
			GST	
			Total Amount	\$1020.00

Received by _____

Authorised Signature

Authorised Signature

E-mail : slautoparte2018@gmail.com

No. 23001

Date: 15. 4. 2019

Terms:

P/O No:

Order by:

Messrs:

Best Auto 12 Pte Hd

[illegible]

Total Amount

950.00

Received by _____

Authorized Signature

Sumit

日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M



Wiper blade: NWB (Nippon Wiper blade), Silper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

CASH SALES

CASH

TAX INVOICE : AR201901-14379
DATE : 28/01/2019
CUSTOMER ID : CAS001
VEH REG. NO. :
TERMS : CASH
PO NO. :
PAGE NO. : Page 1 of 1
CURR. : SGD

ATTN : 98438331

BLK 2 KAKI BUKIT AVE 2 #01-11 AUTO HUB

3Q STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1 TS3113-26050	FRT BUMPER GRILLE LH	UI	1	40.00	40.00 *
HLACE-KDHE201 13"		SUPPLIER			

TO COLLECT : 42.80

SUB-TOTAL : 40.00
ADD GST 7.00% : 2.80

E & O E TOTAL AMOUNT SGD : 42.80

[P] 28/01/2019 9:37:29AM

[E] 28/01/2019 9:37:11AM

Goods Sold are not refundable for Cash

Interest Rate of 1.5% per month will be imposed on OverDue Account(s)

Goods Received in Good Order

JAE Auto Pte. Ltd.

Sales Executive : LOON



This is computer generated document.

No signature is required.

Signature / Co Stamp / Date

ORIGINAL



日美汽車私人有限公司

JAE AUTO PTE LTD

Bik 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9939



Dept Direct: 6417 9791

Dept Direct: 6417 9792

Dept Direct: 6417 9796

Dept Direct: 6417 9792

Wiper blade: NWB (Nippon Wiper blade), Silper (Made in Korea),
Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

CASH SALES

CASH

ATTN : 98438331

BLK 2 KAKI BUKIT AVE 2 #01-11 AUTO HUB

TAX INVOICE : AR201901-13264
DATE : 25/01/2019
CUSTOMER ID : CAS001
VEH REG. NO. : PC7619P
TERMS : CASH
PO NO. :
PAGE NO. : Page 1 of 1
CURR. : SGD

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1	T55708-26080/90 KDH200	WIPER GARNISH	U1 L3-E10	1	170.00	170.00
2	T57017-26010 KDH200	FRT REINF MEMBER L.H	U1 SUPPLIER	1	75.00	75.00 *

Radiator Support

TO COLLECT : 262.15

SUB-TOTAL : 245.00
ADD GST 7.00% : 17.15

E & O E TOTAL AMOUNT SGD : 262.15

[P] 25/01/2019 9:30:17AM

[E] 25/01/2019 9:14:13AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s)

JAE Auto Pte. Ltd.

Sales Executive : LOON



This is computer generated document.
No signature is required.

Goods Received in Good Order

Signature / Co Stamp / Date

ORIGINAL

日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

CASH SALES REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

ATTN :

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 8838



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6

Wiper blades: NWB (Nippon Wiper blade), Siliper (Made in Korea)

Spark plug: NGK (NGK Spark Plug)

TAX INVOICE AR201901-1569

DATE : 29/01/201

CUSTOMER ID : CAS00

VEH REG. NO. :

TERMS : CASI

PO NO. :

PAGE NO. : Page 1 of

CURR. : SGI

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUN
1. T53112-26070 KDH201 14	FRT BUMPER LWR GRILLE	U1 L2-A7	1	70.00	70.0

TO COLLECT : 74.90

SUB-TOTAL : 70.0

ADD GST 7.00 % 4.5

E & OE

TOTAL AMOUNT SGD : 74.9

[P] 29/01/2019 3:15:41PM

[E] 29/01/2019 3:14:30P

Goods Sold are not refundable for Cash

Interest Rate of 1.5% per month will be imposed on OverDue Account(s)

JAE Auto Pte. Ltd.

Sales Executive : LOON



AR201901-15691

This is computer generated document.

No signature is required.

Goods Received in Good Order

Signature / Co Stamp / Date

ORIGINAL

日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 5781 / 5745 9930



Dept Direct: 6417 5784

Dept Direct: 6417 5785

Dept Direct: 6417 5786

Dept Direct: 6417 5787

Wiper blade: HWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

CASH SALES

TAX INVOICE : AR201901-15454

DATE : 29/01/2019

CUSTOMER ID : CAS001

VEH REG. NO. : PC7619P

TERMS : CASH

PO NO. :

PAGE NO. : Page 1 of 1

CURR. : SGD

ATTN : 98438331

BLK 2 #01-11 KAKI BUKIT AVE 2 AUTO HUB

CASH

SO STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
TS2666-26322	HOLDER CONNECTOR	U1	1	55.00	55.00 *
KDH200 2014		L2-C8-G			

Handwritten: eP 29/1/19 CR

TO COLLECT : 58.85

SUB-TOTAL : 55.00
ADD GST 7.00 % 3.85

E & O E

TOTAL AMOUNT SGD : 58.85

[P] 29/01/2019 11:58:07AM

[E] 29/01/2019 11:57:48AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

Goods Received in Good Order

JAE Auto Pte Ltd.

Sales Executive LOON



4 8 2 0 9 0 7 - 1 5 4 5 4 *

This is computer generated document.

No signature is required.

Signature / Co Stamp / Date

ORIGINAL

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Jan 2019		16 Jan 2019 16:53 Edit Adj Rpt	S\$6,420.00 Edit Estimates	S\$6,420.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	L.K.CONSTRUCTION PTE LTD, Co. Reg. No.: 198600969E								
Vehicle Reg. No.:	PC7619P	Date of Loss:	12/01/2019 00:00 - :59 [2 Months and 28 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / SNM19D0200281	Policy/Cover Note No.:	DMCVSN30670818000 (Comprehensive)						
		Excess:	S\$1,500.00						
Repairer:	Best Auto K Pte Ltd (HQ) 2 Kaki Bukit Avenue 2, #01-11 Kaki Bukit Autohub, 417921 Kaki Bukit - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Catherine Thia]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Lim Teow Guan] ... [Final Rpt due 25/01/2019]								
Adj Asg. Remarks:	ALREADY ASSIGN VIA EMAIL TODAY								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- CHINA_TAIPING (22/01/2019): Alert - Adj Mandate Approved (S\$6660.00) - PC7619P - Claim Handler: Catherine Th... - CHINA_TAIPING (22/01/2019): Alert - Adj Mandate Approved (S\$6660.00) - PC7619P - Claim Handler: Catherine Th...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*PC7619P (SNM19D0200281)
 OD
 Jan 12 2019 12:00AM
 [L.K.CONSTRUCTION PTE LTD]
 Best Auto K Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	21/01/19 14:32	Adjuster Immediate Advice	Load HTM	
Photos/Images				
			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	21/01/19 14:25	General View	Load PDF	
2	17/05/19 14:59	Reinspection Photo (1)	Load PDF	
3	17/05/19 15:00	Reinspection Photo (2)	Load PDF	
Documentation				
			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	21/01/19 14:33	MARK ESTIMATE	Load PDF	
2	06/06/19 09:00	Parts Invoice	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset Save Print
There are no document checklists configured.		
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) 		
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.		

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI19000996/BVD3E2

Date: 06/06/2019

REFERENCE

Insured/Claimant: L.K.CONSTRUCTION PTE LTD Policy No: DMCVSN30670818000

Date of Loss: 12/01/2019

Nature of Claim: OD

Claim No: SNM19D0200281

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PC7619P	Engine No:	1GD8299248
Make & Model:	TOYOTA HIACE, 2.8 D (A)	Chassis No:	GDH2011009131
Reg. Date:	15/10/2018 (Man. Year: 2018)	Odometer:	11640 km
Colour:	White		
Engine Capacity:	2754 cc		
Market Value/New Car Price:	S\$68,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/80 R15	Rear Tyre Size:	195/80 R15
Front Left Side:	Dunlop 7 mm	Rear Left Side:	Dunlop 7 mm
Front Right Side:	Dunlop 7 mm	Rear Right Side:	Dunlop 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,195.00	5,920.00	2,275.00	27.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	900.00	500.00	400.00	44.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,095.00	6,420.00	2,675.00	29.41
- Excess (S\$)	1,500.00	1,500.00	0.00	0.00
(S\$)	7,595.00	4,920.00	2,675.00	35.22
+ GST 7.00/7.00% (S\$)	531.65	344.40	187.25	35.22
Nett Amount (S\$)	8,126.65	5,264.40	2,862.25	35.22

INSPECTION

Date of Assignment: 16/01/2019

Date Inspected: 16/01/2019 Inspected At:

Best Auto K Pte Ltd (HQ)
2 Kaki Bukit Avenue 2, #01-11 Kaki Bukit
Autohub
Singapore 417921

Estimated Period of Repair: 5.0 days

Adjuster: Lim Teow Guan

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 04 Jun 2019)	
Parts:	N/A	TOYOTA HIACE 2.8 D (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PC7619P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT LEFT HEAD LAMP (WCP)	Broken	2,200.00 F	*1,560.00 F
2	1	*FRONT BUMPER (WCP)	Broken	450.00 F	*380.00 F
3	1	*FRONT BONNET (WCP)	Dented	680.00 F	*480.00 F
4	1	*FRONT BUMPER BRAKET (LEFT) (WCP)	Broken	90.00 F	*70.00 F
5	1	*FRONT BUMPER GRILL INNER (WCP)	Broken	320.00 F	*230.00 F
6	1	*FRONT BUMPER GRILL UPPER PANEL (WCP)	Dented	280.00 F	*200.00 F
7	1	*FRONT BUMPER GRILL LOWER PANEL (WCP)	Dented	240.00 F	*160.00 F
8	1	*FRONT BUMPER LOWER GRILL (WCP)	Cracked	150.00 F	*70.00 F
9	1	*FRONT WIPER GARNISH (WCP)	Broken	380.00 F	*170.00 F
10	1	*FRONT BUMPER SAFETY BAR SUPPORT (WCP)	Dented	250.00 F	*150.00 F
11	1	*FRONT BUMPER GRILL SAMLL (LEFT) (WCP)	Cut	90.00 F	*40.00 F
12	1	*RADIATOR TOP PANEL (WCP)	Dented	195.00 F	*150.00 F
13	1	*RADIATOR SPARE TANK (WCP)	Cracked	320.00 F	*280.00 F
14	1	*RADIATOR SUPPORT (LEFT) (WCP)	Bent	185.00 F	*75.00 F
15	1	*WIPER TANK (WCP)	Cracked	160.00 F	*100.00 F
16	1	*ADD BLUE SPARE TANK (WCP)	Cut	1,600.00 F	*850.00 F
17	1	*WIRING BRACKET (LEFT) (WCP)	Broken	85.00 F	*55.00 F
18	1	*FRONT BUMPER TOP BEAM (WCP)	Dented	220.00 F	*180.00 F
19	1	*WIRING REPAIR, HOLDER CONNECTOR (LOCAL REPAIR)	Cracked	300.00 FS	*200.00 FS

F=Franchise part. S=SpcNett.

Sub Total (S\$)	8,195.00	5,400.00
+ Margin on L,N Items 0.00/10.00% (S\$)	0.00	520.00
Total Parts (S\$)	8,195.00	5,920.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	WITH LABOUR TO REPLACE & REPAIR }	New	900.00	500.00
2	PANEL BEATING & SPRAY PAINTING }	New	0.00	0.00
3	WIRING REPAIR }	New	0.00	0.00
4	FRONT BUMPER }	New	0.00	0.00
5	COOLANT }	New	0.00	0.00
6	BLEED COOLANT SYSTEM }	New	0.00	0.00
Gross Labour Cost (\$\$)			900.00	500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >