

# 來發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267  
GST No: M2-0128609-3  
UEN: 199407592C

## ESTIMATE

EST. No: EST0021300  
Ang Sioe Hwa

Page: 1 of 1  
Your ref: TP-SHC 7571L MS FC  
Job No: 70141  
Our ref: 19.01.11  
Payment:  
Date: 16/1/2019

Attn:

Vehicle No: SDK 6968M  
Vehicle Model: Mercedes Benz E250  
Accident on: 3/1/2019

*Not Notified  
Resurvey B4 paint  
2 days*

*Direct Settle*

Quantity	Unit	Description	Unit price	Disc pct	Amount
Supply of Parts - Nett item:					
1.00	Pc	Rear bumper	1,505.00	10.00	<i>Pr</i> 1,354.50 ✓
1.00	Pc	Rear bumper parking sensor (outer left)	160.00	10.00	<i>Shan</i> 144.00 ✓
Labour & Mis:					
1.00		To check/erase fault code	60.00		60.00 ✓
1.00		To dismantle and renew above parts	200.00		200.00 ✓
1.00		To spray paint	300.00		300.00 <i>2800</i>

Sub-Total  
GST 7.00%  
Total

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

2,058.50  
144.10  
2,202.60

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."