

51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

Your Ref: 19.26052 PD-O

Date: 18th January 2019

Our Ref: CS1/LAW19001066/Evd3s2

M/s Seah Ong & Partners LLP

36 Robinson Road #12-03 City House Singapore 068877

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO:

FBL 1299L

INSURED VEHICLE: PC 3446Y ACCIDENT DATE: 08/11/2018

We thank you for your instruction on 15/01/2019.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of FBL 1299L from M/s KTO Automobile Assessors.
- b) Final Repair Bill of FBL 1299L from M/s Dynasty Motor Pte Ltd.
- c) Singapore Accident Statement of Vehicles FBL 1299L and PC 3446Y.
- d) Colour damaged vehicle photographs of FBL 1299L.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number

: FBL 1299L

Make & Model

: Kymco Xciting 400I ABS

Year of Registration

: 2016

Chassis Number

: RFBD60010G3300234

Engine Capacity

: 399 cc

- We recommend that the repairs of the entire damage require about 3 (Three) working days to complete.
- We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.