

ASS. REC. BY:

REF:

08/FCI19001181/Kg d3

N2

Special Instruction:

Surveyor:

CWS

ASSIGNMENT (Office)

From (Person):

Stheuer

of

FCI

Date/Time:

3:10pm @ 12/1/19

Estimated Cost:

Bill to:

OD / IP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SFV 7022D

Insured:

SHB 3311C

at Workshop m/s

Accord Auto

Tel:

97400999

of

10 AMK Ind. park 2A AMK Autopoint # 03-11

Policy No:

Claim No:

D19000533MF8H

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

13/01/2019

CA / REV / REP. / REV 24 HRS 'up'

21/01/2019

H.O.D. Endorsement:

Date/Time:

3:46pm @ 12/1/19

Person Contacted:

Jacklyn

Vehicle

IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SFV-7022D-X

SHB 3311C-CC4/ASM/7023454/K1p93s2

D.O.A.: 7/12/12

7/1/19 @ 4:43pm Verified to Serene Lee by email.

31/1

1/1 Long @ 2000il Confirm (Red @ 3085.04, 60%)
MV: @ 4816mm; LTA: @ 41090; NV: @ 6910

REF: FCI

ASSIGNMENT

From: Date: 21/01/2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SFV7022D

at Workshop n/s: Accord Auto

of 10 AMK Ind. Park 24 AMK Autopoint

Insured: #03-11

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up)

3/28

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SFV 7022D Yr Regn: 03 of 08

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Stream A1 NPV C.C. 1799

Colour: M. Silver A/C. Insured / Std / NI / NA

Sp. Reading: 226623 T/Radio: Insured / Std / NI / NA

Eng/No:

Ch/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / STD A/Rim or

Tyre Size: F: 205/85R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 8 mm


L/Bal. 8 mm

D.O.A. 17/1/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.



Date / Time Action / Instruction

22/1 File pass to Car

RECEIVED 31 JAN 2019

Date/Time, File Pass to?

11/3/11 turn in

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.I. (\$)

☐ : Preli. Report☐ : Final Report

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

) \$ + R5 \$

) Photos

) Others:

TOTAL

140

50

30

20

260



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19000533MFSH

Date: 22 January 2019

Our Ref: CS/FCI19001181/Kqd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SFV 7022D.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 21/01/2019 at the premises of M/s ACCORD AUTO, and have the following to report:-

Workshop Estimate Amount	: S\$ 5,045.04 .
Revised Estimate Amount	: S\$ 2,506.12 .
"Check" Items Amount	: S\$ - .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:

The vehicle sustained damages at the rear n/s portion.



Yours faithfully

KONG SENG CHEONG
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT**Date** 18-01-2019 **Our Ref No.** D19000533MFSH**Accident Date** 17-01-2019 **Claim Type.** Third Party**Insured Vehicle** SHB3311C **Third Party Vehicle.** SFV7022D**Survey Location** 10 ANG MO KIO INDUSTRIAL PARK 2A AMK AUTO POINT #03-11**Contact Person.** JESSY SOE**Contact No.** 64819517/ 97400999 **Fax No.** 68419516**Survey Type** WITHOUT PREJUDICE:**Appointed Surveyor** LKK AUTO CONSULTANTS PTE LTD**Contact Person** NA **Fax No.** 68416315**Contact Number.** NA**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST**Cc : Workshop** ACCORD AUTO SERVICES PTE LTD **Attention.** NIL**Cc : TP Solicitor** NA **TP Solicitor Fax No.** NA**Officer Incharge** SITHARA**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 22 January 2019 4:43 PM
To: 'CWS Motor Claims'; assignments
Cc: 'Sithara'; SUR
Subject: RE: SURVEY ASSESSMENT - D19000533MFSH/1
Attachments: CSFCI19001181Kqd3.pdf

Dear Sithara,

Enclosed herewith preliminary advice of SFV 7022D.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Friday, 18 January 2019 3:52 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Sithara' <Sithara@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19000533MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed repairer agreed survey on 21/01/2019.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Friday, 18 January 2019 3:10 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Sithara <Sithara@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19000533MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2936A
Vehicle Details	
Vehicle No.:	SFV7022D
Vehicle to be Exported:	No
Intended Deregistration Date:	31 Jan 2019
Vehicle Make:	HONDA
Vehicle Model:	STREAM 1.8L A
Primary Colour:	Silver
Manufacturing Year:	2007
Engine No.:	R18A12802379
Chassis No.:	JHMRN68408S202378
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$20,486.00
Original Registration Date:	19 Mar 2008
First Registration Date:	19 Mar 2008
Transfer Count:	0
Actual ARF Paid:	\$20,486.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	18 Mar 2028
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$44,998.00
COE Rebate Amount:	\$41,090.00
Total Rebate Amount:	\$41,090.00

The information contained herein is correct as at 31 Jan 2019

OK

> [Back to OneMotoring](#)

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	SFV7022D		
Vehicle Type :	P11 - Passenger Station Wagon/Jeep/Land Rover		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	HONDA		
Vehicle Model :	STREAM 1.8L A		
Chassis No. :	JHMRN68408S202378		
Propellant :	Petrol		
Engine No. :	R18A12802379		
Engine Capacity :	1799 cc		
Maximum Power Output :	103.0 kW (138 bhp)		
Maximum Laden Weight :	1775 kg		
Unladen Weight :	1370 kg		
Year Of Manufacture :	2007		
Original Registration Date :	19 Mar 2008		
Lifespan Expiry Date :	-		
COE Category :	B - Car (1601cc & above)		
PQP Paid :	\$44,998.00		
COE Expiry Date :	18 Mar 2028		
Road Tax Expiry Date :	18 Mar 2019		
Inspection Due Date :	18 Mar 2019		
Intended Transfer Date :	18 Jan 2019		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
The current road tax expiry is 18 Mar 2019. You may renew the road tax from 19 Dec 2018 with all pre-requisite(s) fulfilled. If the road tax is renewed after 18 Mar 2019, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable (From 19 Mar 2019 to 18 Sep 2019)			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	587.00	-	587.00
Total Amount Payable :			612.00
Amount Payable (From 19 Mar 2019 to 18 Mar 2020)			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	1,174.00	-	1,174.00
Total Amount Payable :			1,199.00

You may print this page for reference.

OK

Print

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

ESTIMATE

MS First Capital Insurance Limited
36, Robinson Road
#16-01 City House
Singapore 068877
Attn: Motor Claims Department

Date : 18/01/2019
Vehicle No : SFV7022D
Veh Make/Model : Honda Stream 1.8L A
YOM : 2007
Chassis No : JHMRN68408S202378
Date of Accident : 17/01/2019

Not Authorised
11/1/19
Murray Alan Paim
Edgar

No	Qty	Description	Amount \$
List Items:-			
1	1	Tail gate	\$ 903.20
2	1	Tail gate "STREAM" emblem	\$ 31.60
3	1	Tail gate weatherstrip	\$ 121.60
4	1	LH tail lamp	\$ 352.90
5	1	Rear LH fender	\$ 808.30
6	1	Rear bumper	\$ 588.90
7	1	Rear bumper tow cover	\$ 23.50
8	2	Rear bumper side retainer	\$ 38.80
Total - List Item			\$ 2,868.80
Less 20%			\$ 573.76
Total			\$ 2,295.04
Special Nett Items:-			
1	1	Rear number plate with holder	\$ 55.00
2	1 Set	Rear reverse sensor	\$ 380.00
3	10	Rear bumper clip	\$ 35.00
Total - SN Item			\$ 470.00
Labour Charges:-			
1		Spray painting on all affected area.	\$ 900.00
2		Labour remove/refix accident damages parts to knock, jack, cut weld and realign accident affected area.	\$ 1,000.00
3		To apply anti rust treatment.	\$ 120.00
4		To check wiring system & light.	\$ 80.00
5		To remove and replace reverse sensor.	\$ 120.00
6		To check and test tailgate water leaking.	\$ 60.00
Total - L/C			\$ 2,280.00
Sub-Total			\$ 5,045.04
7% GST			\$ 353.15
Total			\$ 5,398.19

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
Signature:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19001181/Kqd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 01-02-2019	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHB 3311C	Veh. Inspected	SFV 7022D
Policy No.		Coverage (\$)	0.00
Claim No.	D19000533MFSH	Excess (\$)	0.00
Assign From	SITHARA	Assign Date	18/01/2019
2. Vehicle Particulars & Condition			
Make & Model	HONDA STREAM (A)	c.c	1799
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	JHMRN68408S202378	Colour	METALLIC SILVER
Odometer	226625	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/65 R15	WEST LAKE	8 mm
L/H Front Tyre	205/65 R15	WEST LAKE	8 mm
R/H Rear Tyre	205/65 R15	WEST LAKE	8 mm
L/H Rear Tyre	205/65 R15	WEST LAKE	8 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	17/01/2019	Inspection Date	21/01/2019
Survey held at	ACCORD AUTO SERVICES PTE LTD 10 ANG MO KIO INDUSTRIAL PARK 2A AMK AUTO POINT #03-11 SINGAPORE 568047		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFV 7022D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	TAIL GATE	BENT	903.20	903.20
1	TAIL GATE "STREAM" EMBLEM	NECESSARY	31.60	31.60
1	TAIL GATE WEATHERSTRIP	SERVICEABLE	121.60	-
1	LH TAIL LAMP	CRACKED	352.90	352.90
1	REAR LH FENDER	TO REPAIR SEE LABOUR	808.30	-
1	REAR BUMPER	BUCKLED / CRACKED	588.90	588.90
1	REAR BUMPER TOW COVER	DENTED	23.50	23.50
2	REAR BUMPER SIDE RETAINER	DISTORTED	38.80	38.80
	LESS 20% DISCOUNT		-573.76	-387.78
			2,295.04	1,551.12
SPECIAL NETT ITEMS				
1	REAR NUMBER PLATE WITH HOLDER (SN)	SERVICEABLE	55.00	-
1	SET REAR REVERSE SENSOR (SN)	SERVICEABLE	380.00	-
10	REAR BUMPER CLIP (SN)	NECESSARY	35.00	35.00
			470.00	35.00
LABOUR				
	SPRAY PAINTING ON ALL AFFECTED AREA.		900.00	420.00
	LABOUR REMOVE/REFIX ACCIDENT DAMAGES PARTS TO KNOCK,JACK,CUT WELD AND REALIGN ACCIDENT AFFECTED AREA.INCLUSIVE OF THE REPAIR OF REAR LH FENDER.		1,000.00	400.00
	TO APPLY ANTI RUST TREATMENT.		120.00	30.00
	TO CHECK WIRING SYSTEM & LUGHT.		80.00	20.00
	TO REMOVE AND REPLACE REVERSE SENSOR.		120.00	50.00
	TO CHECK AND TEST TAILGATE WATER LEAKING.	NOT NECESSARY	60.00	-
			2,280.00	920.00
GRAND TOTAL			5,045.04	2,506.12
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,000.00

Report Ref No. CS/FC19001181/Kqd3n2



Report Ref No. CS/FCI19001181/Kqd3n2

MARKET VALUE: \$48,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$41,090.00=NETT VALUE: \$6,910.00

A handwritten signature in black ink, appearing to read 'KSC'.

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.